## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2018 - Fall

25341

**Oracle Unit:** 

Address: 1000 W. 52nd St. Region: Mail Room: Asbestos Surveyor: Rivera, Amalio X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/17/2018 Email Address: lovedonthateme5@gmai A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Each child's backpack Notice printed in school's newsletter Notice printed in school's calendar Other HA No Material Description Material Material Material Location Asbestos Material Friable Damage Damage Damage Change in Assessment Category Quantity Units Type Category Quantity Units Type **Throughout Classrooms** X NO 12"x12" Brown Floor Tile YES Miscellaneous and Corridors 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

William T Sherman Elementary School

School:

5890

**Building ID:** 

1A	9" x 9" Brown Floor Tile w/ Burgundy Streaks - Abated	First and Second Floor Corridors		Miscellaneous			YES	X NO
0040 5 11 1			1					
2016 - Fall: N	lo Change							
Comments:								
2017 - Spring	g: No Change							
Comments:								
			1					
2017 - Fall: N	lo Change							
Comments:	-		]					
2018 - Fall: N	lo Change							
Comments:								
			1					
2018 - Spring	j : No Change							
Comments:	-		1					
			]					
			=					

Type

Material

Category

Damage Quantity Damage

Units

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1B	9" x 9" Black Floor Tile - Abated			First and Second Floor Corridors		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2A	12" x 12" Light Blue Floor Tile	400	SF	Office		Miscellaneous	No	Loc	1		YES X NO
					1						

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3	2' x 4' Ceiling Tile	5000	SF	Corridors		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
4	Hard Coat Plaster	20000	SF	1st & 2nd floors in 1936 Building		Surface	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	: No Change											
Comments:	J											

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	Acoustical Plaster	2000	SF	All Purpose Room		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

2018 - Fall: No Change

Comments:

Material Description

Material

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
6	Mastic for HA: 1A and 1B - Abated			Hallways		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Spring	g: No Change				1							
Comments:												
2017 - Fall: N	lo Change				=							
Comments:												
2018 - Spring	g : No Change				=							
Comments:												
2018 - Fall: N	lo Change				=							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7	12" x 12" Lt. Blue Floor Tile Mastic	400	SF	Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
8	6" x 6" Ceramic Border			Teacher's Restroom		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	-											
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9	6" x 6" Ceramic Border Grout			Teacher's Restroom		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
10	6" x 6" Ceramic Border Tile Mastic			Teacher's Restroom		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	V											
2017 - Spring	g: No Change				1							
Comments:												
2017 - Fall: N	lo Change											
Comments:	-											
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	Ţ.											
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	6" x 12" Ceramic Base Block			All Purpose Room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
12	6" x 12" Ceramic Base Block Grout			All Purpose Room		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	<u> </u>											
2017 - Spring	g: No Change				]							
Comments:					_							
2017 - Fall: N	lo Change				]							
Comments:					1							
	ı: No Change											
Comments:					1							
2018 - Fall: N	lo Change				]							
Comments:					-							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	6" x 8" Ceramic Off-White Tile			Restrooms		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
14	6" x 8" Ceramic Off-White Tile Mortar			Restrooms		Miscellaneous					YES	X NO
2016 - Fall: N	o Change				]							
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:	<u> </u>											
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	1" x 2" Ceramic Tile			Restrooms		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 9

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
16	1" x 2" Ceramic Tile Grout			Restrooms		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	J											
2017 - Spring	ı: No Change				1							
Comments:	,											
2017 - Fall: N	lo Change				1							
Comments:	Ţ.											
2018 - Spring	: No Change				1							
Comments:												
2018 - Fall: N	lo Change				1							
Comments:	<u> </u>				]							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	1" x 2" Ceramic Tile Mastic			Restrooms		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Туре	Category		Type	Quantity	Units		
18	Cinder Block			Throughout Building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:					1							
2017 - Fall: N	lo Change				]							
Comments:					1							
2018 - Spring	g : No Change				]							
Comments:					_							
2018 - Fall: N	lo Change											
Comments:	·				_							
					J							
	T			I was a series of			T =		_		- · · ·	

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	Cinder Block Mortar			Throughout Building		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
20	2" x 8" Ceramic Block			First and Second Floor Corridors, Restrooms		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	<u> </u>											
2017 - Spring	ı: No Change				1							
Comments:	<b>.</b>											
2017 - Fall: N	lo Change				_							
Comments:												
2018 - Spring	; No Change				-							
Comments:												
2018 - Fall: N	lo Change				_							
Comments:					]							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	2" x 8" Ceramic Block Mortar			First and Second Floor Corridors, Restroom		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

22	9" x 9" Fuzzy Black Floor Tile - Abated	First and Second Floor Corridors		Miscellaneous			YES	X NO
004C Fall N	la Ohanana		7					
2016 - Fall: N	lo Change							
Comments:								
2017 - Spring	: No Change							
Comments:								
2017 - Fall: N	lo Change							
Comments:								
2018 - Spring	ı : No Change							
Comments:								
2018 - Fall: N	lo Change							
Comments:								

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	9" x 9" Fuzzy Brown Floor Tile - Abated			First and Second Floor Corridors		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
24	Mastic for HA: 22 and 23 - Abated			Hallways		Miscellaneous					YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:	<b>.</b>											
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall: I	No Change				=							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	9" x 9" Green Floor Tile	28	SF	Engineer's Washroom		Miscellaneous	No	Loc	6		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

	1 44 4 4 4 5 6 4 4 4				1		1	1 -	_	_	O		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessn	nent Category
		- Cuantity	00		.,,,,,	- Catogoty		. )   0	- Cuarinty	O.m.o			
26	9" x 9" Green Floor Tile Mastic	28	SF	Engineer's Washroom		Miscellaneous	No	None	0		YES		X NO
		•											
2016 - Fall: N	No Change												
Comments:	-												
2017 - Spring	g: No Change												
Comments:													
2017 Fall: N	lo Chango												
2017 - Fall: N	no Change												
Comments:													
2018 - Spring	g : No Change												
Comments:													
<u> </u>													
2018 - Fall: N	No Change												
Comments:		•	•										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	9" x 9" Red/Orange Floor Tile - ABATED			Rm. 103		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

28	9" x 9" Light Orange Floor Tile - ABATED		Rm. 103		Miscellaneous			YES	X NO
				1					
2016 - Fall: N	o Change								
Comments:									
2017 - Spring	: No Change								
Comments:									
2017 - Fall: N	o Change								
Comments:	-								
2018 - Spring	: No Change								
Comments:	-								
2018 - Fall: N	o Change								
Comments:									
				•					

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	9" x 9" Orange Floor Tile w/ Burgundy Streaks - ABATED			Rm. 103		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
30	HA 27, 28 & 29 Floor Tile Mastic - Abated			Rm. 103		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	V				]							
2017 - Spring	g: No Change				_							
Comments:												
2017 - Fall: N	lo Change											
Comments:					-							
2018 - Spring	; No Change				]							
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					_							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	2" x 2" Black Border Floor Tile - Abated			First and Second Floor Corridors		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

32	2" x 2" Black Border Floor Tile Mastic - Abated		First and Second Floor Corridors	Miscellaneous			YES	X NO
2016 - Fall: N	lo Change							
Comments:	io Change							
Comments.								
2017 - Spring	: No Change							
Comments:	<u> </u>							
2017 - Fall: N	lo Change							
Comments:								
2018 - Spring	ı : No Change							
Comments:								
2018 - Fall: N	lo Change							
Comments:								

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	9" x 9" Tan/Yellow Floor Tile - Abated			All Purpose Room and 1st Floor North Bathroom		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
34	9" x 9" Tan/Yellow Floor Tile Mastic - Abated			All Purpose Room and 1st Floor North Bathroom		Miscellaneous					YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:	_											
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
					I							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	9" x 9" Salmon Floor Tile			All Purpose Room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
36	9" x 9" Salmon Floor Tile Mastic - Abated			All Purpose Room		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					1							
	; No Change											
Comments:					1							
2018 - Fall: N	lo Change											
Comments:					 							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	9" x 9" Off-White w/ Tan Speck Floor Tile			All Purpose Room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

38	Speck Floor Tile Mastic - ABATED			All Purpose Room		Miscellaneous					YES	X NO
2016 Fa	II: No Change		<u> </u>	·	7				•		,	
Comment					_							
Comment	J.				-							
2017 - Sp	ring: No Change											
Comment	S:											
2017 Fo	II: No Change				_							
Comment					+							
Comment	5.				_							
2018 - Sp	ring : No Change				1							
Comment	S:											
2018 - Fa	II: No Change				1							
Comment					1							
COMMINGING	<u>.                                    </u>				-							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

Damage

Туре

Туре

Damage

Quantity

Quantity

Damage

YES

X NO

Units

Units

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Quantity

Units

HA No

39

Material Description

9" x 9" Brown Floor Tile -

Abated

Material

Units

Material

Quantity

Material Location

2nd Floor Corridor

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
40	9" x 9" Red/ Brown Floor Tile - ABATED			2nd Floor Corridor		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	<u> </u>				]							
2017 - Spring	g: No Change				-							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:					]							
2018 - Spring	g : No Change				-							
Comments:												
2018 - Fall: N	lo Change				-							
Comments:					]							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Mastic for HA: 39 and 40 - ABATED			2nd Floor Corridor		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

Page 22

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
42	4" Black Vinyl Cove Base			All Purpose Room		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	· · ·				]							
2017 - Spring	ı: No Change				1							
Comments:	J											
2017 - Fall: N	lo Change				1							
Comments:	Ţ,				]							
2018 - Spring	ı : No Change				_							
Comments:	J											
2018 - Fall: N	lo Change				1							
Comments:	<u> </u>				]							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	4" Black Vinyl Cove Base Mastic			All Purpose Room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

44	Interior Metal Window Glaze	400	LF	Boiler Room		Miscellaneous	No	None	0	YES	X NO
					i						
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:	-										
2018 - Spring	: No Change										
Comments:	-										
2018 - Fall: N	o Change										
Comments:	-										
					<u>.</u>						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Interior Metal Window Glaze			1st & 2nd Floor of 1936 Bldg.		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
46	12" x 12" Tan Floor Tile- ABATED			Teacher's Washroom		Miscellaneous					YES	X NO
2016 - Fall: N	o Change				]							
Comments:	<u> </u>											
2017 - Spring	: No Change				_							
Comments:					]							
2017 - Fall: N	o Change											
Comments:					-							
2018 - Spring	: No Change				<u> </u>							
Comments:					-							
2018 - Fall: N	o Change											
Comments:												
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	12" x 12" Tan Floor Tile Mastic - Abated			Teacher's Restroom		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
48	9" x 9" Light Blue Floor Tile - Abated			All Purpose Room		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					-							
2018 - Spring	: No Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					-							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	9" x 9" Light Blue Floor Tile Mastic - Abated			All Purpose Room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Туре	Category	Type	Quantity	Units		
50	Window Blinds			Throughout Building		Miscellaneous				YES	X NO
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											
					J						

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	Interior Window Caulk	150	LF	1959 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	12" x 12" Cream Floor Tile	100	SF	Engineer's Office		Miscellaneous	No	Loc	5		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	12" x 12" Cream Floor Tile Mastic	100	SF	Engineer's Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
54	Exterior Brick-Non AHERA			1936 Building		Miscellaneous					YES	X NO
2016 - Fall: N	No Change											
Comments:	U											
2017 - Sprin	g: No Change											
Comments:	<u> </u>											
2017 - Fall: N	No Change											
Comments:	<u> </u>											
2018 - Fall: N	No Change											
Comments:	<u> </u>											
2018 - Sprin	g : No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	Exterior Brick Mortar-Non AHERA			1936 Bldg.		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
56	Interior Brick			1936 Basement		Miscellaneous				YES	X NO
2016 - Fall: N	lo Change										
Comments:											
2017 - Spring	j: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:											
	j : No Change										
Comments:											
		1	1								

Material

Friable

Damage

Damage

Damage

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	Interior Brick Mortar			1936 Basement		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Page 30

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
58	Exterior Window Caulk - Non AHERA			1936 Building		Miscellaneous					YES	X NO
2016 - Fall: N	o Change											
Comments:	•											
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:	•											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	Interior Window Block Mortar			1959 Building		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
60	Exterior Brick-NON AHERA			1959 Building		Miscellaneous					YES	X NO
2016 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Spring	: No Change											
Comments:					_							
2018 - Fall: N	o Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	Exterior Brick Mortar-NON AHERA			1959 Building		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
62	12" x 12" Light Brown w/ White Streaks - Abated			Rm. 101		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:					_							
2018 - Spring	: No Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	12" x 12" Light Brown w/ White Streaks Mastic - Abated			Rm. 101		Miscellaneous					YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
64	Brown Carpet Mastic			Library		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	<b>.</b>											
2017 - Spring	g: No Change											
Comments:	•											
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
					T	I	T =	_	_			

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	9: x 9" Tan Floor Tile - Abated			M.R.F. Room in Library and Under Carpet in Library		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

66	9: x 9" Tan Floor Tile Mastic - Abated			M.R.F. Room in Library and Under Carpet in Library		Miscellaneous					YES	X NO
2016 - Fa	II: No Change				1							
Comment					1							
Commen					1							
2017 - Sp	ring: No Change											
Comment	ts:											
0047	II. No Obosos				4							
	II: No Change											
Comment	ts:											
2018 - Fa	II: No Change											
Comment												
2018 - Sp	ring : No Change											
Comment	ts:											
		_			1	1						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Asbestos

Type

Material

Category

Category

Miscellaneous

Friable

Damage

Туре

Туре

Damage

Quantity

Quantity

Units

YES

X NO

Damage

Units

2016 - Fall: No	o Change		
Comments:			
2017 - Spring:	: No Change		
Comments:			
2017 - Fall: No	o Change		
Comments:			
2018 - Fall: No	o Change		
Comments:			
2018 - Spring	: No Change		
Comments:		•	·

Quantity

Units

HA No

67

Material Description

4" Black Vinyl Baseboard

Material

Units

Material

Quantity

Material Location

All Purpose Room

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessme	ent Category
68	4" Black Vinyl Baseboard Mastic			All Purpose Room		Miscellaneous					YES		X NO
2016 - Fall: N	lo Change				1								
Comments:													
2017 - Spring	: No Change				_								
Comments:					1								
2017 - Fall: N	lo Change				_								
Comments:					_								
2018 - Fall: N	lo Change												
Comments:					_								
2018 - Spring	: No Change												
Comments:					_								
[					1								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	Wrap on Fiberglass Duct Insulation	1000	LF	Basement		TSI	Yes	Loc	2		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 36

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
70	12" x 12" Black Patch Floor Tile - Abated			1st & 2nd Floor Corridors		Miscellaneous					YES	X NO
2016 - Fall: N	o Change				]							
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change				-							
Comments:												
2018 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change				<u> </u>							
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	12" x 12" Black Patch Floor Tile Mastic - Abated			1st & 2nd Floor Corridors		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72	12"X12" Off White Floor Tile	2290	SF	Cafeteria, Storage, Teacher's Washroom		Miscellaneous	No	None	0		YES X NO
					i						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	12"X12" Off White Floor Tile Mastic	2290	SF	Cafeteria, Storage, Teacher's Washroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
74	12"X12" Light Blue Floor Tile			Main Office		Miscellaneous					YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:					4							
2018 - Fall: N	o Change											
Comments:					4							
2018 - Spring	: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
75	12"X12" Light Blue Floor Tile Mastic			Main Office		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
76	12"X12" Off White w/marble Streaks Floor Tile	750	SF	Room 023		Miscellaneous	No	None	0		YES X NO
204C Fall N	a Changa										

2016 - Fall: No Change Comments: 2017 - Spring: No Change
Comments:
2017 - Spring: No Change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2019 Falls No Change
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	12"X12" Off White w/marble Streaks Floor Tile Mastic	750	SF	Room 023		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	ment Category
78	2' x 4' Ceiling Tile	3500	SF	2nd Floor Corridor Halls		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall: N	No Change				]								
Comments:					=								
2017 - Spring	g: No Change				1								
Comments:	<b>.</b>												
2017 - Fall: N	No Change				1								
Comments:	Ŭ												
2018 - Fall: N	No Change												
Comments:													
2018 - Spring	g : No Change				_								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
79	Ceramic Floor Tile w/ Grout	900	SF	1st and 2nd Floor Bathroom Entrances		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
80	Mastic Associated w/ Ceramic Floor Tile w/ Grout	900	SF	1st and 2nd Floor Bathroom Entrances		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
<u> </u>

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
81	Baseboard	130	LF	1st Floor Cafeteria		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
82	Mastic Associated w/ Baseboard	130	LF	1st Floor Cafeteria		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:					4							
	g: No Change											
Comments:					4							
2017 - Fall: N	No Change											
Comments:												
2018 - Fall: N	No Change				-							
Comments:	-				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	Cardboard Pipe Insulation	250	LF	Basement		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2018 - Spring : No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	Cardboard Pipe Insulation Fittings	40	LF	Basement		TSI	Yes	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Aircell Pipe Insulation	300	LF	Basement		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
D	Aircell Joint Insulation	50	LF	Basement		TSI	Yes	None	0		YES X NO	
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Joint Insulation On Fiberglass Runs	35	LF	Basement		TSI	Yes	Loc	3		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

G	2- Layer Tank Covering	150	SF	Basement and Basement Crawlspace		TSI	Yes	Loc	6	YES	X NO
0040 Fall N	. 01				Ī						
2016 - Fall: N	o Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2018 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											
	-			•							

Asbestos

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	Blue/Grey Fiberglass Duct Insulation			Basement							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Page 46

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
I	Fiberglass Silver Duct Insulation			Boiler Room							YES	X NO
2016 - Fall: N	No Change											
Comments:	J											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:	-											
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
	1.4			I				1 -	T =	T _		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	White Fiberglass Duct Insulation			Boiler Room							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	nt Category
К	Insulation Jackets on Boilers- Fiberglass			Boiler Room							YES	X NO
2016 - Fall: N	lo Change											
Comments:	Ü											
2017 - Spring	g: No Change											
Comments:	, <u> </u>											
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:	•											
2018 - Fall: N	lo Change											
Comments:	J											
						•						

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Insulation Jacket on Hot Water Tank- Fiberglass			Boiler Room							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	Fiberglass Pipe Insulation			Boiler Room, Pipe Chase							YES X NO
					1						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Oracle Unit: 25341

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: William T Sherman Elementary School
Date: 12/17/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 25341

SCHOOL'S ASBESTOS MANAGEMENT PLAN.