Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

25401

Oracle Unit:

Address: 4310 N Melvina Avenue Region: Mail Room: Asbestos Surveyor: BALLEN24 X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/17/2018 Email Address: ballen@learncharter.org A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type 12" x 12" Acoustic Ceiling Assembly Hall, 1932 YES 02 2000 SF X NO Miscellaneous Yes None 0 Building 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments:

Washington D Smyser Elementary School

School:

5960

Building ID:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
03	12"x12" Green w/ White Streaks VFT	1800	SF	Third Floor Corridor, 1932 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				1							
Comments:	-											
2017 - Spring	g: No Change											
Comments:					_							
2017 - Fall: N	No Change											
Comments:												
2018 - Fall: N	No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	12"x12" Brown Speckled VFT	3000	SF	2nd Floor Corridor & Room 205 (under carpet), 1932 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

				- 1932 Building							
004C Falls	No Obosos		•	•	7	•	•	•	•	•	•
2016 - Fall:											
Comments:					_						
2017 - Fall:	No Change										
Comments:	.				-						
2017 - Spring: No Change					1						
Comments:					=						
2018 - Fall:	No Change				=						
Comments:											
					_						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Damage

Туре

None

Damage

Quantity

0

Damage

Units

06	9"x9" Light Green VFT ABATED		Room 104 A & 104 B, 1932 Building
2016 - Fall: I	No Change		
Comments:			
2017 - Sprin	g: No Change		
Comments:			
2017 - Fall: I	No Change		
Comments:			
2018 - Fall: I	No Change		
Comments:			
		•	

HA No

05

Material Description

12"x12" Red VFT

Material

Quantity

2000

Material

Units

SF

Material Location

First Floor Corridor and

Main Office public space

Page 3

Change in Assessment Category

X NO

X NO

YES

YES

07	9"x9" Black VFT	1000	SF	Assembly Hall, 1932 Building	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	9"x 9" Tan VFT	4000	SF	Main Office Storage Rm; Main Office (under existing VFT & carpet); Principal's Office (under the carpet); Teachers' Restroom (107); 2nd Floor Teachers' Restroom; Library 303/305 (under the carpet) – 1932 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

		Quantity	Units		Туре	Category		Type	Quantity	Units		
09	12"x12" Brown VFT	300	SF	Engineers Office, 1932 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Spring Comments:	g: No Change											
2017 - Fall: N	lo Change											

Material

Damage

Friable

Damage

Damage

Comments:

2018 - Fall: No Change

Material

Material

Material Location

Comments:

Material Description

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12"x12" Green w/ White Streaks VFT Mastic	1800	SF	Third Floor Corridor, 1932 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 5

11	12"x12" Brown Speckled VFT Mastic	3000	SF	2nd Floor Corridor; Room 205 (under the carpet), 1932 Building		Miscellaneous	No	None	0		YES	X NO
204C Fall	No Change				٦							
	: No Change											
Comments	:											
2017 - Spri	ng: No Change											
Comments	:											
	-											
2017 - Fall:	: No Change											
Comments	:											
2018 - Fall:	: No Change											
Comments	· ·											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
1		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Type

Material

Category

Category

Miscellaneous

Friable

No

Damage

Type

Type

None

Damage

Quantity

0

Damage

Units

12	12"x12" Red VFT Mastic	2000	SF	Main Office public space - 1932 Building							
2016 - Fall: N	o Chango										
2016 - Fall: No Change											
Comments:											
	<u> </u>	·-	·	<u>-</u>							
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change			·							
Comments:											
2018 - Fall: N	o Change										
Comments:			•								
	•		·	•							

Material

Units

Material

Quantity

Material Location

2nd Floor Corridor; Room

First Floor Corridor and

HA No

Material Description

Change in Assessment Category

X NO

YES

2016 - Fall: N	o Change										
Comments:	o change										
2017 - Fall: N	o Change										
Comments:	Comments:										
2017 - Spring	· No Change										
Comments:	. No Onlange										
2018 - Fall: N	o Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

0

None

Damage

Units

HA No

13

14

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

9"x9" Light Green VFT Mastic ABATED

9"x9" Black VFT Mastic

Material

Units

SF

1000

Material Quantity

Material Location

Room 104 A & 104 B,

Assembly Hall, 1932

Building

1932 Building

Change in Assessment Category

X NO

X NO

YES

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	9"x9" Tan VFT Mastic	4000	SF	Main Office Storage Rm; Main Office (under existing VFT & carpet); Principal's Office (under the carpet); Teachers' Restroom (107); 2nd Floor Teachers' Restroom; Library 303/305 (under the carpet) – 1932 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"x12" Brown VFT Mastic	300	SF	Engineers Office, 1932 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	-
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

17	9"x9" Dark Red VFT	1000	SF	Assembly Hall, 1932 Building	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2017 - Spring	ı: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

Assembly Hall, 1932

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	9"x9" Dark Red VFT Mastic	1000	SF	Assembly Hall, 1932 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

19	12"x12" Black w/ White Streaks VFT	250	SF	Engineer's Storage (under the carpet) -1932 Building		Miscellaneous	No	None	0	YES	X NO
2016 - Fa	II: No Change			·]						
Comment					-						
Comment	ა.										
2017 - Sp	ring: No Change										
Comment											
0047	II. No. Ohomoro										
	II: No Change										
Comment	S:										
2018 - Fa	II: No Change										
Comment											
]						

Type

Asbestos

Type

Material

Material

Category

Miscellaneous

Category

Friable

Friable

No

Damage

Damage

Type

None

Type

Damage

Quantity

Damage

Quantity

0

Damage

Damage

Units

Units

20	Streaks VFT Mastic	250	SF	(under the carpet) -1932 Building						
					7					
2016 - Fall: N	o Change									
Comments:										
2017 - Fall: No Change										
Comments:										
]					
2017 - Spring	: No Change									
Comments:]					
2018 - Fall: N	o Change									
Comments:										

Material

Quantity

250

Material

Quantity

Material

Material

Units

SF

Units

Material Location

Engineer's Storage

Material Location

Engineer's Storage

(under the carpet) -1932

HA No

HA No

20

Material Description

Material Description

12"x12" Black w/ White

Change in Assessment Category

Change in Assessment Category

YES

X NO

21	12"x 12" Black VFT	250	SF	Engineer's Storage (under the carpet) -1932 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change			·	7							
	NO Change				-							
Comments:												
2017 - Fall: I	No Change											
Comments:	<u> </u>											
2017 - Sprin	g: No Change											
Comments:	<u> </u>											
2018 - Fall: 1	No Change											
Comments:												
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
1		Quantity	Units		Type	Category		Type	Quantity	Units	1	

Type

Material

Category

Miscellaneous

Friable

No

Damage

Туре

None

Damage

Quantity

0

Damage

Units

22	12"x12" Black VFT Mastic	250	SF	(under the carpet) -1932 Building									
2016 Falls N													
2016 - Fall: N	no Change												
Comments:													
2017 - Fall: N	No Change												
Comments:													
2017 - Spring	g: No Change												
Comments:													
2018 - Fall: N	No Change												
Comments:	·			·									
		•											

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Engineer's Storage

Page 11

YES

Change in Assessment Category

X NO

23	9"x 9" Black w/ White Streaks VFT(Under HA # 108)	900	SF	Rooms 105A & 105B, 1932 Building	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: I	No Change					•				
Comments:										
2017 - Sprin	g: No Change									
Comments:										
2017 - Fall: I	No Change									
Comments:										
2018 - Fall: I	No Change									
Comments:	·			·						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	9"x 9" Black w/ Wht Strks VFT Mastic(Under HA#108)	900	SF	Rooms 105A & 105B, 1932 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

25	12"x12" Cream w/ Light Brown Specks VFT ABATED			Rooms 104A & 104B, 1932 Building		Miscellaneous					YES	X NO
0040 5 11 1		•	•	•	7	•	•	•	•	•	•	
2016 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:	<u> </u>											
	_		•		_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Friable

Damage

Туре

Damage

Quantity

Damage

Units

		,		
26	12"x12" Cream w/ Light Brown Specks VFT Mastic ABATED			Rooms 104 A & 104 B, 1932 Building
2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				
		•	•	_

HA No

Material Description

Material

Quantity

Material

Units

Material Location

YES

X NO

101	12" X 12" Grey VFT	9500	SF	Throughout, 1998 Annex		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	V											
2017 - Fall: N	lo Change				1							
Comments:	V											
2017 - Spring	ı: No Change				1							
Comments:												
2018 - Fall: N	lo Change											
Comments:	Ţ.											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

Damage

Quantity

0

None

Damage

Units

2016 - Fall: No Change			
Comments:			
2017 - Fall: No Change			
Comments:			
2017 - Spring: No Change			
Comments:			
2018 - Fall: No Change			
Comments:	•	•	

9500

Material

Quantity

Material

Units

SF

Material Location

Throughout, 1998 Annex

HA No

102

Material Description

12" X 12" Grey VFT Mastic

YES

X NO

103	2' x 4' Ceiling Tile	10000	SF	Throughout, 1998 Annex		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:]							
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:					-							
2018 - Fall: N	No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

Yes

Damage

Type

None

Damage

Quantity

0

Damage

Units

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No

104

Comments:

Comments:

Comments:

Comments:

Material Description

Drywall

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material

Quantity

Material

Units

SF

10000

Material Location

Throughout, 1998 Annex

YES

X NO

105	Drywall Joint Compound	8000	SF	Throughout, 1998 Annex		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:	<u> </u>											
2017 - Spring	g: No Change				}							
Comments:												
2017 - Fall: N	No Change											
Comments:					 							
2018 - Fall: N	No Change											
Comments:					 							
			J									
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
		1			1							

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

HA No

106

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Vinyl Baseboard

Material

Quantity

5000

LF

Material

Units

Material Location

Throughout, 1998 Annex

YES

X NO

107	Vinyl Baseboard Mastic	5000	LF	Throughout, 1998 Annex		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	Vo Change											
Comments:	10 Onange											
]							
2017 - Spring	g: No Change											
Comments:												
					_							
2017 - Fall: I	No Change											
Comments:					_							
					1							
2018 - Fall: I	No Change											
Comments:												
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

		-							-	
108	Carpet Mastic	2500	SF	Library (303/305); 205; 105 A/B; Main Office; Principal's Office; Assembly Hall; Engineer' s Office-Storage - 1932 Bldg.		Miscellaneous	No	None	0	
2016 - Fa	all: No Change]					
	Comments:									
2017 - Fa	all: No Change									
Commen	Comments:									
2017 - Sp	2017 - Spring: No Change									
Commen	Comments:									

HA No

2018 - Fall: No Change

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

YES

X NO

109	Fire Doors (Two)	2	EA	1st Floor Auditorium (Assembly Hall), Entry Doors - 1932 Bldg.		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: I	No Change				1						
Comments:	10 Change				_						
Comments.					_						
2017 - Fall: N	No Change										
Comments:	-										
2017 - Spring	g: No Change										
Comments:											
2018 - Fall: N	No Change										
Comments:											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
110	Heat Shield Insulation	240	SF	gymnasium between walls and duct cover		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
111	Terrazzo	6000	SF	Stairwells 1st, 2nd, and 3rd Floors; Corridors; Rm 104; Stage Stairs; Assembly Hall Vestibule; Balcony Stairs - 1932 Bldg		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:	J										
2017 - Spring	g: No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:											
					l						

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
112	2' x 2' Ceiling Tiles	1500	SF	Lunch Room (108/110) - 1932 Bldg		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

113	Linoleum Flooring	1600	SF	Lunch Room (108/110) - 1932 Bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	II: No Change]							
Commen												
2017 - Fa	II: No Change											
Commen	ts:				_							
	ring: No Change											
Commen	ts:				_							
2018 - Fa	II: No Change											
Comment	ts:				_							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

No

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

X NO

113A	Linoleum Flooring Mastic	1600	SF	Lunch Room (108/110) - 1932 Bldg
2016 - Fall: N	o Change			
	o Change			
Comments:				
2017 - Spring				
Comments:				
2017 - Fall: N	o Change			
Comments:				
2018 - Fall: N	o Change			
Comments:			•	

Quantity

Units

Material

Units

Material Quantity Material Location

Lunch Room (108/110) -

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
114	2' x 4' Smooth Ceiling Tile	600	SF	Kitchen - 1932 Bldg		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change]							
	017 - Fall: No Change											

Comments:
2017 - Spring: No Change

Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
115	12"X12" Off-white w/ Lt Tan Streaks VFT	700	SF	Rm 104; Main Office - 1932 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categorial	ory
115A	12"X12" Off-white w/ Lt Tan Streaks VFT Mastic	700	SF	Rm 104; Main Office - 1932 Bldg		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: No Change												

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
116	12" X 12" Beige W/ Brown & Beige Streaks Floor Tiles	144	SF	Rm 104 - 1932 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

116A	12" X 12" Beige W/ Brown & Beige Streaks Floor Tiles Mastic	144	SF	Rm 104- 1932 Bldg	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
	g: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	MJP E/F/V on Fiberglass Pipe Insulation	20	LF	Pipe Chases in Eng. Off. Storage and Brk Rm Tlt; Pipe chases in 1st -3rd Floor Boys Toilet and 2nd & 3rd Flr Girls Tlts - 1932 Buildng		TSI	Yes	None	0		YES X NO
2016 - Fall:	No Change]						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

		Quantity	Units		Type	Category		Type	Quantity	Units		
В	Air Cell Duct Insulation	440	SF	North & South Crawl Spaces, 1932 Building		TSI	Yes	None	0		YES	X NO
2016 - Fall: No Change												
Comments:	J											
2017 - Spring: No Change					_							
Comments:												

Material

Friable

Damage

Damage

Asbestos

2017 - Fall: No Change Comments:

Material

Material Location

Material Description

2018 - Fall: No Change

Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Air Cell Pipe Insulation	60	LF	North & South Crawl Spaces, 1932 Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	MJP E/F/V on Aircell Pipe Insulation	15	LF	North & South Crawl Spaces, 1932 Building		TSI	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	Cardboard Pipe Insulation	20	LF	North & South Crawl Spaces, 1932 Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

I	MJP E/F/V on Cardboard Pipe Insulation	10	SF	North & South Crawl Spaces, 1932 Building		TSI	Yes	None	0	YES	X NO
2016 - Fall: No Change											
Comments:											
2017 - Fall: No Change											
Comments:											
2017 - Spring: No Change											
Comments:											
2018 - Fall: No Change											
Comments:											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Mag Block Pipe Insulation	732	LF	Crawl Spaces; 2nd Floor Corridor by Rms 201 and 212; 1st Floor Vestibule by Rm 101; 1st Floor Corridor by Rm 108 (Lunch Rm); Teachers' Restroom (107) - 1932 Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	MJP E/F/V on Mag Block Pipe Insulation	133	LF	Throughout Crawl Spaces, 1932 Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Washington D Smyser Elementary School
Date: 12/17/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 25401

SCHOOL'S ASBESTOS MANAGEMENT PLAN.