Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Adlai E Stevenson Elementary School 25471 6030 School: **Oracle Unit: Building ID:** Address: 8010 S. Kostner Region: Mail Room: Asbestos Surveyor: Noe, Juan X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 11/28/2018 Email Address: jnoe@cps.edu A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type 1st and 2nd floor hall -YES 05 X NO 9x9 floor tile Miscellaneous 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

06	12x12 ft tan w/brown and green			1954 building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	10 Orlange				-							
2017 - Fall: N	Jo Chango											
Comments:	vo change				_							
2017 - Spring	g: No Change				-							
Comments:	<i>y</i>											
2018 - Fall: N	No Change				_							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
07	linoleum	4000	SF	1957 building- rooms 105, 107, 108, 110		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

(nurses office) and 111

HA No

Material Description

2016 - Fall: No Change

Material

Quantity

Material

Units

08	baseboard	2500	LF	1st and 2nd floor 1957 building, rooms 209 and 211		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change	<u> </u>	•	•	7			•				
	10 Change				-							
Comments:												
2017 - Fall: N	No Change											
Comments:												
					1							
2017 - Spring	g: No Change				1							
Comments:	•											
2018 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

No

Friable

Damage

Туре

Type

None

0

Damage

Quantity

Damage

Units

09	baseboard mastic	2500	LF	1957 building
			•	•
2016 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				
		•		

2500

LF

Material

Quantity

Material

Units

Material Location

1st and 2nd floor hall -

HA No

09

Material Description

baseboard mastic

Change in Assessment Category

X NO

	I .										
2016 - Fall: N	lo Change										
Comments:	io change										
2017 - Spring	g: No Change										
Comments:											
2047 Fall N	la Changa										
2017 - Fall: N	io Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

HA No

10

11

Comments:

Material Description

and brown

9x9 ft mastic

2016 - Fall: No Change

12x12 floor tile tan w/cream

Material

Quantity

18000

Material

Units

SF

Material Location

classrooms 1957 building

1st and 2nd floor hall -

1st & 2nd floor

Change in Assessment Category

X NO

X NO

YES

12	12x12 mastic			throughout 1957 building		Miscellaneous					YES	X NO
2016 - Fall:	No Change]							
Comments:					1							
2017 - Fall:	No Change											
Comments:] -							
2017 - Sprin	ng: No Change											
Comments:					-							
2018 - Fall:	No Change											
Comments:					 							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
40	12x12 mastic tan w/cream	40000	0.5	1st & 2nd floor		Minague	NI-	Nissa	0			Ty.

Type

Material

Category

Miscellaneous

No

None

0

Friable

Damage

Type

Damage

Quantity

Damage

-

YES

X NO

Units

18000

SF

Material

Quantity

Material

Units

Material Location

classrooms 1957 building

HA No

13

Material Description

and brown

14	linoleum mastic	4000	SF	1st floor 1957 building- Rooms 105, 107, 108, 110(nurse office) and 111	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	lo Change									
2017 - Fall: N Comments:	lo Change									
2017 - Spring Comments:	g: No Change									
2018 - Fall: N Comments:	lo Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
15	12" x 12" White w/ Beige Specks Floor Tile	20000	SF	1954 & 1957 1st and 2nd Floor Hallway		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change											
Comments	S:											
2017 - Spr	ring: No Change											

Comments:

2017 - Fall: No Change
Comments:

2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

16	Mastic Associated w/ 12" x 12" White w/ Beige Specks Floor Tile	20000	SF	1954 & 1957 1st and 2nd Floor Hallway		Miscellaneous	No	None	0		YES	X NO
0040 5 11		•	•	•	1	•	•	•	•	•	•	
	l: No Change											
Comments	S:											
2017 - Fall	l: No Change											
Comments	S:											
	-											
2017 - Spr	ing: No Change											
Comments	S:											
					1							
2018 - Fall	l: No Change											
Comments	S:											
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

TSI

Asbestos

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

2016 - Fall: No	Change			
Comments:				
2017 - Spring:	No Change			
Comments:				
				,
2017 - Fall: No	Change			
Comments:				
2018 - Fall: No	Change			
Comments:				·

Material

Quantity

Material

Units

Material Location

54 basement boiler room

HA No

Material Description

aircell pipe insulation -

abated

Mastic Associated w/ 12" x

Change in Assessment Category

X NO

2016 - Fall: N	No Change				7						
Comments:											
2017 - Fall: I	No Change										
Comments:											
2017 - Sprin	g: No Change										
Comments:											
2018 - Fall: N	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
BB-1	BASEBOARD	550	SF	MODULAR UNIT		Miscellaneous	No	None	0		YES X NO

Type

Material

TSI

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

В

Material Description

boiler insulation - abated

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material

Quantity

Material

Units

Material Location

boiler room

Change in Assessment Category

X NO

2016 - Fall:	No Change										
Comments											
2017 - Fall:	No Change										
Comments	•										
2017 - Spri	ng: No Change										
Comments	•										
2018 - Fall:	No Change										
Comments	· ·										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

TSI

Asbestos

Type

Material

Category

Miscellaneous

Friable

No

Yes

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

HA No

BBM-1

С

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material Description

BASEBOARD MASTIC

preform pipe insulation

Material

Quantity

550

Material

Units

SF

LF

3000

Material Location

MODULAR

54 building

Change in Assessment Category

X NO

X NO

YES

											1
2016 - Fall: N	lo Change]								
Comments:	10 Onlange				-						
Comments.					1						
2017 - Fall: N	lo Change										
Comments:	-										
2017 2	N. O.										
2017 - Spring	g: No Change										
Comments:											
2010 5 11 1					-						
2018 - Fall: N	No Change										
Comments:											
]						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units	
	I	1	1	1	1	1	1	1	1	1	1

TSI

Asbestos

Type

Material

TSI

Category

Friable

Yes

Damage

Type

Damage

Quantity

0

None

Damage

Units

200

LF

HA No

D

Ε

Material Description

water tank insulation -

cardboard pipe insulation

abated

Material

Quantity

Material

Units

Material Location

bathrooms and chases

boiler room

Change in Assessment Category

X NO

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
FT - 11	1' x 1' Ceiling Tile w/ Holes	425	SF	Basement Teacher's Lounge		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2040 Falls No Change	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT - 12	12" x 12" Cream VFT	800	SF	1st Floor Annex Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT-1	12x12 ft gray w/black cream & red streaks	2500	SF	Rm. 121, 123, 125, 129, 221, 223, and 225.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT-10	1' x 1' Ceiling Tile w/ Fissures	425	SF	Basement Teacher's Lounge		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

2016 - Fal	: No Change										
Comments	5:										
2017 - Fal	l: No Change										
Comments	S:										
2017 - Spr	ing: No Change										
Comments	S:										
2018 - Fal	: No Change										
Comments											
HA No	Material Description	Material	Material	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
11/4140	Waterial Description			Waterial Education			1 Habie				Change in Assessment Category
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor

Type

Material

Category

Miscellaneous

Miscellaneous

No

Friable

Damage

Type

None

None

Damage

Quantity

0

Damage

Units

HA No

FT-2

FT-3

Comments:

Comments:

Comments:

Comments:

Material Description

12x12 ft blue w/cream

12x12 ft light tam w/ cream,

red streaks

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

streaks

Material

Quantity

200

SF

Material

Units

Material Location

room 201

room 101

Change in Assessment Category

X NO

X NO

YES

FT-4	streaks			room202		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change				1							
Comments:					1							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
FT-5	9x9 tan w/cream & brwon streaks ft			57 1st floor corridor		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

FT-6	12x12 ft peach and tan checker			kitchen, teachers lunch room		Miscellaneous		None			YES	X NO
0040 5 11 1		•	•	•	7	•	•	•	•	•	•	
2016 - Fall: N	lo Change											
Comments:												
					1							
2017 - Fall: N	lo Change											
Comments:	-											
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

Friable

No

Damage

Туре

None

0

Damage

Quantity

Damage

Units

2016 - Fall: N	o Change				
Comments:					
2017 - Spring	: No Change	<u>.</u>	<u>.</u>	<u>.</u>	
Comments:					
2017 - Fall: N	o Change				
Comments:					
2018 - Fall: N	o Change				
Comments:					

3080

Material

Quantity

Material

Units

SF

Material Location

basement lunchroom,

MODULAR UNIT

HA No

FT-7

Material Description

12X12 WHITE W/BROWN

SPECKS

Change in Assessment Category

X NO

FT-8	12x12 Floor tile tan w/black & white streaks			Room 202		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:					- -							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:					- -							
2018 - Fall: N	lo Change											
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
FT-9	12x12 blue floor tile			Basement, lunchroom, kitchen, teachers lunch room		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FTM - 10	1' x 1' Ceiling Tile w/ Fissures Mastic	425	SF	Basement Teacher's Lounge		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FTM - 11	1' x 1' Ceiling Tile w/ Holes Mastic	425	SF	Basement Teacher's Lounge		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

FTM - 12	12" x 12" Cream VFT Mastic	808	SF	1st Floor Annex Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
					l							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

No

Friable

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

FTM-1	12x12 ft gray w/black cream & red streaks mastic	800	SF	Rm. 129
2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:			•	
	_		•	_

Quantity

Units

Material

Units

Material

Quantity

Material Location

HA No

Material Description

Change in Assessment Category

X NO

FTM-2	mastic beneath 12x12 FT-2			room 201		Miscellaneous		None			YES	X NO
2016 - Fall: N	No Change]							
Comments:												
2017 - Fall: N	No Change											
Comments:												
	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
					I							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

0

None

Damage

-

YES

X NO

Units

200

SF

room 101

Material

Quantity

Material

Units

Material Location

HA No

FTM-3

Material Description

12x12 ft light tam w/ cream, red streaks mastic

FTM-4	streaks mastic			room 202		Miscellaneous		None			YES	X NO
2016 - Fall:	No Change											
Comments:					-							
Comments.					-							
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	<u> </u>											
Comments:												
2018 - Fall:	No Change											
Comments:	<u> </u>											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
FTM-5	9x9 tan w/cream & brwon			57 1st floor corridor		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

9x9 ft tan w/ hrwon & cream

Material

Quantity

Material

Units

Material Location

FTM-6	mastic for FT-6			basement		Miscellaneous		None			YES X NO
2016 - Fall:	No Change				7						
Comments:											
2017 - Sprii	ng: No Change										
Comments:											
2017 - Fall:	No Change										
Comments:					_						
2018 - Fall:	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
ETN4 7	12X12 WHITE W/BROWN		0.5	1400111.45				1	1.		

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

3080

SF

MODULAR

HA No

FTM-7

Material Description

SPECKS MASTIC

Material

Quantity

Material

Units

Material Location

Page 21

YES

X NO

G	cementitious pipe fitting	480	LF	54 building basement		TSI	No	None	0		YES	X NO
2016 - Fall: No	o Change]							
Comments:	J											
2017 - Fall: No	o Change											
Comments:												
2017 - Spring	No Change											
Comments:												
2018 - Fall: No	o Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
Н	breeching cement - abated			boiler room		Miscellaneous					VES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

2016 - Fall: N	lo Change				\neg						
Comments:	io change										
Comments.					-						
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:	J										
2018 - Fall: N	lo Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
TIA NO	Material Description	Quantity	Units	Ivialeriai LOCALIOTI	Type	Category	Filable	Type	Quantity	Units	Change in Assessment Category

Type

Material

TSI

TSI

Category

Friable

Yes

Damage

Type

None

Damage

Quantity

0

Damage

Units

Material

Quantity

30

Material

Units

LF

Material Location

areas

57 builiding unexcavated

57 building/bathrooms

and air pelnum

HA No

Κ

Material Description

cementitious pipe fittings

aircell pipe insulation

fiberglass runs

Change in Assessment Category

X NO

X NO

YES

L	cardboard pipe insulation	1000	LF	57 building air plenum	TSI	Yes	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2017 - Fall: N	o Change									
Comments:	•									
2018 - Fall: N	o Change									
Comments:	Ü									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessn	ment Category
М	cementitious pipe fittings	300	LF	57 building airplenum		TSI	No	None	0		YES	X NO
2016 - Fall: No Change												

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

N	boiler gasket - abated			boiler room		TSI					YES	X NO
2016 - Fall: I	No Change]							
Comments:	<u> </u>											
2017 - Sprin	g: No Change											
Comments:]							
2017 - Fall: I	No Change											
Comments:					 							
2018 - Fall: I	No Change											
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
WC-1	window caulk			54 building		Miscellaneous					YES	X NO
2016 - Fall: No Change												

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

WC-2	window caulk			57 building		Miscellaneous					YES	X NO
2016 - Fall:	No Change]							
Comments	:											
2017 - Spri	ng: No Change											
Comments												
2017 - Fall:	No Change											
Comments	:											
2018 - Fall:	No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
WG-1	window glaze			54 building		Miscellaneous					YES	X NO
2016 - Fall:	2016 - Fall: No Change											
Comments:												

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material Description

Material

Units

Material

Quantity

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
WG-2	window glaze			57 addtion		Miscellaneous					YES X NO

16 - Fall: No Change
omments:
17 - Fall: No Change
omments:
17 - Spring: No Change
omments:
18 - Fall: No Change
omments:
omments: 17 - Fall: No Change omments: 17 - Spring: No Change omments: 18 - Fall: No Change

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Adlai E Stevenson Elementary School
Date: 11/30/2018

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.