Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

George B Swift Elementary Specialty School 25571 6130 School: **Oracle Unit:** Building ID: Address: 5900 N Winthrop Avenue Region: 01 Mail Room: Asbestos Surveyor: Liberty, Steve X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/19/2018 Email Address: A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type 12"x12" Off White w/ Main Office - 1914 YES X NO 01 SF Speckles VFT NOT 80 Miscellaneous No None 0 **OBSERVED** NOT OBSERVED 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Oracle Unit: 25571

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
02	12"x12" Off White w/ Speckles VFT Mastic NOT OBSERVED	80	SF	Main Office - 1914 NOT OBSERVED		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]				•			

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	9"x9" Beige VFT	740	SF	Room 106 (under the carpet) and Storage Rm. Next to Rm. 106 - 1914		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
04	9"x9" Beige VFT Mastic	740	SF	Room 106 (under the carpet) and Storage Rm. Next to Rm.106 -1914		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change		•			,	•		•	•	•	
Comments:	ı: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	12"x12" White w/ Tan VFT	900	SF	Room 205 - 1914		Miscellaneous	No	None	20		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	12"x12" White w/ Tan VFT Mastic	900	SF	Room 205 - 1914		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change]						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	12"x12" Off White VFT	1400	SF	Stage & Stage Storage's - 1914		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

08	12"x12" Off White VFT Mastic	1400	SF	Stage & Stage Storage's - 1914	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:	to onango									
2017 - Spring	n: No Change									
Comments:	y. 110 Ondingo									
2017 - Fall: N	lo Change									
Comments:	<u> </u>									
2018 - Spring	g : No Change									
Comments:	<u> </u>									
2018 - Fall: N	lo Change									
Comments:	J									
1										

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	Red Linoleum	400	SF	Rooms 108 (Under HA 39) & 109 (Under HA41) - 1914		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
10	Red Linoleum Mastic	400	SF	Rooms 108 (Under HA 39) & 109 (Under HA 41) - 1914		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change				1							
Comments	:											
2017 - Spri	ing: No Change											
Comments	:											
2017 - Fall:	: No Change											
Comments	:											
2018 - Spri	ng : No Change											
Comments	:											
2018 - Fall:	: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Hard Coat Plaster	30000	SF	Throughout - 1914		Surface	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	2'x2' Transite Ceiling Panel	3100	SF	Natatorium (Pool), men's and women's bath/shower room - 1914		Miscellaneous	No	None	0		YES X NO
	•		•	•		•	•	-	-		

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12"x12" White w/ Light Brown Spots VFT	120	SF	Rooms 201,301,101 (speech), 2nd & 3rd Floor Teacher Toliets - 1914		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

14	12"x12" White w/ Light Brown Spots VFT Mastic	120	SF	Rooms 201,301,101 (speech), 2nd & 3rd Floor Teacher Toliets - 1914		Miscellaneous	No	None	0	YES	X NO
					i						
2016 - Fall:	No Change										
Comments:											
2017 - Sprii	ng: No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
2018 - Sprii	ng : No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

Rooms 201,301,101

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Carpet Mastic OBSERVED ONLY IN ROOM 104	600	SF	Rooms 101, 102, 103, 104, 108, & 109 - 1914 OBSERVED ONLY IN ROOM 104		Miscellaneous	No	None	0		YES X NO

HA No

Material Description

Material

Quantity

Material

Units

		Quantity	Units		Туре	Category		Туре	Quantity	Units	· ·	,
16	12"x12" White w/ Light Brown Spots VFT	16200	SF	Throughout - 1999 Addition		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No	o Change											
Comments:												
2017 - Spring:	: No Change											
Comments:												
2017 - Fall: No	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: No	o Change											
Comments:												

Material

Friable

Damage

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"x12" White w/ Light Brown Spots VFT Mastic	16200	SF	Throughout - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12"x12" Red VFT	540	SF	Rooms 112, 113, 213, 311, & 314 - 1999 Addition		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change	•	•	•]	•	•	•	•	•	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12"x12" Red VFT Mastic	540	SF	Rooms 112, 113, 213, 311, & 314 - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12"x12" Green VFT	540	SF	Rooms 114, 215, 312, & 313 - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12"x12" Green VFT Mastic	540	SF	Rooms 114, 215, 312, & 313 - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12"x12" Rust VFT	540	SF	Rooms 111, 112, 217, 310, & 315 - 1999 Addition		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change									·	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Rust VFT Mastic	540	SF	Rooms 111, 112, 217, 310, & 315 - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
24	Rust Linoleum	264	SF	Lunchroom, & Elevator - 1999 Addition		Miscellaneous	No	None	40		YES	X NO
2016 - Fall:	No Change]							
Comments:	<u> </u>											
2017 - Sprin	ng: No Change				-							
Comments:					1							
2017 - Fall:	No Change											
Comments:	-											
2018 - Sprin	ng : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	5											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Rust Linoleum Mastic	354	SF	Lunchroom, & Elevator - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

26	Green Linoleum	780	SF	Lunchroom, Serving Area, & Elevator - 1999 Addition		Miscellaneous	No	None	40		YES	X NO
2016 - Fall:	No Change			•	1	•	•	•	•	•	•	
Comments:					-							
2017 - Sprir	ng: No Change				_							
Comments:	· ·				1							
2017 - Fall:	No Change				-							
Comments:	Ţ											
2018 - Sprir	ng : No Change				_							
Comments:					1							
2018 - Fall:	No Change				=							
Comments:												

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Green Linoleum Mastic	780	SF	Lunchroom, Serving Area, & Elevator - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

28	Beige Linoleum	2405	SF	Lunchroom, Serving Area, & Elevator - 1999 Addition		Miscellaneous	No	None	40	YES	X NO
2016 - Fa	all: No Change	<u> </u>			7					·	
Commen											
2017 - Sp	oring: No Change										
Commen											
2017 - Fa	all: No Change										
Commen	ts:										
2018 - Sp	oring : No Change										
Commen	ts:										
2018 - Fa	all: No Change				_						
Commen	ts:										

Type

Material

Category

Damage

Type

Damage

Quantity

Damage

Units

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Beige Linoleum Mastic	2405	SF	Lunchroom, Serving Area, & Elevator - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

30	2'x4' Smooth Ceiling Tile	10000	SF	Throughout - 1999 Addtion	Miscellaneous	Yes	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2018 - Spring	: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:	•									

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	2'x4' Dot Ceiling Tile	12000	SF	Kitchen: (Toliet, Corridor, & Office), Serving Area, Food Storage, & Dishwash - 1999 Addition		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Vinyl Baseboard	8000	LF	Throughout - 1999 Addition		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change			·							

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Vinyl Baseboard Mastic	8000	LF	Throughout - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
34	Drywall	3000	SF	Throughout - 1999 Addition		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: No Change]							_
Comments:	Comments:											
2017 - Fall: No Change												
Comments:												

2017 - Spring: No Change Comments:

2018 - Fall: No Change Comments:

2018 - Spring : No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category		
35	Drywall Compound	150	SF	Throughout - 1999 Addition		Miscellaneous	Yes	None	0		YES X NO		

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	ment Category
36	Carpet Mastic	700	SF	Library - 1999 Addition		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change]								
Comments:					=								
2017 - Fall:	No Change				1								
Comments:													
2017 - Sprir	ng: No Change												
Comments:	<u> </u>												
2018 - Sprir	ng : No Change												
Comments:	<u> </u>												
2018 - Fall:	No Change				_								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Spray-on Insulation	7000	SF	Throughout Above Drop Ceilings - 1999 Addition		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

		Quantity	Units		Type	Category		Type	Quantity	Units		
38	Terrazo	7000	SF	Throughout 1999 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
	j : No Change											
Comments:												
					I							

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12"x12" Light blue with light blue specks VFT	80	SF	Main Office - 1914 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39 A	12"x12" Light blue with light blue specks VFT (MASTIC)	80	SF	Main Office - 1914 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12"x12" White with Blue specks VFT	200	SF	Room 108 - 1914 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40 A	12"x12" White with Blue specks VFT (MASTIC)	200	SF	Room 108 - 1914 Bldg.		Miscellaneous	No	None	0		YES X NO
					1						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12"x12" Beige with White specks VFT	200	SF	Room 109 - 1914 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41 A	12"x12" Beige with White specks VFT (MASTIC)	200	SF	Room 109 - 1914 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12" x 12" BLUE, VFT	80	SF	1st and 2nd floor corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42A	12" X 12" blue, mastic	80	SF	1st and 2nd floor corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12" X 12" yellow, VFT	70	SF	1st and 2nd floor corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43A	12" X 12" yellow, Mastic	70	SF	1st and 2nd floor corridors		Miscellaneous	No	None	0		YES X NO
					i						

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	Carpet mastic	600	SF	Rm 104 (Removed from Rms 101, 102, 103, 108, and 109)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12" X 12" white with blue specks, VFT	6000	SF	1st and 2nd floor corridors; Rm 108		Miscellaneous	No	None	0		YES X NO
					1						_

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
45A	12" X 12" white with blue specks, Mastic	6000	SF	1st and 2nd floor corridors; Rm 108		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Units	Material Location	Asbestos Type	Material Category	Friable	Type	Quantity Quantity	Units	Change in Asse	ssment Category
46	Fire Door	10	EA	Balcony		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments	: No Change :											
2017 - Spri Comments	ng: No Change :				_							
2017 - Fall: Comments	: No Change :											
2018 - Spri	ing : No Change]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	12" X 12" white with gray specks, VFT	320	SF	Assembly Hall		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

Comments:

2018 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47A	12" X 12" white with gray specks, Mastic	320	SF	Assembly Hall		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

0040 Fall No Olassa	
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
48	Carpet mastic	400	SF	Auditorium, between isles		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
49	Drywall System			1919 Building		Miscellaneous	Yes	Unknown			YES	X NO
2016 - Fall:	No Change											
Comments:												
	ng: No Change											
Comments:												
2017 - Fall:												
Comments:												
2018 - Fall:	No Change											
Comments:												
2018 - Sprir	ng : No Change											
Comments:												

Material

Friable

Damage

Damage

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	2'x4' Ceiling Tile			1919 Building		Miscellaneous	Yes	Unknown			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Α	Aircell Pipe Insulation	16	LF	Room 202 & 2nd Floor Corridor - 1914		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		
2018 - Fall: No Change		
Comments:	 	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	MJP E/F/V on Aircell Pipe Insulation	4	LF	Room 202 & 2nd Floor Corridor - 1914		TSI	Yes		0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Mag Block Pipe Insulation	168	LF	North & South Engine Rooms, Boiler Room, Natatorium, Natatorium Entry Hall - 1914		TSI	Yes	None	0		YES X NO

0040 F.II N. Ol	
2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
Comments.	
2018 - Fall: No Change	
Comments:	·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	MJP E/F/V on Mag Block Pipe Insulation	50	LF	North & South Engine Rooms, Boiler Room, Natatorium, Natatorium Entry Hall - 1914		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Cardboard Pipe Insulation	100	LF	Room 202 & 208, Room 202 & 208 Closets, 2nd Floor Corridor - 1914		TSI	Yes	None	0		YES X NO

·	
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	<u> </u>

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	MJP E/F/V on Cardboard Pipe Insulation	8	LF	Room 202 (old 208), Room 202 (old 208) Closet, 2nd Floor Corridor - 1914		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

G	MJP E/F/V on Fiberglass Pipe Insulation	90	LF	Throughout - 1914		TSI	Yes	None	0	YES	X NO
2016 - Fall: N	o Change										
Comments:											
Commonio.											
2017 - Fall: N	o Change										
Comments:	<u> </u>										
2017 - Spring	: No Change										
Comments:											
2018 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:	-										

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	Boiler Rope	50	LF	Boiler Room - 1914		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: _George B Swift Elementary Specialty School
Date: 1/1/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 25571