## **Chicago Public Schools**

## **6 Month Asbestos Surveillance** 2018 - Fall

25621

**Oracle Unit:** 

**Building ID:** Address: 223 N. Keeler Region: 03 Mail Room: Asbestos Surveyor: Thompson, Darren X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/18/2018 Email Address: dthompson72@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other Material Description HA No Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type 1908 Building -YES 001 X NO Plaster Surface Throughout 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

George W Tilton Elementary School

School:

Oracle Unit: 25621

6210

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
001A	Smooth Plaster			1908 Building - Throughout		Surface					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	j : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
002	Rough Plaster			1966 Addition - Throughout		Surface					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
005	9" x 9" Brick Red w/Beige Streaks Floor Tile	10200	SF	1908 Building - Throughout, 1, 2, 3, 4, Floor Hallways & 118		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
006	9" x 9" Brick Red w/Beige Streaks FT Mastic	10200	SF	1908 Building - Throughout, 1, 2, 3, 4, Floor Hallway Room 118		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

007	12" x 12" Lt. Brn w/Grey Streaks Floor Tile Mastic	1908 Building - Throughout (see comments for locations)		Miscellaneous			YES	X NO
2016 - Fall	: No Change		1					
Comments								
2017 - Spr	ing: No Change		-					
Comments			1					
2017 - Fall	: No Change		-					
Comments	:							
2018 - Spr	ing : No Change		-					
Comments			1					
2018 - Fall	: No Change		_					
Comments			1					
			J					

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
008	12" x 12" Lt. Brown w/Grey Streaks Floor Tile			1908 Building - Throughout		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
009	2' x 2' Rough Ceiling Tile			1908 Building - 1st Floor Hallway		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	•											
2017 - Spring	ı: No Change				-							
Comments:	, <u> </u>											
2017 - Fall: N	lo Change				-							
Comments:												
2018 - Spring	: No Change				-							
Comments:												
2018 - Fall: N	lo Change				-							
Comments:	<u> </u>											
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
010	9" x 9" Tan w/Beige & Choc. Streaks Floor Tile	16900	SF	2nd floor hallway, 3rd floor hallway, main office, and classrooms: 110, 110A, 112, 114, 208-212, 214, 308-312, and 314		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
011	9" x 9" Tan w/Beige & Choc. Floor Tile Mastic	16900	SF	2nd floor hallway, 3rd floor hallway, main office, and classrooms: 110, 110A, 112, 114, 208-212, 214, 308-312, and 314		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
012	Sheet Rock Board Material			1908 Building - Throughout		Miscellaneous					YES	X NO
2016 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:	J											
2017 - Fall: N	o Change											
Comments:	Ü											
2018 - Spring	: No Change											
Comments:	<u> </u>											
2018 - Fall: N	o Change											
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
013	Joint Compound on Sheetrock Board Material			1908 Building - Throughout		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 7

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
014	Black Flooring Beneath 9" x 9" Red Floor Tile			1908 Building - Throughout (see comments for locations)		Miscellaneous					YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change				-							
Comments:	g											
2017 - Fall: N	No Chango											
Comments:	NO Change				-							
	g : No Change				-							
Comments:					-							
2018 - Fall: N	No Change											
Comments:					4							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	sessment Category
		Quantity	Units	1000 P. II II.	Туре	Category		Туре	Quantity	Units	<u> </u>	
015	Interior Brick			1908 Building - 1st - 4th Floor Hallways, 2nd-4th Floor Girls and Boys Washrooms		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				7							
Comments:	10 Onango											
2017 Comin	a. No Change				-							
Comments:	g: No Change				_							
					_							
2017 - Fall: N	No Change				_							
Comments:					-							
	g : No Change											
Comments:												
2018 - Fall: N	No Change				-							
Comments:		1										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessi	ment Category
016	Interior Brick Mortar			1908 Building - 1st - 4th Floor Hallways, 2nd-4th Floor Girls and Boys Washrooms		Miscellaneous					YES		X NO
204C Falls	No Change				7								
2016 - Fall:	No Change												
Comments:													
2017 - Sprin	ıg: No Change												
Comments:													
2017 - Fall:	No Change												
Comments:													
2018 - Sprin	g : No Change												
Comments:	<u> </u>												
					_								
2018 - Fall:	No Change												
Comments:													
					_								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
017	Black Vinyl Baseboard			1908 Building - Throughout, Foyers		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

018	Black Vinyl Baseboard Mastic			1908 Building - Throughout, Foyers		Miscellaneous					YES	X NO
2016 - Fall:	No Change				7							
Comments					1							
2017 - Spri	ng: No Change											
Comments	:				-							
	No Change											
Comments	:				_							
	ng : No Change											
Comments	:				_							
	No Change											
Comments	:				_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
019	Black Border Tile	500	SF	1908 Building - Lobby,		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Units

Damage

Quantity

Change in Assessment Category

HA No

Material Description

Material

Units

Material

Quantity

Material Location

and 3rd Floor Hallways

Page 10

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
020	Black Border Tile Mastic	500	SF	1908 Building - Lobby, and 3rd Floor Hallways		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	V											
2017 - Spring	: No Change				1							
Comments:	•				1							
2017 - Fall: N	lo Change											
Comments:	-				1							
2018 - Spring	: No Change				-							
Comments:					1							
2018 - Fall: N	lo Change											
Comments:	<u> </u>											
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
021	12" x 12" Lt. Beige w/Light Brn Streaks Floor Tile	6000	SF	1908 Building - Rooms 100, 101A, 104, 105, 203, 205, Library, 1st Floor Foyers		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
022	12" x 12" Lt. Beige w/Lt. Brn Streaks FT Mastic	6000	SF	1908 Building - Rooms 100, 100A, 104, 105, 203, 205, Library, 1st Floor Foyers		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
023	9" x 9" Leaf Green w/Beige Streaks Floor Tile	6	SF	1908 Building - Room 205		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
024	9" x 9" Leaf Green w/Beige Streaks FT Mastic	6	SF	1908 Building - Room 205		Miscellaneous	No	None	0		YES X NO

·			·-
2016 - Fall: No Change			
Comments:			
2017 - Spring: No Change			
Comments:			
2017 - Fall: No Change			
Comments:			
2018 - Spring : No Change			
Comments:			
2018 - Fall: No Change			
Comments:			
	•	•	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
025	9" x 9" Cherry Red w/Beige Streaks Floor Tile	90	SF	1908 Building - Engineer's Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
026	9" x 9" Cherry Red w/Beige Streaks FT Mastic	90	SF	1908 Building - Engineer's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	Comments:											
2017 - Sprin	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprin	ng : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
027	9" x 9" Black w/Beige Streaks Floor Tile			1908 Building - Room 203		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

Comments:

2018 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
028	9" x 9" Black w/Beige Streaks Floor Tile Mastic			1908 Building - Room 203		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
029	Exterior Window Caulk - ABATED			1908 Building - Exterior		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
030	Exterior Door Caulk			1908 Building - Exterior		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	U											
2017 - Spring	ı: No Change				_							
Comments:	,											
2017 - Fall: N	lo Change											
Comments:	3											
2018 - Spring	ı : No Change											
Comments:	, <u> </u>											
2018 - Fall: N	lo Change				<u> </u>							
Comments:												
					]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
031	Exterior Brick - Non AHERA			1908 Building - Exterior		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 16

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
032	Exterior Brick Mortar - Non AHERA			1908 Building - Exterior		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	J				1							
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					 							
2018 - Spring	j : No Change											
Comments:					 							
2018 - Fall: N	lo Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
033	Exterior (window side) Wall Caulk - Not AHERA			1908 Building - Exterior		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
034	Exterior Window Caulk - Non Ahera ABATED			1966 Addition - Exterior		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Spring	g: No Change				_							
Comments:												
2017 - Fall: N	lo Change											
Comments:					-							
2018 - Spring	ј : No Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
035	Exterior Door Caulk - Non AHERA, ABATED			1966 Addition - Exterior		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	ent Category
036	Exterior Window Glazing Non AHERA			1966 Addition - Exterior		Miscellaneous					YES	X NO
2016 - Fall: N	o Change				]							
Comments:	<u> </u>											
2017 - Spring	: No Change				-							
Comments:					1							
2017 - Fall: N	o Change											
Comments:					]							
2018 - Spring	: No Change											
Comments:					]							
2018 - Fall: N	o Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
037	Exterior Brick - Non AHERA			1966 Addition - Exterior		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
038	Exterior Brick Mortar - Non AHERA			1966 Addition - Exterior		Miscellaneous					YES X NO
2016 - Fall: N	No Change				7						
Comments:	<u> </u>										
2017 - Sprin	g: No Change										
Comments:											
2017 - Fall: I	No Change										
Comments:											
2018 - Sprin	g : No Change										
Comments:											
2018 - Fall: N	No Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
039	9" x 9" Beige & Brn. w/Choc. Streaks Floor Tile			1908 Building - Auditorium, Assistant Principal's Office, Conference Room by 100		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
040	9" x 9" Beige & Brown w/Choc. Streaks FT Mastic			1908 Building - Auditorium, Assistant Principal's Office, Conference Room by 100		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 25621

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
041	12" x 12" Lt. Off-white & Cream Mix Floor Tile	2378	SF	1966 Addition - Lunchroom, Main Office Washroom/Vault, Kitchen Serving Area, Kitchen Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
042	12" x 12" Lt. Off-White w/Cream FT Mastic	2378	SF	1966 Addition - Lunchroom, Main Office Washroom/Vault, Kitchen Serving Area, Kitchen Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
043	Blue Vinyl Baseboard			1966 Addition - Kitchen Serving Area		Miscellaneous					YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

											i	
044	Blue Vinyl Baseboard Mastic			1966 Addition - Kitchen Serving Area		Miscellaneous					YES	X NO
0040 5.11 1	I. Ol				1							
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:	-											
2018 - Fall: N	lo Change											
Comments:												
					1							
HA No	Material Description	Material	Material	Material Location	Acheetoe	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

TIANO	iviaterial Description	Quantity	Units	iviaterial Education	Type	Category	THADIE	Type	Quantity	Units	Change in Asses	Sillelli Calegory
045	9" x 9" Choc. Mix w/Off- White Streaks Floor Tile	1750	SF	1966 Addition - 1st, 2nd and 3rd Floor Hallways		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

Comments:

2017 - Spring: No Change
Comments:

2017 - Fall: No Change
Comments:

2018 - Spring : No Change
Comments:

2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment	Category
046	9" x 9" Choc. Mix w/Off- white Streaks FT Mastic	1800	SF	1966 Addition - 1st, 2nd and 3rd Floor Hallways		Miscellaneous	No	None	0		YES	Х	NO
2016 - Fall: N	No Change				]				•				
Comments:													
2017 - Spring	g: No Change												
Comments:													
2017 - Fall: N	No Change												
Comments:													
2018 - Spring	g : No Change												
Comments:													
2018 - Fall: N	No Change												
Comments:	-												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
047	Cream Rubber Floor Adhesive			1908 Building - 1st Floor Hallway (West Corridor)		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

048	Partition Bridging Floor Compound	1966 Addition - 2nd Floor Hallway (between original building and addition)	Miscellaneous			YES	X NO
004C F-	II. N. Okarana						
	II: No Change						
Comment	s:						
2017 - Sp	ring: No Change						
Comment	:S:						
2017 - Fa	II: No Change						
Comment	S:						
2018 - Sp	ring : No Change						
Comment							
	· <del>·</del>						
2018 - Fa	II: No Change						
Comment							

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
049	9" x 9" Lt. Brown w/Beige Streaks Floor Tile	42	SF	1966 Addition - Room 209		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
050	9" x 9" Lt. Brown w/Beige Strks Floor Tile Mastic	42	SF	1966 Addition - Room 209		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Spri	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Spri	ng : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
051	Countertop Masonite Material			1966 Addition - Lunchroom		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
052	Countertop Masonite Backing Insulation			1966 Addition - Lunchroom		Miscellaneous					YES	X NO
2016 - Fall: N	o Change				1							
Comments:	<b>V</b>											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
053	Black Vinyl Baseboard			1966 Addition - Main Office Areas		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
054	Black Vinyl Baseboard Mastic			1966 Addition - Main Office Areas		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	<u> </u>											
2017 - Fall: N	lo Change				1							
Comments:	J											
2017 - Spring	g: No Change				1							
Comments:												
2018 - Spring	g : No Change				1							
Comments:	,											
2018 - Fall: N	lo Change				1							
Comments:	J											
					J							
			•		•							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
055	Sheet Rock			1966 Addition - Lunchroom		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
056	Joint Compound on Sheet Rock			1966 Addition - Lunchroom		Miscellaneous					YES	X NO
2016 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	-											
2018 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
057	Smooth Plaster			1966 Addition - Throughout		Surface					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
058	Rough Ornamental Ceiling Plaster (Acoustical)			1966 Addition - Main Office Areas, Rooms 110, 112, and 114		Surface					YES	X NO
2016 - Fall: N	lo Change	•			]	•		•	•	•	•	
Comments:	, and the second											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	ј : No Change											
Comments:		•										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
059	Black Ceiling Pipe Filler	5	LF	1908 Building - 2nd Floor Girls Toilet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

060	Pipe Coating Material		1966 Addition - Crawl space		TSI	None		YES	X NO
2012 5 11 1				1					
2016 - Fall: N	lo Change								
Comments:									
2017 - Spring	g: No Change								
Comments:									
2017 - Fall: N	lo Change								
Comments:	-								
2018 - Fall: N	lo Change								
Comments:	Ţ.								
2018 - Spring	g : No Change								
Comments:	,								

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
061	Stack Fire Brick Material			1908 Building - Boiler Room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

		Quantity	Units		Type	Category	Type	Quantity	Units		
062	Incinerator Brick			1908 Building - Boiler Room		Miscellaneous				YES	X NO
2016 - Fall: N	No Change										
Comments:											
	g: No Change										
Comments:					_						
2017 - Fall: N	No Change										
Comments:					-						
2018 - Fall: N	No Change										
Comments:					_						
	g : No Change										
Comments:					_						
1											

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
063	Sink Bottom Caulk Material	12	LF	1966 Addition - Rooms 112, and 212		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	nent Category
064	Interior Window Glazing Compound Abated 2002			1966 Addition - Throughout		Miscellaneous					YES	X NO
2016 - Fall: N	o Change				]							
Comments:	Ü											
2017 - Spring	: No Change				-							
Comments:					1							
2017 - Fall: N	o Change											
Comments:					1							
2018 - Fall: N	o Change				-							
Comments:												
2018 - Spring	: No Change				=							
Comments:					1							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
065	Caulk Between Ceramic and Metal Windows Abated 2002			1966 Addition - Throughout		Miscellaneous					YES X NO

066	Black Flooring			1908 Building - 1st Floor Teacher's Lounge next to 104 (museum)		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				1							
Comments:	Tto Onango											
2017 - Sprin	g: No Change				-							
Comments:	g o o				-							
2017 - Fall: N	No Change				-							
Comments:												
2018 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Damage

Quantity

Damage

Units

YES

Change in Assessment Category

Damage

Type

Friable

067	Pink Mix Flooring Material	1908 Building - 1st Floor Teacher's Lounge (Museum)	Miscellaneous		
2016 - Fa	II: No Change				
Comment	ts:				
2017 - Fa	II: No Change				
Comment	ts:				
2017 - Sp	oring: No Change				
Comment	ts:				
2018 - Sp	oring : No Change				

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No

Comments:

Comments:

2018 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
068	Stairway Floor Material (Stair Tread)			1908 Building - 3rd Floor by Library		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	J				]							
2017 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	g: No Change				-							
Comments:					]							
2018 - Spring	g : No Change				-							
Comments:												
2018 - Fall: N	lo Change				-							
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
069	Roofing Material			1908 Building - Exterior Non-AHERA		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
070	Roofing Material			1966 Addition - Exterior Not AHERA		Miscellaneous					YES	X NO
2016 - Fall: I	No Change				1							
Comments:	<b>-</b>											
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
	g : No Change											
Comments:					_							
2018 - Fall: I	No Change											
Comments:					_							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
071	Boiler Interior Materials	100	SF	1908 Building - Boiler Room		Miscellaneous	No	Unknown	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
072	Incinerator Interior Materials	80	SF	1908 Building - Boiler Room		Miscellaneous	No	Unknown	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Fall: N	lo Change				_							
Comments:												
2017 - Spring	j: No Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					-							
2018 - Spring	: No Change				]							
Comments:					_							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
074	Purple Carpet Adhesive			Room 104 (Now Supply Room)		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
075	Floor Tile			Beneath Tiles in First Floor Foyer		Miscellaneous		None			YES	X NO
2016 - Fall:	No Change				7							
Comments:	J											
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	Ţ											
					_							
								,				

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
076	Floor Tile Mastic			Beneath Tiles in First Floor Foyer		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
077	Vault Door Core	25	SF	Office 1966 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2018 - Sprir	ng : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
078	12" x 12" Red Floor Tile	1000	SF	2nd and 3rd Floor Corridors 1908 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
079	12" x 12" Red Floor Tile Mastic	1000	SF	2nd and 3rd Floor Corridors 1908 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
080	Blue Carpet Adhesive	1570	SF	Room 206 and Library		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
081	Lab Table Tops	150	SF	Room 102		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments	S:											
2017 - Spri	ing: No Change											
Comments	S:				_							
2017 - Fall:	: No Change											
Comments	S:				_							
2018 - Fall:	: No Change											
Comments	S:				_							
2018 - Spri	ing : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
082	Chalk Board/Poster Board Adhesive	3700	SF	Classrooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
084	12"x12" Off White/Beige Floor Tile	270	SF	Room 203 Closet and Washroom, Rm 102		Miscellaneous	No	None	0		YES X NO
2016 Fall N	o Changa	<u> </u>					•				

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
085	12"x12" Off White/Beige Floor Tile Mastic	270	SF	Room 203 Closet and Washroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
086	12"x12" Off White/Beige Floor Tile	935	SF	Auditorium, 1908 Hallway, Auditorium & Room 100		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change	]									

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
087	12"x12" Off White/Beige Floor Tile Mastic	935	SF	Auditorium		Miscellaneous	No	None	0		YES X NO

Page 44

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
088	9"x9" Red/Gray Floor Tile	336	SF	101A (Assistant Principal's Office)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
0040 5 11 N 01	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
089	9"x9" Red/Gray Floor Tile Mastic	336	SF	101A (Assistant Principal's Office)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
090	Carpet Adhesive			Room 206 (Library)		Miscellaneous		None			YES X NO
2016 - Fall: No	Change										
Comments:											
2017 - Spring:	No Change										
Comments:											
2017 - Fall: No	Change										
Comments:											
2018 - Fall: No	Change										
Comments:	Ţ.										
2018 - Spring :	: No Change										
Comments:	Ţ.										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
91	Gray Vinyl Sheeting	50	SF	Elevator (1966)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
92	Gray Vinyl Sheeting Adhesive	50	SF	Elevator (1966)		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
93	2' x 2' Smooth White Ceiling Tile	1750	SF	1966 Building West Main Foyer & Stairway		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
94	Purple Carpet Adhesive	500	SF	1966 Building Room 114		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:					1							
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					=							
2018 - Fall: N	lo Change											
Comments:												
	j : No Change											
Comments:												
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	Tank Insulation - ABATED			1908 Building - Tank Room/Boiler Room		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

С	Joint Compound on Fiberglass Pipe Insulation	75	LF	1908 Building - Boiler Room, Pipe Chases, and throughout facility		TSI	Yes	None	0		YES	X NO
2016 Falls	No Changa				7							
	: No Change				-							
Comments	•				_							
2017 - Fall:	: No Change											
Comments	:											
2017 - Spri	ng: No Change											
Comments	:											
2018 - Spri	ng : No Change											
Comments	:											
2018 - Fall:	: No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Asbestos

Type

Material

Category

Category

TSI

Friable

Damage

Type

None

0

Yes

Damage

Quantity

	areas throughout facility
2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

210

LF

HA No

D

Material Description

Paperwrap Pipe Insulation

Material

Units

Material

Quantity

Material Location

1908 Building - Boiler

Room, Tunnel, and possibly in inaccessible

Change in Assessment Category

Damage

Units

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	Joint Compound on Paperwrap Pipe Insulation	21	LF	1908 Building - Boiler Room, Tunnel, and throughout facility		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
v	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Aircell Pipe Insulation	150	LF	1908 Building - Boiler Room, Tank Room, and Throughout Facility		TSI	Yes	None	0		YES X NO

		i i i cagi cat i aciity
2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		
	·	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
Н	Mag-block Pipe Insulation			1908 Building - Throughout Facility		TSI					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
	g : No Change											
Comments:												
L												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	Joint Compound on Mag- block Pipe Insulation			1908 Building - Throughout Facility		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Joint Compound on Aircell Pipe Insulation	19	LF	1908 Building - Boiler Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
К	Joint Compound on Fiberglass Pipe Insulation	100	LF	1966 Addition - Throughout Facility, Crawl Space		TSI	Yes	Dist	10		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in Asses	sment Category
L	Beige Terrazzo	3000	SF	Bathrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I Comments:	No Change											
2017 - Sprin Comments:	g: No Change											
2017 - Fall: I	No Change				-							
Comments:	-											
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall: I	No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
М	Carpet Mastic	1000	SF	Room 307, Museum		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	ment Category
N	9 x 9 White Floor Tile	500	SF	Room 118		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: I	No Change				1								
Comments:	_												
2017 - Fall: I	No Change				1								
Comments:	•												
2017 - Sprin	g: No Change				1								
Comments:													
2018 - Sprin	g : No Change												
Comments:					]								
2018 - Fall: I	No Change				-								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
0	9 x 9 Floor Tile Mastic	500	SF	Room 118		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
Р	12 x 12 Grey Floor Tile	700	SF	Room 114		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Q	12 x 12 Grey Floor Tile Mastic	700	SF	Room 114		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

	George W Tilton Elementary School
Date: 1	2/18/2018
the Asbestos	tify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of a Management Plan is available at each school during school hours by appointment. review the Asbestos Management Plan must be made at least 24 hours in advance.
The last insp	be advised that CPS conducts asbestos inspections of all Schools every three years. ection was completed in 2016. rveillances are conducted every six months.
CHECK ONE	
A cop	y of this notice was sent home in each child's backpack.
A cop	y of this notice was printed in the school's newsletter and sent home with each child
A cop	y of this notice was printed in the school's calendar and sent home with each child
Other.	•
	OF THIS NOTICE MUST BE PLACED IN THE OOL'S ASBESTOS MANAGEMENT PLAN.