Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Enrico Tonti Elementary School 25631 6220 School: **Oracle Unit: Building ID:** Address: 5815 S. Homan Region: 05 Mail Room: Asbestos Surveyor: Jeske, Michael X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 11/27/2018 Email Address: A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Material Friable Damage Damage Change in Assessment Category Damage Quantity Units Type Category Quantity Type YES 06 X NO fiberglass joints - abated boiler room pipechase TSI 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Oracle Unit: 25631

07	boiler insulation - abated			boiler room		TSI					YES	X NO
2016 - Fall: N	No Change				7							
Comments:												
2017 - Fall: N	No Change											
Comments:					-							
	g: No Change											
Comments:					_							
2018 - Fall: I	No Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	ent Category
08	boiler joints packing -			boiler room		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

09	tank insulation			storage room off boiler room (ABATED 1988)		TSI					YES	X NO
2016 - Fall: N	o Change				7							
Comments:												
2017 - Fall: N	o Change				1							
Comments:	<u> </u>											
2017 - Spring	: No Change]							
Comments:					-							
2018 - Fall: N	o Change]							
Comments:					_							
					<u>.</u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
10	tank joints packing			storage room off boiler		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material

Quantity

Material

Units

Material Location

room (ABATED 1988)

11	air cell pipe insulation	300	LF	airtunneis, pipe chases, blower room, storage rooms (basement)		TSI	Yes	None	0		YES	X NO
0040 5 11	NI OI				7							
2016 - Fall	: No Change											
Comments	:											
2017 - Fall	: No Change											
Comments	:											
2017 - Spr	ing: No Change											
Comments	:											
2018 - Fall	: No Change											
Comments	:											
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

TSI

Friable

Damage

Туре

Damage

Quantity

Damage

Units

2016 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			
			_

Material

Quantity

Material

Units

Material Location

airtunnels, pipe chases,

pipe chases, tunnels, air

blower rooms

HA No

12

Material Description

pipe covering cardboard

YES

Change in Assessment Category

X NO

	13	aircell packing joints			airtunnels, fan rooms, basement storage areas		TSI					YES	X NO
Ī	2016 - Fall: No	o Change											
- 1	Comments:												
ŀ	2017 - Fall: No	o Change											
	Comments:												
l	2017 - Spring:	: No Change											
- 1	Comments:	<u> </u>											
l	2018 - Fall: No	o Change											
ŀ	Comments:												
Į													
	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
	14	cardboard joints and elbows			pipechases, air tunnels, boiler room storage areas		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

boiler room storage areas

HA No

Material Description

15	aircell duct cover		storage areas, basement area	TSI			YES	X NO
2016 - Fall: N	o Change							
Comments:	o onango							
2017 Caring	u No Chango							
2017 - Spring Comments:	. No Change							
2017 - Fall: N	o Change							
Comments:								
2018 - Fall: N	lo Change							
Comments:								

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

НА	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
17		9x9 brown w/orange floor tile	125	SF	engineer's office & adjacent storage room		Miscellaneous	No	Dist	5		YES	X NO
	l6 - Fall: Noments:	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

18	12x12 off white w/white specks floor tile	1700	SF	kitchen office, 3rd floor corridor	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2017 - Spring	ı: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	brown linoleum flooring	1140	SF	kitchen cafeteria		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

9x9 brown w/orange floor tile mastic	125	SF	engineer's office & adjacent storage room		Miscellaneous	No	None	0		YES	X NO
lo Change											
lo Change											
j: No Change											
lo Change											
	·										
		lo Change lo Change g: No Change	lo Change lo Change g: No Change	tile mastic 125 SF adjacent storage room No Change So Change G: No Change	tile mastic SF adjacent storage room No Change No Change g: No Change	tile mastic To SF adjacent storage room No Change To Change To Change To Change	tile mastic SF adjacent storage room Niscellaneous No Change No Change g: No Change	tile mastic SF adjacent storage room Miscellaneous No None No Change Jo Change J: No Change	tile mastic	tile mastic SF adjacent storage room Miscellaneous No None O No Change Io Change g: No Change	tile mastic No Change No Change Is No Change Is No Change

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12x12 off white w/ white specks floor tile mastic	2050	SF	kitchen office, 3rd floor corridor,. Counselor's office, nurses station		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

22	brown linoleum mastic	1140	SF	kitchen cafeteria flooring		Miscellaneous	No	None	0		YES	X NO
2016 Fall N	lo Chango				1							
2016 - Fall: N	no Change											
Comments:												
0047 5-11 1	1. 01											
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:	-				1							
		•	•		_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

No

Dist

15

Friable

Damage

Туре

Damage

Quantity

Damage

Units

23	12x12 tan w/brown streaks floor tile	1950	SF	conference room, room 209, 211
2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				

HA No

Material Description

12x12 tan w/brown streaks

Material

Quantity

Material

Units

Material Location

1st floor offices, 1st floor

YES

X NO

23A	12x12 tan w/brown streaks floor tile mastic	1950	SF	1st floor offices, 1st floor conference room, room 209, room 211		Miscellaneous	No	None	0	YES	X NO
		•	•	•	1	•					
2016 - Fall: N	o Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	· No Change										
	. No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12x12 gray w/brown streaks floor tile	6150	SF	1st floor corridor, room 209, 2nd floor corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Page 10

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
24A	12x12 gray w/brown streaks floor tile mastic	6150	SF	1st floor corridor, room 209, 2nd floor corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	g: No Change											
Comments:												

Material

Damage

Friable

Damage

Damage

Comments:

2017 - Fall: No Change
Comments:

Material

Material

Material Location

2018 - Fall: No Change Comments:

Material Description

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	9x9 maroon floor tile	900	SF	auditorium		Miscellaneous	No	Loc	2		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Page 11

2016 - Fal	: No Change										
Comments	5:										
2017 - Fal	l: No Change										
Comments	S:										
2017 - Spring: No Change											
Comments	S:										
2018 - Fal	: No Change										
Comments											
HA No	Material Description	Material	Material	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
11/4140	Waterial Description			Waterial Education			1 Habie				Change in Assessment Category
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

Loc

Damage

Quantity

0

3

Damage

Units

HA No

25A

26

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

9x9 black floor tile

9x9 maroon floor tile mastic 900

Material

Units

SF

SF

Material Quantity

900

Material Location

auditorium

assembly room

Change in Assessment Category

X NO

X NO

YES

26A	9x9 black floor tile mastic	900	SF	assembly room	Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change									
Comments:										
2017 - Fall: Comments:	No Change									
	g: No Change									
Comments:	g. No Change									
2018 - Fall:	No Change									
Comments:	-									

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	9x9x tan w/brown streaks floor tile	125	SF	engineer's storage and office		Miscellaneous	No	Loc	2		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
27A	9x9x tan w/brown streaks floor tile mastic	30	SF	engineer's storage and office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments	Comments:											
2017 - Fall:	: No Change											
Comments	Comments:											
2017 - Spring: No Change												
Comments	Comments:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
28	black baseboard	1140	SF	kitchen, cafeteria		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

28A	black baseboard mastic	1140	SF	kitchen, cafeteria	Miscellaneous	No	None	0	YES	X NO
2016 - Fall:										
Comments:										
2017 - Fall:										
Comments:										
2017 - Sprin	g: No Change									
Comments:										
2018 - Fall:	No Change									
Comments:										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12x18 black edging floor tile	285	SF	engineer's office & storage, assembly room		Miscellaneous	No	Loc	2		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

29A	mastic	285	SF	assembly room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			

440

Material

Quantity

285

Material

Units

SF

SF

Material Location

assembly room

engineer's office storage,

HA No

29A

30

Material Description

green carpet mastic

12x18 black edging floor tile

Change in Assessment Category

X NO

X NO

YES

31	dark mauve carpet mastic	622	SF	rooms 102		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No	o Change]							
Comments:												
2017 - Fall: No	Change											
Comments:												
2017 - Spring:	No Change											
Comments:	Ţ.											
2018 - Fall: No	o Change											
Comments:	J .											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
32	metal stall partitions-			boys washrooms		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

REMOVED

33	cementitious partitions	1400	SF	all wash rooms except boys		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:	<u> </u>											
2017 - Fall: N	No Change				_							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material	Material Location	Asbestos	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Surface

Friable

Yes

None

0

Damage

Type

Damage

Quantity

Damage

Units

34	textured plaster on ceilings and walls	3100	SF	storage (off of boiler room, top of stairs)								
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	2017 - Fall: No Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
	·			·								

HA No

Material Description

textured plaster on ceilings

Material

Quantity

Material

Units

Material Location

air tunnels, janitors

Page 18

YES

X NO

35	gray carpet mastic	224	SF	main office, principal's office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
					4							
Comments:												
2017 - Fall:	No Change											
Comments:												
					1							
2017 - Sprir	ng: No Change				1							
Comments:												
2018 - Fall:	No Change											
Comments:	•											
					1							
					-							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Surface

Friable

No

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

2016 - Fall: No Change										
Comments:										
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										

Quantity

64

Units

LF

Material

Units

Material

Quantity

Material Location

main office, principal's

basement windows

HA No

36

Material Description

window caulk (interior)

Change in Assessment Category

X NO

37	windows interior glazing	240	LF	4 basement windows	Miscellaneous	No	None	0	YES	X NO
0040 Fall No	Ohana									
2016 - Fall: No	Change									
Comments:										
2017 - Fall: No	o Change									
Comments:										
2017 - Spring:	No Change									
Comments:										
2018 - Fall: No	o Change									
Comments:										
		•								

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12x12 gray w/brown specks floor tile	325	SF	room 202		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

40A	12x12 gray w/brown streaks floor tile mastic	325	SF	room 202 (teachers lounge)		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change				1							
Comments												
2017 - Fal	I: No Change				_							
Comments												
2017 - Spi	ring: No Change				1							
Comments	S:											
2018 - Fal	I: No Change				-							
Comments	s:											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
41	terrazzo	3006	QF.	stairway edging on hall auditorium, Border of 1st-		Miscellaneous	No	None			YES	X NO

Type

Material

Category

Miscellaneous

No

None

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

41

Comments:

Comments:

Comments:

Comments:

Material Description

terrazzo

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material

Quantity

3996

SF

Material

Units

Material Location

3rd Floor Hallways, Stairways

Change in Assessment Category

42	fire brick under boilers	600	SF	boiler room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>]							
2017 - Fall: N	lo Change											
Comments:					1							
	g: No Change											
Comments:					-							
2018 - Fall: N	No Change											
Comments:												
					J							
HA No	Material Description	Material	Material	Material Location	Achestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

No

Damage

Туре

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

		100111
2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		
	-	

Quantity

84

Units

SF

Material

Units

Material

Quantity

Material Location

boiler room, assembly

HA No

43

Material Description

firedoor

Change in Assessment Category

X NO

2016 - Fall:	: No Change										
Comments	:										
2017 - Fall	: No Change										
Comments											
2017 - Spri	ng: No Change										
Comments											
2018 - Fall:	: No Change										
Comments											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

TSI

Friable

Yes

Yes

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:		•		·

6000

Material

Quantity

10

Material

Units

LF

SF

gym

Material Location

boiler room

HA No

44

45

Material Description

boiler gasket

2x2 ceiling tile

Change in Assessment Category

X NO

X NO

YES

2016 - Fall:	No Change										
Comments											
2017 - Fall:	No Change										
Comments	•										
2017 - Spri	ng: No Change										
Comments	•										
2018 - Fall:	No Change										
Comments	· ·										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

HA No

Annex-01

Annex-01A

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material Description

floor tile

12x12 gray w/dark specks

12x12 gray w/dark specks

floor tile mastic

Material

Quantity

4500

Material

Units

SF

SF

4500

Material Location

throughout annex

throughout annex

Change in Assessment Category

X NO

X NO

YES

0046 Falls N	Na Obasana				7						
2016 - Fall: N	No Change										
Comments:											
2017 Spring	a: No Chango				4						
	g: No Change										
Comments:											
2017 - Fall: N	No Change										
Comments:											
2018 - Fall: N	No Change										
Comments:											
					_						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
1	1	Quantity	Units		Type	Category		Type	Quantity	Units	I

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

60

HA No

Annex-02

Annex-02A

2016 - Fall: No Change

Material Description

floor tile

12x12 blue w/dark specks

12x12 blue w/dark specks

floor tile mastic

Material

Units

SF

SF

Material

Quantity

60

Material Location

throughout annex

throughout annex

Change in Assessment Category

X NO

X NO

YES

Annex-03	12x12 peach w/dark specks floor tile	60	SF	throughout annex		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	to oriange				-							
2017 Caring	y No Chango											
2017 - Spring Comments:	g: No Change				-							
2017 - Fall: N	lo Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

60

Material

Units

SF

Material

Quantity

Material Location

throughout annex

HA No

Annex-03A

Material Description

12x12 peach w/dark specks

12x12 peach w/dark specks

floor tile mastic

YES

Change in Assessment Category

X NO

Annex-04	12x12 beige w/dark specks floor tile	60	SF	throughout annex		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	to oriange				-							
2017 - Spring	g: No Change											
Comments:												
2015 5 11 1					1							
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change				-							
Comments:	to onange				-							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

HA No

Annex-04A

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

12x12 beige w/dark specks

12x12 beige w/dark specks

floor tile mastic

Material

Quantity

60

Material

Units

SF

Material Location

throughout annex

YES

Change in Assessment Category

X NO

Annex-05	12x12 green w/specks floor tile	60	SF	throughout annex		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				1							
Comments:	10 Onlango	_										
2017 - Spring	g: No Change											
Comments:	•]							
2017 - Fall: N	No Change											
Comments:					-							
2018 - Fall: N	No Change											
Comments:					-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

60

HA No

Annex-05A

2016 - Fall: No Change

Material Description

12x12 green w/specks floor

12x12 green w/specks floor

Material

Units

SF

Material

Quantity

Material Location

throughouot annex

YES

X NO

Annex-06	gray vinyl baseboard	2500	LF	throughout annex		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	: No Change											
Comments:					1							
2018 - Fall: N	lo Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
Annex-06A	gray vinyl baseboard mastic	2500	LF	throughout annex		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No

Material Description

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

VFT = Vinyl Floor Tile

Comments:

Comments:

Comments:

Comments:

Material

Quantity

Material

Units

Material Location

Annex-07	2x4 bisected white ceiling tile	4000	SF	throughout annex		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change	7										
Comments:]										
2017 - Fall: N	lo Change				1							
Comments:	J]							
2017 - Spring	g: No Change				_							
Comments:]							
2018 - Fall: N	lo Change				-							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
Annex-08	drywall ceiling	120	SF	men's and women's washrooms, mechanical		Surface	No	None	0		YES	X NO

Asbestos

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

washrooms, mechanical room, vestibules

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Enrico Tonti Elementary School
Date: 11/14/2018

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 25631

SCHOOL'S ASBESTOS MANAGEMENT PLAN.