Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

James Ward Elementary School 25751 6330 School: **Oracle Unit: Building ID:** Address: 2701 S. Shields Region: Mail Room: Asbestos Surveyor: Lagiglia, Brian X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/8/2019 Email Address: A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type Throughout the 1874 YES 001.1 Wall & Ceiling Plaster X NO Surface Building 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments:

001.2	Wall & Ceiling Plaster			Throughout the 1894 Building		Surface					YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Spri	ng: No Change				-							
Comments:	· ·]							
2018 - Fall:	No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
001.3	Wall & Ceiling Plaster			Throughout the 1927 Building		Surface					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

	x 12" Brown Speckled or Tile	900	SF	Room 103 in the 1894 Building		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: No Cl	hange]						
Comments:											
2017 - Spring: No	Change										
Comments:					<u> </u>						
2017 - Fall: No Cl	hange										
Comments:					<u> </u>						
2018 - Fall: No Cl	hange										
Comments:					-						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

Room 103 in the 1894

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
002.3	12" x 12" Brown Speckled Floor Tile			2nd Floor Gym of the 1927 Building		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

12" x 12" Brown Speckled

003.1	9" x 9" Red Speckled Floor Tile	500	SF	1st Floor Corridor of the 1874 Building	Miscellaneous	No	Loc	20	YES	X NO
2016 - Fall: N Comments:	lo Change									
2017 - Spring Comments:	: No Change									
2017 - Fall: N Comments:	lo Change									
2018 - Fall: N	lo Change									

Material

Category

Friable

Damage

Type

Asbestos

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
003.2	9" x 9" Red Speckled Floor Tile			1st Floor Corridor of the 1894 Building		Miscellaneous					YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

005.1	1' x 1' Ceiling Tile			Basement Classroom 010 of the 1874 Building		Miscellaneous					YES	X NO
2016 - Fall:	No Change				1							
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change				1							
Comments:												
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
005A.1	Brown Tag Associated with			Basement Classroom		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

HA 5.1 Ceiling Tile

Material

Units

Material

Quantity

Material Location

010 of the 1874 Building

005B.1	Black Ceiling Tile Adhesive (for HA5.1)			Basement Classroom 0100 of the 1874 Building		Miscellaneous					YES	X NO
2016 - Fall:	No Change				1							
Comments:	0											
2017 - Sprii	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:	<u> </u>											
2018 - Fall:	No Change											
Comments:	-											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
006.2	12" x 12" Brown Speckled			Room 103 of the 1894		Miscellaneous		None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No

Material Description

Floor Tile Mastic

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material

Units

Material

Quantity

Material Location

Building

Change in Assessment Category

Damage

Units

006.3	12" x 12" Speckled Brown Floor Tile Mastic			2nd Floor Gym of the 1927 Building		Miscellaneous		None			YES	X NO
2016 - Fall	: No Change				7							
Comments												
2017 - Fall	: No Change											
Comments	<u> </u>											
2017 - Spr	ing: No Change											
Comments	<u> </u>											
2018 - Fall	: No Change				-							
Comments	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
007.1	9" x 9" Red Speckled Floor Tile Mastic			1st Floor Corridor of the		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Units

Material

Quantity

Material Location

1874 Building

Change in Assessment Category

007.2	9" x 9" Red Speckled Floor Tile Mastic			1st Floor Corridor of the 1894 Building		Miscellaneous					YES	X NO
2016 - Fall	No Change				7							
Comments:												
2017 - Fall:	No Change				-							
Comments:												
2017 - Spri	ng: No Change				-							
Comments:	· ·											
2018 - Fall:	No Change				-							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
009.3	12" x 12" Black Floor Tile			Room 204 of the 1927		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Units

Material

Quantity

Material Location

Building

010.3	9" x 9" Reddish Floor Tile	230	SF	Throughout the 1927 Building		Miscellaneous	No	None	0		YES	X NO
0040 5 11	N. O.		•	•	1							
	: No Change											
Comments	:											
2017 - Fall:	: No Change]							
Comments	:											
					1							
2017 - Spri	ng: No Change											
Comments	:]							
2018 - Fall:	: No Change											
Comments	:											
					1							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
Í		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

011.3

Material Description

12" x 12" Black Floor Tile

Material

Units

Material

Quantity

Material Location

Room 204 of the 1927

Building

1st & 3rd Floor Corridor's

YES

Change in Assessment Category

X NO

012.3	9" x 9" Reddish Floor Tile Mastic	500	SF	Throughout the 1927 Building		Miscellaneous	No	None	0		YES	X NO
0040 5 11	N. O.	•		•	7							
2016 - Fall:	No Change											
Comments:												
					1							
2017 - Fall:	No Change				1							
Comments:	-				1							
					1							
2017 - Sprin	ng: No Change				1							
Comments:												
2018 - Fall:	No Change											
Comments:	-				1							
					1							
	_	•	•	_	_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category	1	Type	Quantity	Units		

Type

Material

Category

Miscellaneous

Friable

Damage

Туре

Damage

Quantity

Damage

Units

			3
2016 - Fall: N	lo Change		
Comments:			
2017 - Spring	j: No Change		
Comments:			
2017 - Fall: N	lo Change		
Comments:			
2018 - Fall: N	lo Change		
Comments:			·

Material

Quantity

Material

Units

Material Location

Room 204 of the 1927

Building

1st & 3rd Floor Corridors

HA No

013.3

Material Description

12" x 12" White Floor Tile

Change in Assessment Category

X NO

YES

013A.3	12" x 12" White Floor Tile Mastic			Room 204 of the 1927 Building		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments												
2017 - Fall:	No Change											
Comments												
2017 - Spri	ng: No Change											
Comments												
	No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
014.3	9" x 9" Black Floor Tile	500	SF	1st, 3rd Floor South Corridors of the 1927		Miscellaneous	No	Loc	25		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Building

Material

Quantity

Material

Units

HA No

Material Description

014A.3	Mastic	500	SF	South Corridors of the 1927 Building		Miscellaneous	No	None	0		YES	<u>X</u> NO
2016 - Fall:	No Chango			•	7							
Comments:												
2017 - Fall:	No Changa											
Comments:												
0047 0	. N. Olasas				4							
2017 - Sprir	ng: No Change											
Comments:												
0040 5 11	N. O.				_							
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

Material Location

1st, 2nd & 3rd Floor

South Corridors of the

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
015.3	9" x 24" Black Floor Tile			1st & 3rd Floor Corridors of the 1927 Building		Miscellaneous					YES	X NO
2016 - Fall: N Comments:	o Change											

2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments:

HA No

014A.3

Material Description

9" x 9" Black Floor Tile

Material

Quantity

500

Material

Units

SF

Change in Assessment Category

X NO

YES

											<u> </u>
204C Falls	No Change				7						
2016 - Fall.	No Change										
Comments:) 										
0047 5 11	NI OI				4						
2017 - Fall:	No Change										
Comments:											
2017 - Spri	ng: No Change				+						
	· ·				_						
Comments:											
2040 Falls	No Change				4						
	No Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

0

None

HA No

015A.3

016.3

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material Description

9" x 18" Black Floor Tile

9" x 9" Brown Floor Tile

Mastic

Material

Units

SF

212

Material

Quantity

Material Location

of the 1927 Building

1st & 3rd Floor Corridors

2nd Floor Corridor of the

1927 Building

Change in Assessment Category

X NO

X NO

YES

YES

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
016A.3	9" x 9" Brown Floor Tile Mastic	212	SF	2nd Floor Corridor of the 1927 Building		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
017.3	9" x 9" Tan Floor Tile	212	SF	2nd Floor Corridor of the 1927 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Ca	ategory
017A.3	9" x 9" Tan Floor Tile Mastic	212	SF	2nd Floor Corridor of the 1927 Building		Miscellaneous	No	None	0		YES XN	0
2016 - Fall: N	lo Change]							

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
018.2	12" x 12" Tan Speckled Floor Tile	140	SF	Engineer's Office of the 1894 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

018A.2	12" x 12' Tan Speckled Floor Tile Mastic	140	SF	Engineer's Office of the 1894 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change				-							
Comments:					= =							
2017 - Sprir	ng: No Change				1							
Comments:					=							
2018 - Fall:	No Change				=							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
019.1	Aluminum Ceiling			Room 208 & Assistant Principal's Office of the		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

1894 Building

020.3	12" x 12" Tan w/Brown Specks Floor Tile			Student's Lunchroom/Kitchen of the 1927 Building		Miscellaneous					YES	X NO
0040 5-11	N. Oleana	•	•	•	1	•	•	•	•	•	•	
	No Change											
Comments												
2017 - Spri	ng: No Change											
Comments	· ·]							
2017 - Fall:	No Change											
Comments												
2018 - Fall:	No Change											
Comments												
					l							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
020A.3	12" x 12" Tan w/Brown Speckled Floor Tile Mastic			Student's Lunchroom/Kitchen of the 1927 Building		Miscellaneous		None			YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

			Dallaing
2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			
		•	

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Student's

Page 17

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor	
021.3	9" x 9" Brown w/White Streaks Floor Tile	830	SF	Room 301 (Old Library of the 1927 Building)		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: No Change												

2016 Fall: No Change
2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
021A.3	9" x 9" Brown w/White Streaks Floor Tile Mastic	830	SF	Room 301 (Old Library of the 1927 Building)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

022.1	Light Gray & White Mixed Carpet Mastic			Basement Counselor's Room 010 in 1874 Building		Miscellaneous					YES	X NO
2016 Fall:	No Change			·]							
	<u> </u>											
Comments					_							
2017 - Fall:	No Change											
Comments												
					1							
2017 - Spri	ng: No Change											
Comments												
2018 - Fall:	No Change											
Comments					1							
					1							
					-							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	ement Category
TIA NO	Material Description	Quantity	Units	iviateriai Location	Type	Category	Thable	Type	Quantity	Units	Change in Asses	Sillerit Category
		Quantity	01110		.,,,,	Catogory		1,750	Quantity	010		
023.1	4" Brown Vinyl Baseboard			Basement Room 010 of the 1874 Building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

Basement Counselor's

the 1874 Building

HA No

Material Description

023A.1	4" Brown Vinyl Baseboard Mastic			Basement Room 010 of the 1874 Building		Miscellaneous					YES	X NO
2016 - Fall	: No Change				7							
Comments]							
2017 - Fall	: No Change											
Comments	:	_										
2017 - Spri	ng: No Change											
Comments	:				-							
2018 - Fall	: No Change											
Comments	:											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
024.1	12"x12" Beige & White			Classroom 107		Miscellaneous					VES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Building

025.1	Drywall			Washroom of the 1874 Building		Miscellaneous					YES	X NO
2016 - Fall: N	o Change	•	•	•	7	•	•	•	•	•		
Comments:	o onange											
2017 - Fall: N	o Change											
Comments:												
0047 0	N. Olasas				4							
2017 - Spring	: No Change											
Comments:												
0040 Fall N	- Oh											
2018 - Fall: N	o Change				4							
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
025.3	Drywall			1st Floor Girl's		Miscellaneous					YES	X NO
020.0	D1, 11411			Washroom		Micconditions						V INO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

025A.1	Drywall Joint Compound	100	LF	Classroom 107 of the 1874 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:												
2017 - Spring	g: No Change				_							
Comments:												
2017 - Fall: N	No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Friable

No

Miscellaneous

Damage

Type

None

0

Damage

Quantity

Damage

Units

025A.5	Bry wan don't dompound	100	O.	Building
2016 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				

100

SF

Material

Quantity

Material

Units

Material Location

Classroom 107 of the

1st Floor Girl's

Washroom of the 1927

HA No

025A.3

Material Description

Drywall Joint Compound

YES

X NO

026.1	12" x 12" Beige Speckled Floor Tile			Classroom 107 of the 1874 Building		Miscellaneous					YES	X NO
2016 - Fall	: No Change				7							
Comments]							
2017 - Spri	ng: No Change											
Comments	:				_							
2017 - Fall	: No Change											
Comments	:				_							
2018 - Fall	: No Change											
Comments	:				_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
026A.1	12" x 12" Beige Speckled Floor Tile Mastic			Classroom 107 of the 1874 Building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Material

Units

Material

Quantity

Material Location

Classroom 107 of the

HA No

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

Material Description

12" x 12" Beige Speckled

Change in Assessment Category

Damage

Units

027.1	9" x 9" Beige, Tan & Brown Speckled Floor Tile			1st Floor Corridor of the 1874 Building		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments												
2017 - Fall:	No Change											
Comments												
2017 - Spri	ng: No Change											
Comments	:				_							
2018 - Fall:	No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
027.2	9" x 9" Beige, Tan & Brown Speckled Floor Tile			1st Floor Corridor of the		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No

Material Description

Speckled Floor Tile

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material

Units

Material

Quantity

Material Location

1894 Building

Change in Assessment Category

Damage

Units

027A.1	Speckled Floor Tile Mastic			1874 Building		Miscellaneous					YES	X NO
2016 - Fall: I	No Change				1							
Comments:	TTO OTHERINGO											
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Chango				_							
Comments:	No Change				-							
Comments.					1							
2018 - Fall: I	No Change											
Comments:												
]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
027A.2	9" x 9" Beige, Tan & Brown Speckled Floor Tile			1st Floor Corridor of the		Miscellaneous					YES	X NO

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

027A.1

Material Description

9"x9" Beige,Tan & Brown

Speckled Floor Tile

2016 - Fall: No Change

Material

Units

Material

Quantity

Material Location

1894 Building

1st Floor Corridor of the

Change in Assessment Category

X NO

YES

028.1	9" x 9" Beige Floor Tile w/White Streaks			1st Floor Corridor of the 1874 Building		Miscellaneous					YES	X NO
2016 - Fall: I	No Change				1							
Comments:					_							
	g: No Change]							
Comments:					1							
2017 - Fall: I	No Change											
Comments:					1							
2018 - Fall: I	No Change]							
Comments:					_							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
028A.1	9" x 9" Beige Floor Tile w/White Streaks Mastic			1st Floor Corridor of the 1874 Building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Material

Units

Material

Quantity

Material Location

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Change in Assessment Category

Damage

Units

029.1	9" x 9" Beige Floor Tile w/Brown & White Streaks			1st Floor Corridor of the 1874 Building		Miscellaneous					YES	X NO
2016 - Fall	: No Change]							
Comments]							
2017 - Fall	: No Change				_							
Comments	:]							
2017 - Spri	ng: No Change											
Comments	:				-							
2018 - Fall	: No Change											
Comments	:				-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
029.2	9"x9"Beige Floor Tile w/Brown White Streaks Mastic			1st Floor Corridor of the 1894 Building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

029A.1	9"x9"Beige Floor Tile w/Brown & Wht Streaks Mastic			1st Floor Corridor of the 1874 Building		Miscellaneous					YES	X NO
2016 - Fall:	No Chango	*		•	1	•	•	•	•	•	•	
					4							
Comments:												
2017 - Sprir	ng: No Change											
Comments:					1							
2017 - Fall:	No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

029A.2	9"x9" Beige Floor Tile w/Brn & Wht Streaks Mastic		1st Floor Corridor of the 1894 Building
2016 - Fall: N	No Change		
Comments:		 	
2017 - Spring	g: No Change		
Comments:			
2017 - Fall: N	No Change		
Comments:			
2018 - Fall: N	No Change		
Comments:			

Material

Units

Material Quantity Material Location

HA No

Material Description

Change in Assessment Category

X NO

YES

030.2	Incinerator Brick			Boiler Room of the 1894 Building		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:												
	No Change											
Comments:												
	ng: No Change											
Comments:	:											
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
030A.2	Incinerator Brick Mortar			Boiler Room of the 1894		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

031.3	Gray, Green, White & Red Mixed Carpet Mastic			Counselor's Office of the 1927 Building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	<u> </u>				- -							
2017 - Fall: N	lo Change				-							
Comments:					1							
2017 - Spring	j: No Change											
Comments:					-							
2018 - Fall: N	lo Change				-							
Comments:					1							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
032.3	4" Black Vinyl Baseboard			Basement Counselor's Office of the 1927 Building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

032A.3	4" Black Vinyl Baseboard Mastic			Basement Counselor's Office of the 1927 Building		Miscellaneous					YES	X NO
2016 - Fall: N	No Change			•	7						·	
	10 Change				-							
Comments:					_							
2017 - Fall: N	No Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:	-				1							
2018 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Friable

No

Miscellaneous

Damage

Туре

Damage

Quantity

0

None

Damage

Units

2016 - Fall: No Change			
Comments:			
2017 - Fall: No Change			
Comments:			
2017 - Spring: No Change)		
Comments:			
2018 - Fall: No Change			
Comments:			

150

HA No

033

Material Description

3" Wide Black Border Floor Tile

Material

Quantity

Material

Units

SF

Room 301

Material Location

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
034	3" Wide Black Border Floor Tile Mastic	150	SF	Room 301		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12"x12" New Blotted Grey VFT	900	SF	Room 107 (1874 Building)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

36	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	36		900	SF			Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
	·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12"x12" Grey and Black Blotted VFT Mastic	1800	SF	Room 107 (1874 Building)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 33

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Ca	ategory
38	Lab Table Tops	25	SF	Room 309,310 (Building 1874)		Miscellaneous	No	None	0		YES XN	0
2016 - Fall: No Change												

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Lab Countertops	5	EA	Room 309,310 (Building 1874)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

40	White Sink Insulation	5	EA	Room 107,203,303		Miscellaneous	No	None	0	YES	X NO
2016 - Fal	II: No Change				1						
Comment	S:										
2017 - Fal	II: No Change				1						
Comment											
2017 - Sp	ring: No Change				-						
Comment	S:										
2018 - Fal	II: No Change				1						
Comment											

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12" x 12" Black w/ White Specks Floor Tile	600	SF	3rd Floor S. Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Page 35

42	Mastic Associated w/ 12" x 12" Black w/ White Specks Floor Tile	600	SF	3rd Floor S. Corridor		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change				1						
Comments:	<u> </u>				-						
2017 - Fall:	No Change										
Comments:	-				1						
2017 - Sprin	g: No Change				_						
Comments:											
2018 - Fall:	No Change										
Comments:											

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12" x 12" Painted Blue Floor Tile	225	SF	Lunch Room Manager's Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Mastic Associated w/ 12" x

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	Mastic Associated w/ 12" x 12" Painted Blue Floor Tile	225	SF	Lunch Room Manager's Office		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12" x 12" Tan Marble Floor Tile	80	SF	Base by NW Elevator		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessmen	Category
46	Mastic Associated w/ 12" x 12" Tan Marble Floor Tile	80	SF	Base by NW Elevator		Miscellaneous	No	None	0		YES	NO
2016 - Fall: No Change												

016 - Fall: No Change
Comments:
017 - Spring: No Change
Comments:
017 - Fall: No Change
Comments:
018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A.1	Cardboard Thermal System Pipe Insulation	10	LF	Room 110 Library Closet of the 1874 Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B.1	Cardboard Thermal System Pipe Insulation Elbow/Fit	10	SF	This material may be in inaccessible pipe chase or inside walls		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 39

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: _James Ward Elementary School
Date: 1/8/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.