Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Thomas J Waters Elementary School 25781 6370 School: **Oracle Unit: Building ID:** Address: 4540 N Campbell Avenue Region: 01 Mail Room: Asbestos Surveyor: Carney, Patrick X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/21/2018 Email Address: A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type 12"x12" Beige w/Brown YES 03 100 SF 0 X NO Office Storage Miscellaneous No None Streaks VFT 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	12"x12" Brown w/Brown Specks VFT - NOT OBSERVED	450	SF	Room 108 (under new Fir)		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change	•	•	•]	•	•	•	•	•	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04A	12"x12" Brown w/Brown Specks VFT Mastic	450	SF	Room 108		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	ment Category
05	9"x9" Brown w/ Dark & Light Streaks VFT	1500	SF	Rooms 101		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change	
Comments:	
	-
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05A	9"x9" Brown w/Dark and Light Streaks VFT Mastic	1500	SF	Rooms 101		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
06	12"x12" Brown w/ Light Streaks VFT	200	SF	Gym Storage		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06A	12"x12" Brown w/Light Streaks VFT Mastic	200	SF	Gym Storage		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

07	12"x12" Off-White w/Beige Specks VFT	450	SF	Main Office Closet Room 108-NOT OBSERVED		Miscellaneous	No	None	0	YES	X NO
004C Fall	. No Oborono				_						
	: No Change										
Comments	s:										
2017 - Spr	ing: No Change										
Comments):										
2017 - Fall	: No Change										
Comments	:										
2018 - Spr	ing : No Change										
Comments):										
2018 - Fall	: No Change										
Comments											
L											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

Main Office Closet

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	Red Linoleum- Removed	0		Assembly Hall Stage							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
10	12"x12" Beige w/Brown Streaks VFT Mastic	100	SF	Office Storage		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change	
Comments:	
Comments.	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12"x12" Off-White w/Beige Streaks VFT MasticNOT OBSERVED	450	SF	Room 108, Main Office Closet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
12	Red Linoleum Mastic- REMOVED	0		Assembly Hall Stage							YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	<u> </u>											
2017 - Spring	g: No Change				=							
Comments:												
2017 - Fall: N	lo Change											
Comments:					4							
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12"x12" Beige w/Brown Streaks VFT -NOT OBSERVED	3000	SF	Assembly Hall/Gym		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
13A	12"x12" Beige w/Brown Streaks VFT Mastic -NOT OBSERVED	3000	SF	Assembly Hall/Gym		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change		•	•]	•				•		

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	9"x9" Green w/Light Streaks VFT -NOT OBSERVED	10	SF	Room 108 Closet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

14A	Streaks VFT Mastic -NOT OBSERVED	10	SF	Room 108 Closet		Miscellaneous	No	None	0	YES	X NO
2016 Fall I	No Change				7						
2016 - Fall: I	vo Change										
Comments:											
2017 - Sprin	g: No Change										
Comments:											
2017 - Fall: I	No Change										
Comments:											
2018 - Sprin	g : No Change										
Comments:											
2018 - Fall: No Change											
Comments:											
<u> </u>		•	•		<u>-</u>						

Type

Material

Category

Asbestos

Type

Material

Category

Friable

Friable

Damage

Туре

Damage

Type

Damage

Quantity

Damage

Quantity

Damage

Damage

Units

 \Box

Units

15	Carpet Mastic	Office, Engineer's Office, Main Office								
2016 - I	Fall: No Change									
Comments:										
2017 - Spring: No Change										
Comments:										
2017 - F	Fall: No Change									
Comme	ents:									
2018 - 3	Spring : No Change									
Comme	ents:									
2018 - I	Fall: No Change									
Comme	ents:									

Material

Quantity

Material

Units

HA No

HA No

Material Description

9"x9" Green w/Light

Material Description

Material

Units

Material

Quantity

Material Location

Material Location

Rooms 101, Principal's

Change in Assessment Category

Change in Assessment Category

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"X12" Beige w/Spots VFT	6000	SF	1st, 2nd and 3rd Floor Corridos, Stairwell Landings		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change]	•	•	•	•	•	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16A	12"X12" Beige w/Spots VFT Mastic	6000	SF	1st, 2nd and 3rd Floor Corridos, Stairwell Landings		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"X12" Avacdo Green VFT	3500	SF	Rm 312, 3rd Floor Corridor, Stairwell Landings, Teachers Lounge Rm 300, Music Rm 200, Rm 212, Main Office Public Area, 1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
17A	12"X12" Avacdo Green VFT Mastic	3500	SF	Rm 312, 3rd Floor Corridor, Stairwell Landings, Teachers Lounge Rm 300, Music Rm 200, Rm 212, Main Office Public Area, 1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES	X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12"X12" Red VFT	2500	SF	Rm 312, 3rd Floor Corridor, Stairwell Landings, Teachers Lounge Rm 300, Music Rm 200, Rm 212, Main Office Public Area, 1st and 2nd Floor Corridors and Vestbules		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18A	12"X12" Red VFT Mastic	1800	SF	Rm 312, 3rd Floor Corridor, Stairwell Landings, Teachers Lounge Rm 300, Music Rm 200, Rm 212, Main Office Public Area, 1st and 2nd Floor Corridors and Vestbules		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
19	12"X12" Orange VFT	2000	SF	Rm 312, 3rd Floor Corridor, Stairwell Landings, Teachers Lounge Rm 300, Music Rm 200, Rm 212, Main Office Public Area, 1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES	X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19A	12"X12" Orange VFT Mastic	2000	SF	Rm 312, 3rd Floor Corridor, Stairwell Landings, Teachers Lounge Rm 300, Music Rm 200, Rm 212, Main Office Public Area, 1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
20	12"X12" Blue VFT	500	SF	1st, 2nd and 3rd Floor Corridors, Stairwell Landings		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change	<u> </u>		·	7							
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
2018 - Sprin	ng : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20A	12"X12" Blue VFT Mastic	300	SF	1st, 2nd, 3rd Floor Corridor, Stairwell Landings		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12"X12" White w/Spots VFT	200	SF	1st, 2nd, 3rd Floor Corridor, Stairwell Landings		Miscellaneous	No	None	0		YES X NO
0040 F.II N	01				1	•	•	•	•	•	_

2016 - Fall: No Change Comments:
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21A	12"X12" White w/Spots VFT Mastic	200	SF	1st, 2nd, 3rd Floor Corridor, Stairwell Landings		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Beige Linoleum Flooring	40	SF	Pre-K Bathroom First Floor Next to Rm 105		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change Comments: 2017 - Spring: No Change
Comments:
2017 - Spring: No Change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2019 Falls No Change
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22A	Beige Linoleum Flooring Mastic	40	SF	Pre-K Bathroom First Floor Next to Rm 105		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Boiler Gasket(s)	20	LF	Boiiler Room		Miscellaneous	Yes	None	0		YES X NO
2016 - Fall: N Comments:	o Change										
2017 - Fall: N	o Change										

2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

2018 - Spring : No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	Tan Wood Laminate Flooring	3600	SF	Library (Rm 111), Rm 108, Assembly Hall, Gym		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No Mate	erial Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
25 2x4 to	textured ceiling tile	60	SF	Engineers Office		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: No Ch	nange]							
Comments:	•											
2017 - Fall: No Ch	nange				-							
Comments:	•											
2017 - Spring: No	Change											
Comments:					1							
2018 - Spring : No	Change											
Comments:	•											
2018 - Fall: No Ch	nange				-							
Comments:	Ţ.											
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	Mag Block Pipe Insulation	100	LF	Boiler Room, SW Store Room(Asst. Principal), 1st and 2nd Floor Boys Toliets		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	MJP E/F/V on Mag Block Pipe Insulation	95	LF	Boiler Room, SW Store Room(Asst. Prin.), 1st and 2nd Floor Boys Toliets		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 25781

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Cardboard Pipe Insulation	800	LF	Boiler Room, Eng. Off., Boys/Girls Toliets on 1st and 2nd Floors, SW Store Rm(asst.prin), SW Corridor		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	MJP E/F/V on Cardboard Pipe Insulation	200	LF	Boiler Room, Eng. Off., Boys/Girls Toliets on 1st and 2nd Floors, SW Store Rm(asst.prin), SW Corridor		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Air Cell Pipe Insulation	400	LF	E & W Fresh Air Chamber, Boiler Rm, SW Store Rm(asst prin)		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	MJP E/F/V on Air Cell Pipe Insulation	80	LF	E & W Fresh Air Chamber, Boiler Rm, SW Store Rm(asst. prin)		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	MJP E/F/V on Fiberglass Pipe Insulation	189	LF	Boiler Rm, 1st Floor Girls Toliet NOT OBSERVED		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

1	Hard Coat Plaster	0		2nd Floor, 3rd Floor and Basement							YES	X NO
2016 Fall	: No Change	<u> </u>	<u> </u>	·	1							
					-							
Comments): -											
	: No Change				_							
Comments	S:				-							
2017 - Spr	ing: No Change				_							
Comments	S:											
	ing : No Change				_							
Comments	:				-							
2018 - Fall	: No Change				-							
Comments	S:											
]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

TSI

Category

Asbestos

Type

Material

Category

Friable

Yes

Туре

None

Damage

Туре

Damage

Quantity

Quantity

0

Damage

YES

X NO

Units

Units

Quantity

1800

Units

SF

HA No

Material Description

Boiler Insulation

Material

Units

Material

Quantity

Material Location

Boiler Room

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	Decorative Plaster	100	SF	Assembly Hall/Gym		Surface	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Oracle Unit: 25781

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Thomas J Waters Elementary School
Date: 12/21/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 25781

SCHOOL'S ASBESTOS MANAGEMENT PLAN.