Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

John Whistler Elementary School 25831 6420 School: **Oracle Unit: Building ID:** Address: 11533 S Ada Region: Mail Room: Asbestos Surveyor: Micou, Alan X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/10/2019 Email Address: A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type 9x9 brown/white streaks flr YES 01A SF 0 X NO 1680 Rm 122,119 Miscellaneous No None 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
01B	9x9 light gray/brown and white streak floor tile	3390	SF	Rooms 123, 120, 117, 116		Miscellaneous	No	None	0		YES X NO	
2016 Fall N	o Chango											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
0040 Fall Na Obaras	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
01C	9x9 tan.brown and white streak floor tile	8600	SF	Rooms 105, 121,118, 217, 218, 219, 221, 220, 223, 222		Miscellaneous	No	None	0		YES X NO	

016 - Fall: No Change	
Comments:	
017 - Spring: No Change	
Comments:	
017 - Fall: No Change	
Comments:	
018 - Fall: No Change	
Comments:	
018 - Spring : Damaged	
Comments:damaged	

01D	9x9 light gray/white streaks floor tile	1975	SF	2nd floor cooridor		Miscellaneous	No	Loc	5	YES	X NO
2016 - Fall: N	lo Change										
Comments:											
2017 - Spring	ı: No Change										
Comments:	J										
2017 - Fall: N	lo Change										
Comments:	Ţ										
2018 - Fall: N	lo Change										
Comments:	Ţ										
2018 - Spring	ı : Damaged										
Comments:d											

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06A	9x9 tan/white streak floor tile (abated)			Main office, principals office, office store room, and vault ABATED		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : Damaged
Comments:damaged
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06B	9x9 light gray/white streak floor tile	2720	SF	Rooms 115, 129, 126, 125, 216, and adjustment room		Miscellaneous	No	None	0		YES X NO
2016 Fall: N	lo Chango	•	•	•		•	•	•	•	•	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : Damaged
Comments:damaged

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
06C	9"x9" Beige w/Brown Streaks Floor tile	2522	SF	Rooms 124, 127(Kitchen) and 128		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Damaged
Comments:MULTI AREA DAMAGED
2018 - Spring : Damaged
Comments:damaged
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
09A	9x9 white/green streaked floor tile	1680	SF	Rooms 114,115, in 1957 bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change	
Comments:	
2017 - Fall: Deteriorated	
Comments:TILES DISTURBED	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09B	9"x9" Brown w/White Streaks Floor Tile	881	SF	1957 Bldg: Men's Washroom and Teacher's Lounge		Miscellaneous	No	None	0		YES X NO

016 - Fall: No Change	
Comments:	
017 - Spring: No Change	
Comments:	
017 - Fall: No Change	
Comments:	
018 - Spring : Damaged	
Comments:damaged	
018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09C	9"x9" Gray w/ White and Black Streaks Floor Tile	3242	SF	Rooms 113,115,110,103, and 104		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : Damaged
Comments:damaged
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09D	9x9 tan/beige streak floor tile	1680	SF	Rooms 112 and 102		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
09E	9x9 tan/green and orange streak flr tile	1680	SF	Rooms 111 and 101		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	_											
2017 - Spring	g: No Change											
Comments:	•											
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09F	9x9 tan/white specks floor tile	2158	SF	Rooms 108 and 109		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : Damaged
Comments:damaged
2018 - Fall: No Change
Comments:

Comments:

Page 7

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
09G	9x9 green/white specks floor tile	1080	SF	Room 106		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09H	9x9 black/white streak flr tile	840	SF	Rm 100, 110, 115		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : Damaged
Comments:damaged
2018 - Fall: No Change
Comments:

12	Acoustical spray on plaster	1860	SF	Ceiling of Teachers Lounge (1957 Bldg)		Surface	Yes	Loc	3	YES	X NO
2016 - Fall: N	o Change										
Comments:	o Change										
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:	-										

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Baseboard			6 FT in each classroom		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Quantity

Material

Units

Material Location

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
14	baseboard mastic			6 LF in each classroom		Miscellaneous				YES	X NO
2016 - Fall: N	o Change										
Comments:	<u> </u>										
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Insulation in fire doors	8	Each	boiler room doors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : Damaged
Comments:damaged
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

Page 10

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
16	Fire brick (incenerator)	20	SF	Boiler room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
2017 Spring: No Change												

Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : Deteriorated
Comments:worn over time
2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	Transite (incinerator)	3	SF	Boiler room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : Deteriorated
Comments:worn over time
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
18A	Boiler gasket	40	LF	1966 boiler room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	•											
2017 - Fall: N	lo Change				1							
Comments:	•											
2017 - Spring	: No Change											
Comments:												
2018 - Spring	ı : Repaired											
Comments:re	placed											
2018 - Fall: N	lo Change				1							
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18B	Boiler gasket			1957 boiler room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : Repaired
Comments:replaced
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
20	Vibration dampener cloth			1966 mechanical room, 2nd floor		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	•											
2017 - Spring	: No Change				-							
Comments:	_]							
2017 - Fall: N	lo Change]							
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	·			·	_							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21A	9x9 white/green streak floor tile mastic under 12x12	1680	SF	Rooms 114 and 115		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 13

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21B	9x9 brown/white streak floor tile mastic	881	SF	Mens toilet & teachers lounge in 1957 bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21C	9x9 grey/black and white streak floor tile mastic	3242	SF	rooms 113, 115, 110, 103, and 104		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21D	9x9 tan/beige streak floor tile mastic	1680	SF	Rooms 112 and 102		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change Comments:											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21E	9x9 tan/green and orange streak floor tile mastic	1680	SF	Rooms 111 and 101		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21F	9x9 tan/white specks floor tile Mastic	2158	SF	Rm 108,109		Miscellaneous	No	None	0		YES X NO
					1						_

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: Damaged	
Comments:BY OUTSIDE DOOR	
2018 - Spring : Damaged	
Comments:damaged	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21G	9x9 green/white specks floor tile mastic	1080	SF	Room 106		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

21H	9x9 black/white streak floor tile mastic	840	SF	Rm 100, 110, 115		Miscellaneous	No	None	0	YES	X NO
0040 = 11 1					1						
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
0010 0 :											
2018 - Spring	: No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:											
					•						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23A	9x9 tan/white streak floor tile mastic			Main office, principals office, office store room, and vault		Miscellaneous					YES X NO
					1						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : Deteriorated
Comments:worn over time
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	ment Category
23B	9x9 light gray/white streaks flr tile mastic	2720	SF	Rooms 115, 129, 126, 125, 216, and adjustment room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change	•	•			•		•	•		•		
Comments:													
2017 - Spring	g: No Change				1								
Comments:]								
2017 - Fall: N	lo Change				1								
Comments:	•												
2018 - Fall: N	lo Change				1								
Comments:													
2018 - Spring	g : Damaged				-								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23C	9"x9" Beige w/ Brown Streaks VFT Mastic (abated)			Rooms 128, 127, Kitchen and 124		Miscellaneous	No				YES X NO

Comments:damaged

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
24	Baseboard			Classrooms, lobby and main office		Miscellaneous					YES	X NO
2016 - Fall:	No Change]							
Comments:	Ü											
2017 - Sprin	ıg: No Change				-							
Comments:					1							
2017 - Fall:	No Change				1							
Comments:	<u> </u>				1							
2018 - Sprin	g : No Change				1							
Comments:	<u> </u>				1							
2018 - Fall:	No Change				1							
Comments:	· · · · · · · · · · · · · · · · · ·				1							
					_							
				1	•	r		r			1	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Baseboard mastic			1962 classrooms, lobby, and main office		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26A	9x9 brown/white streak floor tile mastic	1680	SF	Room 122 and 119		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26B	9x9 light gray/brown & white strike floor tile mastic	3390	SF	Rooms 123, 120, 117, and 116		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : Damaged
Comments:damaged
2018 - Fall: No Change
Comments:

Page 20

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26C	9x9 tan/brown and white streaks floor tile mastic	8700	SF	Rooms 105, 121, 118, 217, 218, 219, 221, 220, 223, 222, and coaches office in gym		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : Damaged	
Comments:damaged	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26D	9x9 light gray/white streaks floor tile masic	1975	SF	2nd floor corridors		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26E	9"x9" Light Green Floor Tile with White Streaks Mastic	1040	SF	Gym Storage Room, Janitor Closets, Second Floor Storage, Stage Entrances, Storage Room by Stage		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Damaged
Comments:WATER DAMAGE
2018 - Fall: No Change
Comments:
2018 - Spring : Damaged
Comments:damaged

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Carpet mastic			Library (room 107)		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: Deteriorated
Comments:OLD, WORN,SHERREDING
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

28	Mastic under 1x1 acoustical ceiling tile			1966 throughout corridors and all purpose room		Miscellaneous					YES	X NO
2016 - Fall: I	No Change]							
Comments:	<u> </u>											
2017 - Sprin	g: No Change				_							
Comments:	g. 110 0.1141.1g0											
2017 - Fall: I	Damaged				-							
Comments:MULTI AREA DAMAGED												
2018 - Sprin	g : Deteriorated				-							
	vorn over time											
2018 - Fall: I	No Change				-							
Comments:	To Change]							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
29	29 Mastic under 1x1 acoustical 1962 classrooms, office and corridors					Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
30	Mastic under 1x1 acoustical ceiling tile			1957 classrooms and library		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Spring	g: No Change				_							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : Deteriorated											
Comments:w	orn over time											
2018 - Fall: N	lo Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Baseboard			1957 bldg - 6 LF in each classroom		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: Damaged
Comments:MULTI AREA DAMAGED
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
32	Baseboard mastic			1957 bldg - 6 LF in each classroom		Miscellaneous					YES	X NO
2016 - Fall: N	o Change]							
Comments:					1							
2017 - Fall: N	lo Change											
Comments:	-]							
2017 - Spring	: No Change											
Comments:					 							
2018 - Spring	: No Change											
Comments:					-							
2018 - Fall: N	o Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	window glazing			throughout 1966 bldg windows		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : Deteriorated
Comments:worn over time

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
34	Plaster	67000	SF	Throughout School		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: D	Damaged											
	EILING DAMAGES											
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	<u> </u>											
2018 - Spring	g : Deteriorated											
	orn over time											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Brown, Tan and White Ceramic Tile Grout	25	SF	Teacher's Longe Toilet (Room 148)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Brown, Tan and White Ceramic Tile Adhesive	25	SF	Teacher's Longe Toilet (Room 148)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: Repaired	
Comments:REATTECHED	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Grey and Green Ceramic Tile Grout	352	SF	Rooms 106, 108, 109, and Principal's Office Toilet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: Damaged
Comments:BY OUTSIDE DOORS
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Grey and Green Ceramic Tile Adhesive	352	SF	Rooms 106, 108, 109, and Principal's Office Toilet		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change						•	•	•	•	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Grey Carpet Mastic	728	SF	Room 114		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Purple and Grey Ceramic Tile Grout	280	SF	North Center Girls Restroom		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2010 0 : 11 01
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Purple and Grey Ceramic Tile Adhesive	280	SF	North Center Girls Restroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12 x 12 Dark Blue Floor Tile	575	SF	Gym Stage and Gym Storage Room		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change Comments:											
0047 5 11 1											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43M	12 x 12 Dark Blue Floor Tile Mastic	575	SF	Gym Stage and Gym Storage Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
44	Brown and White Ceramic Tile Grout	1148	SF	SE Boys and Girls Restrooms and 2nd Floor Boys Restroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change		•	-]	•	-			•		

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : Damaged
Comments:damaged

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Brown and White Ceramic Tile Adhesive	1148	SF	SE Boys and Girls Restrooms and 2nd Floor Boys Restroom		Miscellaneous	No	None	0		YES X NO

	• • • • • • • • • • • • • • • • • • • •
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : Damaged	
Comments:damaged	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	2 x 4 White Ceiling Tile	13472	SF	Rooms 116 - 123, and 216 - 223		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change Comments:	
Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	
2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	2016 - Fall: No Change
Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	Comments:
Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	
2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	2017 - Spring: No Change
Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	Comments:
Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	
2018 - Fall: No Change Comments: 2018 - Spring : No Change	2017 - Fall: No Change
Comments: 2018 - Spring : No Change	Comments:
Comments: 2018 - Spring : No Change	2018 - Fall: No Change
Comments:	2018 - Spring : No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	9 x 9 Tan Speckled Floor Tile	1448	SF	Main Office and Assistant Principals Office		Miscellaneous	Yes	Loc	6		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : Damaged
Comments:damaged

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
47M	12 x 12 Tan Speckled Floor Tile Mastic	1448	SF	Main Office and Assistant Principals Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : Damaged
Comments:damaged

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Light Grey Ceramic Tile Grout	504	SF	Lobby Boys and Girls Restrooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Damaged
Comments:FLOOR TILE FROM DRAIN REPAIR
2018 - Fall: No Change
Comments:
2018 - Spring : Damaged
Comments:damaged

		Quantity	Units		Туре	Category		Type	Quantity	Units		
49	Light Grey Ceramic Tile Adhesive	504	SF	Lobby Boys and Girls Restrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				1							
Comments:	_											
2017 - Sprin	g: No Change				1							
Comments:												
2017 - Fall: I	No Change				1							
Comments:												
2018 - Fall: I	No Change				-							
Comments:	•											
2018 - Sprin	ig : Damaged											

Material

Damage

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	Grey Speckled Terrazzo	7525	SF	Throughout School Corridors, except 2nd Floor Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Deteriorated
Comments:WORN AT STAIRS AND ENTRYS
2018 - Fall: No Change
Comments:
2018 - Spring : Deteriorated
Comments:worn over time

HA No

Comments:damaged

Material Description

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	12" X 12" blue-streaked VFT	1600	SF	Rooms 102 and 112		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51A	12" X 12" blue-streaked, Mastic	1600	SF	Rooms 102 and 112		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor
52	12" X 12" tan streaked VFT	3800	SF	Room 107/Library Rooms 114 and 133 Rooms 116/117 (Lunchroom)		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
John Horica.
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52A	12" X 12" tan-streaked, Mastic	3800	SF	Room 107/Library Rooms 114 and 133 Rooms 116/117 (Lunchroom)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

53	12" X 12" white-streaked VFT	100	SF	Coach's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:	J											
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : Damaged											
Comments:	damaged											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
53A	12" X 12" white-streaked, Mastic	100	SF	Coach's Office		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Units

Damage

Quantity

Change in Assessment Category

HA No

2016 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

		Quantity	Units		Type	Category		Туре	Quantity	Units		
54	12" X 12" blue VFT	80	SF	Coach's Office		Miscellaneous	No	None	0		YES	X NO
	: No Change											
Comments	:											
2017 - Fall	: No Change											
Comments):											
2017 - Spr	ing: No Change											
Comments):											
2018 - Fall	: No Change											
Comments);											
2018 - Spr	ing : Damaged											
Comments	<u> </u>											

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54A	12" X 12" blue, Mastic	80	SF	Coach's Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : Damaged
Comments:damaged

HA No

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
01E	9"x9" Light Green w/White Streaks Floor Tile	1040	SF	Gym Storage Room, Janitor Closets, Second Floor Storage, Stage Entrances, Storage Room by Stage		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : Damaged
Comments:damaged
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	Preform insulation- breaching	25	LF	Boiler room-1966 bldg		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Damaged
Comments:MULTI AREA DAMAGED
2018 - Fall: No Change
Comments:
2018 - Spring : Deteriorated
Comments:worn over time

В	Hard fittings on fiberglass insulation	150	LF	throughout 1966 bldg boiler room and corridors		TSI	Yes	Loc	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	J											
2017 - Spring	ı: No Change											
Comments:	, <u>-</u>											
2017 - Fall: N	lo Change											
Comments:	J]							
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : Deteriorated											
	orn over time											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
С	Hard fittings on fiberglass insulation	150	LF	Throughout 1957 bldg First Floor Boiler Room (on pipe near E wall) and		TSI	Yes	Dist	5		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

corridors

HA No

Material Description

Material

Quantity

Material

Units

2016 - Fall: N	No Change										
Comments:											
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: Damaged											
Comments:N	MULTI AREA DAMAGE	:D									
	g : Deteriorated										
Comments:w	orn over time										
2018 - Fall: N	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Boiler insulation mag block	450	SF	1957 boiler room		TSI	Yes	None	0		YES X NO

Type

Material

Category

TSI

Friable

Yes

Damage

Type

None

Damage

Units

Damage Quantity

0

Change in Assessment Category

X NO

YES

Material Location

1957 boiller room

HA No

D

Material Description

Preform boiler breeching

Material

Quantity

50

Material

Units

LF

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Hard fittings on fiberglass insulation	125	LF	1962 bldg throughout		TSI	Yes	None	0		YES X NO
2016 - Fall: N	lo Change]						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : Deteriorated
Comments:worn over time
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Spray-on Fireproofing	1700	SF	1966 - Boiler Room and 2nd Floor Mechanical Room		Surface	Yes	Dist	300		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : Deteriorated
Comments:worn over time

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
Н	12"x12" Blue Floor Tile	500	SF	Kitchen		Miscellaneous	No	None	0		YES	X NO
	2016 - Fall: No Change											
Comments:												
2017 - Spring: No Change												
Comments:	Comments:											

2017 - Fall: Damaged

Comments:MULTI AREA DAMAGED

2018 - Fall: No Change

Comments:

2018 - Spring : Damaged Comments:damaged

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	12"x12" Blue Floor Tile Mastic	500	SF	Kitchen		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: Damaged
Comments:ABOVE SMALL FREEZER
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : Damaged
Comments:damaged

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
J	1'x1' Acoustic Ceiling Tile	9500	SF	1966 - Corridors and All Purpose Room		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: F	Repaired											
Comments:T	ILES REPLACED											
2018 - Spring	g : Damaged				-							

Comments:damaged
2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
К	1'x1' Acoustic Ceiling Tile	7700	SF	1962 Classrooms and Corridors - Except in Rooms 116, 117, 118, 119, 120, 121, 122, 123, 216 and 217		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Damaged
Comments:MULTI AREA DAMAGED
2018 - Fall: No Change
Comments:
2018 - Spring : Damaged
Comments:damaged

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	1'x1' Acoustic Ceiling Tile	7700	SF	1957 Classsrooms and Library		Miscellaneous	Yes	None	0		YES X NO
0040 Fall N	1. 01				1						

2016 - Fall: No Change
Comments:
2017 - Fall: Damaged
Comments:MULTI AREA DAMAGED
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : Damaged
Comments:damaged

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: John Whistler Elementary School
Date: 1/10/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 25831