Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

	School: John Great Address: 1900 W. 2				acle Unit: gion:	2586 03	51	Building ID: 6450 Mail Room: 37					
CHECK	HERE IF NO CHA	ANGE TO	O ASBE	STOS	Asbestos Survey Da Email Add		Terrazas, 1/10/2019 mpterraza		<u> </u>				
	A copy of the2016/201	7 notice to	parents and	staff regarding	g the asbe	estos manage	ement plan noti	fications w	as distributed	l via:			
	Each child's backpa	nck	Notice	orinted in scho	ool's newsi	letter	Notice prin	ted in scho	ool's calendar	X Otl	ner parent	info bd	
HA No	Material Description Material Material Location Quantity Units Material Location						Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
4	12"x12" Light Blue Floor Tile	3900	SF	Rooms 102, 106	6, 107		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change												
Comments:													
2017 - Fall: N	o Change												
Comments:													
2017 - Spring	: No Change												
Comments:													
2018 - Fall: N	lo Change												
Comments:	-												

	·	Quantity	Units		Туре	Category		Type	Quantity	Units		
4.1	12"x12" Dark Beige Floor Tile	800	SF	Throughout		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				7							
Comments	:				-							
2017 - Spri	017 - Spring: No Change											
Comments	:											

Material

Friable

Damage

Damage

2017 - Fall: No Change Comments:

Material Material Location

2018 - Fall: No Change

Material Description

Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4.2	12"x12" Beige Floor Tile	2500	SF	1st & 2nd Floor Corridors, 205 & 208		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Damage Change in Assessment Category

5	Linoleum			Gym & Gym Entrances							YES	X NO
2016 - Fall:	No Change				7							
Comments:	110 Orlango											
2017 - Fall:	No Change				_							
Comments:	<u> </u>				1							
2017 - Sprin	ng: No Change		_									
Comments:												
2018 - Fall:	No Change											
Comments:					-							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
6	12"x12" Light Blue VFT	2000	QE .	Poomo 102 106 107		Miggallangous	No	None	0		Dvco I	V No

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Material Location

Rooms 102, 106, 107

HA No

6

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material Description

Material

Quantity

3900

SF

Material

Units

YES

X NO

6.1	12"x12" Dark Beige VFT Mastic	4000	SF			Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:	<u> </u>]							
2017 - Fall:	No Change											
Comments:					 							
	ıg: No Change				-							
Comments:					-							
2018 - Fall:	No Change											
Comments:					-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
6.2	12"x12" Beige Floor Tile			1st & 2nd Floor Corridors,							Dyro I	V NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

6.2

Material Description

12"x12" Dark Beige VFT

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
7	Linoleum Floor Mastic			Gym							YES	X NO
2016 - Fall Comments	: No Change											
	: No Change											
Comments												
	ing: No Change											
Comments):											
	: No Change											
Comments	S:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
8	Interior Brick			Interior of Bldg.							YES	X NO
2016 - Fall	: No Change											
Comments): 											
2017 - Fall	: No Change											

Comments:

Comments:

Comments:

2017 - Spring: No Change

2018 - Fall: No Change

9	Interior Brick Mortar			Interior of Bldg.							YES	X NO
2016 - Fall	: No Change				7							
Comments												
2017 - Fall	: No Change				1							
Comments					=							
2017 - Spri	ng: No Change											
Comments	:											
2018 - Fall	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
10	Exterior Brick			Exteior of Bldg Non- AHERA							YES	X NO
2016 - Fall	No Change				7							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Units

Material

Quantity

Material Location

11	Exterior Brick Mortar			Exterior of Bldg Non - AHERA							YES	X NO
2016 - Fall: N	lo Change											
Comments:	to change				-							
2017 - Fall: N	lo Change											
Comments:												
					=							
	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
12	Roof Field			Upper Roof Level - Non - AHERA		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

12.1	Roof Field			Lower Level - Non- AHERA		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	io oriange											
2017 - Fall: N	lo Change											
Comments:												
0047 0	N. Observe											
2017 - Spring	j: No Change											
Comments:												
2010 Fall N	la Changa											
2018 - Fall: N	io Change											
Comments:												
]							
	I Maria de la compansión de la compansió					I sa	Levis	T 5		_		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
13	Roof Flashing			Upper Level - Non- AHERA		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Material

Quantity

Material

Units

HA No

Material Description

13.1	Roof Flashing			Lower Level - Non - AHERA		Miscellaneous					YES	X NO
2016 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
					I							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
14	Purple Carpet Mastic			202		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

15	Wiring for Flood Lights in Field House	500	LF	Field House		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments												
2017 - Fall:	Other				1							
Comments	demolition											
2017 - Spri	ng: No Change				_							
Comments	:											
2018 - Fall:	Abated											
Comments	field house demolished				-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
16	12" x 12" Dark Beige Floor			Lunghrooms and Kitchen		Missellansous					Dyro I	V No

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

16

Material Description

Material

Quantity

Material

Units

Material Location

Lunchrooms and Kitchen

Change in Assessment Category

X NO

YES

17	12" x 12" Dark Beige Floor Tile Mastic			Lunchrooms and Kitchen		Miscellaneous					YES	X NO
2016 - Fall:	No Change]							
Comments:					1							
2017 - Fall:	No Change											
Comments:					=							
	ng: No Change											
Comments:					-							
2018 - Fall:	No Change											
Comments:					=							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
18	12" x 12" Light Beige Floor Tile			Lunchrooms and Kitchen		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

19	12" x 12" Light Beige Floor Tile Mastic			Lunchrooms and Kitchen		Miscellaneous					YES	X NO
2016 - Fall: I	No Change											
Comments:	110 Onlango											
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
20	Interior Incinerator Material/Breeching	178	SF	Boiler Room		TSI	Yes	None	0		YES	X NO

Asbestos

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

Material/Breeching

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material

Quantity

Material

Units

21	Black Vinyl Floor Covering	200	SF	Main Entrance Foyer and Stairs	Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change									
Comments:	_									
2017 - Fall:	No Change									
Comments:										
2017 - Sprii	ng: No Change									
Comments:										
2018 - Fall:	No Change									
Comments:										

Type

Material

Category

Damage

Type

Damage

Quantity

Damage

Units

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Black Vinyl Floor Covering Mastic	200	SF	Main Entrance Foyer and Stairs		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

23	2' x 4' Ceiling Tile w/Fissures/Pinholes	9480	SF	1st, 2nd & 3rd Floor Corridors, Classrooms & Main Office		Miscellaneous	Yes	None	0	YES	X NO
2016 - Fall:	No Change]						
Comments					- -						
2017 - Fall:	No Change				1						
Comments					1						
2017 - Spri	ng: No Change										
Comments											
2018 - Fall:	No Change										
Comments					1						
1											

Type

Material

Category

Friable

Damage

Туре

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	2'x2' Sectional CeilingTile w/Sm.Fissures/Pinholes	4000	SF	Gym, Room 303 & 305		Miscellaneous	Yes	Dist	800		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

Change in Assessment Category

Damage

Quantity

Damage

Units

25	Light Grey Linoleum	800	SF	Room 027		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:]							
2017 - Fall:	No Change											
Comments:					 							
	ng: No Change				-							
Comments:					-							
2018 - Fall:	No Change											
Comments:												
					J							
HA No	Material Description	Material	Material	Material Location	Achestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

No

Damage

Туре

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

26	Light Grey Linoleum Adhesive	800	SF	Room 027
2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				

Quantity

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Change in Assessment Category

X NO

100	White Linoleum	3200	SF	Parent Rm., Science Rm. 027, Lunch Rm., Kitchen		Miscellaneous	No	None	0		YES	X NO
0040 = 11.1					1							
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:	<u>-</u>											
					1							
					_							
HA No	Material Description	Material	Material	Material Location	Achoetoe	Material	Eriable	Domogo	Damago	Damaga	Change in Access	mont Catagory

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

TIA NO	Material Description	Quantity	Units	iviaterial Education	Type	Category	Filable	Type	Quantity	Units	Change in Asses	Sment Category
101	White Linoleum Adhesive	3200	SF	Parent Rm., Science Rm. 027, Lunch Rm., Kitchen		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change			_								

Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No

Material Description

Material

Quantity

Material

Units

2016 - Fall:	No Change										
Comments:											
2017 - Fall: No Change											
Comments:	1										
2017 - Spri	ng: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
					<u> </u>						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
	·	Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

HA No

102

103

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material Description

Brown Epoxy Flooring

Lab Counter Tops

Material

Quantity

13

Material

Units

EΑ

SF

2000

Material Location

Basement Corridors

Science Rm.

Change in Assessment Category

X NO

X NO

YES

YES

104	Kaowool Gaskets	10	FITTING	Boiler Rm.		TSI	Yes	None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

TSI

Friable

Yes

Damage

Туре

None

Damage

Quantity

0

Damage

Units

OOAC Falls No Charage		
2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

4

Material

Quantity

Material

Units

SF

Material Location

Fire Pump Rm.

HA No

105

Material Description

Mudded Pipe Insulation

Change in Assessment Category

YES

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
106	12"x12" Beige w/ Streaks VFT	1600	SF	Rms. 202, 206A		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change	
Comments:	
0047 0 : N 01	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
107	12"x12" Beige w/ Streaks VFT Mastic	1600	SF	Rms. 202, 206A		Miscellaneous	No	None	0		YES X NO

0040 5 11 N1 O1	
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

108	Drywall	5000	SF	Restroom, Kitchen, Lunch Rm.		Miscellaneous	No	None	0		YES	X NO
0040 5-1	L. N. C.		•		7							
	I: No Change											
Comments	S:											
2017 - Fal	l: No Change											
Comments	S:											
2017 - Spi	ring: No Change											
Comments	S:											
2018 - Fal	I: No Change											
Comments	S:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

Friable

No

Damage

Туре

None

Damage

Quantity

0

Damage

Units

500

HA No

109

Material Description

Drywall Joint Compund

Material

Units

LF

Material Quantity Material Location

2nd Floor Faculty

2nd Floor Faculty

Lunch Rm.

Restroom, Kitchen,

Change in Assessment Category

X NO

YES

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
110	12"x12" Blotted Beige VFT	200	SF	3rd Floor Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall Comments	: No Change											
2017 - Spri	ing: No Change											
2017 - Fall: No Change Comments:												
2018 - Fall	: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
111	12"x12" Blotted Beige VFT Mastic	200	SF	3rd Floor Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

2016 - Fall: N	No Change										
Comments:											
2017 - Fall: N	No Change										
Comments:											
	g: No Change										
Comments:											
2018 - Fall: N	No Change										
Comments:					_						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Surface

Category

Miscellaneous

Friable

Yes

No

Damage

Type

Dist

None

Damage

Quantity

1050

0

Damage

Units

10

Material

FITTING

Units

SF

Material Quantity

3000

Material Location

Attic Ducting

Throughout

HA No

112

113

Material Description

Spray-on Fire Proofing

Firedoors

Change in Assessment Category

X NO

X NO

YES

YES

114	Door Frame Caulk	500	LF	Throughout		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:]							
2017 - Spring	j: No Change											
Comments:					-							
2017 - Fall: N	lo Change				-							
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					1							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
	 	1	<u> </u>		<u> </u>	 	 	-				

Surface

Asbestos

Type

Material

Category

Friable

Damage

Type

Dist

Yes

Damage

Quantity

6000

Damage

Units

Material Location

Throughout

HA No

115

Comments:

Comments:

Comments:

Comments:

Material Description

Plaster

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material

Quantity

120000

SF

Material

Units

YES

X NO

116	Light Beige w/ Gray Spots Linoleum	2000	SF	Kitchen, South and North Lunchroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:	o o				<u> </u>							
2017 - Spring	: No Change				-							
Comments:	J											
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

TSI

Asbestos

Type

Material

Category

Friable

Yes

None

0

Damage

Туре

Damage

Quantity

Damage

Units

В	Aircell Pipe Insulation	1000	LF	Kitchen, B'smt Corridor, Lunchroom, Store Rm.						
2016 - Fall: N	lo Change									
Comments:										
2017 - Fall: D	eteriorated									
Comments:bo	Comments:boiler room cracking									
2017 - Spring	2017 - Spring: No Change									
Comments:										
2018 - Fall: No Change										
Comments:	Comments:									

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Mechanical Areas,

YES

X NO

С	Cardboard Pipe Covering	600	LF	Mechanical Areas, Lunchrrom, Basement Corridor, & Entrance Door		TSI	Yes	None	0	YES	X NO
0040 Falls N	In Ohaman				1						
2016 - Fall: N	io Change										
Comments:											
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: D	Deteriorated										
Comments:b	oiler room peeling										
•			•								
2018 - Fall: N	lo Change										
Comments:											

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

Mechanical Areas,

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Pipe Joint Compound	200	EA	Kitchen, Playroom & Lunchroom, Basement Corridor, Mechanical Areas		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: _John Greenleaf Whittier Elementary School
Date: 1/31/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
X Other. parent info bd
A COPY OF THIS NOTICE MUST BE PLACED IN THE

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.