## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2018 - Fall

25881

**Oracle Unit:** 

Address: 6950 N Hiawatha Avenue Region: 01 Mail Room: Asbestos Surveyor: Birriel, Victor X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 11/18/2018 Email Address: vbirriel@cps.edu A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Type Quantity MJP E/F/V on Cardboard YES 03 17 ΙF X NO Janitors Closet - 1944 TSI Yes None 0 Pipe Insulation 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Wildwood IB World Magnet School

School:

Oracle Unit: 25881

6470

**Building ID:** 

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
04	Cardboard Pipe Insulation	5	LF	Janitors Closet - 1944		TSI	Yes	None	0		YES	X NO
2016 - Fall: No Change												
Comments:					1							
2017 - Spring	g: No Change											
Comments:					-							
2017 - Fall: No Change					=							
Comments:					]							

2018 - Spring : No Change Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	Blown Insulation	1500	SF	Attic Space - 1944		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
05A	Blown Insulation	2000	SF	South and West Attic Areas - 1952		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprin	ng : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
1					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	Cardboard Pipe Insulation	60	LF	Pipe Chases - 1952		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

06A	MJP E/F/V on Cardboard Pipe Insulation	15	LF	Pipe Chases - 1952	TSI	Yes	None	0	YES	X NO
2016 - Fall: I	No Change									
Comments:	go									
2017 - Sprin	g: No Change									
Comments:										
2017 - Fall: I	No Change									
Comments:										
2018 - Sprin	g : No Change									
Comments:										
2018 - Fall: I	No Change									
Comments:										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	Mag Block Pipe Insulation	60	LF	Boiler Room, Girl's Washroom Pipe Chase and the Janitor's Closet - 1944		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
7A	Mag Block Pipe Insulation - ABATED			Room 101 and the Crawl Space - 1952 -ABATED		TSI		None			YES	X NO
2016 - Fall: I	No Change				]		•	•				
Comments:	<u> </u>											
2017 - Sprin	g: No Change				-							
Comments:	<u> </u>											
2017 - Fall: I	No Change											
Comments:	Ü											
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall: I	No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	1'x1' White Ceiling Tile	1000	SF	Gym - 1952		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
09	Hard Coat Plaster			Throughout - 1944		Surface	No				YES	X NO
2016 - Fall: N	o Change				1							
Comments:	•											
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09A	Hard Coat Plaster			Throughout - 1952		Surface	No				YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

H	A No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	)	MJP E/F/V on Mag Block Pipe Insulation	15	LF	Boiler Room, Girls Washroom Pipe Chases and Janitor's Closet - 1944		TSI	Yes	None	0		YES X NO
20	16 - Fall: N	o Change										

2040 Felli No Change	
2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
Commond.	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10A	MJP E/F/V on Mag Block Pipe Insulation - ABATED			Room 101 and the Crawl Space - 1952 - ABATED		TSI		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
11	Tunnel Floor Debris - ABATED			Tunnel - 1952 - ABATED		TSI		None			YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:					1							
2018 - Fall: N	lo Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Aircell Pipe Insulation	20	LF	Janitor's Closet - 1944		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12A	MJP E/F/V on Aircell Pipe Insulation	10	LF	Janitor's Closet - 1944		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12"x12" Brown w/speckles VFT (Under HA# 33)	700	SF	Room 104 - 1944		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 9

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"x12" Brown w/Speckles VFT Mastic (Under HA# 33A)	700	SF	Room 104 - 1944		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	9"x9" Tan w/ Dark Brown Streaks VFT	300	SF	Room 107, Women Washroom (by Room 105), Principal's Office (Under Carpet) and Engineer's Office (Under HA#33 and HA#33A) - 1944		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment (	Category
17A	9"x9" Tan w/ Dark Brown Streaks VFT Mastic	300	SF	Room 107, Women Washroom (by Room 105), Principal's Office (Under Carpet) and Engineer's Office (Under HA#33 & HA#33A) - 1944		Miscellaneous	No	None	0		YES X	NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
18	9"x9" Light Blue w/ Black Streaks VFT	750	SF	Engineers Office (Under HA33 and HA33A), Women's Washroom (by Room 105), Principal's Office (Under Carpet) and Room 107 - 1944		Miscellaneous	No	None	0		YES	X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
18A	9"x9" Light Blue w/ Black Streaks VFT Mastic	750	SF	Engineer's Office (Under HA#33 and HA#33A) Women's Washroom (by Room 105) Principal's Office (Under Carpet) and Room 107 - 1944		Miscellaneous	No	None	0		YES	X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	9"x9" Gray w/ Black & White Streaks VFT	750	SF	Room 106 (Under HA#32) - 1944		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19A	9"x9" Gray w/ Black & White Streaks VFT Mastic	750	SF	Room 106 (Under HA#32) - 1944		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12"x12" Light Blue w/ Black & White Streaks VFT	3500	SF	Rooms 101, 102, 103, 108, 109, 111, Gym (Under HA44, 44A, 45 and 45A) and Gym Office - 1952		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
<u> </u>

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20A	12"x12" Light Blue w/ Blk & White Streaks VFT Mastic	3500	SF	Rooms 101, 102, 103, 108, 109 and 111, Gym (Under HA44, 44A, 45 and 45A) and the Gym Office - 1952		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12"x12" Beige w/Black & White Streaks VFT	750	SF	Rooms 101, 102, 103, 108, 109, 111, Gym (Under HA44, 44A, 45 and 45A) and Gym Office - 1952		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21A	12"x12" Beige w/ Black & White Streaks VFT Mastic	750	SF	Rooms 101, 102, 103, 108, 109, 111, Gym (Under HA44, 44A, 45 and 45A) and Gym Office - 1952		Miscellaneous	No	None	0		YES X NO

		<u> </u>
2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	9"x9" Light Blue w/ Black & White Streaks VFT	1300	SF	Rooms 112 and 115, Main Office and Counselor's Office - 1952		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22A	9"x9" Lt Blue w/ Black & White Streaks VFT Mastic	1300	SF	Rooms 112 and 115, Main Office and Counselor's Office - 1952		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	9"x9" Beige w/ Black & White Streaks VFT	1300	SF	Rooms 112 and 115, Main Office and Counselor's Office - 1952		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

	Quantity	Units		Type	Category		Туре	Quantity	Units	
23A 9"x9" Beige w/ White Streaks		SF	Rooms 112 and 115, Main Office and Counselor's Office - 1952		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12"x12" Gray w/white streaks VFT	750	SF	Under Carpet in the Library (Room 114) - 1952		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24A	12"x12" Gray w/white streaks VFT Mastic	750	SF	Under Carpet in Library (Room 114) - 1952		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change Comments:  2017 - Spring: No Change Comments:  2017 - Fall: No Change Comments:  2018 - Spring: No Change Comments:  2018 - Fall: No Change	Comments:  2017 - Spring: No Change Comments:  2017 - Fall: No Change Comments:  2018 - Spring : No Change Comments:	
Comments:  2017 - Spring: No Change Comments:  2017 - Fall: No Change Comments:  2018 - Spring: No Change Comments:  2018 - Fall: No Change	Comments:  2017 - Spring: No Change Comments:  2017 - Fall: No Change Comments:  2018 - Spring: No Change Comments:  2018 - Fall: No Change	
2017 - Spring: No Change Comments:  2017 - Fall: No Change Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	2017 - Spring: No Change Comments:  2017 - Fall: No Change Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	2016 - Fall: No Change
Comments:  2017 - Fall: No Change Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	Comments:  2017 - Fall: No Change Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	Comments:
Comments:  2017 - Fall: No Change Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	Comments:  2017 - Fall: No Change Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	
2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Fall: No Change Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	2017 - Spring: No Change
Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	Comments:
Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	Comments:  2018 - Spring : No Change Comments:  2018 - Fall: No Change	
2018 - Spring : No Change Comments: 2018 - Fall: No Change	2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Fall: No Change
Comments: 2018 - Fall: No Change	Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Fall: No Change	Comments: 2018 - Fall: No Change	
2018 - Fall: No Change	2018 - Fall: No Change	2018 - Spring : No Change
		Comments:
Commonto	Comments:	2018 - Fall: No Change
Comments:		Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" Gray w/black and white streaks VFT	300	SF	Library (under carpet) - 1952		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25A	12"x12" Gray w/ Black & White Streaks VFT Mastic	300	SF	Library (under carpet) - 1952		Miscellaneous	No	None	0		YES X NO
004C Fall N	- Oh										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	MJP E/F/V on Fiberglass Pipe Insulation	35	LF	Boiler Room - 1944		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 23

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
27	12"x12" White w/ Beige Streaks VFT	1000	SF	North, South and West Corridors (Under HA#39 through HA#43A), Room 110 - 1952		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27A	12"x12" White w/Beige Streaks VFT Mastic	1000	SF	North, South and West Corridors (Under HA#39 through HA#43A), Room 110 - 1952		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12"x12" Brown w/ Beige Streaks VFT	1000	SF	North, South and West Corridors (Under HA#39 Through HA#43A) and Room 110 - 1952		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28A	12"x12" Brown w/Beige Streaks VFT Mastic	1000	SF	North, South and West Corridors (Under HA#39 Through HA#43A) and Room 110 - 1952		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2047 5 11 N O	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
0040 5 11 N 01	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" Off White w/ Brown Speckles VFT	800	SF	Room 113 - 1952		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29A	12"x12" Off White w/ Brown Speckles VFT Mastic	800	SF	Room 113 - 1952		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2010 0 1 11 01	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12"x12" White w/ Beige Streaks VFT	1000	SF	Main Corridor (Under HA#34 through HA#38A) - 1944		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 27

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
30A	12"x12" White w/ Beige Streaks VFT Mastic	1000	SF	Main Corridor (Under HA#34 through HA#38A) - 1944		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change	•	•			,	•	•	•	•		

0040 Fall No Olesco
2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12"x12" Brown w/ Beige Streaks VFT	750	SF	Main Corridor (Under HA34 through HA38A) - 1944		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
31A	12"x12" Brown w/ Beige VFT Mastic	750	SF	Main Corridor (Under HA34 through HA38A) - 1944		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												
2017 - Spring: No Change					-							

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
0040 5 11 N 01
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12"x12" Light Blue w/ Specks VFT	800	SF	Room 106 - 1944		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

32A	12"x12" Light Blue w/ Specks VFT Mastic	800	SF	Room 106 - 1944	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:										
2017 - Spring: No Change										
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2018 - Spring	g : No Change									
Comments:										
2018 - Fall: No Change										
Comments:										

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12"x12" White w/Black Streaks VFT	1500	SF	Rooms 104 and 105, Engineer's Office, Janitor's Washroom (near Boiler Room) - 1944		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12"x12" white w/gray specks VFT - ABATED			Corridor - 1944		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

34A	12"x12" white w/gray specks VFT (Mastic) - ABATED		Corridor - 1944		Miscellaneous	None		YES	X NO
2016 - Fall: N	o Change	· ·	•	]		·			
2016 - Fall: No Change									
Comments:									
22.17									
2017 - Spring	: No Change								
Comments:									
2017 - Fall: N	lo Change								
Comments:	-			1					
				1					
2018 - Spring	: No Change			]					
Comments:				1					
2018 - Fall: N	o Change								
Comments:									
Common.									
L				1					

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12"x12" Orange VFT - ABATED			Corridor - 1944		Miscellaneous		None			YES X NO
•											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
35A	12"x12" Orange VFT Mastic - ABATED			Corridor - 1944		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:	•											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change				-							
Comments:												
2018 - Spring	g : No Change				-							
Comments:												
2018 - Fall: N	lo Change				-							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12"x12" Yellow VFT - ABATED			Corridor - 1944		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
36A	12"x12" Yellow VFT Mastic - ABATED			Corridor - 1944		Miscellaneous		None			YES	X NO
2016 - Fall:	No Change									•		
Comments	•											
2017 - Spri	ng: No Change											
Comments	:											
2017 - Fall:	No Change											
Comments	:											
2018 - Spri	ng : No Change											
Comments												
2018 - Fall:	No Change											
Comments	:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12"x12" Blue VFT	45	SF	Corridor - 1944		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
37A	12"x12" Blue VFT Mastic	45	SF	Corridor - 1944		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change				=							
Comments:												
2017 - Fall: N	o Change											
Comments:	-											
2018 - Spring	: No Change											
Comments:	J											
2018 - Fall: N	o Change				-							
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12"x12" Red VFT - ABATED			Corridors - 1944		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
38A	12"x12" Red VFT Mastic - ABATED			Corridors - 1944		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12"x12" White w/ gray specks VFT - NOT OBSERVED	3000	SF	Corridors - 1952 (Material presumed under existing flooring)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39A	12"x12" White w/gray specks VFT Mastic - NOT OBSERVED	3000	SF	Corridors - 1952 - (Material presumed under existing flooring)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12"x12" Orange VFT - NOT OBSERVED	80	SF	Corridors - 1952 (Material presumed under existing flooring)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
40A	12"x12" Orange VFT Mastic - NOT OBSERVED	80	SF	Corridors -1952 (Material presumed under existing flooring)		Miscellaneous	No	None	0		YES	X NO
2046 Fall N	a Change	•		•	· · ·	•		•	•	•		

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12"x12" Yellow VFT - NOT OBSERVED	40	SF	Corridors - 1952 (Material presumed under existing flooring)		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41A	12"x12" Yellow VFT Mastic - NOT OBSERVED	40	SF	Corridors - 1952 (Material presumed under existing flooring)		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change	•		•	]	•	•	•	•	•	

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12"x12" Blue VFT	150	SF	Corridors - 1952		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 39

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
42A	12"x12" Blue VFT Mastic	150	SF	Corridor - 1952		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change					]							_
Comments:	Comments:											
2017 - Spring: No Change												
Comments:												

2017 - Fall: No Change Comments:

2018 - Spring : No Change Comments:

2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12"x12" Red VFT - NOT OBSERVED	40	SF	Corridors - 1952 (Material presumed under existing flooring)		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43A	12"x12" Red VFT Mastic - NOT OBSERVED	40	SF	Corridors - 1952 (Material presumed under existing flooring)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12"x12" Light Blue Speckled VFT	1500	SF	Gym - 1952		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44A	12"x12" Light Blue Speckled Mastic	1500	SF	Gym - 1952		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12"x12" Dark blue speckled VFT	500	SF	Gym - 1952		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45A	12"x12" Dark Blue speckled Mastic	500	SF	Gym - 1952		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										
Comments:											
2017 - Spring	ı: No Change										
Comments:	, <u> </u>										
2017 - Fall: N	lo Change										
Comments:											
2018 - Spring	g : No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Miscellaneous

REMOVED, JUNE 2015
2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

46

2'x2' Ceiling Tile

Classrooms, Washrooms, Corridors and Closets -

Mobile Unit

MOBILE UNIT

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	12"x12" Off white w/tan specks VFT Mobile Unit (REMOVED, June 2015)			Classrooms, Washrooms, Corridors and Closets - Mobile Unit (REMOVED, June 2015)		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 25881

47A	12"x12" Off white w/tan specks VFT Mastic - Mobile Unit (REMOVED, June 2015)	Classrooms, Washroom, Corridors and Closets - Mobile Unit (REMOVED, June 2015)	Miscellaneous			YES	X NO
2016 - Fall: N	lo Change						
Comments:	go						
2017 - Spring	ı: No Change						
Comments:	g. 140 Orlange						
2017 Falls N	lo Chongo						
2017 - Fall: N Comments:	lo Change						
Comments.							
	g : No Change						
Comments:							
2018 - Fall: N	lo Change						
Comments:							

Asbestos

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Drywall - Mobile Unit (REMOVED, June 2015)			Classrooms, Washrooms, Corridors and Closets - Mobile Unit (REMOVED, June 2015)		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

49	12"x12" White w/blue streaks VFT	1800	SF	Corridor - 1944		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:					]							
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					1							
2018 - Spring	: No Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					  -							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Asbestos

Type

Material

Category

Friable

Damage

Type

Damage

Units

Damage

Quantity

0

Change in Assessment Category

50	12"x12" White w/ blue streaks Mastic	1800	SF	Corridor - 1944	Miscellaneous	No	None
2016 - Fall: N	lo Change						
Comments:	<u> </u>						
2017 - Spring	g: No Change						
Comments:							
2017 - Fall: N	lo Change						
Comments:							
2018 - Spring	g : No Change						
Comments:	_						

HA No

2018 - Fall: No Change

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	12"12" White w/blue streaks VFT	2500	SF	Corridors - 1952		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change Comments:											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
<u> </u>

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	12"x12" White w/blue streaks Mastic	2500	SF	Corridors - 1952		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

Page 47

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	18"x18" Gray w/ Blue Streaks VFT	1200	SF	Rms 102, 107, and 112		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
Confinents.	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53A	18"x18" Gray w/ Blue Streaks VFT Mastic	1200	SF	Rms 102, 107, and 112		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
54	12"x12" Green w/ Green Specks VFT	1700	SF	Room 115 and the Office across from Room 107		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54A	12"x12" Green w/ Green Specks VFT Mastic	1700	SF	Room 115 and the Office across from Room 107		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	Vinyl Baseboard	1000	SF	Throughout the School		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 25881

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

accordance with Illinois and Federal Asbestos Regulations, that a copy of nent Plan is available at each school during school hours by appointment. Asbestos Management Plan must be made at least 24 hours in advance. that CPS conducts asbestos inspections of all Schools every three years.
nent Plan is available at each school during school hours by appointment. Asbestos Management Plan must be made at least 24 hours in advance.
nent Plan is available at each school during school hours by appointment. Asbestos Management Plan must be made at least 24 hours in advance.
that CDS conducts ashastas inspections of all Schools every three years
completed in 2016. are conducted every six months.
ce was sent home in each child's backpack.
ce was printed in the school's newsletter and sent home with each child
ce was printed in the school's calendar and sent home with each child
i

VFT = Vinyl Floor Tile
Oracle Unit: 25881

SCHOOL'S ASBESTOS MANAGEMENT PLAN.