## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2018 - Fall

Ella Flagg Young Elementary School 25921 6520 School: **Oracle Unit: Building ID:** 1434 N. Parkside Avenue Address: Region: 02 Mail Room: Asbestos Surveyor: Rehberg, Mr. Caleb M. X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/11/2019 Email Address: A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type 9"x9" Gray w/White Streaks Room 315 & Engineer's YES 01 850 SF X NO Miscellaneous No None 0 Office- 1924 Building 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	12"x12" Beige w/Brown Streaks VFT	400	SF	109 Toliet, Gym Office- 1924 Building		Miscellaneous	No	Loc	20		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	9"x9" Gray w/White Streaks VFT Mastic	850	SF	Room 315 & Engineer's Office- 1924 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

04	12"x12" Beige w/Brown Streaks VFT Mastic	400	SF	109 Toliet, Gym Office- 1924 Building	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Chango									
	io Change									
Comments:										
2017 - Spring	g: No Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:	-									
2018 - Spring	g : No Change									
Comments:	<u> </u>									
2018 - Fall: N	lo Change									
Comments:	<u> </u>									

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	9"x9" Gray w/Black & White Streaks VFT	600	SF	Bilingual Classroom (Computer Room), 3rd Floor Corridor (Office near Gym)- 1924 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
06	9"x9" Gray w/Black & White Streaks VFT Mastic	600	SF	Computer Room, 3rd Floor Corridor (Office near Gym)- 1924 Building		Miscellaneous	No	None	0		YES	X NO
0040 5 11 1	. 01	•	•	•	1	•	•	•	•	•	•	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6	Boiler Rope	20	LF	Boiler Room- 1924 Building		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Units Units	Change in Assessment Category
07	12"x12" Grey w/Blue Streaks VFT	1000	SF	Main Office; Astt Principal's Office; Store Room by Room 105- 1924 Building		Miscellaneous	No	Loc	15		YES X NO
2016 - Fall: N Comments:	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	12"x12" Grey w/Blue Streaks VFT Mastic	1000	SF	Main Office, Store Room by Room 105- 1924 Building		Miscellaneous	No	None	0		YES X NO

09	2'x2' Gray Terrazo	2400	SF	2nd & 3rd Floor Corridors- 1924 Building		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:					1							
2017 - Spring	g: No Change				1							
Comments:	<b>,</b>				]							
2017 - Fall: N	lo Change				_							
Comments:												
2018 - Spring	g : No Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					_							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

Damage

Units

Damage

Quantity

0

None

Change in Assessment Category

						_				
2016 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2018 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										

2400

HA No

10

Material Description

2'x2' Gray Linoleum Mastic

Material

Units

SF

Material

Quantity

Material Location

2nd & 3rd Floor

Corridors- 1924 Building

Page 6

YES

X NO

24 Aircell Pipe Insulation 2500 LF Northeast Air Tunnel, Fan Room & Auditorium Crawlspace- 1924 Building	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	24	Aircell Pipe Insulation	2500	LF	Room & Auditorium		TSI	Yes	None	0		

2016 - Fall: No Change	
Comments:	
Comments.	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Exterior Window Caulk	3000	LF	Throughout- 1924 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:window rehab 2008-2009
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Interior Window Caulk	3000	LF	Throughout- 1924 Building		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:window rehab 2008-2009
2017 - Fall: No Change
Comments:
0040 Ossis No Olessa
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12"x12" Tangerine VFT	10500	SF	Throughout 1998 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12"x12" Tangerine VFT Mastic	10500	SF	Throughout 1998 Addition		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12"x12" Black VFT	3000	SF	Throughout 1998 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12"x12" Black VFT Mastic	3000	SF	Throughout 1998 Addition		Miscellaneous	No	None	0		YES X NO
204C Fall N	a Changa										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	2'x4' White w/ Grooves CT	20000	SF	Throughout 1998 Addition		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 10

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
40	2'x4' Smooth CT			Throughout 1998 Addition							YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	-											
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					_							
2018 - Spring	ı : No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Drywall			Throughout 1998 Addition							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
42	Drywall Compound			Throughout 1998 Addition							YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	<u> </u>				]							
2017 - Spring	: No Change	-										
Comments:					]							
2017 - Fall: N	lo Change				-							
Comments:	<u> </u>				]							
2018 - Fall: N	lo Change				-							
Comments:	J											
2018 - Spring	ı : No Change				-							
Comments:					]							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	Vinyl Baseboard			Throughout 1998 Addition							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
44	Vinyl Baseboard Mastic			Throughout 1998 Addition							YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	ı: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	ı : No Change											
Comments:												
				1			_		1		T	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Gray Linoleum			Throughout 1998 Addition							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
46	Gray Linoleum Mastic			Throughout 1998 Addition							YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Fall: No Change												
Comments:					_							
2017 - Spring	g: No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change				_							
Comments:												
					]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	Terrazzo	10000	SF	Old Bldg Hallway and Stairwells- 1924 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
48	Beige and Black Terrazzo	10000	SF	1998 Bldg Hallways and Stairwell		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:	-											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	Carpet Mastic	500	SF	1998 Bldg - Room 231		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
50	Carpet Mastic	1800	SF	Rm 214 Office - Bldg 1924		Miscellaneous		None	0		YES	X NO
2016 - Fal	II: No Change											
Comment												
2017 - Sp	ring: No Change											
Comment	S:											
2017 - Fal	II: No Change											
Comment	S:											
2018 - Fal	II: No Change											
Comment	S:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
51	2 x 2 White Ceiling	2400	SF	Gym		Miscellaneous	Yes	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2018 - Spring: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	Insulation behind window seat, covering radiator	40	SF	Rm 107		TSI	Yes	Loc	5		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:window rehab 2008-2009
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
53	Stage Curtains	2000	SF	Assembly Hall		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment C	ategory
EE	Paperwrap Pipe Insulation	1805	LF	Auditorium Crawlspace- 1924 Building		TSI	Yes	None	0		YES X	0
2016 - Fall: N	o Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FF	MJP E/F/V on Paperwrap Pipe Insulation	86	LF	Auditorium Crawlspace- 1924 Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

		Quantity	Units		Type	Category	Туре	Quantity	Units		
GG	2'x4' White Speckled Ceiling Tile			1st, 2nd, & 3rd Floor Corridors & Classrooms, Boiler Room Toliet- 1924 Building						YES	X NO
2016 - Fall:	No Change										
Comments:	-										
2017 - Fall:	No Change										
Comments:	-										
2017 - Sprin	ig: No Change										
Comments:											
2018 - Sprin	g : No Change										
Comments:											
2018 - Fall:	No Change										
Comments:					]						

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
НН	MJP E/F/V on Aircell Pipe Insulation	232	LF	Auditorium Crawlspaces, Fan Room & Northeast Air Tunnel- 1924 Building		TSI	Yes	None	0		YES X NO	

	•		•	•	
2016 - Fall: N	o Change				
Comments:					
2017 - Spring	: No Change				
Comments:					
2017 - Fall: N	o Change				
Comments:					
2018 - Fall: N	o Change				
Comments:					
2018 - Spring	: No Change				
Comments:			•		
			•		•

HA No

Material Description

Material

		Quantity	Units		Type	Category		Type	Quantity	Units	3	,
II	Mag Block Elbows	15	LF	Auditorium Crawlspaces- 1924 Building		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:					_							
2017 - Spring	: No Change											
Comments:					_							
2017 - Fall: N	o Change				1							
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change				1							
Comments:	<u> </u>				]							
					J							

Material

Friable

Damage

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
JJ	Mag Block Pipe Insulation	450	LF	Auditorium Crawlspaces- 1924 Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
KK	Fiberglass Elbows	15	LF	Northeast Crawlspaces- 1924 Building		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change				_							
Comments:												
2018 - Sprin	g : No Change				1							
Comments:												
2018 - Fall:	No Change											
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
0	Hardcoat Plaster			Throughout- 1924 Building							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Ella Flagg Young Elementary School
Date:1/11/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 25921

SCHOOL'S ASBESTOS MANAGEMENT PLAN.