## **Chicago Public Schools**

## **6 Month Asbestos Surveillance** 2018 - Fall

Jackie Robinson Elementary School 26061 6780 School: **Oracle Unit: Building ID:** Address: 4225 S. Lake Park Ave Region: Mail Room: Asbestos Surveyor: Collins, Michael X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/10/2019 Email Address: mdcollins5@cps.edu A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type YES 2'x4' Lay In Ceiling Panels SF 0 X NO 40200 Throughout Facility Miscellaneous No None 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments:

2	Ceiling Plaster	40000	SF	Throughout Facility		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:												
2017 - Fall: N	o Change											
Comments:	<b>.</b>											
2017 - Spring	: No Change				-							
Comments:	Ü											
2018 - Fall: N	o Change				_							
Comments:	Ü											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

Damage

Quantity

0

None

Damage

Units

18200

HA No

3

Material Description

12"x12" White Floor Tile

Material

Quantity

Material

Units

SF

Material Location

Corridors, Lunchroom,

Storages, 101, 102

YES

X NO

3 A	12"x12" Brown Gray Floor Tile	1400	SF	Gym		Miscellaneous	No	None	0	YES	X NO
					Ī						
2016 - Fall: N	o Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											
	·			·							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4	12"x12" White Floor Tile Mastic	20000	SF	Corridors, Offices, Lunchroom, Storages, 101, 102		Miscellaneous	No	Dist	14		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

4 A	12"x12" Brown Floor Tile Mastic	1400	SF	Gym		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				1							
Comments:	o Onange				-							
					]							
2017 - Fall: N	o Change											
Comments:					]							
2017 - Spring	: No Change											
Comments:												
2040 Fall N	o Change				_							
2018 - Fall: N	o Change				_							
Comments:												
					J							
	1			T		•	1	•	•	1		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
5	Incinerator Fire Brick			Material Not Present		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

2016 - Fall: N	lo Change				1						
Comments:	io onango										
0047 Falls N	la Ohanan				]						
2017 - Fall: N	io Change										
Comments:											
2017 - Spring	ı: No Change				-						
	j. 140 Orlange				+						
Comments:											
2018 - Fall: N	lo Change										
Comments:											
			•								
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage Units	Change in Assessment Category
		Quantity	Units		Type	Category		Туре	Quantity	UTILS	

Type

Material

TSI

Category

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

0

None

Damage

Units

21350

SF

HA No

6

7

2016 - Fall: No Change

Material Description

Insulation Inside of

Blue/Brown Mix Carpet

Firedoors

Material

Quantity

Material

Units

Material Location

Material Not Present

Classrooms and Offices,

Change in Assessment Category

X NO

X NO

YES

8	Window Glazing	10000	LF	Throughout Facility		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Fall: N	lo Change											
Comments:					1							
2017 - Spring	g: No Change				Ī							
Comments:					-							
2018 - Fall: N	lo Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
9	Gasket Material			Material Not Present	71	Miscellaneous		7.			YES	X NO
	I	1	1	1	1	1	ı	1	I			

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

2016 - Fall	: No Change										
Comments	<u> </u>										
2017 - Fall	: No Change										
Comments	:										
	ing: No Change										
Comments	:										
2018 - Fall	: No Change										
Comments	:										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
			+			+	_	+	+	-	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

Yes

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

130

Material

Quantity

800

Material

Units

SF

LF

Material Location

Stage

Library

HA No

10

11

Material Description

Vinyl Baseboard Mastic

Drywall

Change in Assessment Category

X NO

X NO

YES

12	Vinyl Baseboard	130	LF	Library		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	<u> </u>				<del>-</del> -							
2017 - Fall: N	lo Change				_							
Comments:					1							
2017 - Spring	j: No Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
13	Transite Table Tops			Material Not Present		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

14	Coating on Bottoms of Sinks	6	SF	Rooms 102 & 104		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fa	all: No Change											
Commen												
2017 - Fa	all: No Change											
Commen	its:											
2017 - Sp	pring: No Change											
Commen	its:				_							
2018 - Fa	all: No Change											
Commen	its:											
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asses	essment Category
15	Duct Vibration Absorbers	40	LF	2nd Floor Fan Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
2017 - Fall: N	o Change											

Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

16	Window Caulk	2000	LF	Throughout Facility		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				]							
Comments:	<u> </u>											
2017 - Fall: N	No Change				-							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

TSI

Asbestos

Type

Material

Category

Friable

Damage

Туре

None

Yes

0

Damage

Quantity

Damage

Units

2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:		•	•	

32

SF

Office

Material

Quantity

Material

Units

Material Location

HA No

17

Material Description

Insulation Inside of Vault

Door

YES

X NO

18	Chalk Board and Bulletin Board Adhesive	2000	SF	Throughout Classrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:												
2017 - Fall: N	o Change				_							
Comments:					<u> </u>							
2017 - Spring	: No Change				_							
Comments:	•											
2018 - Fall: N	o Change											
Comments:	•											
					]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
19	Cloth Wiring Insulation on Unit Ventilators			Material Not Present		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Unit Ventilators

20	Cinderblock	40000	SF	Throughout Facility		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Fall: N	lo Change											
Comments:					1							
2017 - Spring	g: No Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
	1	1	†		†		1	†	†	1	İ	

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Material Location

Throughout Facility

HA No

21

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Cinderblock Mortar

Material

Quantity

Material

Units

SF

20000

YES

X NO

2016 - Fall: N	lo Change				7						
	o Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:	<u> </u>										
1					<u></u>						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
	2 2001/211011	Quantity	Units		Туре	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

Yes

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

1800

Material

Units

SF

SF

Offices

Material Quantity

28

Material Location

Incinerator Room

HA No

22

23

Material Description

Steel Door Insulation

12" x 12" White Floor Tile

Change in Assessment Category

X NO

X NO

YES

	***************************************										
2016 - Fall:	No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
	ng: No Change										
Comments:											
	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
-		_	<del> </del>	<b>\</b>	-	+	-			+	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Damage

Type

None

None

Damage

Quantity

0

Damage

Units

Material

Quantity

1800

Material

Units

SF

Material Location

Material Not Present

Offices

HA No

24

25

Material Description

Laminate Table Tops

Mastic

12" x 12" White Floor Tile

Change in Assessment Category

X NO

X NO

YES

26	Laminate Table Top Adhesive			Material Not Present		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	io change											
2017 - Fall: N	lo Change				-							
Comments:	io Chango				- -							
2017 - Spring	ı: No Change				_							
Comments:												
2018 - Fall: N	lo Change				_							
Comments:	-				1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
27	Drywall Joint Compound	200	SF	Stage		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

2016 - Fall: No Change

Material

Quantity

Material

Units

											· I
0040 5 11	N. O.				7						
	: No Change										
Comments	S:										
2017 - Fall	: No Change										
Comments	<b>:</b>										
2017 - Spr	ing: No Change										
Comments	<b>:</b>										
2018 - Fall	: No Change										
Comments	S:				1						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
	·	Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

600

Material

Quantity

200

Material

Units

LF

SF

Material Location

Principal's Office

Stage

HA No

28

29

Material Description

Drywall Joint Tape

Linoleum

Change in Assessment Category

X NO

X NO

YES

30	Linoleum Mastic	600	SF	Principal's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				]							
Comments:	<u> </u>											
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:					1							
2018 - Fall: I	No Change											
Comments:					<u> </u>							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

Damage

Quantity

0

None

Damage

Units

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

825

SF

Rm. 309

Material

Quantity

Material

Units

Material Location

HA No

31

Material Description

Carpet Mastic

YES

X NO

32	12" x 12" Blue VFT	3600	SF	Rms. 201/203, 307		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change				]						
Comments:											
2017 - Sprir	ng: No Change				-						
Comments:											
2017 - Fall:	No Change				-						
Comments:											
2018 - Fall:	No Change										
Comments:											

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12" x 12" Blue VFT Mastic	3600	SF	Rms. 201/203, 307		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA NO	Material Description	Quantity	Units	iviaterial Location	Type	Category	Filable	Type	Quantity	Units	Change in Asses	ssment Category
В	Mag Block Pipe Insulation	10	LF	Closet by Principal's Office		TSI	Yes	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2040 Falls No Channe	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Cementitious Joint Insulation -Fiberglass Lagging	6	JOINTS	2nd Floor Fan Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Jackie Robinson Elementary School
Date: 1/11/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 26061