Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

26091

Oracle Unit:

Building ID: Address: 431 North Troy Street Region: 02 Mail Room: Asbestos Surveyor: Robinson, Zurbanus X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/21/2018 Email Address: zrobinson8@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type YES 01 SF 2 X NO 9"x9" Brown VFT 2400 Miscellaneous No Auditorium Loc 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Morton School of Excellence

School:

Oracle Unit: 26091

6800

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	12"x12" Taupe VFT (ABATED 2008)			1st Flr Corr., Rm 103, 109, Main Off, Tchrs Lunchrm, 201-203, 205- 207, 211, 212, 303, 306, 307, 402 ABATED 2008							YES X NO
2016 - Fall: N Comments:	No Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 2

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
07	9"x9" Brown VFT Mastic	2400	SF	Auditorium		Miscellaneous	No	None	2		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change				-							
Comments:	<u> </u>											
2018 - Spring	g : No Change				-							
Comments:	<u> </u>											
2018 - Fall: N	lo Change				-							
Comments:	<u> </u>											
	ı			T		1		1	1	1		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	12"x12" Taupe VFT Mastic (ABATED 2008)			1st Flr Corr., Rm 103, 109, Main Off, Tchrs Lunchrm, 201-203, 211, 212, 303, 306, 307, 402 (ABATED 2008)		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

09	9"x9" Gray VFT (ABATED)			Lunchroom, Attendance Office, Room 106 - 1st Floor Storage ABATED		Miscellaneous					YES	X NO
2016 - Fa	II: No Change											
Comment												
2017 - Sp	ring: No Change											
Comment												
2017 - Fa	II: No Change				_							
Comment	S:											
2018 - Sp	ring : No Change											
Comment	s:											
2018 - Fa	II: No Change											
Comment	s:											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
10	9"x9" Gray VFT Mastic (ABATED)			Lunchroom, Attendance Office, Room 106 ABATED		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

2016 - Fall: No Change

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12"x12" Cream VFT (ABATED)			1st Flr Corr., Rm 103, 109, Main Off, Tchrs Lunchrm, 201-203, 205- 207, 211, 212, 303, 306, 307, 402ABATED							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 26091

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12"x12" Cream VFT Mastic (ABATED 2008)			1st Flr Corr., Rm 103, 109, Main Off, Tchrs Lunchrm, 201-203, 205- 207, 211, 212, 303, 306, 307, 402 ABATED 2008		Miscellaneous					YES X NO
2016 - Fall: Comments:	No Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

13	12"x12" Brown w/ Rust Streaks VFT (ABATED 2008)	Corridor Outside Auditorium, Room 304 ABATED 2008		Miscellaneous			YES	X NO
2016 - Fall: N	lo Change]					
Comments:								
2017 - Spring	g: No Change							
Comments:			_					
2017 - Fall: N	lo Change							
Comments:			_					
	g : No Change							
Comments:								
2018 - Fall: N	lo Change							
Comments:								
			 ⊒					

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"x12" Brown w/ Rust Streaks VFT Mastic (ABATED 2008)			Corridor Outside Auditorium, Room 304 ABATED 2008							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

15	12"x12" Sand VFT (ABATED 8/22/08)		Room 110, 2nd Floor Corridor, Room 305		Miscellaneous			YES	X NO
2016 - Fall: N	lo Change								
Comments:	to onange								
2017 Coming	v. No Change								
2017 - Spring	g: No Change								
Comments:									
2017 - Fall: N	lo Change								
Comments:									
2018 - Spring	g : No Change								
Comments:	<u> </u>								
2018 - Fall: N	lo Change								
Comments:	-								
		•		-					

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"x12" Sand VFT Mastic (ABATED 2008)			Room 110, 2nd Floor Corridor, Room 305 ABATED 2008		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
17	12"x12" Beige VFT (ABATED 2008)			Main Entrance, 1st Floor Corridor ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:					1							
2017 - Spring	: No Change				_							
Comments:					1							
2017 - Fall: N	lo Change				_							
Comments:												
2018 - Spring	: No Change				_							
Comments:					-							
2018 - Fall: N	lo Change				_							
Comments:					1							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12"x12" Beige VFT Mastic (ABATED 2008)			Main Entrance, 1st Floor Corridor ABATED 2008		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
19	9"x9" Dark Gray VFT (ABATED 2008)			2nd Floor Corridor, 4th Floor Corridor, Room 204		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	•											
2017 - Spring	g: No Change											
Comments:	•											
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:	_]							
2018 - Fall: N	lo Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	9"x9" Dark Gray VFT Mastic (ABATED 2008)			2nd & 4th Floor Corridors, Room 204 ABATED 2008		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:	21	9"x9" Light Green VFT (ABATED 2008)	2nd Floor Corridor ABATED 2008		Miscellaneous			YES	X NO
Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change	2016 Fall: N	o Chango		1					
2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change		o Change		4					
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:								
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change									
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Spring	: No Change							
2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change		<u>-</u>							
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change				1					
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Fall: N	o Change		1					
Comments: 2018 - Fall: No Change	Comments:								
Comments: 2018 - Fall: No Change									
Comments: 2018 - Fall: No Change	2018 - Spring	: No Change							
2018 - Fall: No Change									
				1					
	2018 - Fall: N	o Change							
				1					
				1					

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	9"x9" Light Green VFT Mastic (ABATED 2008)			2nd Floor Corridor ABATED 2008		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

23	9" x 9" Beige VFT (ABATED 2008)			Throughout (See Hatching Maps) ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall:	No Change			•							•	
Comments:												
2017 - Sprii	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprii	ng : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
2311111011101												
			<u></u>									
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

Damage

Type

Туре

Damage

Quantity

Quantity

Units

YES

X NO

Damage

Units

		2006	
2016 - Fall: No Change			
Comments:			
2017 - Spring: No Change			
Comments:			
2017 - Fall: No Change			
Comments:			
2018 - Spring : No Change			
Comments:			
2018 - Fall: No Change			
Comments:			_
	•	•	•

Quantity

Units

HA No

24

Material Description

9"x9" Beige VFT Mastic (ABATED 2008) Material

Quantity

Material

Units

Material Location

Throughout (See

Hatching Maps) ABATED

25	9"x9" Dark Green VFT (ABATED 2008)		Kitchen, Elevator ABATED 2008	Miscellaneous				YES	X NO
		I.			I	1	1		
2016 - Fall: N	o Change								
Comments:									
2017 - Spring	: No Change								
Comments:									
2017 - Fall: N	o Change								
Comments:	-								
2018 - Spring	: No Change								
Comments:									
2018 - Fall: N	o Change								
Comments:									

Type

Material

Category

Damage Quantity Damage

Units

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	9"x9" Dark Green VFT Mastic (ABATED 2008)			Kitchen, Elevator ABATED 2008		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Page 13

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
27	9"x 9" Moss Green VFT (ABATED 2008)			Rooms 101, 108 ABATED 2008		Miscellaneous					YES	X NO
0040 5 11 1	. 01	•	•						•			
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:	, J											
0040 5 " 1					4							
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	9"x9" Moss Green VFT Mastic (ABATED 2008)			Rooms 101, 108 ABATED 2008		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

29	Interior Window Caulk	250	EA	Interior Windows	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:	io Change									
Comments.										
2017 - Spring	: No Change									
Comments:	<u> </u>									
2017 - Fall: N	lo Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:										
2018 - Spring	ı : No Change									
Comments:										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12 x 12 inch Gray w/ White & Brown Streaks VFT (ABATED 2008)			Elevator ABATED 2008		Miscellaneous					YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

32 A	12 x 12 inch Gray w/ White & Brown VFT Mastic (ABATED 2008)		Elevator ABATED 2008		Miscellaneous			YES	X NO
2016 Fall N	o Changa	<u> </u>	·	1		•	•	•	
2016 - Fall: N	o Change			4					
Comments:									
2017 - Spring	: No Change								
Comments:	-								
				1					
2017 - Fall: N	o Change								
Comments:	•								
2018 - Spring	: No Change]					
Comments:	-			1					
				1					
2018 - Fall: N	o Change								
Comments:				1					
				_					

Type

Material

Category

Miscellaneous

Asbestos

Type

Material

Category

Friable

Friable

Damage

Туре

Damage

Type

Damage

Quantity

Damage

Quantity

Damage

Damage

Units

Units

	,			
2016 - Fall: N	lo Chango			
	io Change			
Comments:				
2017 - Fall: N	lo Change			
Comments:				
2017 - Spring	g: No Change			
Comments:				
2018 - Spring	g : No Change			
Comments:				
2018 - Fall: N	lo Change	•	•	
Comments:	·	•	•	
	•	•	•	

Material

Quantity

Material

Units

HA No

HA No

33

Material Description

Material Description

Carpet Mastic (ABATED

2008)

Material

Units

Material

Quantity

Material Location

Material Location

Rooms 102, 103, Main

Office ABATED 2008

Change in Assessment Category

Change in Assessment Category

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12 x 12 inch Brown w/Yellow Streaks VFT	80	SF	Gymnasium Office		Miscellaneous	No	None	0		YES X NO
204C Fall N	2016 Falls No Change										

2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:	
Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change	
2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2016 - Fall: No Change
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Spring: No Change
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Fall: No Change
Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Fall: No Change	2019 Caring : No Change
2018 - Fall: No Change	1 0 0
	Comments:
Comments:	2018 - Fall: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34 A	12 x 12 inch Brown w/ Yellow Streaks VFT Mastic	80	SF	Gymnasium Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
35	12 x 12 Burgundy Floor Tile	4000	SF	Throughout 2nd and 4th Floors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
0047 Caria es Na Changa	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35A	12 x 12 Burgundy Floor Tile Mastic	4000	SF	Throughout 2nd and 4th Floors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Units Units	Change in Asses	sment Category
36	12 x 12 Light Blue Floor Tile	4000	SF	Throughout 3rd Floor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:												
2017 - Spring	g: No Change											
Comments:												

2017 - Fall: No Change Comments:

2018 - Spring : No Change

Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36A	12 x 12 Light Blue Floor Tile Mastic	4000	SF	Throughout 3rd Floor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
37	12 x 12 Beige Floor Tile	31500	SF	Throughout 1st Floor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change	•						•				
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change				=							
Comments:	_											
2018 - Sprin	g : No Change											
Comments:	· ·											
2018 - Fall: I	No Change				_							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37A	12 x 12 Beige Floor Tile Mastic	31500	SF	Throughout 1st Floor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12 x 12 Blue Floor Tile	4500	SF	Lunchroom and Kitchen & Throughout 1st Floor		Miscellaneous	No	None	2		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	·
	·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38A	12 x 12 Blue Floor Tile Mastic	4500	SF	Lunchroom and Kitchen & Throughout 1st Floor		Miscellaneous	No	None	2		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Incinerator Insulation	50	SF	Engine Room		TSI	Yes	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Black Spray on Under Sink Coating	20	SF	Room #304 Art Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
41	Boiler Rope Gasket	40	LF	Boiler/Engine Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprii	ng: No Change											
Comments:												
2018 - Sprii	ng : No Change											
Comments:												
2018 - Fall: No Change					_							
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Vinyl Baseboard Mastic/Adhesive	4500	LF	Throughout Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

			1				1				
А	Mag Block Tank Insulation	300	SF	Boiler Room		TSI	Yes	None	0	YES	X NO
					1						
2016 - Fall: N	o Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:	•										
2018 - Spring	: No Change										
Comments:	•										
2018 - Fall: No Change											
Comments:											
					•						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	MJP E/F/V on Fiberglass Pipe Insulation	657	LF	Boiler Room & Above Suspended Ceiling Tiles Throughout 1st - 4th Floors		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	KILN	15	LF	Throughout 1st Floor & 1st Floor Storage Room		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Morton School of Excellence
Date: 12/21/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.