## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2018 - Fall

26141

**Oracle Unit:** 

Address: 6311 S. Calumet Region: 05 Mail Room: Asbestos Surveyor: Harris, Charles X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/9/2019 Email Address: cdharris18@cps.edu A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type 12x12 Ceiling Tile (small 1st, 2nd, and 3rd floor YES 01 SF X NO 1550 Miscellaneous Yes None 0 Washrooms 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

John Foster Dulles Elementary School

School:

Oracle Unit: 26141

6860

**Building ID:** 

2016 - Fall: No Change				7						
Comments:										
2017 - Fall: No Change				+						
Comments:										
2017 - Spring: No Change				-						
Comments:										
2018 - Fall: No Change				-						
Comments:										
				_						
HA No Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

Yes

Yes

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

38000

Material

Quantity

63400

Material

Units

SF

SF

Material Location

Throughout Building

Throughout Building

HA No

02

04

Material Description

12x12 Ceiling Tile (large

9x9 Light Brown Floor Tile

hole)

Change in Assessment Category

X NO

X NO

YES

05	Mastic	38000	SF	I nroughout Building		Miscellaneous	NO	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:					_							
	ng: No Change											
Comments:					1							
2018 - Fall:	No Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
	<u> </u>		1				1	1	1	1		

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

4340

Material

Quantity

38000

Material

Units

SF

LF

Material Location

Throughout Building

Througout Building

HA No

05

06

Material Description

Baseboard Mastic

9x9 Light Brown Floor Tile

Change in Assessment Category

X NO

X NO

YES

08	Baseboard	4340	LF	Throughout Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				]							
Comments:	to enange				]							
2017 - Fall: N	No Change											
Comments:					]							
	g: No Change											
Comments:					-							
2018 - Fall: N	No Change											
Comments:					-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
<del> </del>		<del> </del>			<b>†</b>	<del> </del>	<u> </u>			<del> </del>		

Type

Material

Category

Miscellaneous

Yes

None

0

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

10

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

12x12 Ceiling Tile (smooth)

Material

Quantity

950

SF

Kitchen

Material

Units

Change in Assessment Category

YES

X NO

2016 - Fall: N	No Change				$\neg$						
Comments:	No Change										
Comments.											
2017 - Fall: N	No Change										
Comments:											
2017 - Sprin	g: No Change										
Comments:											
2018 - Fall: N	No Change										
Comments:	<u> </u>										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

66000

HA No

11

12

Material Description

12x12 Ceiling Tile Mastic

(smooth)

Panelboard

Material

Quantity

950

Material

Units

SF

SF

Material Location

Throughout Building

Kitchen

Change in Assessment Category

X NO

X NO

YES

13	9X9 Brown Tri Color Floor Tile	16740	SF	Hallways		Miscellaneous	No	None	0	YES	X NO
204C Fall N	la Channa				Ī						
2016 - Fall: N	lo Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	ı: No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:	·	·									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	9x9 Brown Tri Color Floor Tile Mastic	16470	SF	Hallways		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
Commente.
2040 Fall No Observe
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

2016 - Fall: I	No Chango				7						
	No Change										
Comments:											
2017 - Fall: I	No Change				-						
	No Change										
Comments:											
2017 - Sprin	g: No Change										
Comments:											
2018 - Fall: I	No Change										
Comments:	-										
		·									
HA No	Material Description	Material	Material Units	Material Location	Asbestos	Material	Friable	Damage Type	Damage	Damage	Change in Assessment Category
1	1	Quantity	LUDIIIS		Type	Category	1	LVDE	Quantity	Units	1

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

400

HA No

15

16

Material Description

9x9 Cream Floor Tile

9x9 Cream Floor Tile

Material

Units

SF

SF

Material Quantity

400

Material Location

Clerical Office

Clerical Office

Change in Assessment Category

X NO

X NO

YES

2016 - Fall	No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
	ng: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

18	12x12 Brown Floor Tile Mastic	600	SF	202/Faculty Lounge
2016 - Fall: N	o Change			
Comments:	o Onange			
0047 5 11 11				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				

Material

Quantity

600

Material

Units

SF

Material Location

202/Faculty Lounge

HA No

17

Material Description

12x12 Brown Floor Tile

Page 8

Change in Assessment Category

X NO

X NO

YES

2016 - Fall:	No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
	ng: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

600

HA No

19

20

Material Description

12x12 Pink Floor Tile

12x12 Pink Floor Tile

Material

Units

SF

SF

Material

Quantity

600

Material Location

Room 208 and Room 214

Room 208 and Room 214

Change in Assessment Category

X NO

X NO

YES

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
21	12x12 Orange Floor Tile	1000	SF	Room 101, principal's office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Fall: N	o Change											
Comments:	<u> </u>											

Material

Friable

Damage

Damage

Asbestos

2017 - Spring: No Change Comments:

Material

Material Material Location

Material Description

2018 - Fall: No Change

Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12x12 Orange Floor Tile Mastic	1000	SF	Room 101		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Damage Change in Assessment Category

23	12x12 Tan Floor Tile	30	SF	101 Foyer	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:	io onango									
2017 - Fall: N	lo Change									
Comments:	go									
2017 - Spring	ı: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:	<u> </u>									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
24	12x12 Tan Floor Tile Mastic	30	SF	101 Foyer		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change	]										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

25	12x12 Light Bue Floor Tile	1950	SF	Kitchen/Faculty Dining/ Lunchroom	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:	-									
2018 - Fall: N	o Change									
Comments:										
			•							

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12x12 Light Blue Floor Tile Mastic	1950	SF	Kitchen/Faculty Dining/Lunch Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

2016 - Fall: I	No Change										
Comments:											
2017 - Fall: I	No Change										
Comments:											
2017 - Sprin	g: No Change										
Comments:											
2018 - Fall: I	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

HA No

27

28

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Vibration Dampener

Electrical Wire Jacket

Material

Quantity

20

Material

Units

SF

LF

100

Material Location

Fan Room

Stage

Change in Assessment Category

X NO

X NO

YES

2016 - Fall: N	No Change										
	10 Change										
Comments:											
2017 - Fall: N	No Change										
Comments:	10 Onango										
2017 - Spring	g: No Change										
Comments:											
2018 - Fall: N	No Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
1		Quantity	Units		Type	Category	1	Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

HA No

29

30

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

12x12 blue floor tile

Fire Door

Material

Quantity

2

Material

Units

Each

SF

800

Material Location

Clerical Office, rm 103

Boiler Room

Change in Assessment Category

X NO

X NO

YES

30A	12x12 blue floor tile mastic	800	SF	clerical office, rm 103	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										
L										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12x12 beige floor tile	3500	SF	rooms 213, 211, 312, 217 and 105		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

32	12x12 beige mastic	3500	SF	rooms 213, 211, 312, 217 and 105	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

33 Spray-On Ceiling Insulation 600 SF Boiler Room Surface No None 0 TYES X NO	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	33	Spray-On Ceiling Insulation	600	SF	Boiler Room		Surface	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

Α	fittings fiberglass	60	LF	Fan Room	TSI	Yes	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:										

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
С	Fittings on Paperwrap	10	LF	Fan Room, 210A, 2nd fl. Janitors closet		TSI	Yes	None	0		YES	X NO
2016 - Fall: No Change												
Comments:												
	2017 - Spring: No Change											

Comments:

2017 - Spring: No Change

2017 - Fall: No Change

Comments:

2018 - Fall: No Change

Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

E	Paperwrap Pipe Insulation	130	LF	Fan Room, 210A, janitors closet 1st and 2nd floor		TSI	Yes	None	0	YES	X NO
2016 - Fall: N	o Change										
Comments:	_										
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2018 - Fall: N	Ţ										
Comments:Charles Harris											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Magblock Pipe Insulation	40	LF	Fan Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:Charles Harris

Material

Quantity

Material

Units

HA No

Material Description

G	Fittings on Magblock	8	LF	Fan Room		TSI	Yes	None	0	YES	X NO
					1						
2016 - Fall: N	lo Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	ı: No Change										
Comments:											
		•									
2018 - Fall: N	lo Change	•		_							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	ACM Pipe Insulation w/ fittings (Abated)	0		Crawlspace		TSI		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:Chaarles Harris

Material

Quantity

Material

Units

Material Location

HA No

Comments: Charles Harris

Material Description

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

_	John Foster Dulles Elementary School
Date: _	1/16/2019
the Asbesto	otify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of os Management Plan is available at each school during school hours by appointment. or review the Asbestos Management Plan must be made at least 24 hours in advance.
The last ins	e be advised that CPS conducts asbestos inspections of all Schools every three years. spection was completed in 2016. urveillances are conducted every six months.
CHECK ON	<u>E</u>
A co	py of this notice was sent home in each child's backpack.
X A co	py of this notice was printed in the school's newsletter and sent home with each child
A co	py of this notice was printed in the school's calendar and sent home with each child
Othe	er.
X A co	py of this notice was printed in the school's newsletter and sent home with each child

VFT = Vinyl Floor Tile
Oracle Unit: 26141

SCHOOL'S ASBESTOS MANAGEMENT PLAN.