

Chicago Public Schools

6 Month Asbestos Surveillance

2018 - Fall

School: Ronald E McNair Elementary School
Address: 4840 West Walton

Oracle Unit: 26301
Region: 02

Building ID: 7040
Mail Room: 36

CHECK HERE IF NO CHANGE TO ASBESTOS

Asbestos Surveyor: Pope, Eric
Survey Date: 1/9/2019
Email Address: _____

A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via:
 Each child's backpack
 Notice printed in school's newsletter
 Notice printed in school's calendar
 Other

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 01 | Hard Coat Plaster | | | Throughout 1897 Bldg | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|-------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments: building demolished |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 02 | Canvas | | | Throughout 1897 Bldg | | | | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 03 | Hard Coat Plaster | | | Throughout Annex | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 04 | 1'x1' White Ceiling Tile | | | Throughout 1897 Bldg | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 06 | 12"x12" Gray VFT | | | Main Office (14) - 1897 Bldg | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 08 | Brown Linoleum | | | Rooms 203, 204, 208 - Annex | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10 | 12"x12" Gray VFT Mastic | | | Main Office - 1897 Bldg | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11 | Brown Linoleum Mastic | | | Rooms 203, 204, 208 - Annex | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 12 | 9"x9" Red w/ White VFT | | | Room 24, 26 - 1897 Bldg | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 13 | 9"x9" Red w/ White VFT Mastic | | | Room 24, 26 - 1897 Bldg | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 14 | 9"x9" Gray w/ Yellow VFT | | | Room 13, 25 - 1897 Bldg | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 15 | 9"x9" Gray w/ Yellow VFT Mastic | | | Room 13, 25 - 1897 Bldg | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 16 | 12"x12" Tan VFT | | | 1st Floor Teachers Lounge & Toilet - 1897 Bldg | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 17 | 12"x12" Tan VFT Mastic | | | 1st Floor Teachers Lounge & Toilet - 1897 Bldg | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 20 | 9"x9" Marble Green VFT | | | Room 13, 25 - 1897 Bldg | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 21 | 9"x9" Marble Green VFT Mastic | | | Room 13, 25 - 1897 Bldg | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 24 | 9"x9" Brown w/ Red & White VFT | | | Room 15 - 1897 Bldg | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 25 | 9"x9" Brown w/ Red & White VFT Mastic | | | Room 15 - 1897 Bldg | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 26 | 9"x9" Green VFT | 1000 | SF | 1st, 2nd, & 3rd Floor Corridors, & West Stairwell - 1897 Bldg | | Miscellaneous | No | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 27 | 9"x9" Green VFT Mastic | 1000 | SF | 1st, 2nd, & 3rd Floor Corridors, & West Stairwell - 1897 Bldg | | Miscellaneous | No | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 28 | 12"x12" White VFT | | | 1st, 2nd, & 3rd Floor Corridors - 1897 Bldg | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 29 | 12"x12' White VFT Mastic | 1200 | SF | 1st, 2nd, & 3rd Floor Corridors - 1897 Bldg | | Miscellaneous | No | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 30 | 12"x12" Black VFT | 200 | SF | 1st, 2nd, & 3rd Floor Corridors - 1897 Bldg | | Miscellaneous | No | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 31 | 12"x12" Black VFT Mastic | 200 | SF | 1st, 2nd, & 3rd Floor Corridors - 1897 Bldg | | Miscellaneous | No | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 36 | 9"x9" Brown w/ Green & Cream VFT | | | Room 15 - 1897 Bldg | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 37 | 9"x9" Brown w/ Green & Cream VFT Mastic | | | Room 15 - 1897 Bldg | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 38 | 9"x9" Cream w/ Brown & Green VFT | | | Room 15 - 1897 Bldg | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 39 | 9"x9" Cream w/ Brown & Green VFT Mastic | | | Room 15 - 1897 Bldg | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 42 | Black Vinyl Baseboard | | | Throughout 1897 Bldg | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 43 | Black Vinyl Baseboard Mastic | | | Throughout 1897 Bldg | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 44 | Brown Vinyl Baseboard | | | Throughout 1897 Bldg | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 45 | Brown Vinyl Baseboard Mastic | | | Throughout 1897 Bldg | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 46 | 9"x9" Brown VFT | 3000 | SF | Rooms 202, 203, 204, 206, 207, & 208 - Annex | | Miscellaneous | No | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 47 | 9"x9" Brown VFT Mastic | 3000 | SF | Rooms 202, 203, 204, 206, 207 & 208 - Annex | | Miscellaneous | No | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 48 | Black Tile Border | 500 | SF | Rooms 202, 203, 204, 206, 207 & 208 - Annex | | Miscellaneous | No | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 49 | Black Tile Border Mastic | 500 | SF | Rooms 202, 203, 204, 206, 207, & 208 - Annex | | Miscellaneous | No | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 50 | Green Wall Covering | | | 206, 207, & 208 - Annex | | | | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 51 | Brown Wall Covering | | | 202, 203, & 204 - Annex | | | | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 52 | 1'x1' White Ceiling Tile | | | Corridor, Rooms 202-204, 203, 207 & 206-208 - Annex | | | | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 53 | 9"x9" Red VFT | 1500 | SF | Cafeteria - Annex | | Miscellaneous | No | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 54 | 9"x9" Red VFT Mastic | 1500 | SF | Cafeteria - Annex | | Miscellaneous | No | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 55 | 9"x9" Brown VFT | 1600 | SF | Cafeteria & Basement Stairway - Annex | | Miscellaneous | No | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|---------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 56 | 9"x9" Brown VFT Mastic | 1600 | SF | Cafeteria & Basement Stairway - Annex | | Miscellaneous | No | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 57 | 12"x12" White w/ Brown Streaks VFT | | | Principal's Office, 2nd & 3rd Floor Janitor's Closet - 1897 Bldg | | | | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 58 | 12"x12" White w/ Brown Streaks VFT Mastic | 300 | SF | Principal's Office, 2nd & 3rd Floor Janitor's Closet - 1897 Bldg | | Miscellaneous | No | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 63 | 12"X12" White w/ Blue Specks VFT | 0 | | Corridors & Stairwells - 1897 | | | | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 64 | 12"X12" White w/ Blue Specks VFT Mastic | 0 | | Corridors & Stairwells - 1897 | | | | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 65 | 12"x12" Brown VFT | 0 | | Stair Treads and Classrooms Throughout 1897 | | | | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

| |
|--|
| 2017 - Spring: Other Comments:building demolished |
| 2017 - Fall: No Change Comments: |
| 2018 - Fall: No Change Comments: |
| 2018 - Spring : No Change Comments: |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 66 | 12"x12" Brown VFT Mastic | 0 | | Stair Treads and Classrooms Throughout 1897 | | | | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

| |
|--|
| 2017 - Spring: Other Comments:building demolished |
| 2017 - Fall: No Change Comments: |
| 2018 - Fall: No Change Comments: |
| 2018 - Spring : No Change Comments: |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 67 | 12"x12" Brown VFT | 0 | | Room 203, 202, 204 - Annex | | | | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 68 | 12"x12" Brown VFT Mastic | 0 | | Room 203, 202, 204 - Annex | | | | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| A | Cardboard Pipe Insulation | 250 | LF | Boiler Room & Basement Boys & Girls Toilets - 1897 Bldg | | TSI | Yes | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| B | MJP E/F/V on Cardboard Pipe Insulation | 52 | LF | Boiler Room & Basement Boys & Girls Toilets - 1897 Bldg | | TSI | Yes | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| C | Aircell Pipe Insulation | 785 | LF | Basement Boys Girls Toilets - Annex | | TSI | Yes | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------------|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| D | MJP E/F/V on Aircell Pipe Insulation | 100 | LF | Basement Boys Girls Toilets - Annex | | TSI | Yes | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| E | Wall Caulk | | | Throughout 1897 Bldg | | | | | | | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

| |
|------------------------------|
| 2017 - Spring: Other |
| Comments:building demolished |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.



Robert Christlieb

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Ronald E McNair Elementary School
Date: 1/11/2019

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
-

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.