Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

26321

Oracle Unit:

Address: 6656 S. Normal Region: 05 Mail Room: Asbestos Surveyor: Davis, Shaler X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/10/2019 Email Address: shalershaler@yahoo. com A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Each child's backpack Notice printed in school's newsletter Notice printed in school's calendar Other HA No **Material Description** Material Material Material Location Asbestos Material Friable Damage Damage Damage Change in Assessment Category Quantity Units Type Category Type Quantity Units Rooms 210-214, 2nd X NO YES floor Server Room, 2nd Floor Library, Toilets, 01 SF Hard coat plaster 9100 Surface Yes None 0 corridors, stairwells, storage rooms and boiler 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Benjamin E Mays Elementary Academy

School:

Oracle Unit: 26321

6880

Building ID:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	9x9 beige w/tan specks flr tile	11500	SF	rooms 112, 212, 213, 214, 215, 310-315, women's lounge, 1st flr offices,		Miscellaneous	No	Loc	10		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06A	9x9 tan/beige streak vft	1100	SF	1st, 2nd, 3rd flr corridors east wing		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

	· ·	Quantity	Units		Туре	Category		Туре	Quantity	Units		0 ,
06B	9x9 It beige tan specks vft	1100	SF	1st, 2nd, 3rd flr corridor north wing		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:	J											
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												

Material

Damage

Friable

Damage

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06C	9x9 Gray/white vft	200	SF	Storage Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Material Material Location

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
06D	9x 9 gray with black specks			gym		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					I							
			1		1		1	1				

Material

Friable

Damage

Damage

Damage

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	mastic under 9x9 beige/tan speckled vft	8500	SF	rooms 112, 212, 213, 214, 215, 312, 314, 315, women's lounge, 1st flr offices,		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Type	Damage Quantity	Units	Change in Asses	sment Category
08A	Mastic under 9x9 tan/beige streaked vft	1100	SF	1st, 2nd, fl north corridors wing		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change											
Comments	S:											
2017 - Fall	: No Change											
Comments	S:											
2017 - Spr	ing: No Change											

Comments:

2018 - Spring : No Change Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08B	mastic under 9x9 beige/tan streaks	1100	SF	1st 2nd , 3rd flr corridors north wing		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
08C	Mastic 9x9 black/white vft			gym		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change				_							
Comments:												
2018 - Fall: N	lo Change				_							
Comments:					-							
2018 - Spring	g : No Change				=							
Comments:												
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
09	Carpet mastic	5216	SF	rooms 200, 201, 202, 216		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
10	12x12 green vft	2500	SF	1st, 2nd, 3rd flr corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	No Change											
Comments:					-							
2017 - Spring	g: No Change											
Comments:					-							
2018 - Spring	g : No Change				<u> </u>							
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					_							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10A	12x12 white vft	8000	SF	rm 107, 106, 108, 105, 109, 104, 103, 102, 101, 203- 209, 303- 309		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Mastic for green 12x12 vft	2500	SF	1st, 2nd and 3rd flr corridors		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change Comments:											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11A	Mastic for white 12x12 vft	8000	SF	rms 107, 106, 108, 105, 109, 104, 103, 102, 101, 203- 209, 303- 309		Miscellaneous	No	None	0		YES X NO

016 - Fall: No Change	
Comments:	
017 - Spring: No Change	
Comments:	
017 - Fall: No Change	
Comments:	
018 - Fall: No Change	
Comments:	
018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
12	black vinyl mop board	22	LF	1st flr office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	l: No Change											
Comments	S:											
2017 - Spr	ing: No Change											
Comments	S:											
2017 - Fall	l: No Change											
Comments	S:											
2018 - Fall	l: No Change											
Comments	S:											
2018 - Spr	ing : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
13	Black vinyl mop board	22	SF	1st flr office		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12x12 white floor tile	2747	SF	2nd Floor Janitor's Closet, 2nd Floor New Staff Restroom, Gym		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change					•	•	•	•	•	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	fiberglass joint compound	530	SF	mech, pipe chases		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
AA	12" X 12" White Ceiling Tile	1050	SF	Room 201, 202, 203, 310, 311, 312, 313, 314, 315, and Lunchroom		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
AA-1	12" X 12" White Ceiling Tile Glue	1050	SF	Room 201, 202, 203, 310, 311, 312, 314, 315, and Lunchroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	sment Category
AB	12" X 12" Floor Tile	1500	SF	Lunchroom		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change												
Comments													
2017 - Spr	ing: No Change												
Comments	s:												
2017 - Fall	: No Change												
Comments	S:												
2018 - Fall	: No Change												
Comments	S:												
2018 - Spr	ing : No Change												
Comments	S:	•	•	•									

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
AB-1	12" X 12" Floor Tile Mastic	1500	SF	Lunchroom		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment (Category
AC	Troweled on Ceiling	2600	SF	Rooms 203-209		Miscellaneous	No	None	0		YES	X	NO
2016 - Fall: No Change													
Comments:]								
2017 - Fall: N	2017 - Fall: No Change												
Comments:													
2017 - Spring	g: No Change				-								
Comments:													
2018 - Spring : No Change													
Comments:]								
2018 - Fall: N	lo Change				-								
Comments:													

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	Mag block pipe wrap	60	LF	mechanics room/boiler room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

Page 13

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Fiberglass pipe wrap	3400	SF	mechanics room/boiler room		TSI	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Mag block pipe insulation	680	LF	Boiler room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Benjamin E Mays Elementary Academy
Date: 1/10/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.