Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

26521

Oracle Unit:

Building ID: 7760

Address: 7424 S. Morgan Region: 05 Mail Room: Asbestos Surveyor: Walker, Esther X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/28/2018 Email Address: ewalker25@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type First Floor Classrooms YES X NO (with the exception of the 001-A White Finish Coat Plaster 1200 SF Kindergarten Surface Yes None 0 Classrooms) and Washrooms 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring: No Change Comments:

Amos Alonzo Stagg Elementary School

School:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
001-B	Hard Coat Plaster (White Finish Coat)	12000	SF	Second Floor Classrooms, Washrooms and First Floor Fan Room		Surface	Yes	None	0		YES	X NO
2016 - Fall: N	No Change	•]	•		•	•	•	•	
Comments:					1							
2017 - Sprin	g: No Change											
Comments:					=							
2017 - Fall: I	No Change											
Comments:					-							
2018 - Sprin	g · No Change				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
001-C	Plaster	500	SF	Second Floor Fan Rooms		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

Comments:

2018 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
001-D	White Finish Coat Plaster	12000	SF	Third Floor Classrooms and Washrooms		Surface	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2019 Falls No Change	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
001-E	Plaster	500	SF	First Floor Fan Room, 2nd floor, and 3rd floor		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
002	Cementitious Sprayed On Surfacing Material - On Structural Beems	21000	SF	Above Third Floor Ceiling		Surface	Yes	Unknown	0		YES	X NO
2016 - Fall: N	lo Change	•	•	•]		•	•		•		
Comments:					-							
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change				-							
Comments:												
2018 - Spring	g : No Change				=							
Comments:	-											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
003	fireproofing	25000	SF	Structural Beams		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
004	Acoustical Plaster	17000	SF	Corridors, Lunchroom, Rooms 106 and 108		Surface	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	-											
2017 - Spring	j: No Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:					_							
2018 - Spring	ı : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
005A	9x9 offwhite flr tile	60	SF	Engineer's office 205		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
005B	9x9 green flr tile	120	SF	Kitchen Storeroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	<u> </u>											
2017 - Fall: N	lo Change				1							
Comments:	J											
2017 - Spring	g: No Change				1							
Comments:	,											
2018 - Spring	g : No Change				1							
Comments:												
2018 - Fall: N	lo Change				-							
Comments:	go				Ī							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
005C	9x9 Tan Floor Tile	28500	SF	1st, 2nd, 3rd Floor Clorridors and Classrooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
005D	9x9 brown flr tile	4500	SF	1st,2nd and 3rd flr corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
006A	12"x12" Olive Green Floor Tile	100	SF	Classrooms, corridor, custodian closets		Miscellaneous	No	Loc	15		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
006B	12x12 brown speckled flr tile			Lunchroom		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:					_							
2017 - Fall: N	lo Change]							
Comments:					1							
	: No Change											
Comments:					1							
2018 - Fall: N	lo Change											
Comments:					-							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
007	Vinyl Baseboard	500	LF	Throughout school		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 8

		Quantity	Units		Туре	Category	Type	Quantity	Units		
008	Vinyl Baseboard Mastic			Throughout classrooms		Miscellaneous				YES	X NO
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											
					J						

Material

Damage

Friable

Damage

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
009	Firedoors	5	EA	Boiler room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material Location

		Quantity	Units		Туре	Category	Type	Quantity	Units		
010	Incinerator Door- Removed			Boiler Room		Miscellaneous				YES	X NO
2016 - Fall: N	lo Change				1						
Comments:	J-										
2017 - Spring	g: No Change				_						
Comments:					_						
2017 - Fall: N	lo Change										
Comments:											
	g : No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:					-						
					J						
	11.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1							1		O1 1 4	

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
011	Incinerator fire brick			Boiler room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
012A	9x9 brown flr tile mastic	4500	SF	Throughout school corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	-											
2017 - Spring	g: No Change											
Comments:					_							
2017 - Fall: N	No Change											
Comments:					_							
2018 - Spring	g : No Change											
Comments:		·	·									

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
012B	9"x9" Tan Floor Tile Mastic	28500	SF	Corridors and Classrooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
012C	9x9 tan flr tile mastic	60	SF	Engineers office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2018 - Sprir	ng : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	-											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
012D	9x9 green flr tile mastic	30	SF	Engineer bathroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
013	9"x9" Gray Floor Tile (as Patches)			Gym/Stage Access		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				7							
Comments:												
2017 - Spring	g: No Change				_							
Comments:	-											
2017 - Fall: N	No Change				-							
Comments:												
2018 - Spring	g : No Change				-							
Comments:	-											
2018 - Fall: N	No Change				=							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
013A	12"x12" Olive Green Floor Tile Mastic	100	SF	Custodian closets		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
013B	12x12 brown speckled flr tile mastic			Lunchroom		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>											
2017 - Fall: N	lo Change]							
Comments:					_							
2017 - Spring	j: No Change]							
Comments:					1							
2018 - Fall: N	lo Change											
Comments:					_							
2018 - Spring	: No Change]							
Comments:					-							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
014	interior window glazing	7500	LF	Throughout school		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
Brown coat plaster, under acoustical	17000	SF	Throughout corridors and gym		Surface	Yes	None	0		YES	X NO
No Change]							
g: No Change											
No Change											
•											
	Brown coat plaster, under	Brown coat plaster, under acoustical 17000 No Change g: No Change	Brown coat plaster, under acoustical 17000 SF No Change g: No Change	Brown coat plaster, under acoustical 17000 SF Throughout corridors and gym No Change g: No Change	Brown coat plaster, under acoustical 17000 SF Throughout corridors and gym No Change g: No Change	Brown coat plaster, under acoustical 17000 SF Throughout corridors and gym Surface No Change G: No Change	Brown coat plaster, under acoustical 17000 SF Throughout corridors and gym Surface Yes No Change g: No Change	Brown coat plaster, under acoustical 17000 SF Throughout corridors and gym Surface Yes None No Change g: No Change	Brown coat plaster, under acoustical 17000 SF Throughout corridors and gym Surface Yes None 0 No Change g: No Change	Brown coat plaster, under acoustical 17000 SF Throughout corridors and gym Surface Yes None 0 No Change g: No Change	Brown coat plaster, under acoustical 17000 SF Throughout corridors and gym Surface Yes None 0 Type Quantity Units Surface Yes None 0 Type Quantity Units Surface Yes None 0 Type Quantity Units Yes None 0 Type Quantity Units

LIA NI	Material Description	Matarial	Matarial	Material Leasting	Ashastas	Matarial	Twiste	Damana	Damana	Damassa	Characia Assessment Catagoni
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
016	Plaster	2000	SF	Boiler room		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Spring : No Change

2018 - Fall: No Change

Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
017-A	Brown Coat Plaster	12000	SF	First Floor Classrooms (with the exception of the Kindergarten Classrooms) and Washrooms		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
017-B	Brown Coat Plaster	12000	SF	Second Floor Classrooms and Washrooms		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

		Quantity	Units		Туре	Category		Туре	Quantity	Units	3	,
017-C	Brown Coat Plaster	12000	SF	Third Floor Classrooms and Washrooms		Surface	Yes	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	J											
2017 - Fall: N	No Change											
Comments:	J											
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:	-											
2018 - Spring	g : No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
61	12' X 12' White Floor Tile	3410	SF	Rooms 304, 306, 307, 311, 205, 206, 209, 211, 214, 105, 106, 108, 112,		Miscellaneous	No	None	0		YES	X NO

Material

Friable

Damage

Damage

Damage

Change in Assessment Category

			113	
2016 - Fall: No	o Change			
Comments:				
				,
2017 - Spring:	No Change			
Comments:				
2017 - Fall: No	o Change			
Comments:				
2018 - Spring	: No Change			
Comments:	-			
2018 - Fall: No	o Change			
Comments:		·		· <u> </u>

HA No

Material Description

Material

Material

Material Location

Page 17

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61A	12" X 12" White Floor Tile Mastic	3410	SF	Room 304, 306, 307, 311, 205, 206, 209, 211, 214, 105, 106, 108, 112, 113		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	12" X 12" Yellow Floor Tile	2910	SF	Room 304, 306, 307, 311, 206, 205, 209, 211, 214, 105, 106, 108, 112, 113		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62A	12' X 12' Yellow Floor Tile Mastic	2910	SF	Rooms 304, 306, 307, 311, 206, 205, 209, 211, 214, 105, 106, 108, 112, 113		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	12" X 12" Blue Floor Tile	2910	SF	Room 304, 306, 307, 311, 205, 206, 209, 211, 214, 105, 106, 108, 112, 1st, 2nd, and 3rd floor corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 26521

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63A	12' X 12' Blue Floor Tile Mastic	2410	SF	Room 304, 306, 307, 311, 205, 206, 209, 211, 214, 105, 106, 108, 112, 1st, 2nd, and 3rd floor corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	12" x 12" Off-white w/ Gray Streaks Floor Tile	270	SF	Gym/Stage Access		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

	Quantity	Units		Туре	Category		Туре	Quantity	Units	
Mastic Assoc 12" Off-white Streaks Floor	,	SF	Gym/Stage Access		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	12" x 12" White w/ Gray Streaks Floor Tile	2700	SF	Lunchroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 22

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
67	Mastic Associated w/ 12" x 12" White w/ Gray Streaks Floor Tile	2700	SF	Lunchroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change			<u> </u>								
Comments:												
2017 - Sprin	g: No Change				_							
Comments:	3											
2017 - Fall: I	No Change											
Comments:	Ü											
2018 - Sprin	g : No Change											
Comments:	<u> </u>											
2018 - Fall: I	No Change											
Comments:	J											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68	9" x 9" Brown Floor Tile	270	SF	Kitchen Storage		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	Mastic Associated w/ 9" x 9" Brown Floor Tile	270	SF	Kitchen Storage		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change	
Comments:	
Comments.	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Α	Hard elbows	550	LF	Fan Rooms and Above Ceilings		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
В	Tank Insulation (Abated)			Boiler Room		TSI					YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	: No Change				_							
Comments:]							
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	ı : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Boiler Insulation (Abated)			Boiler room		TSI					YES X NO
0040 = 11 1					1						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
D	Boiler Gasket (Removed)			Boiler Room		TSI					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	•											
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	<u> </u>											
2018 - Spring	ı : No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	Blue Carpet Mastic- Abated			Room 201 (over 9"x9" Floor Tile)		Surface					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 26

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Cementitious Pipe Joint Fitting Insulation -Abated			Water Inlet Line		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 26521

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

	Alonzo Stagg Elementary School
Date: 12/28/20	18
the Asbestos Mana	u in accordance with Illinois and Federal Asbestos Regulations, that a copy of agement Plan is available at each school during school hours by appointment. v the Asbestos Management Plan must be made at least 24 hours in advance.
The last inspection	vised that CPS conducts asbestos inspections of all Schools every three years. In was completed in 2016. Indices are conducted every six months.
CHECK ONE	
A copy of thi	is notice was sent home in each child's backpack.
A copy of thi	is notice was printed in the school's newsletter and sent home with each child
A copy of thi	is notice was printed in the school's calendar and sent home with each child
Other.	
	HIS NOTICE MUST BE PLACED IN THE
SCHOOLS	ASBESTOS MANAGEMENT PLAN.