Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

26701

Oracle Unit:

Building ID: 6201 S. FAIRFIELD Address: Region: 05 Mail Room: Asbestos Surveyor: Hughes, Daniel X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/28/2018 Email Address: dhughes36@cps.edu A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Type Quantity Basement, 1st and 2nd YES 01 ΙF X NO Pipe covering 1700 TSI Yes Dist 40 floor classrooms 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Fairfield Elementary Academy

School:

Oracle Unit: 26701

4660

	02	Pipe fittings	275	LF	Basement, 1st and 2nd floor classrooms		TSI	Yes	None	0		YES	X NO
	2016 - Fall: N	o Change]							
	Comments:												
	2017 - Fall: N	o Change											
	Comments:					 							
	2017 - Spring	: No Change											
	Comments:					-							
	2018 - Fall: N	o Change											
	Comments:					-							
ļ						J							
	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
	03	Floor tile			Basement		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material

Quantity

Material

Units

Material Location

04	Corrugated pipe coverings	100	LF	Basement storage room	TSI	Yes	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:	•									
2017 - Fall: N	lo Change									
Comments:										
	g: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
05	Pipe fittings on corrugated pipe coverings	20	LF	Basement storage room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
					i							

2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change

Material

Quantity

Material

Units

HA No

Material Description

06	12x12 maroon/tan floor tile	8920	SF	3rd Floor Teachers Lounge		Miscellaneous	No	None	0		YES	X NO
204C Fall N	la Change		<u> </u>		1							
2016 - Fall: N	io Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	-											
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	-											
			•		-							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

Damage

Quantity

Damage

Units

	mastic		Lounge	
0010 = 11				1
2016 - Fall:	No Change			
Comments:				
2017 - Fall:	No Change			
Comments:	-			
2017 - Sprir	ng: No Change			
Comments:				
2018 - Fall:	No Change			
Comments:				

8920

Material

Quantity

Material

Units

SF

Material Location

Basement, Corridors and

Basement, Corridors and

3rd Floor Teachers

HA No

06A

Material Description

12x12 marron/tan floor tile

Change in Assessment Category

X NO

07	12x12 pink/white floor tile	700	SF	kitchen/corridor		Miscellaneous	NO	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	to onlange											
2017 - Spring	g: No Change				-							
Comments:	g. No Change				-							
2017 - Fall: N	lo Change				<u> </u>							
Comments:	<u> </u>				1							
2018 - Fall: N	lo Change				_							
Comments:												
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

Type

None

Damage

Quantity

Quantity

0

0

Damage

Units

Units

	madio		
2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			
		•	

Quantity

700

Units

SF

Material

Units

SF

Material

Quantity

700

Material Location

basemen kitchen/corridor

basemen,

HA No

07

07A

Material Description

12x12 pink/white floor tile

12x12 pink/whit floor tile

Change in Assessment Category

X NO

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
08	Corrugated pipe covering	200	LF	Boiler room		TSI	Yes	Dist	10		YES	X NO
2016 - Fall	I: No Change											
Comments	S:				_							
2017 - Spr	ring: No Change											
Comments	S:											
2017 - Fall	I: No Change											
Comments	3:											
2018 - Fall	I: No Change				-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08A	Pipe fittings on corrugated pipe covering	30	LF	Boiler room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

08B	Boiler breeching insulation	400	SF	Boiler room		TSI	Yes	None	0	YES	X NO
2016 - Fall: N	o Change				Ì						
Comments:	go										
2017 - Spring	: No Change										
Comments:	J										
2017 - Fall: N	o Change										
Comments:	Ţ.										
2018 - Fall: N	o Change										
Comments:	Ü										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
09	9x9 brown/beige floor tile	225	SF	2nd floor corridor Southwest end		Miscellaneous	No	Loc	10		YES	X NO
2016 - Fall: No	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

2016 - Fall:	No Change										
Comments:											
2017 - Fall:	No Change										
Comments:	1										
2017 - Spri	ng: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
					<u> </u>						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
	·	Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

HA No

09A

10

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material Description

9x9 brown/beige floor tile

9x9 brown floor tile

mastic

Material

Quantity

225

5445

SF

Material

Units

SF

Material Location

2nd floor corridor

Basement - Engineer's

office, corridors

North/South

Southwest end

Change in Assessment Category

X NO

X NO

YES

10A	9x9 brown floor tile mastic	5445	SF	office, corridors North/South		Miscellaneous	No	None	0		YES	X NO
0040 Fall	Na Ohanas	•		•	_ _							
	No Change											
Comments:	• •											
2017 - Fall:	No Change											
Comments												
2017 - Spri	ng: No Change											
Comments	:											
2018 - Fall:	No Change											
Comments												
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Type

Material

Category

Category

Miscellaneous

Friable

No

Damage

Туре

Type

None

Damage

Quantity

0

Damage

Units

			3 -
2016 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2018 - Fall: N	o Change		
Comments:		 	

3600

SF

HA No

11

Material Description

12x12 black floor tile

Material

Quantity

Material

Units

Material Location

Basement - Engineer's

Bathrooms - boys and

Change in Assessment Category

X NO

2016 - Fall: I	No Change										
	No Change										
Comments:											
2017 - Fall: I	No Change										
	No Change										
Comments:											
2217 2											
2017 - Sprin	g: No Change										
Comments:											
2018 - Fall: I	No Change										
Comments:	<u> </u>										
	Taranta and		T. B. B. C. C. L.			1	Levis	T 5	T 5	1.5	
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category	1	Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

1600

HA No

11A

12

2016 - Fall: No Change

Material Description

12x12 white floor tile

12x12 black floor tile mastic

Material

Units

SF

SF

Material

Quantity

3600

Material Location

Bathrooms - boys and

basement boy's bath

Change in Assessment Category

X NO

X NO

YES

2016 - Fall: I	No Change										
Comments:											
2017 - Fall: I	No Change										
Comments:					_						
	g: No Change										
Comments:											
2018 - Fall: I	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

1365

Material

Units

SF

SF

Material

Quantity

Material Location

basement boy's bath

1st floor main office,

corridor

HA No

12A

13

Material Description

12x12 grey floor tile

12x12 white floor tile mastic 1600

Change in Assessment Category

X NO

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
13A	12x12 grey floor tile mastic	1365	SF	1st floor main office, corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments	:											
2017 - Fall:	: No Change											
Comments	:											
2017 - Spri	ng: No Change											
Comments	:											
2018 - Fall	· No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	9x9 tan floor tile	745	SF	Room 201 (Teacher's Lounge), Room 300		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	·
<u> </u>	

Comments:

Page 12

14A	9x9 tan floor tile mastic	745	SF	Room 201 (Teacher's Lounge), Room 300		Miscellaneous	No	None	0	YES	X NO
2016 - Fal	II: No Change										
Comment	s:				-						
	ll: No Change				- -						
Comment	S:				_						
	ring: No Change										
Comment	S:				-						
2018 - Fal	II: No Change										
Comment	s:				-						
					J						

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
15	Grey sheet flooring	175	SF	Gym/Auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Comments:	o Change											
2017 - Spring	: No Change											

Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments:

HA No

Material Description

Material

Quantity

Material

Units

15A	Grey sheet flooring mastic	175	SF	Gym/Auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	io Chango											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	-											
2018 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

	·	Quantity	Units		Туре	Category		Type	Quantity	Units	
16	12x12 beige floor tile	1020	SF	2nd floor East/West Corridor		Miscellaneous	No	None	0		YES
2016 - Fa	all: No Change				7						
Commer					1						
2017 - S	pring: No Change										
Commer	nts:										
2017 - Fa	all: No Change				1						

Comments: 2018 - Fall: No Change Comments:

HA No

Material Description

Material

Units

Material

Quantity

Material Location

Change in Assessment Category

X NO

16A	12X12 beige floor tile mastic	1020	SF	Corridor		Miscellaneous	NO	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:	<u> </u>											
2017 - Fall: No Change												
Comments:												
	g: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

2016 - Fall: No Change									
Comments:									
2017 - Fall: No Change									
Comments:									
2017 - Spring: No Change									
Comments:									
2018 - Fall: No Change									
Comments:									
	·								

3000

Material

Quantity

Material

Units

SF

SF

stairwells

Material Location

2nd floor East/West

HA No

16A

17

Material Description

Gray Terrazzo

12x12 beige floor tile mastic 1020

Change in Assessment Category

X NO

X NO

YES

	rtomovou										
2016 Fall I	No Chango										
2016 - Fall: I	No Change										
Comments:											
2017 - Fall: No Change											
Comments:	<u> </u>										
2017 - Spring: No Change											
Comments:											
2018 - Fall: I	No Change				1						
Comments:	-										
	Taria de la composición dela composición de la composición de la composición de la composición dela composición de la composición dela composición dela composición de la composición de la composición dela composición de la composición dela composición de	1	T		1	T	T =				
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

0

None

Damage

Units

150

SF

HA No

18

19

Material Description

Red carpet mastic -

12" x 12" white Floor Tile

with light brown

Removed

Material

Units

Material Quantity

Material Location

Room 103

Room 201

Change in Assessment Category

X NO

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment	Category
20	Mastic for 12" x 12" white floor tile with light brown	150	SF	Room 201		Miscellaneous	No	None	0		YES	NO
2016 - Fall: N	lo Change]							

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12" x 12" It browm floor tile with dark brown	350	SF	Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

22	Mastic for 12" x 12" It brown woth dark brown and white floor tile	350	SF	office		Miscellaneous	No	None	0		YES	X NO
			•	•	1	•	•				•	
2016 - Fall	: No Change											
Comments	S:											
2017 - Fall	: No Change				1							
	<u> </u>				1							
Comments	S:											
					_							
2017 - Spr	ing: No Change											
Comments	:											
2018 - Fall	: No Change											
Comments	3:											
		•]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

No

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

X NO

23	Chalk board adhesive 5000 SF Classrooms							
2016 - Fall: No Change Comments:								
Comments.								
2017 - Spring	2017 - Spring: No Change							
Comments:	Comments:							
2017 - Fall: N	o Change							
Comments:	Comments:							
2018 - Fall: No Change								
Comments:	Comments:							

Quantity

Units

HA No

Material Description

Mastic for 12" x 12" It brown

Material

Units

Material Quantity Material Location

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Fairfield Elementary Academy
Date: 1/7/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.