## **Chicago Public Schools**

## **6 Month Asbestos Surveillance** 2018 - Fall

26881

**Oracle Unit:** 

**Building ID:** Address: 2022 W. Washington Blvd. Region: 03 Mail Room: Asbestos Surveyor: Terry, Crystal X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/8/2019 Email Address: cterry7@cps.edu A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Type Quantity YES SF X NO Acoustical Plaster Ceiling 300 Teacher's Lunchroom Yes None 0 Surface 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:No Change 2018 - Fall: No Change Comments:No Change

Suder Montessori Magnet ES

School:

6090

2	Smooth Plaster	100000	SF	Throughout Building		Surface	Yes	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	J											
2017 - Fall:	No Change											
Comments:	J											
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	No Change											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Yes

Friable

Damage

Туре

None

0

Damage

Quantity

Damage

Units

2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change	 	
Comments:No	o Change		
2018 - Fall: N	o Change		
Comments:No	o Change		

1600

Material

Quantity

Material

Units

SF

Lunchroom

Material Location

HA No

3

Material Description

1' x 1' Ceiling Tile

YES

X NO

4	2' x 4' Ceiling Tile	3200	SF	to Gymnasium, 101, 103		Miscellaneous	Yes	None	0	YES	X NO
2016 Fall N	la Changa				]						
2016 - Fall: N	no Change										
Comments:											
2017 - Fall: N	No Change										
Comments:											
2017 - Spring	g: No Change										
Comments:N	lo Change										
2018 - Fall: N	No Change										
Comments:N	lo Change										
	_										
·			_		-						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	Scratch Coat Plaster	2500	SF	Rooms 101, 105, Lobby by Gymnasium, Library 215		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:No Change	
2018 - Fall: No Change	
Comments:No Change	

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6	12" x 12" Light Brown w/White Specks Floor Tile	4000	SF	Lunchroom, Rooms 101, 213, 210, Library 215		Miscellaneous	No	None	0		YES X NO
0040 5 11 11	01				ĺ						

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:No Change	
2018 - Fall: No Change	
Comments:No Change	
	_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7A	9" x 9" Light Brown w/Dark Brown Specks Floor Tile	300	SF	Room 229 (old fan room)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:No Change	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:No Change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7B	9" x 9" Light Green w/Dark Green Flecks Floor Tile	350	SF	Room 225		Miscellaneous	No	None	0		YES X NO
•											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Fall: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7C	9" x 9" Beige w/Brown & White Strips Floor Tile	30300	SF	Throughout Building (see comments for locations)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:No Change
1

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
8	2' x 4' Smooth Ceiling Tile	3750	SF	Gymnasium		Miscellaneous	Yes	None	0		YES X NO	
2016 - Fall: No Change												

016 - Fall: No Change
Comments:
017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
018 - Fall: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
9	12" x 12" Lt. Brn w/White Specks Floor Tile Mastic	4000	SF	Room 101, Lunchroom, Rooms 210, 213, 215		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Fall: No Change
Comments:No Change

10A	9" x 9" Lt. Brn w/Dk. Brn Specks Floor Tile Mastic - Abated	Room 229 (old fan room)		Miscellaneous	None		YES	X NO
2016 - Fall	No Change		]					
Comments:			1					
0047 0	Alacia I							
2017 - Spri	<u> </u>							
Comments:	ABATED in 2010, 12x12 instal	led						
2017 - Fall:	No Change		-					
Comments:								
2018 - Fall:	No Change		-					
	No Change							
			J					

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
10B	9" x 9" Lt. Green w/Dk. Green Flecks FT Mastic	750	SF	Room 225		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:No Change	
2018 - Fall: No Change	
Comments:No Change	

HA No

Material Description

Material

Quantity

Material

Units

Material Location

10C	9" x 9" Beige w/Brn & Wt. Strips Floor Tile Mastic	30300	SF	Throughout Building (see comments for locations)		Miscellaneous	No	None	0	YES	,
2016 - Fall	: No Change				]						
Comments	:				1						
2017 - Spr	ing: No Change										
Comments	:No Change										
2017 - Fall	: No Change										
Comments	): -				=						
2018 - Fall	: No Change										
Comments	:No Change										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
11	Baseboard	120	LF	Room 225		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Fall: No Change
Comments:No Change
-

Material

Quantity

Material

Units

Material Location

HA No

Material Description

12	2	Baseboard Mastic	120	LF	Room 225	Miscellaneous	No	None	0	YES	X NO
20	16 - Fall: N	o Change									
Со	mments:										
	17 - Fall: N	o Change									
Co	mments:										
		: No Change									
Co	mments:No	o Change									
20	18 - Fall: N	o Change									

Material

Category

Asbestos

Type

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Pegboard	20	SF	Room 225		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Fall: No Change
Comments:No Change

Material

Quantity

Material

Units

Material Location

HA No

Comments:No Change

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
14	Hard Plaster Base Coat	210000	SF	Throughout Building		Surface	Yes	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments	:											
2017 - Fall:	: No Change											
Comments	:				_							
2017 - Spri	ng: No Change											
Comments	:No Change				_							
2018 - Fall:	: No Change											
Comments	:No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12" x 12" Grey w/white & brown floor tile	6000	SF	Rooms 105, 103, 109, 111, 209, 211, 213, 217 (patch)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Fall: No Change
Comments:No Change
-

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
16	12" x 12" Grey w/white & brown floor tile mastic	6000	SF	Rooms 105, 107, 109, 111, 209, 211, 213, 217 (patch)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change	•	-	· ·	]	•		•		•	•	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Fall: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12" x 12" White w/Black Floor Tile	660	SF	Room 116		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Fall: No Change
Comments:No Change
-

	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment C	ategory
	18	12" x 12" White w/Black Floor Tile Mastic	660	SF	Room 116		Miscellaneous	No	None	0		YES X	10
Ī	2016 - Fall: N	o Change											

016 - Fall: No Change	
omments:	
017 - Fall: No Change	
comments:	
017 - Spring: No Change	
comments:No Change	
018 - Fall: No Change	
comments:No Change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	Vault Door	32	SF	Main Office Area		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Fall: No Change
Comments:No Change

20	Vibration Collars	32	LF	2nd Floor Fan Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Fall:	No Change				-							
Comments:												
2017 - Sprir	ng: Abated				1							
	abated in 2010											
2018 - Fall:	No Change				1							
Comments:	No Change											
HA No	Material Description	Material	Material	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Friable

Damage

Type

Type

Damage

Quantity

Quantity

Damage

Units

Units

21	12x12 Lt Brown w/brown & white floor tile	7000	SF	1sr fl hall, 1sr fl storage rms, 2nd fl teachers lounge; 221,206,210,204,201,214 patch	Miscellaneous	No	None	0	YES
2016 - F	all: No Change								
Commer	•								
2017 - Fa	all: No Change								
Commer	•								
2017 - S	Spring: No Change								
Commer	nts:No Change								

HA No

2018 - Fall: No Change Comments:No Change

Material Description

Material

Quantity

Quantity

Units

Material

Units

Material Location

Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12x12 It brown w/brown& white FT mastic	7000	SF	1sr fl hall, 1sr fl storage rms, 2nd fl teachers lounge; 221,206,210,204,201,214 patch		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Fall: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Brown w/black carpet adhesive	750	SF	Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Fall: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
24	Blue carpet adhesive	1850	SF	Rooms 215		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Fall: N Comments:	lo Change											

2017 - Spring: No Change Comments:No Change 2018 - Fall: No Change

Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Sink undercoating	10	SF	Room 225		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Fall: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12x12 Lt. grey w/grey floor tile	50	SF	Room 212 patch		Miscellaneous	No	None	0		YES X NO
•											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Fall: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12x12 Lt. grey w/grey floor tile mastic	5	SF	Room 212 patch		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Fall: No Change
Comments:No Change

28	Green Checkered Ceramic Tile Grout	1500	SF	Vestibuled Entrances, 1st,2nd Floor-Boys/Girls Washrooms		Miscellaneous	No	None	0	YES	X NO
2016 - Fall	: No Change		<u> </u>	<u> </u>	]						
Comments					1						
2017 - Spri	ing: No Change				_						
Comments	:No Change				1						
2017 - Fall	: No Change				-						
Comments	:				1						
2018 - Fall	: No Change				-						
Comments	:No Change										
					J						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28m	Green Checkered Ceramic Tile Adhesive	1500	SF	Vestibuled Entrances, 1st,2nd Floor Boys/Girls Washroom		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Fall: No Change
Comments:No Change

HA No

Material Description

Material

Quantity

Material

Units

29	Maroon, White Terrazon	3500	SF	At Stairway, Entrances	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2017 - Spring										
Comments:N	o Change									
2018 - Fall: N	lo Change									

Material

Category

Asbestos

Type

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Green, White Checkered Terrazo	800	SF	Northeast Entrance		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Fall: No Change
Comments:No Change

Material

Quantity

Material

Units

Material Location

HA No

Comments:No Change

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
31	12x12 Dark Green Tile	300	SF	Lunchroom, Manager Office, Storage Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31m	12x12 Dark Green Tile Mastic	300	SF	Lunchroom, Manager Office, Sotrage Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:No Change	
2018 - Fall: No Change	
Comments:No Change	

Page 19

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
32	12x12 Silver, White Floor Tile			Rms. 103,105,109,111,209,211 ,213, Counseling Room, Nurses Office		Miscellaneous					YES	X NO
2016 - Fall: N	o Change				]							
Comments:	<u> </u>											
2017 - Spring	: No Change				-							
Comments:No												
2017 - Fall: N	o Change				<u> </u>							
Comments:												
2018 - Fall: N	o Change											
Comments:No												
					]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
32m						Miscellaneous					YES	X NO
2016 - Fall: N	o Change				]							
Comments:	U											
2017 - Fall: N	o Change				-							
Comments:	<u> </u>											
2017 - Spring	: No Change				-							
Comments:No												
2018 - Fall: N	o Change				-							
Comments:No					]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
34	Elbow on Fiber Glass - Abated			Crawl Space Abover Wall In Boiler Room		TSI		Loc			YES	X NO
2016 - Fall:	No Change											
Comments:	<u>u</u>											
2017 - Fall:	No Change											
Comments:												
2017 - Sprii	ng: No Change											
Comments:	No Change											

Comments.No Change
2018 - Fall: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Sink Undercoating	6	EA	Rooms 101, 102, 103, 104, 105,		Surface	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Fall: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Blotted Brown 12" X 12" VFT	1500	SF	All Uni vents Book Room, Industrial Art, Shop 223, porch on 2nd floor, and stairway		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 5 11 11 21	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:No Change	
2018 - Fall: No Change	
Comments:No Change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Blotted Brown 12" X 12" VFT Mastic	1500	SF	All Uni vents Book room, Industrial Art, Shop 223, 2nd floor porch, stairways		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Fall: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Blotted Beige VFT 12" X 12"	120	SF	2nd floor uni vents and 2nd book room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Fall: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Blotted 12" X 12" Mastic	1200	SF	2nd floor Uni vents and 2nd floor book room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Fall: No Change
Comments:No Change

40	Window Caulk	3000	LF	Throughout		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments												
2017 - Fall:	No Change											
Comments	:				_							
	ng: No Change											
Comments	:No Change				_							
2018 - Fall:	No Change											
Comments	:No Change				_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

Damage

Quantity

Damage

Units

2016 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:No	c Change		
2017 - Fall: N	o Change		
Comments:			
2018 - Fall: N	o Change		
Comments:No	change		
		<u> </u>	•

3000

LF

Throughout

Material

Quantity

Material

Units

Material Location

HA No

41

Material Description

Door Caulk

YES

X NO

В	Boiler Insulation - Abated			Boiler Room		TSI		None			YES	X NO
2016 - Fall: No	o Change											
Comments:	-											
2017 - Spring:	: No Change											
Comments:No	Change											
2017 - Fall: No	o Change											
Comments:												
2018 - Fall: No	o Change											
Comments:No	Change											
					I							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
G	Woolfelt Pipe Insulation (Paperwrap) - Abated			Boiler Room, Pipe Chases		TSI		None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Material

Quantity

Material

Units

HA No

Material Description

(Paperwrap) - Abated

Н	Fittings on Woolfelt Pipe Insulation (Paperwrap) - Abated			Boiler Room, Pipe Chases		TSI		None			YES	X NO
2016 - Fall: N	No Change			·	1							
Comments:	ge											
2017 - Sprine	g: No Change											
Comments:N												
2017 - Fall: N	No Change				_							
Comments:	Ţ.											
2018 - Fall: N	No Change											
Comments:N												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

TSI

Asbestos

Type

Material

Category

Friable

Damage

Туре

None

Damage

Quantity

Damage

Units

I	Mag Block Pipe Insulation - Abated		Boiler Room
204C Fall N	o Change		
2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:No	o Change		
		•	_
2018 - Fall: N	o Change		
Comments:No	o Change		
			•

Material

Quantity

Material

Units

Material Location

HA No

Material Description

YES

X NO

J	Fittings on Mag-block Pipe Insulation - Abated			Boiler Room		TSI		None			YES	X NO
2016 - Fall	I: No Change											
Comments												
2017 - Fall	I: No Change											
Comments												
2017 - Spr	ing: No Change											
	s:No Change											
2018 - Fall	I: No Change											
Comments	s:No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
K	Aircell Pipe Insulation	1500	LF	Boiler Room, Pipe Chases, Crawl Space (inaccessible), 2nd Floor	71 -	TSI	Yes	None	0		YES	X NO

Asbestos

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Fan Room

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Fittings on Aircell Pipe Insulation	200	LF	Boiler Room, Pipe Chases, Crawl Space (inaccessible), 2nd Floor Fan Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
М	Boiler Gaskets (Packing) - Abated			Boiler Room							YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:No Change	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:No Change	
	·

Ī	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
-	N	Fittings on Fiberglass Pipe Insulation			Boiler Room							YES X NO

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Suder Montessori Magnet ES
Date:	1/18/2019
the Asbes	notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of tos Management Plan is available at each school during school hours by appointment. to review the Asbestos Management Plan must be made at least 24 hours in advance.
The last in	se be advised that CPS conducts asbestos inspections of all Schools every three years. aspection was completed in 2016. surveillances are conducted every six months.
CHECK O	<u>NE</u>
A c	copy of this notice was sent home in each child's backpack.
A c	copy of this notice was printed in the school's newsletter and sent home with each child
A c	copy of this notice was printed in the school's calendar and sent home with each child
Oth	ner.
	Y OF THIS NOTICE MUST BE PLACED IN THE HOOL'S ASBESTOS MANAGEMENT PLAN.