## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2018 - Fall

Leif Ericson Elementary Scholastic Academy 29051 3240 School: **Oracle Unit: Building ID:** Address: 3600 W. Fifth Region: 03 Mail Room: Asbestos Surveyor: Smith, Joshua X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/4/2019 Email Address: jsmith297@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type YES 001 X NO Sprayed On Fireproofing Second Floor Mechanical Surface 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
1	Sprayed on Fireproofing Insulation			Second Floor Mechanical Room		Surface					YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	<u> </u>											
2017 - Spring	ı: No Change				-							
Comments:	,				1							
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:	<u> </u>				]							
					J							
	1			1	1			1	1	1		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1A	Spray-on Fireproofing			Boiler Room							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
2	Sprayed on Fireproofing	1000	SF	Second Floor Mechanical Room		Surface	Yes	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
0040 0 1 N 01
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2A	2' x 4' Random Dot Ceiling Panels	32000	SF	Lunchroom, Corridors and Classrooms		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2B	2' x 4' Random Dot (Dense Pattern) Ceiling Panels			Corridors and Classrooms		Miscellaneous			YES	X NO
2016 - Fall: N	lo Change									
Comments:	io Change									
Comments.										
2017 - Fall: No Change										
Comments:	<u> </u>									
2017 - Spring	g: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:	io change									
2018 - Spring	g : No Change									
Comments:	Comments:									

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
3	1' x 1' Dotted Ceiling Tile			Special Projects Room							YES	X NO
2016 - Fall: No Change Comments:												
2047 Chairm No Change												

2017 - Spring: No Change

Comments:

HA No

Material Description

Material

Quantity

Material

Units

**Material Location** 

2017 - Fall: No Change Comments:

2018 - Fall: No Change Comments:

2018 - Spring : No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4	1' x 1' Fissured Ceiling Tile			1st Floor Rotunda							YES X NO
2016 - Fall: N	lo Change										
Comments:	<u> </u>										
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:					_						
2018 - Fall: N	lo Change										
Comments:					_						
	j : No Change										
Comments:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	9" x 9" Grey Floor Tile	2250	SF	1st Floor & 2nd Floor Rooms 201, 212, 218		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

6	12" x 12" Tan Floor Tile	3000	SF	1st Floor Offices, Teacher's Lunchroom and Kitchen		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	to oriange				1							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	a: No Change				-							
Comments:												
2018 - Fall: N	lo Change				-							
Comments:												
2018 - Spring	g : No Change				=							
Comments:	, <u> </u>				1							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Asbestos

Type

Material

Category

Category

Friable

Damage

Type

Туре

Damage

Quantity

Quantity

Units

YES

X NO

Damage

Units

2016 - Fall: N	o Change			
Comments:		 <u> </u>		
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				
		 	_	

Quantity

Units

Auditorium

HA No

7

Material Description

Acoustical Ceiling Tile

Material

Units

Material

Quantity

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8	9" x 9" Grey Floor Tile Mastic	2250	SF	1st Floor & 2nd Floor rooms 201, 212, 218		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9	12" x 12" Tan Floor Tile Mastic	5355	SF	1st Floor Offices, Lunchroom and Kitchen		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
10	Insulation Inside of Vault Door	20	SF	Main Office		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:					_							
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change				_							
Comments:												
2018 - Spring	g : No Change											
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Kiln Insulation			Room 110		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
12	Stack Interior Material			Boiler Room							YES	X NO
2016 - Fall: N	No Change											
Comments:	J											
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
	1			I		1		1 -		T _	1 01 1 4	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	2' x 4' Ceiling Panels w/ Symmetrical Dots			Girl's and Boy's 1st & 2nd Floor Washrooms							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	9" x 9" Beige Floor Tile	15200	SF	Auditorium, Vault, Rooms 101, 103, 104, 107, 108, 112, 202, 203, 206, 207, 210, 211, 214-216, 219, 220, 224		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	9" x 9" Beige Floor Tile Mastic	15200	SF	Auditorium, Vault, Rooms 101, 103, 104, 107, 108, 112, 202, 203, 206, 207, 210, 211, 214-216, 219, 220, 224		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12" x 12" Blue Floor Tile			Room 102		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

17	12" x 12" Blue Floor Tile Mastic			Room 102							YES	X NO
2016 - Fall: I	No Change				]							
Comments:												
2017 - Fall: I	No Change				_							
Comments:	J											
2017 - Sprin	g: No Change				1							
Comments:												
2018 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
18	9' x 9' White Floor Tile	2400	SF	Rooms 109 & 115		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Units

Damage

Quantity

Change in Assessment Category

Material

Units

Material

Quantity

Material Location

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

2018 - Spring : No Change

Comments:

Comments:

Comments:

Comments:

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	9' x 9' White Floor Tile Mastic	2400	SF	Rooms 109 & 115		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	9" x 9" Marble Grey Floor Tile	9000	SF	1st & 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	9" x 9" Marble Grey Floor Tile Mastic	9000	SF	1st & 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change	
Comments:	
Offinitions.	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	9" x 9" Olive Green Floor Tile	1200	SF	Room 111		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	9" x 9" Olive Green Floor Tile Mastic	1200	SF	Room 111		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	9" x 9" Dark Gray Floor Tile	2000	SF	1st Floor Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
25	9" x 9" Dark Gray Floor Tile Mastic			1st Floor Corridor							YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:	-											
2018 - Fall: N	No Change											
Comments:	J											
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	9" x 9" Tan Floor Tile w/ Specks	150	SF	2nd Floor North Corridor End Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	9" x 9" Tan Floor Tile w/ Specks Mastic	150	SF	2nd Floor North Corridor End Office		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12" x 12" Light Beige Floor Tile	200	SF	1st Floor Foyer & Corridor by Boiler Room Stairs		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
29	12" x 12" Light Beige Floor Tile Mastic	200	SF	1st Floor Foyer & Corridor by Boiler Room Stairs		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				]							
Comments:	<u> </u>											
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	ig: No Change											
Comments:												
2018 - Sprin	g : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12" x 12" Brown Floor Tile	620	SF	North End of 1st Floor Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

Comments:

2018 - Fall: No Change

31	12" x 12" Brown Floor Tile Mastic	500	SF	North End of 1st Floor Corridor		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Chango										
	io Change										
Comments:	Comments:										
2017 - Fall: No Change											
Comments:											
2017 - Spring	j: No Change										
Comments:											
2018 - Spring	j : No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:											
1					1						

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Hard Ceiling Plaster			Book Room by the Gymnasium							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
33	12" x 12" White Floor Tile	500	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Fall: N Comments:	lo Change				-							

2017 - Spring: No Change
Comments:

2018 - Spring : No Change Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12" x 12" White Floor Tile Mastic	500	SF	Auditorium		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
35	Incinerator Lining			Boiler Room		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	Ü											
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Window Caulk	6300	SF	Throughout Building Interior		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
37	Vibration Isolator Cloth			2nd Floor Mechanical Room		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				7							
Comments:	J											
2017 - Fall: N	No Change				+							
Comments:	•											
2017 - Spring	g: No Change				-							
Comments:												
2018 - Fall: N	No Change				-							
Comments:												
2018 - Spring	g : No Change				-							
Comments:												
					_							
	_			1								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Exterior Brick - not AHERA			Building Exterior							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessn	nent Category
39	Exterior Brick Mortar - not AHERA			Building Exterior							YES	X NO
2016 - Fall: N	lo Change											
Comments:	V											
2017 - Fall: N	lo Change											
Comments:	V											
2017 - Spring	: No Change											
Comments:	-											
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
I	_											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Water Tank Insulation			Boiler Room							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
41	Wire Insulation on Stage lights	50	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:					1							
2017 - Fall: N	lo Change				-							
Comments:												
2017 - Spring	g: No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:					_							
	ј : No Change											
Comments:					_							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	9" x 9"Grey Floor Tile w/Dk & Lt Grey Streaks	11880	SF	Rooms 106, 109, 110, 113, 115, 201, 204, 205, 208, 209, 212, 213, 217, 218, 222		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	9"x9"Grey Floor Tile w/Dk & Lt Grey Streaks Mastic	9600	SF	Rooms 106, 109, 110, 113, 115, 201, 204, 205, 208, 209, 212, 213, 217, 218, 222		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
Commond.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12" x 12" Off-White Spots Floor Tile w/ White	1200	SF	Office Complex, Counselor's Office, Photo Lab, Room before 2nd Floor Mechanical Room		Miscellaneous	No	None	0		YES X NO

			1 1001 MCCHarlical 100111
2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			
2018 - Spring	: No Change		
Comments:			

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
45	12" x 12" Off-White Floor Tile w/ White Mastic	1200	SF	Office Complex, Counselor's Office, Photo Lab, Room before 2nd Floor Mechanical Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	II: No Change				]							
Comment												
2017 - Fa	II: No Change				-							
Comment	ts:											
2017 - Sp	oring: No Change				-							
Comment	is:											
2018 - Fa	II: No Change											
Comment	ts:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
46	12" x 12" Brown Floor Tile	200	SF	MDF Room		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2018 - Spring : No Change

Comments:

47	Mastic	200	SF	MDF Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	<b>-</b>											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	j : No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

No

Loc

0

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

2016 - Fall: N	lo Change		
Comments:			
2017 - Spring	j: No Change		
Comments:			
2017 - Fall: N	lo Change		
Comments:			
2018 - Spring	j : No Change		
Comments:			
2018 - Fall: N	lo Change		
Comments:			

54

HA No

48

Material Description

12x12 Tan VFT patches

Material

Quantity

Material

Units

SF

Material Location

Room 103, 115

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	12x12 Tan VFT patches mastic	54	SF	Room 103, 115		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
50	12x12 Brown VFT patches	65	SF	Room 103		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 28

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
51	12x12 Brown VFT patches mastic	65	SF	Room 103		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	12x12 Yellow VFT patches	160	SF	Room 115, 111		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	12x12 Yellow VFT mastic	160	SF	Rooms 115,111		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
54	T.S.I.	10	LF	Room 113		TSI	Yes	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

											1	
55	9x9 Green floor tile	405	SF	Teacher's Lunchroom, backroom, 1st floor janitor's room		Miscellaneous	No	Loc	20		YES	X NO
0040 5 11 1		•	*	•	1	•	•	•	•	•	,	
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:	-											
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	ı: No Change											
Comments:												
0040 5 11 1	. 01				4							
2018 - Fall: N	io Change											
Comments:												

Type

Material

Category

Damage Quantity Damage

Units

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	9x9 green floor tile mastic	405	SF	Teacher's room, backroom, 1st floor janitor's room		Miscellaneous	No	None	0		YES X NO

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
57	Brown Ceramic Floor Tile	2300	SF	1st, 2nd Floor Boys Bathroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	2016 - Fall: No Change Comments:											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	Brown Ceramic Floor Tile Mastic	2300	SF	1st, 2nd, floor Boys Bathroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
59	White Grey Terrazzo	14500	SF	1st Floor Entrance and Stairs and Landings in 2nd Floor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change				-							
Comments:												
2017 - Fall:	No Change				-							
Comments:												
2018 - Sprir	ng : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	Blue Ceramic Floor Tile and Grout	2300	SF	1st, 2nd, Floor Girls Bathroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

	·	Quantity	Units		Туре	Category		Туре	Quantity	Units		0,
61	Blue Ceramic Floor Tile Mastic	2300	SF	1st, 2nd Floor Girls Bathroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change											
Comments												
2017 - Fall	: No Change											
Comments	): :											
2017 - Spri	ing: No Change											
Comments	): :											
2018 - Fall	: No Change											
Comments	):											
2018 - Spri	ing : No Change											

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Α	Hard Joint Compound on Fiberglass Pipe Runs	210	LF	Above Ceilings in Corridors, Locker Rooms, etc.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Comments:

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
В	Insulation on Air Handling Unit			2nd Floor Mechanical Room		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					 							
2018 - Spring	: No Change											
Comments:					<u> </u>							
2018 - Fall: N	lo Change											
Comments:					-							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Boiler Tank Insulation			Boiler Room		TSI					YES X NO
0040 5 11 11	. 01				1						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessn	nent Category
C 1	Metal Jacketed Tank Insulation			Boiler Room							YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	g: No Change											
Comments:	<i>y</i>											
2017 - Fall: N	lo Change											
Comments:	Ţ.											
2018 - Fall: N	lo Change											
Comments:	J											
2018 - Spring	g : No Change											
Comments:	<i>y</i>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
C 2	Front Boiler Gasket			Boiler Room							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
C 3	Rear Gasket on Cleaver Brooks Boiler			Boiler Room							YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	ı: No Change											
Comments:	,											
2017 - Fall: N	lo Change											
Comments:	J											
2018 - Spring	g : No Change											
Comments:	, <u> </u>											
2018 - Fall: N	lo Change				_							
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
C 4	Boiler Burner Gasket			Boiler Room							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Boiler Breeching Insulation			Boiler Room		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Leif Ericson Elementary Scholastic Academy
Date: 1/4/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 29051

SCHOOL'S ASBESTOS MANAGEMENT PLAN.