Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Gerald Delgado Kanoon Elementary Magnet School 29071 3370 School: **Oracle Unit: Building ID:** Address: 2233 S. Kedzie Region: 03 Mail Room: Asbestos Surveyor: Trevino, David X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/10/2019 Email Address: dtrevino4@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type YES 2' x 4' Ceiling tile X NO Miscellaneous Throughout building 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

2	Spray-on Fire Proofing			Throughout school		Surface					YES	X NO
2016 - Fall: N	Vo Change]							
Comments:	to change				-							
2017 - Fall: N	No Change				_							
Comments:	-				1							
	g: No Change				-							
Comments:												
2018 - Fall: N	No Change											
Comments:					-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
3	12" x 12" Beige w/ Brown	30000	SF	Throughout building in all classrooms and hallways		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Material Description

Specks Floor Tile

Material

Units

Material

Quantity

Material Location

except washrooms

4	12" x 12" Beige w/Brown Specks Floor Tile Mastic	30000	SF	Throughout building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	o onango											
2017 - Fall: N	o Change											
Comments:	o onango											
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
5	Baseboard			Throughout building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

6	Baseboard Mastic			Throughout building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:					1							
2017 - Fall: N	lo Change											
Comments:					-							
2017 - Spring	g: No Change				-							
Comments:					1							
2018 - Fall: N	lo Change											
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
7	Vault Door Insulation	60	SF	Main Office (Room 100D/Storage), Room		TSI	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

8	Transite Counter Top	150	SF	Science Lab (Room 201)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	-											
2017 - Fall:	No Change				_							
Comments:					_							
	g: No Change											
Comments:					_							
2018 - Fall:	No Change				_							
Comments:					-							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
9	Vibration Collar (isolation	100	LF	Ductwork throughout building - mechanical		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

	•		aleas
2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:		·	

HA No

9

Material Description

cloth)

Material

Quantity

Material

Units

Material Location

	•			,							
2016 - Fall:	No Chango				7						
	No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
2017 - Sprin	g: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
					_						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
TIA NO	Waterial Description	Quantity	Units	Material Location		Category	Fliable		Quantity	Units	Change in Assessment Category
		Qualitity	Office		Туре	Calegory		Туре	Quartity	UtillS	
11	2' x 4' Metal covered ceiling			Throughout classrooms		Missollansous					

Type

Material

Surface

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material Quantity Material Location

Small Gymnasium

on the 1st & 2nd floors

(Handball Court)

HA No

10

11

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Hard plaster on walls &

ceiling

Change in Assessment Category

X NO

X NO

YES

12	Duct interior lining			Mechanical/Fan Rooms		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change				•							
Comments:												
2017 - Spring	j: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
13	Folding Doors Cloth Cover			Rooms 120 &122		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

Material Description

Material

Units

Material

Quantity

Material Location

14	Black pipe insulation			Mechanical/Fan Rooms		TSI					YES	X NO
2016 - Fall:	No Change				7							
Comments:					1							
2017 - Fall:	No Change											
Comments:												
2017 - Spri	ng: No Change											
Comments:					_							
2018 - Fall:	No Change											
Comments:					4							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	nent Category
15	Duct Exterior Insulation			Mechanical/Fan Room		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

16	Interior window caulk			Throughout school		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	-]							
2017 - Fall: N	lo Change											
Comments:					1							
2017 - Spring	j: No Change											
Comments:				 								
2018 - Fall: N	lo Change											
Comments:					 -							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
17	Exterior window caulk - not AHERA			Exterior of building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

Material Description

Material

Units

Material

Quantity

Material Location

18	Exterior window glaze - not AHERA			Exterior of building		Miscellaneous					YES	X NO
2016 - Fa	II: No Change]							
Comment	s:											
2017 - Fa	II: No Change											
Comment	s:				_							
2017 - Sp	ring: No Change											
Comment	s:				_							
2018 - Fa	II: No Change											
Comment	S:				_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
19	Lower Roof Field - not			Lower roof		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

20	Lower Roof Flashing - not AHERA			Lower roof		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:					1							
2017 - Fall: N	lo Change											
Comments:					-							
2017 - Spring	ı: No Change				-							
Comments:												
2018 - Fall: N	lo Change											
Comments:]							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
0.4	Upper Roof Field - not	Quantity	Office		1,700			1,700	Guarity	Office		
21	AHERA			Upper roof		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

2016 - Fall: I	No Chango				7						
	No Change										
Comments:											
2017 - Fall: I	No Change				-						
	No Change										
Comments:											
2017 - Sprin	g: No Change										
Comments:											
2018 - Fall: I	No Change										
Comments:	-										
		·									
HA No	Material Description	Material	Material Units	Material Location	Asbestos	Material	Friable	Damage Type	Damage	Damage	Change in Assessment Category
1	1	Quantity	LUDIIIS		Type	Category	1	LVDE	Quantity	Units	1

TSI

Asbestos

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

None

0

Damage

Quantity

Damage

Units

20

LF

HA No

22

23

Material Description

Stage Lights Electrical

AHERA

Upper Roof Flashing - not

Material

Quantity

Material

Units

Material Location

Upper roof

Auditorium

Change in Assessment Category

X NO

X NO

YES

24	Carpet Mastic	18000	SF	108,110,114,200,202- 208,210,214,218,220- 224,226,228,230,232,234		Miscellaneous	No	None	0		YES	X NO
	*	•	•	•	•	•	•	•	•	-		
2016 - Fall: N	o Change											
Comments:					1							
					1							
2017 - Fall: N	o Change											
Comments:					1							
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change				1							
Comments:	<u> </u>				1							
					1							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Sink Coating	135	SF	200, 201, 202, 204, 206, 208, 210, 212, 205, 214, 218, 220, 222,223, 224, 226,105,108, 110, 112, 114, 116, 118,120,122		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12" x 12" White w/Blue Specks FT	2400	SF	Room 105,112,118		Miscellaneous	No	None	0		YES X NO
		•	•					•	•	•	

[
2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
27	12" x 12" White w/Blue Specks FT Mastic	2400	SF	Room 105, 112, 118		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12" x 12" Blue Speckled Floor Tile	225	SF	Room 105, 112, 118, and 212		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12" x 12" Blue Speckled Floor Tile Mastic	225	SF	Room 105, 112, 118, and 212		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

30	Beige Ceramic Floor Tile Grout	4000	SF	All 1st and 2nd Floor Washrooms, 1st Floor Janitors Closets, and Kitchen Area		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: Comments:	•										
2017 - Fall: Comments:	<u> </u>										
2017 - Sprin Comments:	g: No Change				- - -						

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Brown Ceramic Baseboard Grout	600	LF	All 1st and 2nd Floor Washrooms, 1st Floor Janitors Closets, and Kitchen Area		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No

2018 - Fall: No Change

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

32	Interior Door Caulk	1280	LF	floors		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	II: No Change											
Comment					1							
Commen												
2017 - Fa	II: No Change											
Commen	ts:											
	ring: No Change											
Commen	ts:											
0040 5	II No Olesco											
	III: No Change											
Commen	ts:											
		1	T	I sa a sa a sa	T	T	T =					
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
		Quantity	Office	Main Office Conf Decor	Турс	Category		Турс	Quantity	Offito		
00		4000	0.5	Main Office, Conf Room, Faculty Lounge, Asst Prin							YES	X NO
33	Burgandy Carpet Mastic	4600	SF	Office, Rms 106C and D,		Miscellaneous	No	None	0			

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Student Services,

All door on 1st and 2nd

	-	Quantity	Units		Type	Category		Type	Quantity	Units		
34	4" Black Vinyl Baseboard	600	LF	Assembly Hall, 1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	all: No Change				1							
	Comments:											
2017 - Fall: No Change												
Commen												

Material

Friable

Damage

Damage

2017 - Spring: No Change

Comments:

Material Material Location

2018 - Fall: No Change

Material Description

HA No

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	4" Black Vinyl Baseboard Adhesive	600	LF	Assembly Hall, 1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Damage Change in Assessment Category

2016 - Fall:	No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
	g: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Yes

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

400

HA No

36

37

Material Description

Drywall Ceiling

Wall Expansion Joint Caulk

Material

Units

LF

SF

Material Quantity

300

Material Location

Assembly Hall

Room 221

Change in Assessment Category

X NO

X NO

YES

	I .										
38	Drywall Ceiling Joint Compound	50	SF	Room 221		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change]						
Comments:											
2017 - Fall:	No Change										
Comments:											
	ng: No Change				-						
Comments:					-						
2018 - Fall:	No Change										

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Drywall Ceiling Joint Tape	32	LF	Room 221		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

2016 - Fall: No Change				7						
Comments:										
2017 - Fall: No Change				+						
Comments:										
2017 - Spring: No Change	-									
Comments:										
2018 - Fall: No Change				-						
Comments:										
				_						
HA No Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material Quantity

Material Location

2nd Floor Hall outside

2nd Floor Hall outside

room 234 and Stairs

room 234 and Stairs

HA No

40

41

Material Description

12" X 12" Beige Speckled Floor Tile (Patch)

12" X 12" Beige Speckled Floor Tile (Patch) Change in Assessment Category

X NO

X NO

YES

42	Gray Skid Pad Covering Adhesive	25	SF	Elevator		Miscellaneous	No	None	0	YES	X NO
2016 - Fa	ıll: No Change]						
Comment	ts:]						
2017 - Fa	III: No Change										
Comment	ts:				 						
2017 - Sp	oring: No Change				-						
Comment	ts:				-						
2018 - Fa	ıll: No Change				-						
Comment	ts:				-						
					1						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
43	Ceramic Wall Tile Grout	20	SF	Janitors Closets		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

2016 - Fall: I	No Chango				7						
	No Change										
Comments:											
2017 - Fall: I	No Change										
Comments:											
0047 Oznin	a. Na Ohana				4						
2017 - Sprin	g: No Change										
Comments:											
2018 - Fall: I	No Change										
Comments:											
		·									
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

HA No

44

45

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Gray Carpet Adhesive

Ceramic Wall Tile Adhesive

Material

Quantity

20

Material

Units

SF

SF

4000

Material Location

Janitor's Closets

Assembly Hall

Change in Assessment Category

X NO

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
46	12"x12" Grey w/Dark Grey Streaks VFT	3300	SF	Rooms 116,120,122		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: N	lo Change	1										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
47	12"x12" Grey w/Dark Grey Streaks VFT Mastic	3300	SF	Rooms 116,120,122		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
48	12"x12" Beige w/White Streaks VFT	2740	SF	Room 208, 210, 212, 214, 226		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
49	12"x12" Beige w/White Streaks VFT Mastic	740	SF	Room 208, 210, 212, 214, 226		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

50	12"x12" Red VFT	30	SF	Room 212		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change				1							
Comments	:											
	: No Change											
Comments	:				-							
	ing: No Change											
Comments	:				_							
2018 - Fall:	: No Change											
Comments	:				-							
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessi	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

		Quantity	Units		Туре	Category		Туре	Quantity	Units	_	
51	12"x12" Red VFT Mastic	30	SF	Room 212		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	II: No Change s:											
2017 - Fa	II: No Change				- - -							

2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No

Material Description

Material

Units

Material Quantity Material Location

52	Grey Patterned Carpet Mastic	1430	SF	Room 225(Library)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change												
Comments:												
2017 - Spring: No Change												
Comments:	,g				-							
2017 - Fall: No Change					-							
Comments:					1							
2018 - Fall: No Change					1							
Comments:	.											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
В	Hard Joint Compound on Fiberglass Pipe Runs			Throughout school (above ceiling tiles)		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

_	Gerald Delgado Kanoon Elementary Magnet School
Date: _	1/14/2019
the Asbesto	otify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of s Management Plan is available at each school during school hours by appointment. review the Asbestos Management Plan must be made at least 24 hours in advance.
The last insp	be advised that CPS conducts asbestos inspections of all Schools every three years. pection was completed in 2016. Irveillances are conducted every six months.
CHECK ONE	
A cop	by of this notice was sent home in each child's backpack.
A cop	by of this notice was printed in the school's newsletter and sent home with each child
A cop	by of this notice was printed in the school's calendar and sent home with each child
Other	r.
	OF THIS NOTICE MUST BE PLACED IN THE DOL'S ASBESTOS MANAGEMENT PLAN.