Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

29081

Oracle Unit:

Address: 225 W. Evergreen Avenue Region: 02 Mail Room: Asbestos Surveyor: Hohenadel, Ryan X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/9/2019 Email Address: rthohenadel@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Type Quantity YES 01 Hard Plaster SF 0 X NO 200000 Yes Throughout Surface 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Franklin Elementary Fine Arts Center

School:

3420

Building ID:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	12"x 12" Beige w/ Brown & White Streaks VFT	5000	SF	Room 209 ((2nd Floor Corridor, , Main Office (112), & 2nd Floor Teacher's Break Room (213),NOT OBSERVED)) 1925 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
03	9"x9" Gray w/ Black, White, & Pink Streaks VFT	200	SF	1st Floor Corridor (Abated) & Room 114 Storage Room 1925		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change	•		•	1	•	-	•	•	•		

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	Yellow Linoleum	2800	SF	Assembly Hall, 1925		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
05	12"x12" Beige w/ Brown & White Streaks VFT Mastic	2000	SF	Room 209 ((2nd Floor Corridor, , Main Office (112), & 2nd Floor Teacher's Break Room (213),NOT OBSERVED)) 1925 Bldg		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

06	9"x9" Gray w/ Black, White, & Pink Streaks, Mastic	200	SF	1st Floor Corridor (Abated) & Room 114 Storage Room 1925		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change			•]						
Comments:	o Onlange										
2017 - Spring	: No Change										
Comments:	-				1						
2017 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:											
0040 Fall N	- Ob				-						
2018 - Fall: N	o Change										

Type

Material

Category

Damage

Type

Damage

Quantity

Damage

Units

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
07	Yellow Linoleum Mastic			Assembly Hall, 1925							YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
08	Drywall Joint Compound			Kitchen Storage, 1925						YES	X NO
2016 - Fall: N	lo Change]						
Comments:											
2017 - Spring	j: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2018 - Spring	j : No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:	·			·							
					_						
			1								

Material

Friable

Damage

Damage

Damage

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	12"x12" Brown w/ Beige & Black Speck VFT (ABATED)			Room 110, 1925 Abated							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

10	12"x12" Brown w/ Beige & Black Speck VFT Mastic (ABATED	Room 110, 1925 Abated				YES	X NO
204C Falls	No Change		1				
	No Change						
Comments:							
2017 - Sprii	ng: No Change						
Comments:							
			1				
2017 - Fall:	No Change		1				
Comments:							
2018 - Sprii	ng : No Change						
Comments:							
2018 - Fall:	No Change		1				
Comments:	•		1				
			4				

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12"x12" Tan w/ White & Black Specks VFT	100	SF	Room 116, 1925		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12"x12" Tan w/ White & Black Specks VFT Mastic	100	SF	Room 116, 1925		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12" x 12" Beige w/ Brown & White Specks VFT (Not Observed)	700	SF	120, Room 118 (Abated) -1925 Bldg		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12" x 12" Beige w/ Brown & White Specks VFT Mastic (Not Observed)	700	SF	120, Room 118 (Abated) -1925 Bldg		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change						•	•	•	•		

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Green Linoleum (Not Observed)	600	SF	Room 222 - 1925.		Miscellaneous	No		0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	Green Linoleum Mastic (Not Observed)	600	SF	Room 222 - 1925		Miscellaneous	No		0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	2' x 4' Tectum Ceiling Tile	160	SF	Assembly Hall, 1925		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12" x 12" Blue Speckled VFT	1500	SF	Kitchen/Lunchroom, Lunchroom Office, (#110) - 1925		Miscellaneous	No	None	0		YES X NO
							•	-			

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12" x 12" Blue Speckled VFT Mastic	1500	SF	Kitchen/Lunchroom, Lunchroom Office, (#110) - 1925		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Drywall; PLM sample "Non-detect" STAT Lab, # 21229	400	SF	Kitchen Storage, 1925 PLM sample "Non-detect" STAT Lab, # 21229		Miscellaneous	Yes		0		YES X NO
2016 - Fa	all: No Change										

2040 Fall Na Obassa
2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12 x 12 inch Tan w/Dark Tan Streaks VFT - ABATED 2014			New Elevator, On the First Floor, By the Gym		Miscellaneous					YES X NO

1.2
2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21 A	12 x 12 inch Tan w/Dark Tan Streaks VFT Mastic - ABATED 2014			New Elevator, On the First Floor, By the Gym - NOT OBSERVED		Miscellaneous					YES X NO
2016 - Fall: Comments	No Change :										
2017 - Spring: No Change											

o cilinio inci
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12 x 12 inch Biege w/White Streaks VFT - ABATED 2014	300	SF	2nd Floor-South by Room 225 and Stairs, At the New Elevator - NOT OBSERVED		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22 A	12 x 12 inch Biege w/White Streaks VFT Mastic - ABATED 2014	300	SF	2nd Floor-South by Room 225 and Stairs, At the New Elevator - NOT OBSERVED		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Carpet Mastic	600	SF	Main Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
24	Terrazo	2000	SF	Entryways on 1st Floor, to the Stage & Stairs, Border in 1st Floor Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments	•											
2017 - Spri	ng: No Change											
Comments	:											
2017 - Fall:	No Change											
Comments	:											
2018 - Spri	ng : No Change											
Comments	:											
	No Change											
Comments	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12x12 Green w/ Streaks VFT	300	SF	Main Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

	•	Quantity	Units		Type	Category		Туре	Quantity	Units		,
26	12x12 Green w/ Streaks Mastic	300	SF	Main office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:]							
2017 - Fall: N	o Change				_							
Comments:					-							
2017 - Spring	: No Change											
Comments:					_							
2018 - Spring	: No Change											
Comments:					-							
2018 - Fall: N	o Change				_							
Comments:					-							
					_							

Material

Friable

Damage

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12x12 Gray w/Black Streaks VFT	1000	SF	Rooms 221, 222, 223		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Material

Material Location

Page 16

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12x12 Gray w/Black Streaks Mastic	1000	SF	Rooms 221, 222, 223		Miscellaneous	No	None	0		YES X NO
2016 Fall N	o Chango	•	•	_	1		•				

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Ÿ
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12x12 Tan w/light brown VFT Streaks	10500	SF	1st & 2nd Floor Corridors, 115, 117, 119, 120, 121		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

30	12x12 Tan w/light brown Streaks Mastic	10500	SF	1st & 2nd Floor Corridors, 115, 117, 119, 120, 121		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change				Ì						
Comments:	onango										
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2018 - Spring	: No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:	-										
					I						

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
В	Mag Block Tank Insulation No abatement records found.			Pump Room, 1895 (ABATED) No abatement records found.		TSI					YES	X NO
204C Fall	. No Change				7							

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	MJP E/F/V on Fiberglass Pipe Insulation	175	LF	SW Storeroom, Engine Room, Fan Room East, Girls & Boys Toilets, 1925		Miscellaneous	Yes	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:	
Commonte.	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Aircell Duct Insulation	1050	SF	Unexcavated Areas, Engine Room, Fan Room East, 1925		TSI	Yes	None	0		YES X NO

-	
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	•
	·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Aircell Pipe Insulation	2850	LF	Unexcavated Areas, Engine Room, Fan Rooms, Gym Office, 1925		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	MJP E/F/V on Aircell Pipe Insulation	385	LF	Unexcavated Areas, Engine Room, Fan Rooms, Gym Office, 1925		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	Cardboard Pipe Insulation	1085	LF	Unexcavated Areas, Engine Room, & Fan Room East, Gym Office, 1925		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No N	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	MJP E/F/V on Cardboard Pipe Insulation	140	LF	Unexcavated Areas, Engine Room, & Fan Room East, Gym Office, 1925		TSI	Yes	None	0		YES X NO

·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	MJP E/F/V on Fiberglass Pipe Insulation	70	LF	Boiler Room, Pump Room, #113 - 1895		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

L	Spray-On Duct Insulation	3000	SF	Engine Room & Fan Room East, 1925		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	J											
2017 - Fall: N	No Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

TSI

Asbestos

Type

Material

Category

Friable

Yes

None

0

Damage

Type

Damage

Units

Damage

Quantity

Change in Assessment Category

2016 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2018 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			
	_	•	

550

HA No

M

Material Description

Aircell Pipe Insulation

Material

Quantity

Material

Units

LF

Material Location

Boiler Room Lower

Toilet, 1895

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	MJP E/F/V on Aircell Pipe Insulation	65	LF	Boiler Room Lower Toilet, 1895		TSI	Yes	None	0		YES X NO

	•	
2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
0	Cardboard Pipe Insulation	275	LF	Pump Room & Boiler Room Lower Toilet, 1895		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Р	MJP E/F/V on Cardboard Pipe Insulation	40	LF	Boiler Room Lower Toilet, 1895		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Q	Carpet Mastic	1050	SF	Room 118 - NOT OBSERVED		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R	12" X 12" beige with brown & white streaks, VFT	6300	SF	Rooms 210, 212, 215, 216, 217, 218, 219, Rms 115, 117, 119, 121, 122 (Not Observed)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
S	12" X 12" beige with brown & white streaks, Mastic	6300	SF	Rooms 210, 212, 215, 216, 217, 218, 219, Rms 115, 117, 119, 121, 122 (Not Observed)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Т	Mastic (red carpet) - NOT OBSERVED	1200	SF	Rms 221, 222		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Chango											
	io Change											
Comments:												
2017 - Spring	յ։ No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					1							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
U	Mastic (brown & gray carpet) NOT OBSERVED	900	SF	Rms 220, 114		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments: 2017 - Fall: No Change					-							

Comments:

2017 - Spring: No Change
Comments:

2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

2018 - Spring : No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
V	Mastic (green 7 brown carpet) - NOT OBSERVED	750	SF	Rm 118- NOT OBSERVED		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
W	Fire Brick Kiln-Bricks (Oven)	24	SF	Rm 120		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
X	Cloth- rope insulation/gasket for fire brick-kiln oven	16	LF	Rm 120		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: F	ranklin Elementary Fine Arts Center
Date: 2	2/8/2019
	tify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of
	s Management Plan is available at each school during school hours by appointment.
Requests to	review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please I	be advised that CPS conducts asbestos inspections of all Schools every three years.
	pection was completed in 2016.
Asbestos sui	rveillances are conducted every six months.
CHECK ONE	
A cop	y of this notice was sent home in each child's backpack.
A cop	y of this notice was printed in the school's newsletter and sent home with each child
A cop	y of this notice was printed in the school's calendar and sent home with each child
Other	
<u></u>	
A COPY (OF THIS NOTICE MUST BE PLACED IN THE
	OOL'S ASBESTOS MANAGEMENT PLAN.