Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Asa Philip Randolph Elementary School 29111 3550 School: **Oracle Unit: Building ID:** Address: 7316 S. Hoyne Region: 05 Mail Room: Asbestos Surveyor: Grebenor, John X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/13/2018 Email Address: A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type YES 02 2' x 4' wormy ceiling tile SF X NO 44000 Miscellaneous Yes None 0 throughout 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Oracle Unit: 29111

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
03	2' x 4' ceiling tile (smooth)	600	SF	serving area (kitchen)		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change				_							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:												
2018 - Spring	: No Change											
Comments:					-							
2018 - Fall: N	lo Change				-							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	12" x 12" Glue-on Ceiling Tile	2800	SF	Room 115 & office		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
04A	12" x 12" ceiling tile mastic	2800	SF	room 115 & office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change									·		
Comments:												
2017 - Sprin	g: No Change				<u></u>							
Comments:												
2017 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:	J											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	12" x 12" Salmon Floor Tile	9000	SF	throughout 1st floor corridor theater		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05A	Mastic Associated w/ 12" x 12" Salmon Floor Tile	9000	SF	throughout 1st floor corridor theater		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	12" x 12" Orange Floor Tile	400	SF	room 208,115		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

06A	Mastic Associated w/ 12" x 12" Orange Floor Tile	400	SF	room 208,115		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Chango										
	io Change										
Comments:											
2017 - Spring	յ։ No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2018 - Spring	j : No Change										
Comments:	•										
2018 - Fall: N	lo Change										
Comments:											
L					1						

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	12" x 12" Tan Floor Tile	4500	SF	2nd flr. Men restrm., portion kindergarten vault, workshop, gym,art room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

		Quantity	Units		Туре	Category		Type	Quantity	Units		
07A	Mastic Associated w/ 12" x 12" Tan Floor Tile	4500	SF	2nd flr. Men restrm., portion kindergarten vault, gym,art room		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I. No Change			·	j							
	2016 - Fall: No Change Comments:											
2017 - Spi	ring: No Change											
Comments	3:											

Material

Friable

Damage

Damage

Asbestos

2017 - Spring: No Change
Comments:

2017 - Fall: No Change
Comments:

2018 - Spring : No Change
Comments:

2018 - Fall: No Change

Material

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	12" x 12" White Floor Tile	63	SF	stair landing- east, west & center		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
08A	Mastic Associated w/ 12" x 12" White Floor Tile	63	SF	stair landing- east, west & center		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	-											
2018 - Spring	ı : No Change											
Comments:	J											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	12" x 12" Green Floor Tile	6000	SF	throughout 2nd floor corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
09A	Mastic Associated w/ 12" x 12" Green Floor Tile	6000	SF	throughout 2nd floor corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	insulation	2000	SF	inside walls of large group room (theater)		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
12	drywall	6500	SF	throughout		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:					4							
2017 - Spring	g: No Change											
Comments:	,											
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	baseboard	20000	LF	throughout		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
13A	baseboard mastic	20000	LF	throughout		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:					-							
2017 - Fall: N	lo Change											
Comments:	_											
2017 - Spring	: No Change											
Comments:												
2018 - Spring	: No Change				-							
Comments:	•											
2018 - Fall: N	lo Change				-							
Comments:	<u> </u>											
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	fire brick - REMOVED			incinerator room							YES X NO
					•						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 10

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
16	Blue and green carpet mastic			Kindergarten		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>											
2017 - Spring	g: No Change				_							
Comments:												
2017 - Fall: N	lo Change											
Comments:					1							
	ı : No Change				-							
Comments:					1							
2018 - Fall: N	lo Change											
Comments:					1							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	lab table tops	600	SF	room 208		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 11

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
31	spray on ceiling	88000	SF	throughout		Surface	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2040 O. d. N. Obrasa
2018 - Spring : No Change
Comments:Poor condition
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12" x 12" Light Beige w/ Dark Spots Floor Tile	1600	SF	Room 111, Main Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Mastic Associated w/ 12" x 12" Light Beige w/ Dark Spots Floor Tile	1600	SF	Room 111, Main Office		Miscellaneous	No	None	0		YES X NO
		•	•		! 1	•	•				

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12" x 12" Brown w/ Lt. Brown Spots Floor Tile	200	SF	Main Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Mastic Associated w/ 12" x 12" Brown w/ Lt. Brown Spots Floor Tile	200	SF	Main Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
AA	12"x12" Gray w/ White Specks Floor Tile	6300	SF	Room 210,211,212,215,216,217 ,220		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
AA1	Mastic Associated w/ 12" x12" Gray w/ White Specks Floor Tile	6300	SF	Rooms 210,211,212,215,216,217 ,220		Miscellaneous	No	None	0		YES	X NO
0040 5 11 11	. 01	•	•	•	1	•	•	•	•	•	•	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	fiberglass fittings	10	FITTING	1st & 2nd throughout, Boiler Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	ment Category
CM-1	grey carpet mastic	80000	SF	1st & 2nd floor classrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	<u> </u>]							
2017 - Fall: N	lo Change				_							
Comments:												
2017 - Spring	j: No Change											
Comments:					_							
2018 - Fall: N	lo Change]							
Comments:					_							
	j : No Change				<u> </u>							
Comments:					_							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	duct insulation - REMOVED			mechanical room		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
FT-1	12" X 12" beige floor tile	2600	SF	academic interest center		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
2017 - Spring Comments:	g: No Change				-							
2017 - Fall: N	No Change				<u>-</u> -							
2018 - Spring Comments:	g : No Change											
2018 - Fall: N	No Change] - -							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT-2	12" X 12" Mottled Floor Tile	80	SF	room 1141		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
FTM-1	12x12 beige floor tile mastic	2600	SF	academic interest center		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	-	1										
2017 - Spring	: No Change	=										
Comments:					-							
2017 - Fall: N	lo Change				_							
Comments:												
2018 - Spring	ı : No Change				_							
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FTM-2	12x12 mottled F.T. mastic, blue carpet	80	SF	room 114		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in /	Assessr	ment Category
VT	vinyl tread cover	160	SF	stairs		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change				7								
Comments:	_												
2017 - Spring: No Change													
Comments:													
2017 - Fall: N	No Change												
Comments:	•												
2018 - Sprin	g : No Change												
Comments:Fair condition													
2018 - Fall: N	2018 - Fall: No Change												
Comments:													

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
VTM	vinyl tread cover mastic	160	SF	stairs		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Asa Philip Randolph Elementary School
Date: 12/13/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 29111

SCHOOL'S ASBESTOS MANAGEMENT PLAN.