Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Galileo Math & Science Scholastic Academy ES 29141 4160 School: **Oracle Unit: Building ID:** Address: 820 S. Carpenter Region: 03 Mail Room: Asbestos Surveyor: Gonzalez, Armin X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/10/2019 Email Address: agonzalez606@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type YES Hard Plaster X NO Throughout 1909 Building Surface 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

2	Hard Plaster			Throughout 1895 Building		Surface					YES X NO	
2016 - Fall: N	o Change]							
Comments:	¥											
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Cateo	jory
3	Wains Coat Molding	5000	SF	Throughout 1909 Building		Miscellaneous	No	None	0		YES X NO	

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

Page 2

4	Wains Coat Molding	5000	SF	Throughout 1895 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	-											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
5	9"x9" Light Green Floor Tile w/ White Marbling	400	SF	Basement Store Room,		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

6	9"x9" Dark Green Floor Tile w/ White Marbling	400	SF	Basement Store Room		Miscellaneous	No	None	0	YES	X NO
					1						
2016 - Fall: N	o Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7	9"x9" Dk. & Lt. Green Floor Tile Mastic	400	SF	Basement Store Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

8	9"x9" Black Floor Tile - REMOVED			Engineer's Office		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				1							
Comments:	10 Onango											
2017 - Fall: N	No Change											
Comments:												
0047 Caria	No Observe											
	g: No Change				4							
Comments:												
2018 - Fall: N	Jo Change											
Comments:	10 Onlange				1							
Comments.												
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
	,	Quantity	Units		Type	Category		Туре	Quantity	Units	_	
9	9"x9" Red Floor Tile -			Engineer's Office		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

10	9"x9" Red & Black Floor Tile Mastic- Abated			Engineer's Office		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>				1							
2017 - Fall: N	lo Change											
Comments:					 							
2017 - Spring	g: No Change											
Comments:					 							
2018 - Fall: N	lo Change											
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
11	9"x9" Green Floor Tile w/ White Marbling			Kitchen & Teacher's Lunch Room (Abated 2003)		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

12	9"x9" Green & White Floor Tile Mastic			Kitchen & Teacher's Lunch Room (Abated 2003)		Miscellaneous					YES	X NO
2016 Fall	l. No Changa											
	l: No Change											
Comments	S:											
2017 - Fall	l: No Change											
Comments												
2017 - Spr	ring: No Change											
Comments	3:											
2018 - Fall	l: No Change											
Comments	S:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

Friable

No

Damage

Туре

None

0

Damage

Quantity

Damage

Units

	· ·		
2016 - Fall: N	lo Change		
Comments:			
2017 - Fall: N	lo Change		
Comments:			
2017 - Spring	j: No Change		
Comments:			
2018 - Fall: N	lo Change		
Comments:			

700

HA No

14

Material Description

12"x12" Cream Floor Tile

w/Tan Specks

Material

Quantity

Material

Units

SF

Material Location

Kitchen & Teacher's

Kitchen, 2nd & 3rd Floor

Teacher's Rooms

Change in Assessment Category

X NO

YES

15	12"x12" Pale Brn Floor Tile w/Crm & Dk. Brn Specks	700	SF	Kitchen, 2nd & 3rd Floor Teacher's Rooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change				7							
Comments	s:											
2017 - Fal	I: No Change				_							
Comments	S:				_							
	ring: No Change											
Comments	S:											
	I: No Change											
Comments	S:				_							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
	12"x12" Brn Floor Tile			2nd & 3rd Floor								

Type

Material

Category

Miscellaneous

Friable

Damage

Туре

Damage

Quantity

Material

Units

Material

Quantity

Material Location

Teacher's Rooms

(Kitchen Abated 2003)

Kitchen, 2nd & 3rd Floor

HA No

16

Material Description

w/Crm & Dk. Brn Spks

Mastic

12"x12" Pale Brn Floor Tile

Change in Assessment Category

YES

YES

X NO

Damage

Units

17	12"x12" Dark Brown Floor Tile w/ Crm & Red			Lunch Room		Miscellaneous					YES	X NO
2016 - Fall: N	Vo Change				1							
Comments:	10 Orlange											
					1							
2017 - Fall: N	No Change											
Comments:												
0047 On the	a. Na Ohanas				_							
	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
18	12"x12" Dk Brn Floor Tile w/ Crm & Red Mastic			Lunch Room		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

19		12"x12" Coffee Floor Tile w/Cream Specks			Principal's Office (Removed 2003)		Miscellaneous					YES	X NO
2016	i - Fall: N	o Change											
	ments:	J											
2017	' - Fall: N	o Change											
Com	ments:												
2017	' - Spring	: No Change											
Com	ments:												
2018	- Fall: N	o Change											
Com	ments:												
HA N	0	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
20		12"x12" Coffee Floor Tile w/Cream Specks Mastic			Principal's Office (Abated)		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

w/Cream Specks Mastic

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material

Units

Material

Quantity

Material Location

(Abated)

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	9"x9" Coffee Floor Tile w/ Cream Specks	3012	SF	104, 106, 205, 206, 207, 304. 305, 307, 309		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	9"x9" Coffee Floor Tile w/ Cream Specks Mastic	3012	SF	104, 106, 205, 206, 207, 304. 305, 307, 309		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	9"x9" Tan w/Rust & Cream Marbling	3012	SF	104, 106, 205, 206, 207, 304. 305, 307, 309		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	9"x9" Tan w/Rust & Cream Marbling Mastic	3012	SF	104, 106, 205, 206, 207, 304. 305, 307, 309		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

25	9"x9" Black Floor Tile w/ White Marbling			105		Miscellaneous					YES	X NO
2016 - Fa	all: No Change											
Commen												
2017 - Fa	all: No Change											
Commen												
2017 - Sp	oring: No Change											
Commen	ts:											
2018 - Fa	all: No Change											
Commen	ts:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
26	9"x9" Black Floor Tile w/ White Marbling Mastic			105		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

White Marbling Mastic

27	9"x9" Coffee Floor Tile w/Cream Specks			212, 213		Miscellaneous					YES	X NO
2016 - Fall	: No Change											
Comments												
2017 - Fall	: No Change											
Comments	:											
	ing: No Change											
Comments	:											
2018 - Fall	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
		_	+	+		_				+	+	

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

28

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

9"x9" Coffee Floor Tile

9"x9" Coffee Floor Tile

w/Cream Specks Mastic

Material

Quantity

Material

Units

Material Location

212 & 213

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" Multi-Cream w/Tan Specks Floor Tile	1390	SF	101		Miscellaneous	No	None	0		YES X NO
0040 Fall N	- Oh				1						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12"x12" Multi-Cream w/Tan Specks Floor Tile Mastic	1390	SF	101		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

31	2'x4' Lay In Ceiling Panels	1568	SF	Lounge, Offices, 101, 102, 111, 112, 113		Miscellaneous	No	None	0		YES	X NO
0040 Fa	II NI OL TO TO				_							
	II: No Change											
Comment	s:											
2017 - Fa	II: No Change											
Comment	s:											
2017 - Sp	ring: No Change											
Comment	s:											
2018 - Fa	II: No Change											
Comment	S:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Asbestos

Type

Material

Category

Miscellaneous

Category

Friable

No

Damage

Type

None

Type

Damage

Quantity

Damage

Quantity

0

Damage

Damage

Units

Units

			Louinge & Washilooni
2016 - Fall: No	Change		
Comments:			
2017 - Fall: No	Change		
Comments:			
2017 - Spring: I	No Change		
Comments:			
2018 - Fall: No	Change		
Comments:			

Quantity

1600

HA No

32

Material Description

Drywall & Joint Compound

Material

Units

SF

Units

Material Quantity Material Location

Teachers Washroom &

1st Floor Teacher's

Lounge & Washroom

E&W Boys Playrooms,

Change in Assessment Category

X NO

YES

YES

33	2'x4' Black Border Floor Tile			Lunch Room		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				7							
Comments:												
2017 - Fall: N	No Change				-							
Comments:	J				-							
2017 - Spring	g: No Change				-							
Comments:												
2018 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
34	2'x4' Black Border Floor Tile Mastic			Lunch Room		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

Material

Quantity

Material

Units

35	w/Charcoal Streaks			Lunch Room		Miscellaneous					YES	X NO
2016 - Fall:	No Change				\neg							
Comments	•											
2017 - Fall:	No Change											
Comments												
	ng: No Change											
Comments												
2018 - Fall:	No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
36	12"x12" White Floor Tile			Lunch Room		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

37	Interior Brick			Throughout 1909 Building		Miscellaneous					YES	X NO
2016 - Fall: N	o Change]							
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
38	Interior Brick Mortar			Throughout 1909 Building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

39	Interior Brick			Throughout 1895 Building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	•											
2018 - Fall: N	lo Change											
Comments:	Ţ											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	ssment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
40	Interior Brick Mortar			Throughout 1895 Building		Miscellaneous					YES	X NO
			L		1		I .	1	L	L	<u> </u>	

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Units

Material

Quantity

Material Location

41	Glazed Brick			Throughout 1895 Building		Miscellaneous					YES	X NO
2016 - Fall: No	o Change											
Comments:												
2017 - Fall: No	o Change											
Comments:												
2017 - Spring:	: No Change											
Comments:												
2018 - Fall: No	o Change											
Comments:												
L					I							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
42	Glazed Brick Mortar	,		Throughout 1895 Building	71	Miscellaneous		, ,	,		YES	X NO
HA No		Material Quantity	Material Units		Asbestos Type	Category	Friable	Damage Type	Damage Quantity	Damage Units		

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

43	Cinder Block			Throughout 1895 Building		Miscellaneous					YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:	•											
2018 - Fall: N	o Change											
Comments:	-											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
44	Cinder Block Mortar			Throughout 1895 Building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Units

Material

Quantity

Material Location

45	Sink Caulk			Boy's & Girl's Basement Washrooms		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					I							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
46	Window Caulk			Throughout Facility		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Units

Material

Quantity

Material Location

47	Door Caulk			East and West Basement Entry Doors		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				1							
Comments:	to onango											
2017 - Fall: N	No Change				-							
Comments:	10 Onlange				-							
2017 - Spring	g: No Change											
Comments:	g. 140 Ghange											
2018 - Fall: N	No Change											
Comments:	10 Onlange				-							
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
48	Boiler Gaskets			Boiler #1 - Replaced		Miscellaneous					YES	X NO
2016 - Fall: N	No Change	•	•	•]	•	•			•		

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Units

Material

Quantity

Material Location

49	Boiler Gaskets			Boiler #2 - Replaced		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
50	Spray On Fireproofing on Ceiling			Boiler Room & Tank Room		Surface					YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

51	Purple Carpet Mastic			Office, Asst. Principal's Office, Office		Miscellaneous					YES	X NO
2016 - Fall:	No Change]							
Comments:					_							
2017 - Fall:	No Change											
Comments:	-											
2017 - Sprir	ng: No Change											
Comments:												
2018 - Fall:												
Comments:												
					<u></u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
52	Blue Carpet Mastic REMOVED			Rooms 107 (Office and Storage Areas)/108		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

-

Units

Material Location

Main Office, Principal's

HA No

Material Description

Material

Quantity

Material

Units

53	Man Hole & Hand Hole Boiler Gaskets - REMOVED			Boiler #1		Miscellaneous					YES	X NO
2016 - Fal	I: No Change				7							
Comment												
2017 - Fal	I: No Change				-							
Comment	3				-							
2017 - Sp	ring: No Change				1							
Comment	3:											
2018 - Fal	I: No Change											
Comment	3:											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
54	Man Hole & Hand Hole Boiler Gaskets - REMOVED			Boiler #2		Miscellaneous					YES	X NO
2016 - Fal	I: No Change]							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Units

Material

Quantity

Material Location

	'	Quantity	Units		Type	Category		Type	Quantity	Units		0 ,
55	Fire Brick - REMOVED			Boiler #1		Miscellaneous					YES	X NO
2016 - Fall:	: No Change											
Comments												
2017 - Fall:	: No Change											
Comments	:											
2017 - Spri	ng: No Change											
Comments	:											
	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
56	Fire Brick - REMOVED			Boiler #2		Miscellaneous					YES	X NO
2016 - Fall:	: No Change											
Comments												

Material

Asbestos

Friable

Damage

Damage

Damage

HA No

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material Description

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	Insulation Inside of Vault Door	30	SF	Main Office		TSI	No	None	0		YES X NO
2016 - Fall: N	lo Change]						

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	12" x 12" Off White w/Blue Specks VFT	2500	SF	Principal's Office, Main Office, library		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	ent Category
59	12" x 12" Off White w/Blue Specks VFT Mastic	2500	SF	Principal's Office, Main Office, Library		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

016 - Fall: No Change	
Comments:	
017 - Fall: No Change	
Comments:	
017 - Spring: No Change	
Comments:	
018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	12"x12" Off White w/Blue & Gray Specks VFT	925	SF	Room 113/114		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
61	12"x12" Off White w/Blue & Gray Specks VFT Mastic	925	SF	Room 113/114		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:	_											
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:			•									

Н	IA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6	52	12"x12" Off White w/Blue & Gray Streaks VFT	1418	SF	Room 102/103		Miscellaneous	No	None	0		YES X NO

	_			
2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change	 	<u> </u>	
Comments:				
2017 - Spring	: No Change	 	<u> </u>	
Comments:				
2018 - Fall: N	o Change			
Comments:				

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
63	12"x12" Off White w/Blue & Gray Streaks VFT Mastic	1418	SF	Room 102/103		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	2016 - Fall: No Change											
2017 - Fall: N	lo Change	<u> </u>										

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	12"x12" Off White w/Blue & Gray Specks VFT	172	SF	Teacher's Washroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
65	12"x12" Off White w/Blue & Gray Specks VFT Mastic	172	SF	Teacher's Washroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:												
2017 - Spring	r. No Change				-							
Comments:	j. 110 Onango]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	12"x12" Off White w/Blue & Gray Specks VFT	1215	SF	Room 107		Miscellaneous	No	None	0		YES X NO

2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				

2018 - Fall: No Change

Comments:

2016 - Fall: I	No Chango				7						
	No Change										
Comments:											
2017 - Fall: I	No Change										
Comments:											
0047 Oznin	a. Na Ohana				4						
2017 - Sprin	g: No Change										
Comments:											
2018 - Fall: I	No Change										
Comments:											
		·									
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

HA No

67

68

Comments:

Comments:

Comments:

Comments:

Material Description

12"x12" Off White w/Blue &

Gray Specks VFT Mastic

12"x12" Off White w/Black

Specks VFT

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material

Quantity

1215

Material

Units

SF

Material Location

1st Floor Corridor - 1895

Building

Room 107

Change in Assessment Category

X NO

X NO

YES

YES

69	12"x12" Off White w/Black Specks VFT			1st Floor Corridor - 1895 Building		Miscellaneous		None			YES	X NO
2016 - Fall: N	No Change											
Comments:	10 Onlango											
2017 - Fall: N	No Change				-							
Comments:	to onlango											
2017 - Spring	g: No Change				-							
Comments:												
2018 - Fall: N	No Change				-							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
70	Sink Undercoating			Room 106		Surface					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

Material

Quantity

Material

Units

71	6" x 6" Brown Quarry Tile	2313	SF	Lunchroom and Lunchroom.		Miscellaneous	No	None	0		YES	X NO
0040 5-11 1	1. 01		•		7							
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:	-											
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:	-											
			•									
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category	1	Type	Quantity	Units		

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

Damage

Quantity

Damage

Units

12	Mastic	2010	O.	Lunchroom.	
2016 - F	all: No Change				
Comme					
2017 - F	Fall: No Change				
Comme					
2017 - 5	Spring: No Change				
Comme	 				
2018 - F	all: No Change				
Comme	nts:				

2313

SF

Material

Quantity

Material

Units

Material Location

Kitchen, Teacher's

Kitchen, Teacher's

Luchroom and

HA No

72

Material Description

6" x 6" Brown Quarry Tile

Mastic

YES

X NO

73	12"x 2" Off-White w/ Grey & Blue Specs Floor Tile	700	SF	Principal's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
	No Change				1							
Comments:					-							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Friable

No

Miscellaneous

Damage

Туре

None

0

Damage

Quantity

Damage

Units

74	w/gray&blue specks FT Mastic	700	SF	Principal's Office
0040 5 11 11	01			
2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				
		•		

Material

Quantity

Material

Units

Material Location

HA No

Material Description

12"x12" Off-White

YES

X NO

75	Streaks Floor Tile - REMOVED			Engineer's Office		Miscellaneous					YES	X NO
2016 - Fall	: No Change	•	•			•	•	•	•	•	•	
Comments												
2017 - Fall	: No Change											
Comments	<u> </u>											
2017 - Spr	ing: No Change											
Comments): -											
2018 - Fall	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
76	12" X 12" White W/Grey Streaks Floor Tile Mastic -			Engineer's Office		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

77	12" X 12" White W/Blue Streaks Floor Tile	2308	SF	School Elevators, Nurse office, Room 314, 306, 114, 113	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:	-									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
78	12" X 12" White W/Blue Streaks Floor Tile Mastic	2308	SF	School Elevators, Room 314, 306, 114, 113, Nurse Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

	material Decemption	Quantity	Units	material <u>s</u> ecution	Туре	Category	1110010	Type	Quantity	Units	onango my toda	oomoni calegoly
79	12" X 12" Black W/White Streaks Floor Tile	5370	SF	1895 Building basement corridor and 1909 building basement corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:	<u> </u>				-							
2017 - Fall: No Change												
Comments:	Comments:											

Material

Damage

Damage

Damage

Friable

2017 - Spring: No Change
Comments:

Material

Material

Material Location

2018 - Fall: No Change Comments:

Material Description

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
80	12" X 12" Black W/White Streaks Floor Tile Mastic	5370	SF	1895 Building Basement Corridor and 1909 Building Basement Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

81	12" x 12" White Floor Tile w/ Blue Streaks	7612	SF	Rooms 212 and 213, 2nd & 3rd Floor Teacher Rooms, Kitchen, Lunch Room, Basement Lunch Room, 1st Floor Principal's Office		Miscellaneous	No	None	0		YES X NO
2016 - Fal	: No Change										
Comments	•										
2017 - Spr	ing: No Change										
Comments): 										
2017 - Fal	: No Change										
Comments	S:										
2018 - Fal	: No Change										
Comments	S:										
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

Type

Asbestos

Type

Material

Category

Category

Friable

Type

Damage

Туре

Damage

Quantity

Quantity

Damage

Units

Units

82	12" x 12" White Floor Tile w/ Blue Streaks Mastic	7612	SF	Rooms 212 and 213, 2nd & 3rd Floor Teacher Rooms, Kitchen, Lunch Room, Basement Lunch Room, 1st Floor Principal's Office	Miscellaneous	No	None	0	YES
2016 - F	all: No Change								
Commer									
2017 - S	Spring: No Change								
Comme	nts:								
2017 - F	all: No Change								
Comme	nts:								

HA No

2018 - Fall: No Change

Comments:

Material Description

Material

Units

Material

Quantity

Quantity

Units

Material Location

Rooms 212 and 213, 2nd

Change in Assessment Category

X NO

Α	Aircell Pipe Insulation - REMOVED			1909 Building		TSI					YES	X NO
2016 - Fall: N	No Change											
Comments:	10 Oriango											
2017 - Fall: N	No Change				_							
Comments:	10 Orlango											
2017 - Spring	g: No Change				-							
Comments:]							
2018 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
В	Cardboard Pipe Insulation			1909 Building		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

2016 - Fall: No Change

Comments:

Material Description

Material

Quantity

Material

Units

Page 42

С	Cementitious Pipe Joint Insulation off Fiberglass			1909 Building		TSI					YES	X NO
2016 - Fall: N	No Change				7							
Comments:	<u> </u>]							
2017 - Fall: N	No Change											
Comments:												
	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
D	Pipe Cover			1909 Building		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

2016 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Е	Mag Block Insulation on Boiler			Boiler Room		TSI					YES	X NO
2016 - Fall: N	o Change]							
Comments:					1							
2017 - Fall: N	o Change				1							
Comments:					1							
2017 - Spring	: No Change				-							
Comments:					-							
2018 - Fall: N	o Change				1							
Comments:					1							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
F	Cementitious Joint Insulation on Cardboard Lagging			1909 Building		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

G	Boiler Gaskets - REMOVED			Boiler Room							YES	X NO
2016 - Fall: N	No Change				7							
Comments:					1							
2017 - Fall: N	No Change				-							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:					-							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
Н	Aircell Pipe Insulation			1895 Building		TSI					YES	X NO
2016 - Fall: N	No Change]							
Comments:	J											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

Material Description

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material

Quantity

Material

Units

Material Location

1	Cardboard Pipe Insulation			1895 Building		TSI					YES	X NO
2016 - Fall: I	No Change				7							
Comments:					1							
2017 - Fall: I	No Change				_							
Comments:					_							
	g: No Change											
Comments:					-							
2018 - Fall: I	No Change											
Comments:					-							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
J	Cementitious Joint Insulation on Cardboard Lagging			1895 Building		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

К	Mag Block Pipe Insulation			Kitchen & Lunch Room		TSI					YES	X NO
2016 - Fall	: No Change				1							
Comments												
2017 - Fall	: No Change											
Comments	:											
2017 - Spr	ing: No Change											
Comments	:											
	: No Change											
Comments	:											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
L	Felt Pipe Insulation			1895 Building		TSI					YES	X NO
2016 - Fall: No Change]		•					

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Units

Material

Quantity

Material Location

М	Cementitious Joint Insulation on Felt Lagging			1895 Building		TSI					YES	X NO
2016 - Fall:	No Change											
Comments:												
	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:	<u> </u>											
2010 Falls	No Chango											
2018 - Fall:	<u> </u>											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
N	Cementitious Joint			1000 Puilding		TOI					Dyreo I	Z NO

Type

Material

TSI

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

1909 Building

HA No

Ν

Material Description

Insulation on Felt Lagging

Cementitious Joint

YES

X NO

	0	Mag Block Pipe Insulation			1909 Building		TSI					YES	X NO
I	2016 - Fall: N	o Change]							
	Comments:	-											
	2017 - Fall: No Change												
	Comments:					-							
	2017 - Spring	: No Change				1							
	Comments:					-							
	2018 - Fall: N	o Change											
	Comments:					-							
						1							
	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
	Р	Mag Block Pipe Joint			1895 Building		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Material

Quantity

Material

Units

HA No

Material Description

Insulation

C	2	Mag Block Pipe Joint Insulation			1909 Building		TSI					YES	X NO
2	016 - Fall: N	o Change				7							
_	comments:	<u> </u>]							
2	017 - Spring	No Change											
С	comments:					_							
_	017 - Fall: N	o Change]							
С	comments:					1							
_	018 - Fall: N	o Change											
С	comments:					_							
<u> </u>						J							
F	IA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
F	₹	Cementitious Joint Insulation on Aircell			1895 Building		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

Mag Block Pipe Joint

Lagging

Material

Quantity

Material

Units

S	Cementitious Joint Insulation on Aircell Lagging			1909 Building		TSI					YES	X NO
2016 - Fall:	No Change				j	·						
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	<u>~</u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
Т	Cementitious Joint Insulation on Fiberglass Pipes			1895 Building		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
U	Duct Insulation			Engine Room		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

	ath & Science Scholastic Academy ES
Date: 1/10/2019	
the Asbestos Manage	accordance with Illinois and Federal Asbestos Regulations, that a copy of ment Plan is available at each school during school hours by appointment.
Requests to review th	e Asbestos Management Plan must be made at least 24 hours in advance.
The last inspection wa	nd that CPS conducts asbestos inspections of all Schools every three years. as completed in 2016. s are conducted every six months.
CHECK ONE	
A copy of this no	otice was sent home in each child's backpack.
A copy of this no	otice was printed in the school's newsletter and sent home with each child
A copy of this no	otice was printed in the school's calendar and sent home with each child
Other.	
A COPY OF THIS	NOTICE MUST BE PLACED IN THE
	BESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.