Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

29201 Mark Sheridan Math & Science Academy 4920 School: **Oracle Unit: Building ID:** Address: 533 W. 27th St. Region: Mail Room: Asbestos Surveyor: Frost, Steven X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/8/2019 Email Address: A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other Material Description HA No Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type Throughout 1881 YES X NO 1A Plaster Construction 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments:

Oracle Unit: 29201

2A	Tile- Perforated			Rooms 105							YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprii	ng: No Change											
Comments:												
	No Change											
Comments:												
	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
2B	2' X 4' Acoustical Ceiling Tile- Lightly Fissured			Room 105							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

2' X 4' Acoustical Ceiling

Material

Quantity

Material

Units

Material Location

2C	2' X 4' Fissured & Perforated Ceiling Tile			Room 008							YES	X NO
2016 - Fall: N	o Change]							
Comments:	o Onlange											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	2017 - Fall: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Туре	Category		Type	Quantity	Units		
2D	2' X 4' Gypsum Ceiling Tile			2nd Floor (Men's Room)							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3A	12" X 12" Floor Tile (Speckled/Tan)	4500	SF	1st FL-Toilet, 2nd FL- Janitor's Closet, Room 311, 008, 3rd floor hallway, 009,210,108		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3B	12" X 12" Floor Tile (Red/Speckled)	3000	SF	Rooms 106, 206, 203		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 4

3C	12" X 12" Floor Tile (Dark Beige)	300	SF	2nd FL- Janitor's Closets (Right & Left), 3rd FL Janitor's Closet		Miscellaneous	No	None	0	YES	X NO
2016 - Fall	: No Change				1						
Comments					1						
2017 - Fall	: No Change										
Comments	:										
2017 - Spri	ing: No Change										
Comments	:				=						
2018 - Fall	: No Change										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3D	12" X 12" Floor Tile (Beige Marbled)	800	SF	Boy's Playroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

											1
					7						
2016 - Fall: N	No Change										
Comments:											
					1						
2017 - Fall: N	No Change										
Comments:											
2017 - Spring	g: No Change										
Comments:	-				1						
2018 - Fall: N	No Change										
Comments:	-				1						
					1						
					_						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

No

Damage

Type

None

Type

Damage

Quantity

Quantity

0

0

Damage

Units

Units

Change in Assessment Category

X NO

X NO

YES

YES

3F	12" X 12" Floor Tile (White)	800	SF	Room 008	Miscellaneous	No	None
2016 - F	all: No Change						
Comme	nts:						
2017 - F	all: No Change						
Comme	nts:						
2017 - S	Spring: No Change						
Comme	nts:						
2018 - F	all: No Change						

HA No

3E

Comments:

Material Description

12" X 12" Floor Tile

(Cream)

Material

Quantity

Quantity

Units

800

Material

Units

SF

Material Location

Girl's Playroom

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment	Category
3G	12" X 12" Floor Tile (Light Tan Patches)	2000	SF	101, 3rd FL Hallway		Miscellaneous	No	None	0		YES	NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3H	12x12 Gray FT W/White, Gray Specks	1080	SF	Engineer Office and Adjacent Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4A	Mastic for 12x12 Speckled/Tan Floor Tile	11000	SF	008, 009, 210, Basement LR,See HA 3A Locations, 108, 311, 3rd floor halway, first floor toilet, 2nd floor janitors closet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4B	Mastic for 12x12 Red/Speckled Floor Tile	2100	SF	Rooms 206, 203		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

4C	Mastic for 12x12 Floor Tile (Dark Beige)			2nd and 3rd Floor Janitor's Closets							YES	X NO
2016 - Fal	: No Change											
Comments	S:											
2017 - Fal	: No Change											
Comments	S:											
	ing: No Change											
Comments	S:				_							
2018 - Fal	: No Change											
Comments	S:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
4D	Mastic for 12x12 Floor Tile (Beige Marbled)			Boy's Playroom							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

Material

Quantity

Material

Units

4E	Mastic for 12x12 Floor Tile (Cream)			Girl's Playroom							YES	X NO
2016 - Fall: I	No Change				7							
Comments:												
2017 - Fall: I	No Change				-							
Comments:	J											
2017 - Sprin	g: No Change				1							
Comments:												
2018 - Fall: I	No Change				1							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
4F	Mastic for 12x12 Floor Tile (White)			room 008							YES	X NO
2016 - Fall: I	No Change											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
4G	Mastic for 12x12 Floor Tile (Light Tan Patches)	40	SF	101, 3rd Floor Hallway		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4H	12x12 gray FT W/White, Gray Specks Mastic	1080	SF	Engineer Office and Adjacent Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

	·	Quantity	Units		Type	Category		Туре	Quantity	Units		
5	Plaster Walls			1902 building							YES	X NO
2016 - Fall: N	No Change											
Comments:												
	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
				T								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
6	Black Vinyl Cove Base			Basement, 1st, 2nd							YES	X NO
2016 - Fall: N	No Change											
Comments:												

Material

Friable

Damage

Damage

Damage

HA No

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material Description

Material

Material

Material Location

	·	Quantity	Units		Type	Category		Туре	Quantity	Units		
6A/7	Adhesive for Black Vinyl Cove Base			Basement, 1st, 2nd							YES	X NO
2016 - Fall:	No Change											
Comments:	J											
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
8	Plaster on Sheetrock			Basement							YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change				\dashv							

Material

Friable

Damage

Damage

Damage

HA No

Comments:

Comments:

Comments:

2017 - Fall: No Change

2018 - Fall: No Change

Material Description

Material

Material

Material Location

9	Sheetrock			Scattered							YES	X NO
2016 - Fall:	No Change	•			1					•		
Comments:												
2017 - Fall:	No Change				-							
Comments:					1							
2017 - Sprir	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:					-							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
9A	Joint Compound on Sheetrock			Scattered							YES	X NO
2016 - Fall:	No Change	·	·	<u> </u>	7							
Comments:												

Material

Category

Asbestos

Type

Damage

Quantity

Damage

Units

Damage

Type

Friable

HA No

Material Description

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material

Units

Material

Quantity

Material Location

	· ·	Quantity	Units		Туре	Category		Туре	Quantity	Units		3 ,
11	Caulk			2nd Floor Urinals							YES	X NO
2016 - Fall	: No Change											
Comments												
2017 - Spr	ing: No Change											
Comments												
2017 - Fall	: No Change											
Comments												
2018 - Fall	: No Change											
Comments):											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
12	4"x4" White Ceramic Tile			2nd Floor Walls							YES	X NO
2016 - Fall	: No Change											
Comments												

Material

Asbestos

Friable

Damage

Damage

Damage

HA No

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material Description

Material

Material

Material Location

12A	Ceramic Tile			2nd Floor Walls							YES	X NO
2016 - Fall: N	No Change				\neg							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:					_							
2018 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
12B	Mastic for 4"x4" White Ceramic Tile			2nd floor walls							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

13	1"x1" Pastel Ceramic Tile			Floors							YES	X NO
2016 - Fal	I: No Change											
Comment												
2017 - Fal	I: No Change											
Comment	s:											
2017 - Sp	ring: No Change											
Comment	S:											
2018 - Fal	I: No Change											
Comment	S:				_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
13A	Grout for 1"x1" Pastel			2nd Floor Restroom							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

13B	Mastic for 1"x1" Pastel Ceramic Tile			2nd Floor Restroom Floors							YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprii	ng: No Change				_							
Comments:												
2017 - Fall:	No Change											
Comments:	<u> </u>				1							
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
14	1"x1" Dark Multi-Colored Ceramic Tile			Basement Restrooms and Entry to 1st Floor Boy's Restroom							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

14A	Grout for 1"x1" Dark Multi- Colored Ceramic Tile			Basement Restrooms and Entry to 1st Floor Boy's Restroom							YES	X NO
0040 5-11	N. Olasas	•	•	•	_ _		•				•	
	: No Change											
Comments	:											
2017 - Spri	ing: No Change											
Comments	:											
2017 - Fall	: No Change											
Comments	:											
2018 - Fall	: No Change											
Comments	<u>~</u>											
-	•				-							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	esment Category
11/(140	Waterial Description	Quantity	Units	Waterial Ecoation	Type	Category	THADIO	Type	Quantity	Units	Change in 710000	osment outegory
	Adhesive for 1"x1" Dark			Basement Restrooms								
14B	Multi-Colored Ceramic Tile			and Entry to 1st Floor							YES	X NO
l				Boy's Restroom				1	1		1	

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

	·	Quantity	Units		Туре	Category		Туре	Quantity	Units		
15	Wood Window Glaze			1881- Interior Hallways							YES	X NO
2016 - Fall:	No Change				7							
Comments:	-											
2017 - Fall:	No Change											
Comments:					-							
	ig: No Change											
Comments:					_							
2018 - Fall:	No Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
15A	Wood Window Glaze			1902- Interior Hallways							YES	X NO
2016 - Fall:	No Change											
Comments:					_							

Material

Friable

Damage

Damage

Damage

Material Location

HA No

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material Description

Material

Material

16	Metal Window Glaze			1976- Interior Abated 1999							YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Sprir	ng: No Change				-							
Comments:												
2017 - Fall:	No Change				-							
Comments:												
2018 - Fall:	No Change				-							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
17	Metal Window Caulk			1976- Exterior Not							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

18	New 2"x8" Brick			Interior							YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2047 Falls	No Change]							
2017 - Fall:					_							
Comments:					_							
2017 - Sprin	ng: No Change											
Comments:												
2018 - Fall:	No Change				-							
Comments:					1							
Commonto:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	ssment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
18A	Mortar for 2"x8" Brick			Interior							YES	X NO
2016 Falls	No Change		•	<u>'</u>	- 7	1			1			
2016 - Fall:					4							
Comments:												

Material

Category

Asbestos

Type

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material

Quantity

Material

Units

Material Location

19	2"x8" Glazed Brick			Restrooms							YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	<u> </u>											
2017 - Fall: N	lo Change				_							
Comments:					_							
2017 - Spring	g: No Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
19A	Mortar for 2"x8" Glazed Brick			Interior Basement Restrooms							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

Material

Quantity

Material

Units

	·	Quantity	Units		Type	Category		Туре	Quantity	Units		
20	Interior Brick			1881- Basement							YES	X NO
2016 - Fal	I: No Change	•						•		•		
Comments												
2017 - Fal	I: No Change											
Comments	3:											
	ring: No Change											
Comments	S:											
	l: No Change											
Comments	5:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
20A	Mortar for Interior Brick			1881- Basement							YES	X NO
2016 - Fal	I: No Change											
Comments												
2017 - Spi	ring: No Change											

Material

Friable

Damage

Damage

Damage

Material

Material

Material Location

HA No

Comments:

Comments:

Comments:

2017 - Fall: No Change

2018 - Fall: No Change

Material Description

		Quantity	Units		Type	Category		Туре	Quantity	Units		
21	Interior Brick			1902- Basement							YES	X NO
2016 - Fall: N	No Change				\neg							
Comments:	<u> </u>											
2017 - Fall: N	No Change											
Comments:	-											
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
21A	Mortar for Interior Brick			1902- Basement							YES	X NO
2016 - Fall: N	No Change											
Comments:												

Material

Friable

Damage

Damage

Damage

HA No

Material Description

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material

Material

Material Location

22	8"x16" Glazed Block			Basement Restrooms							YES	X NO
204C Falls N	Na Changa				7							
2016 - Fall: N	vo Change				4							
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change				1							
Comments:												
					1							
2018 - Fall: N	No Change				1							
Comments:	ge				1							
Comments.					1							
					1							
LIA No	Motorial Description	Motorial	Motorial	Motorial Logation	Ashastas	Motorial	Frieble	Domose	Domogo	Domoso	Change in Assess	amont Catagoni
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage Units	Change in Assess	sment Category
		Quantity	Ullis		Туре	Category		Туре	Quantity	Units		
22A	Mortar for 8"x16" Glazed			Basement Restrooms							Dvrc I	X NO
224	Block			Dasement Nestrooms							YES	X NO
	•	•	•	•	· 	•	•	•	•	•		
2016 - Fall: N	No Change											

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

	I I											
23	8"x16" Cinderblock			Scattered							YES	X NO
2016 - Fall: I	No Change]							
Comments:					1							
2017 - Fall: I	No Change											
Comments:					-							
	g: No Change											
Comments:												
2018 - Fall: I	No Change				-							
Comments:					1							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
23A	Mortar for 8"x16" Cinderblock			Scattered							YES	X NO
2016 - Fall: I	No Change	<u> </u>	·	<u>-</u>]							
Comments:	<u> </u>				1							

Material

Category

Asbestos

Type

Damage

Quantity

Damage

Units

Damage

Type

Friable

HA No

Material Description

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material

Units

Material

Quantity

Material Location

24	Exterior Brick- Not AHERA			1881- Exterior							YES	X NO
2016 - Fal	: No Change				7							
Comments												
2017 - Fal	: No Change				1							
Comments	S:											
2017 - Spr	ing: No Change											
Comments	S:											
2018 - Fal	: No Change											
Comments	S:											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
24A	Mortar for Exterior Brick- Not AHERA			1881- Exterior							YES	X NO
2016 - Fal	: No Change				7							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material Description

25	Exterior Brick- Not AHERA			1902- Exterior							YES	X NO
2016 - Fall: N	No Change]							
Comments:												
2017 - Fall: N	No Change				<u> </u>							
Comments:												
2017 - Sprin	g: No Change				<u> </u>							
Comments:												
2018 - Fall: N	No Change				<u> </u>							
Comments:	<u> </u>											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
25A	Mortar for Exterior Brick- Not AHERA			1902- Exterior							YES	X NO
2016 - Fall: I	No Change]	•	•	•			•	

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material Description

26	Ceramic Caulk			2nd Floor Restrooms							YES	X NO
2016 - Fall: N	No Change]							
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:					 							
2017 - Fall: N	No Change											
Comments:					<u> </u>							
2018 - Fall: N	No Change											
Comments:					-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
0.7	Sink Insulation, Sink Under	400	0.5	D 400 1000 007		Minnellandon	NI-	Nama				Turbus.

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Material Location

Rooms 102 and 202, 007

HA No

27

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material Description

Material

Quantity

100

SF

Material

Units

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Ca	tegory
28	9x9 VFT, Beneath 12x12 VFT	1200	SF	Lunchroom		Miscellaneous	No	None	0		YES X NO)
2016 - Fall: N	lo Change]							

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28A	Mastic for 9x9 VFT, Beneath 12x12 VFT	1200	SF	Lunchroom, Beneath 12x12 VFT		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

	1											
29	Window Frame Caulk			1881- Interior							YES	X NO
2016 - Fall: I	No Change				7							
Comments:	<u> </u>											
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:					1							
2018 - Fall: I	No Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
30	Window Frame Caulk			1902- Interior							YES	X NO
2016 - Fall: I	No Change	<u> </u>		<u>-</u>	1							
Comments:												

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

Material

Units

Material

Quantity

Material Location

HA No

Material Description

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

31	1'x1' Ceiling Tile			3rd Floor Hallway							YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Sprin	g: No Change				1							
Comments:												
2017 - Fall:	No Change											
Comments:					<u> </u> -							
2018 - Fall:	No Change											
Comments:					1							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
32	Cloth Window Blinds			1976- Throughout							YES	X NO
2016 - Fall:	No Change	•			1			•			•	

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material Description

2016 - Fall: N	No Change										
Comments:	10 Onlange				=						
2017 - Spring	g: No Change										
Comments:											
2017 Falls N	No Changa				4						
2017 - Fall: N	vo Change										
Comments:											
2019 Falls N	No Changa										
2018 - Fall: N	vo Change										
Comments:											
HA No	Material Description	Material	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
		Quantity	Ullits		Type	Calegory		Type	Qualitity	Ullita	

Type

Material

Category

Miscellaneous

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

0

None

Damage

Units

HA No

33

34

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material Description

4" Gray Vinyl Baseboard

Window Caulk

Material

Quantity

Material

Units

LF

180

Material Location

1998- Exterior Not

Engineer's Office and

Teachers' Lounge

AHERA

Change in Assessment Category

X NO

X NO

YES

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	ment Category
35	4" Gray Vinyl Baseboard Adhesive	180	LF	Engineer's Office and Teachers' Lounge		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Blue Ceramic Floor Tile Grout	60	SF	Engineer's Office Washroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
37	4" It Gray Vinyl Baseboard	30	LF	Engineer's Office Washroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 Fall: No Change
2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	4" Lt Gray Vinyl Baseboard Adhesive	30	SF	Engineer's Office Washroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 36

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	White Ceramic Wall Tile Grout	30	SF	Engineer's Office Washroom		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change	•	•	_]					•	

016 - Fall: No Change	
omments:	
247 O. C. N. Oberes	
017 - Spring: No Change	
omments:	
017 - Fall: No Change	
omments:	
018 - Fall: No Change	
omments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	White Ceramic Wall Tile Adhesive	30	SF	Engineer's Office Washroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

41	18"x18" White Ceramic Tile	60	SF	Engineer's Office Washroom		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	lo Change										
2017 - Spring Comments:	g: No Change										
2017 - Fall: N	lo Change										
2018 - Fall: N Comments:	lo Change										
					<u> </u>						

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Blue,Red,Yellow,Purple Multi-Color Carpet Adhesive	1600	SF	Computer Lab and Room 007		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
43	4" Brown Vinyl Baseboard	300	SF	Computer Lab, Room 007 and Lunchroom area		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change				1							
Comments	S:											
2017 - Spri	ring: No Change											
Comments	S:											
2017 - Fall	I: No Change											
Comments	S:											
2018 - Fall	I: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	4" Brown Vinyl Baseboard Adhesive	300	LF	Computer Lab,Room 007, Lunchroom Area		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

Page 39

45	Blue Carpet Mastic	1600	SF	Library, 2nd Floor Counselor's Office	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										

Type

Asbestos

Type

Material

Category

Material

Category

Miscellaneous

Friable

Friable

No

Damage

Damage

Туре

None

Type

Damage

Quantity

Damage

Quantity

0

Damage

Damage

Units

Units

2016 - Fall: N	o Change								
Comments:									
2017 - Spring	: No Change								
Comments:									
2017 - Fall: N	o Change								
Comments:									
2018 - Fall: N	o Change								
Comments:	Comments:								
		•	•						

Material

Quantity

40

Material

Quantity

Material

Material

Units

LF

Units

Material Location

Material Location

Room 008

HA No

HA No

46

Material Description

Material Description

Blue Vinyl Baseboard

Change in Assessment Category

Change in Assessment Category

X NO

YES

47	Blue Vinyl Baseboard Adhesive	40	LF	Room 008		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
	io Change											
Comments:												
2017 - Spring	յ։ No Change											
Comments:												
2017 - Fall: N	lo Change]							
Comments:												
2018 - Fall: N	lo Change											
Comments:	•											
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessi	ment Category

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA NO	Material Description	Quantity	Units	iviaterial Location	Type	Category	Friable	Type	Quantity	Units	Change in Assessme	nt Category
48	12"x12" Lt Beige Floor Tile	4000	SF	Lunchroom/Serving Area, 3rd Floor Hall and MDF Room 311		Miscellaneous	No	Loc	12		YES	X NO
2016 - Fall: N	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

49	12"x12" Lt Beige Floor Tile Mastic	4000	SF	Lunchroom/Serving Area, 3rd Floor Hall and MDF Room 311	Miscellaneous	No	Loc	12	YES	X NO
2016 - Fall: N	lo Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:	•									
2018 - Fall: N	lo Change									
Comments:	•									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	Green Carpet Mastic	1200	SF	Main Office and Asst. Principal's Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
51	12"x12" Orange/Rust Floor Tile	3100	SF	Room 202,207,106		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												

Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	12"x12" Orange/Rust Floor Tile Mastic	3100	SF	Room 202,207,106		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

53	Lab Tables	150	SF	Lab Rooms 202 and 309		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Chango				1							
	NO Change											
Comments:												
2017 - Spring	g: No Change				1							
Comments:]							
2017 - Fall: N	No Change											
Comments:												
					1							
2018 - Fall: N	No Change				1							
Comments:	-]							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Friable

No

Miscellaneous

Damage

Type

None

0

Damage

Quantity

Damage

Units

54	12"x12" Gray Floor Tile w/ White and Black Spots	50	SF	Room 107 Washroom, Boiler Room Stair Landing and Washroom
2016 Falls I	No Change			
2016 - Fall: I	No Change			
Comments:				
2017 - Sprin	g: No Change			
Comments:				
2017 - Fall: I	No Change			
Comments:				
2018 - Fall: I	No Change			
Comments:		•	•	
		•		

Material

Quantity

Material

Units

Material Location

Room 107 Washroom,

HA No

Material Description

YES

X NO

55	12"x12" Gray Floor Tile w/Wht & Blk Spots Mastic	50	SF	Room 107 Washroom, Boiler Room Stair Landing and Washroom	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	No Change									
Comments:										
2017 - Spring	g: No Change									
Comments:										
2017 - Fall: N	No Change									
Comments:										
2018 - Fall: N	No Change									
Comments:										

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
56	Kiln brick	20	SF	Boiler Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Comments:	o Change											

2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments:

Material

Quantity

Material

Units

Material Location

Room 107 Washroom,

HA No

Material Description

2018 - Fall: No Change Comments:

Change in Assessment Category

А	Fiberglass Pipe Insulation			Throughout							YES	X NO
2016 - Fall: I	No Change]							
Comments:					1							
2017 - Fall: I	No Change				1							
Comments:					-							
	g: No Change				=							
Comments:					-							
2018 - Fall: I	No Change											
Comments:					-							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
В	Fiberglass Joint Insulation	200	LF	Throughout Bldg. Boiler Room, Mechanical Room		TSI	Yes	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Page 46

Change in Assessment Category

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Cardboard Pipe Insulation	2000	LF	1902- Basement, 102, 202		TSI	Yes	None	0		YES X NO
2016 - Fall: N	No Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Cardboard Joint Insulation	250	LF	1902- Basement, 102, 202		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Е	Aircell Pipe Insulation	680	LF	1881- Basement and Fan Rooms	TSI	Yes	None	0	YES	X NO
2016 - Fall: N Comments:	o Change									
2017 - Spring Comments:	: No Change									
2017 - Fall: N	o Change									
2018 - Fall: N Comments:	o Change									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Aircell Joint Insulation	81	LF	1881- Basement and Fan Rooms		TSI	Yes	Loc	8		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

											II.
2016 Fall:	No Change				7						
	<u> </u>										
Comments	:										
2017 - Spri	ng: No Change										
Comments	•										
2017 - Fall:	No Change										
Comments	:										
2019 Fall:	No Chango				_						
	No Change										
Comments:	•										
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

HA No

G

Н

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material Description

Boiler Rope Gaskets

Boiler Gaskets

Material

Quantity

40

30

Material

Units

LF

LF

Material Location

Inspection Doors

Clean-Out Doors

Change in Assessment Category

X NO

X NO

YES

YES

I	Interior Fire Brick	100	SF	Boilers		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	<u> </u>											
2017 - Fall: N	No Change											
Comments:												
	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
J	Hot Water Make-up Tank			Boiler Room							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

K	Breeching (Brick Lining)			Incinerator							YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					<u></u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
L	Breeching Liner	150	SF	Boilers		TSI	Yes	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

М	Refractory Brick	10	SF	Boilers		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:					_							
	ng: No Change											
Comments:												
2018 - Fall:	<u> </u>											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
N	Fire Brick			Incinerator							YES	X NO
2016 - Fall:	No Change	<u> </u>		<u>-</u>	1							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

		Quantity	Units		Туре	Category		Type	Quantity	Units		
0	Chimney Brick			Boiler Room							YES	X NO
2016 - Fa	II: No Change											
Comment												
	II: No Change											
Comment	S:											
	ring: No Change											
Comment	S:											
	ll: No Change											
Comment	S:				_							
			_	_	 '							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
O1	Chimney Brick Mortar			Boiler Room							YES	X NO
2016 - Fa	II: No Change											
Comment	S:											
2017 - Sp	ring: No Change											
Comment	s:											

Material

Asbestos

Damage

Friable

Damage

Damage

Change in Assessment Category

Material

Material Description

Material

Material Location

HA No

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
Р	Chimney Liner Brick			Boiler Room							YES	X NO
2016 - Fal	: No Change											
Comments												
2017 - Fal	l: No Change											
Comments	<u>-</u> S:											
2017 - Spr	ing: No Change											
Comments	S:											
2018 - Fal	: No Change											
Comments	S:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
P1	Chimney Liner Brick Mortar			Boiler Room							YES	X NO
2016 - Fal	: No Change											
Comments												
2017 - Fal	: No Change											
Comments:												

Material

Asbestos

Friable

Damage

Damage

Damage

HA No

Material Description

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
Q	Chimney Soot			Boiler Room							YES	X NO
2016 - Fall: I Comments:	No Change											
2017 - Sprin Comments:	g: No Change											
2017 - Fall: I Comments: 2018 - Fall: I Comments:												
Comments.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
R- Field	Roof Field - Not AHERA			Roof- Section E							YES	X NO
2016 - Fall: I Comments: 2017 - Fall: I	-		1			,	,	•		,		

Comments:

Comments:

Comments:

2017 - Spring: No Change

2018 - Fall: No Change

	·	Quantity	Units		Type	Category		Туре	Quantity	Units		
R- Flash	Roof Flashings - Not AHERA			Roof- Section E							YES	X NO
2016 - Fall: I	No Change											
Comments:	- to critically											
2017 - Fall: I	No Change											
Comments:	.											
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
R- X Joint	Expansion Joint			Roof- Section E							YES	X NO
2016 - Fall: N	No Change											
Comments:	<u> </u>											
2017 - Sprin	g: No Change											

Material

Friable

Damage

Damage

Damage

Material Location

HA No

Comments:

Comments:

Comments:

2017 - Fall: No Change

2018 - Fall: No Change

Material Description

Material

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
S	Block Pipe Insulation	30	LF	1881 Building- Throughout Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 29201

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Mark Sheridan Math & Science Academy
Date: 1/11/2019

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 29201

SCHOOL'S ASBESTOS MANAGEMENT PLAN.