## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2018 - Fall

William Bishop Owen Scholastic Academy ES 29241 5240 School: **Oracle Unit: Building ID:** Address: 8247 S. Christiana Region: 05 Mail Room: Asbestos Surveyor: Saldana, Jose X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/26/2018 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type OFFICE, PRINCIPALS YES X NO 01A 12X12 BEIGE VFT SF 660 OFFICE, VAULT, Miscellaneous No None 0 LIBRARY 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Oracle Unit: 29241

01B	12X12 GRAY VFT	660	SF	OFFICE, PRINCIPALS OFFICE, VAULT, LIBRARY		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change				]						
Comments:					-						
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	lo Change				}						
Comments:											
2018 - Fall: N	lo Change										
Comments:											
					J						

Type

Asbestos

Type

Material

Category

Material

Category

Miscellaneous

Friable

Friable

No

Damage

Damage

Type

None

Туре

Damage

Quantity

Damage

Quantity

0

Damage

Damage

Units

Units

01C	12X12 BEIGE W/SPECKS VFT	360	SF	ROOM 203
2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring Comments:	: No Change			
Comments.				
2018 - Fall: N	o Change			
Comments:	·			·

Material

Quantity

Material

Quantity

Material

Material

Units

Units

Material Location

Material Location

HA No

HA No

Material Description

Material Description

Change in Assessment Category

Change in Assessment Category

YES

X NO

01D	12X12 BROWN W/SPECKS VFT	360	SF	ROOM 203		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	go											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					l							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Friable

No

Miscellaneous

Damage

Туре

None

0

Damage

Quantity

Damage

Units

Material Location

1ST & 2ND FLOOR

CORRIDORS, KITCHEN, OFFICE (MAIN),

	VII		105,106,108,204,205,206
2016 - Fall: No	o Change		
Comments:			
2017 - Fall: No	Change		
Comments:			
2017 - Spring:	No Change		
Comments:			
2018 - Fall: No	Change		
Comments:			
		•	

6700

SF

HA No

01E

Material Description

12X12 TAN W/SPECKS

12X12 BROWN

Material

Quantity

Material

Units

YES

X NO

01F	12x12 tan w/brown streaks vft	5300	SF	room 100,105,106,108,204,205 ,206		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change			·	]						
Comments:	ge										
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change										
Comments:	, ,										
2018 - Fall: N	lo Change										
Comments:	<u> </u>										
1					1						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
01G	12X12 GRAY W/TAN & BLACK STREAKS VFT	800	SF	ROOM 205 & STORE ROOM		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

01H	12X12 TAN W/ SPECKS VFT	1400	SF	1ST FLOOR CORRIDOR		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				]							
Comments					]							
2017 - Spri	ng: No Change											
Comments	:				_							
	No Change											
Comments	:				_							
	No Change											
Comments	:				_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
				ROOMS: 103, 104, 106,								

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

1200

SF

HA No

011

Material Description

12X12 BEIGE VFT

Material

Quantity

Material

Units

Material Location

108, 204, 206, 208, 1ST

& 2ND FLOOR CORRIDORS YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
01J	12X12 GRAY VFT	3000	SF	ROOMS: 103, 104, 106, 108, 204, 205, 206, 208, 1ST & 2ND FLOOR CORRIDORS		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	1'X1' CELING TILE	2400	SF	GYMNASIUM		Miscellaneous	Yes	Dist	25		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

											II.
204C Falls	No Change				7						
2016 - Fall:											
Comments:											
2017 - Fall:	No Change										
Comments:											
2017 - Sprir	ng: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
	·	·									
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

56

Material

Quantity

56

Material

Units

SF

SF

Material Location

BLDG. ENGINEERS

OFFICE & WASHROOM

**BUILDING ENGINEERS** 

OFFICE & WASHROOM

HA No

06A

06B

Material Description

9X9 GRAY VFT

9X9 GREEN VFT

Change in Assessment Category

X NO

X NO

YES

YES

07A	9X9 GRAY VFT MASTIC	56	SF	BUILDING ENGINEERS OFFICE & WASHROOM		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments					1							
2017 - Fall:	No Change											
Comments	:											
2017 - Spri	ng: No Change											
Comments	•											
					_							
	No Change											
Comments												
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
				BUILDING ENGINEERS								

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

HA No

07B

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

9X9 GREEN VFT MASTIC

Material

Quantity

56

SF

Material

Units

Material Location

OFFICE AND WASHROOM YES

X NO

08	1' X 1' CELING TILE MASTIC	2400	SF	GYMNASIUM		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											
					l						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Units Units	Change in Asses	sment Category	
09A	12X12 BEIGE VFT MASTIC	660	SF	OFFICE, PRINCIPALS OFFICE, VAULT, LIBRARY		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall: Comments:	No Change												

2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments:

Material

Quantity

Material

Units

HA No

Material Description

										·	
09B	12X12 GRAY VFT MASTIC	660	SF	OFFICE, PRINCIPALS OFFICE, VAULT, LIBRARY		Miscellaneous	No	None	0	YES	X NO
	•	•		•		•	•	•	•		
2016 - Fall: N	lo Change										
Comments:											
					1						
2017 - Spring	: No Change				]						
Comments:											
2017 - Fall: N	lo Change										
Comments:											
					1						
2018 - Fall: N	lo Change				1						
Comments:					1						
					1						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
09C	12X12 BEIGE W/SPECKS VFT MASTIC	360	SF	ROOM 203		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Comments:	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

09D	12X12 BROWN W/SPECKS VFT MASTIC	360	SF	ROOM 203		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	io onango											
2017 - Fall: N	lo Change				-							
Comments:	io change											
2017 - Spring	ı: No Change				=							
Comments:	, J											
2018 - Fall: N	lo Change				-							
Comments:	Ţ.											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

09E	12X12 TAN W/ SPECKS VFT MASTIC	4000	SF	CORRIDORS, KITCHEN, OFFICE (MAIN)
2016 - Fall: I	No Change			
Comments:				
2017 - Sprin	g: No Change			
Comments:				
2017 - Fall: I	No Change			
Comments:				
2018 - Fall: I	No Change			
Comments:			•	

HA No

Material Description

12X12 TAN W/ SPECKS

12X12 BROWN

Material

Quantity

Material

Units

Material Location

1ST & 2ND FLOOR

Page 11

Change in Assessment Category

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
09F	12X12 TAN W/ BROWN STREAKS VFT MASTIC	775	SF	ROOM 100		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09G	12X12 GRAY W/TAN & BLACK STREAKS MASTIC	800	SF	ROOM 205 & STORE ROOM		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

09H	12X12 TAN W/SPECKS VFT MASTIC	1400	SF	1ST FLOOR CORRIDOR		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				]							
Comments:												
2017 - Fall:	No Change				_							
Comments:												
2017 - Sprir	ng: No Change				-							
Comments:					1							
2018 - Fall:	No Change											
Comments:					1							
					<u> </u>							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
		Quantity	Units	DOOMS: 402, 404, 402	Туре	Category		Туре	Quantity	Units		
091	12X12 BEIGE VFT MASTIC	1400	SF	ROOMS: 103, 104, 106, 108, 204, 206, 208, 1ST & 2ND FLOOR		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

Material Description

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material

Quantity

Material

Units

Material Location

CORRIDORS

		Quantity	Units		Туре	Category		Type	Quantity	Units		
09J	12X12 GRAY VFT MASTIC	3200	SF	ROOMS: 103, 104, 106, 108, 204, 206, 208, 1ST & 2ND FLOOR CORRIDORS		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 0	N. 01											

Material

Friable

Damage

Damage

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10A	*9 X 9 GRAY W/ WHITE STREAKS VFT			ROOM 205		Miscellaneous		None			YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
	_

Damage Change in Assessment Category

11A	*9x9 GRAY W/WHITE STREAKS VFT MASTIC			ROOM 205		Miscellaneous					YES	X NO
0040 5-11 1	.l. Ol				7							
2016 - Fall: N	No Change											
Comments:												
					1							
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:					1							
					1							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
	· ·	Quantity	Units		Type	Category		Type	Quantity	Units		0 ,
-	+	-	<del> </del>		1		l		l	-		

TSI

Asbestos

Type

Material

Category

Friable

Yes

None

Damage

Type

Damage

Quantity

0

Damage

Units

HA No

В

Material Description

CEMENTITIOUS FITTINGS 7

Material

FITTING

Units

Material Quantity Material Location

BOILER ROOM

Change in Assessment Category

YES

X NO

С	AIRCELL PIPE INSULATION	550	LF	UNFINISHED PIPE SPACE		TSI	Yes	None	0		YES	X NO
2016 - Fall:	: No Change				7							
Comments												
2017 - Spri	ing: No Change											
Comments					]							
2017 - Fall:	: No Change											
Comments	s:											
2018 - Fall:	: No Change											
Comments	:				_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

TSI

Asbestos

Type

Material

Category

Friable

Yes

None

0

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

THROUGHOUT

BASEMENT UNFINISHED PIPE

		SPACE
2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		·

23

LF

HA No

D

Material Description

AIRCELL PIPE FITTINGS

AIRCELL PIPE

Material

Quantity

Material

Units

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	CEMENTITIOUS FITTINGS	16	LF	THROUGHOUT BASEMENT UNFINISHED PIPE SPACE		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	magblock insulation (unexcav. Area)	500	LF	unfinished pipe space		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Н	magblock joints (unexcav. Area)	25	SF	finished pipe space	TSI	Yes	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	corrugated duct wrap	2400	SF	boiler room unfinished pipe space		TSI	Yes	Loc	200		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

2016 Fall:	No Change										
Comments:											
2017 Spri	ng: No Change										
Comments:	•										
2017 - Fall:	No Change										
Comments:											
2018 - Fall:	No Change										
Comments:	•										
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

TSI

TSI

Friable

Yes

Yes

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

2016 - Fall: No	o Change			
Comments:				
2017 - Spring:	No Change			
Comments:				
2017 - Fall: No	o Change	 	<u> </u>	
Comments:				
2018 - Fall: No	o Change			
Comments:				

6

LF

Material

Quantity

80

Material

Units

LF

Material Location

east store room

east store room

HA No

Κ

Material Description

magblock pipe insulation

magblock elbow insulation

Page 19

Change in Assessment Category

X NO

X NO

YES

YES

L	cardboard elbow insulation	90	LF	store rooms unfinished pipe space	TSI	Yes	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:	O Change									
Comments.										
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M	cardboard pipe insulation	750	LF	unfinished pipespace 1952 addition		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
N	cardboard elbow insulation	100	LF	1952 addition unfinished pipe space		TSI	Yes	None	0		YES	X NO
2016 - Fall: No Change												
Comments:												
2017 - Spring	g: No Change											
Comments:	Comments:											
2017 - Fall: No Change												
Comments:	Comments:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
0	horsehair duct insulation w/tar paper	300	SF	boiler room 1947 building & *crawl spaces	71	TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Р	TRANSITE DUCT INSULATION W/CLOTH WRAP	20	SF	CRAWL SPACE BY ENGINEER'S OFFICE		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: William Bishop Owen Scholastic Academy ES
Date: 9/4/2018
<del></del>
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 29241

SCHOOL'S ASBESTOS MANAGEMENT PLAN.