Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

John H Vanderpoel Elementary Magnet School 29311 6250 School: **Oracle Unit: Building ID:** Address: 9510 S Prospect Avenue Region: 06 Mail Room: Asbestos Surveyor: Dunne, Michael X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/8/2019 Email Address: A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Type Quantity YES 03 Acoustical Celing Plaster SF 0 X NO 180 East Vestibule of Gym Surface Yes None 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
07A	12x12 White w/Green Streaks Floor Tile	222	SF	Assitant Principal's Office, Closet/Washroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change]							
Comments												
2017 - Fal	l: No Change											
Comments	S:				<u> </u>							
2017 - Spr	ring: No Change											
Comments	S:				 -							
2018 - Fal	I: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08A	12 x 12 White w/Green Streaks Floor Tile	410	SF	Gym Office and 1st Floor Hall		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

09A	12x12 White w/Green Streaks Floor Tile Mastic	300	SF	Room 104		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change				7							
					+							
Comment	5.				4							
					4							
2017 - Spi	ring: No Change											
Comments	S:											
					1							
2017 - Fal	I: No Change											
Comments	<u> </u>				1							
00111110111	<u>. </u>				1							
2018 - Fal	I: No Change											
	<u> </u>											
Comments	5.				4							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
				Rooms: 103, 103P, 105,							l — ,	

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

HA No

09B

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

12x12 White w/Green

Streaks Floor Tile

Material

Quantity

4700

SF

Material

Units

Material Location

2nd Floor Corridor, 2nd

Floor East Landing, 3rd Floor Corridor

Change in Assessment Category

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
09C	12x12 Brown Floor Tile (Checkered)	240	SF	Teacher's Lounge/Work Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09D	12x12 White Floor Tile (Checkered)	240	SF	Teacher's Lounge/Work Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

09E	12x12 Tan w/Brown Specks Floor Tile	1600	SF	Library, Room 300 & 305		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:												
2017 - Sprir	ng: No Change											
Comments:	<u> </u>											
2017 - Fall:	No Change											
Comments:												
2010 5 11												
2018 - Fall:	<u> </u>											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
	40:40 Danier Flana Tila	1		Main Office, Principal's								

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

510

SF

Material

Quantity

Material

Units

Material Location

Office, and Janitors

Office

HA No

09F

Material Description

12x12 Brown Floor Tile

(Checkered)

YES

X NO

09G	12x12 White Floor Tile (Checkered)	510	SF	Main Office, Principal's Office, and Janitors Office		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change		<u> </u>]						
Comments:					1						
2017 - Sprii	ng: No Change										
Comments:	:				_						
	No Change										
Comments:	:										
	No Change										
Comments:	:										

Type

Asbestos

Type

Material

Material

Category

Miscellaneous

Category

Friable

Friable

Yes

Damage

Damage

Type

None

Type

Damage

Quantity

Damage

Quantity

0

Damage

Damage

Units

Units

11A	Streaks Floor Tile Mastic	222	SF	Closet/Washroom
2016 Fall N	o Chango			
2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				
	•	•		

Material

Quantity

222

Material

Quantity

Material

Material

Units

SF

Units

Material Location

Material Location

Assistant Pricipal's Office,

Main Office, Principal's

HA No

HA No

11A

Material Description

Material Description

12x12 White w/Green

Change in Assessment Category

Change in Assessment Category

YES

X NO

12A	12 x 12 White w/Green Streaks Floor Tile Mastic	410	SF	Gym Office, 1st Floor Hall	Miscellaneous	No	None	0	YES	X NO
2016 - Fal	I: No Change									
Comments	s:									
2017 - Fal	I: No Change									
Comments	s:									
2017 - Spi	ring: No Change									
Comments	s:									
2018 - Fal	I: No Change									
Comments	s:									

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13A	12x12 White w/ Green Streaks Floor Tile Mastic	300	SF	Room 104		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13B	12x12 White w/Green Floor Tile Mastic	4700	SF	Rooms: 103, 104, 105, 2nd Floor Corridor, 2nd Floor East Landing, 3rd Floor Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 Falls No Change
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13C	12x12 Brown Floor Tile Mastic (Checkered)	240	SF	Teacher's Lounge/Work Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
13D	12x12 White Floor Tile Mastic (Checkered)	240	SF	Teacher's Lounge/Work Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	<u> </u>											
Comments:	, the enteringe											

2017 - Fall: No Change Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13E	12x12 Tan w/Brown Specks Floor Tile	1600	SF	Library, Room 300 & 305		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

13F	12x12 Brown Floor tile Mastic (Checkered)	510	SF	Office, and Janitors Office		Miscellaneous	No	None	0	YES	X NO
2016 - Fall	No Change	<u> </u>		<u> </u>	7						
					-						
Comments	•										
2017 - Fall:	No Change										
Comments											
					1						
2017 - Spri	ng: No Change										
Comments	:										
2018 - Fall:	No Change										
Comments											
					1						
					_						

Type

Asbestos

Type

Material

Material

Category

Category

Friable

Friable

Damage

Damage

Type

None

Type

Damage

Quantity

Damage

Quantity

0

Damage

Damage

Units

Units

13G	12x12 White Floor Tile Mastic (Checkered)	510	SF	Office, and Janitors Office	Miscellaneous	No
2016 - Fa	all: No Change					
Commen	ts:					
2017 - Sp	oring: No Change					
Commen	ts:					
2017 - Fa	all: No Change					
Commen	ts:					
2018 - Fa	all: No Change					

Material

Units

Material

Units

Material

Quantity

Material

Quantity

Material Location

Material Location

Main Office, Principal's

Main Office, Principal's

HA No

HA No

Comments:

Material Description

Material Description

12x12 White Floor Tile

Change in Assessment Category

Change in Assessment Category

YES

X NO

2016 - Fall	: No Change				7						
Comments											
2017 - Fall	: No Change										
Comments	:										
2017 - Spri	ing: No Change										
Comments	:										
2018 - Fall	: No Change										
Comments	:										
					_						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

No

Damage

Type

Type

Damage

Quantity

Quantity

0

Damage

Units

Units

Change in Assessment Category

X NO

X NO

YES

YES

2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	

HA No

Comments:

14

Material Description

Black Mopboard

Material

Quantity

Quantity

Units

60

Material

Units

LF

Material Location

1st Floor Addition

Corridor

Page 11

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
16	12x12 White w/Green Streaks Floor Tile	3300	SF	1st Floor Corridor (Addition)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change												

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
17	2'x4' Ceiling Tile	9100	SF	1st, 2nd and 3rd Floor Corridors		Miscellaneous	Yes	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

18	Tank Insulation	100	SF	Boiler Room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	J											
2017 - Spring	: No Change											
Comments:	<u> </u>											
2018 - Fall: N	o Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Friable

Yes

Miscellaneous

Damage

Туре

None

0

Damage

Quantity

Damage

Units

19	Grout	2550	SF	Boys and Girls and Teachers Washrooms	
					=
2016 - Fall: N	No Change				
Comments:					
2017 - Fall: N	No Change				
Comments:					
2017 - Spring	g: No Change				
Comments:					
2018 - Fall: N	No Change				
Comments:		•			1

2550

SF

Material

Quantity

Material

Units

Material Location

1st, 2nd and 3rd Floor

Boys and Girls and

HA No

19

Material Description

Brown Mosaic Ceramic Tile

YES

X NO

20	Brown Mosaic Ceramic Tile Mastic	2550	SF	1st, 2nd and 3rd Floor Boys and Girls and Teachers Washrooms		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change				1						
Comments:	Ü				1						
2017 - Fall: N	lo Change				-						
Comments:					1						
2017 - Spring	: No Change										
Comments:					1						
2018 - Fall: N	lo Change										
Comments:	•				1						
					J						

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
21	Adobe Mosaic Ceramic Tile Grout	200	SF	Gym Vestibule		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: No Comments:	o Change											

2010 - Fall. No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

Page 14

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
22	Adobe Mosaic Ceramic Tile Adhesive	200	SF	Gym Vestibule		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:					1							
2017 - Spring	g: No Change											
Comments:					 -							
2018 - Fall: N	lo Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
23	1 x 1 White Fissured Ceiling Tile	2400	SF	Gym		Miscellaneous	Yes	None	0		YES X NO	

2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		
	_	

Comments:

23M	1 x 1 White Fissured Ceiling Tile Mastic	2400	SF	Gym	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	Plaster	60000	SF	Throughout Main Building		Surface	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

2016 - Fall:	No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
2017 - Sprii	ng: No Change										
Comments:	:										
2018 - Fall:	No Change										
Comments:	:										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Surface

Miscellaneous

Category

Friable

Yes

Yes

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

26	Drywall	600	SF	Teacher's Lounge Ceiling- 1958 Addition					
2016 - Fall: N	lo Change								
Comments:									
2017 - Fall: No Change									
Comments:									
2017 - Spring	r: No Change								
Comments:									
2018 - Fall: No Change									
Comments:									

Material

Quantity

1000

Material

Units

SF

Material Location

1958 Addition- Corridor

HA No

25

Material Description

Plaster

Change in Assessment Category

X NO

X NO

YES

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
27	Spray On Fire-Proofing	5000	SF	1958 Addtition		Surface	Yes	None	0		YES	X NO
2016 - Fal Comments	II: No Change s:											
2017 - Spi Comments	ring: No Change s:				-							
2017 - Fal Comments	II: No Change s:											
2018 - Fal	II: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	MJP E/F/V on Aircell Pipe Insulation	140	LF	Boiler Room, Crawlspace		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

Page 18

E	Cardboard Pipe Insulation	110	LF	Boiler Room and Crawl Space	TSI	Yes	Loc	20	YES	X NO
0040 F.II N	. 01									
2016 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2017 - Fall: N	o Change									
Comments:	-									
2018 - Fall: N	o Change									

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Aircell Pipe Insulation	200	LF	Boiler Room, Crawlspace, Slop Sink Room, and Fan Room		TSI	Yes	Loc	50		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

Page 19

К	MJP E/F/V on Aircell Pipe Insulation	50	LF	Boiler Room, Crawlspace, Fan Room		TSI	Yes	None	0	YES	X NO
2016 - Fall:	No Change]						
Comments:											
2017 - Fall:	No Change										
Comments:											
2017 - Sprin	g: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Cardboard Pipe Insulation	120	LF	Crawlspace		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

MJP E/F/V on Aircell Pipe

М	Aircell Pipe Insulation	185	LF	Crawlspace, Fan Room, Gym, and Janitors Closet		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	o Chango		•		1	•	•	•	•	•		
	o Change											
Comments:												
2017 - Fall: N	o Change				1							
Comments:	_											
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:					1							
					1							
					1							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
N	MJP E/F/V on Fiberglass Pipe Insulation	100	LF	Boiler Room and Washrooms		TSI	Yes	None	0		YES	X NO
_	2016 - Fall: No Change											
Comments:	N. Olavas											

2017 - Spring: No Change
Comments:

2017 - Fall: No Change
Comments:

2018 - Fall: No Change

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
0	Incinerator Insulation	50	SF	Boiler Room 1911		TSI	Yes	None	0		YES	X NO
2016 - Fall: No Change												
Comments:					-							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring: No Change					=							
Comments:												

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Р	MJP E/F/V on Cardboard Pipe Insulation	25	LF	Boiler Room and Crawl Space		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Page 22

Q	Pipe Insulation	20	LF	Crawispace and 1st Floor		151	Yes	LOC	5		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprii	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
					J							
HA No	Material Description	Material	Material	Material Location	Achaetae	Material	Friable	Damage	Damage	Damage	Change in Access	ment Category

Type

Material

TSI

Category

Friable

Yes

Damage

Type

Loc

Damage

Quantity

5

Damage

Units

HA NO	Material Description	Quantity	Units	Iviaterial Location	Type	Category	Filable	Type	Quantity	Units	Change in Assess	Smem Calegory
R	Boiler Gasket	80	LF	Boiler Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											
2017 - Spring: No Change												

Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments:

HA No

Q

Material Description

MJP E/F/V on Cardboard

Material

Units

LF

Material

Quantity

20

Material Location

Crawlspace and 1st Floor

Change in Assessment Category

X NO

YES

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: John H Vanderpoel Elementary Magnet School
Date: 1/11/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.