## **Chicago Public Schools**

## **6 Month Asbestos Surveillance** 2018 - Fall

30051

Daniel C Beard Elementary School **Oracle Unit: Building ID:** Address: 6445 West Strong Region: 01 Mail Room: 30 Asbestos Surveyor: Walker, Sheena X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/10/2018 Email Address: swalker57@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type Throughout - 1957 bldg, YES X NO 01 1'x1' White Ceiling Tile SF 14800 EXCEPT vault, boiler Miscellaneous Yes None 0 room, and storage room. 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

School:

4950

02	2'x4' White Ceiling Tile	3000	SF	Gym - 1957 bldg		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change				7							
					4							
Comments:					1							
					_							
2017 - Fall:	No Change											
Comments:												
2017 - Spri	ng: No Change				1							
Comments:	· ·											
Commonto					†							
2018 - Fall:	No Change											
Comments:	<u> </u>				1							
1					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

No

None

0

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

	storage room.
2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

14800

HA No

04

Material Description

12"x12" White w/ Gray

Streaks VFT

Material

Quantity

Material

Units

SF

Material Location

Throughout - 1957 bldg,

EXCEPT the following:

boys and girls toilets, vault, boiler room, and

Page 2

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Catego
06	12"x12" White w/ Gray Streaks VFT Mastic	14800	SF	Throughout - 1957 bldg, EXCEPT the following: boys and girls toilets, vault, boiler room, and storage room.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	Vinyl Baseboard	4500	LF	Throughout - 1957 bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

08	Vinyl Baseboard Mastic	4500	LF	Throughout - 1957 bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				7							
Comments	U				1							
2017 - Fall	: No Change				_							
Comments	:											
2017 - Spri	ing: No Change				-							
Comments	:											
2018 - Fall	: No Change				-							
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
				Room 105 and Nurse								

Type

Material

Category

Miscellaneous

Yes

Friable

Damage

Type

None

0

Damage

Quantity

Damage

-

YES

X NO

Units

800

SF

HA No

09

Drywall

Material Description

Material

Quantity

Material

Units

Material Location

Rm, Old Office (#103) -

1957 bldg

Change in Assessment Category

09A	Drywall Joint Compound	420	SF	Room 105 & Nurse Room - 1957		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	No Change				]							
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Friable

Damage

Type

None

0

No

Damage

Quantity

11	VFT Under 12"x12" White w/ Gray Streaks VFT	120	SF	Storage & Room 104 Toilet - 1957
2016 Falls	: No Change			
	•			
Comments	:			
2017 - Spri	ing: No Change			
Comments	:			
2017 - Fall:	: No Change			
Comments	:			
2018 - Fall:	: No Change			
Comments	:			
	_		•	

HA No

Material Description

VFT Under 12"x12" White

Material

Quantity

Material

Units

Material Location

Nurse's Room General

Page 5

Change in Assessment Category

X NO

Damage

Units

11A	VFT Mastic Under 12"x12" White w/ Gray Streaks VFT	120	SF	Nurse's Room General Storage & Room 104 Toilet - 1957		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]	•	•	•	•	•	•	
Comments:	J											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					J							

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
12	9"x9" Cream, Black, & Gray w/ Spots VFT	14900	SF	Throughout under HA# 04 & 06 - 1957 bldg, EXCEPT the following: boys and girls toilets, vault, boiler room, and storage room.		Miscellaneous	No	None	0		YES [	X NO
2016 - Fall: N	No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Change in Assessment Category

12A	9"x9" Cream, Black, & Gray w/ Spots VFT Mastic	14900	SF	Throughout under HA# 04 & 06 - 1957 bldg, EXCEPT the following: boys and girls toilets, vault, boiler room, and storage room.		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change				]						
Comments:					1						
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change				<u> </u>						
Comments:	ge										
2018 - Fall: N	o Change										
Comments:					]						
					J						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12"x12" White w/ Grey Specks VFT	14000	SF	Throughout 1995 Annex, EXCEPT the following: lobby, main entry vestibule, toilets, room 118, kitchen, mechanical room, MDF, Elec. room.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"x12" White w/ Grey Specks VFT Mastic	14000	SF	Throughout 1995 Annex, EXCEPT the following: lobby, main entry vestibule, toilets, room 118, kitchen, mechanical room, MDF, elec. room.		Miscellaneous	No	None	0		YES X NO
2016 - Fall:	No Change										
Comments:	•										
2017 - Fall:	No Change										
Comments:											
2017 - Sprii	ng: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
					J						

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	2'x4' White Ceiling Tile	13500	SF	Throughout 1995 Annex, EXCEPT Rooms 118, 114, Kitchen, and Toilets		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	2'x4' White Smooth Ceiling Tile	2000	SF	Rooms 114 (Dining Room), Laundry Rm, Girls and Boys Toilets, Kitchen, and Storage Room - 1995 Annex		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	Vinyl Baseboard	3500	LF	Throughout 1995 Annex, EXCEPT corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

											1
2016 - Fall: N	lo Change				]						
Comments:	to onlange										
2017 - Fall: N	lo Change				<u> </u>						
2017 - Fall: No Change Comments:											
2017 - Spring: No Change											
Comments:	g. No Change				_						
2018 - Fall: N	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
ı	1	1	1		1		1	1	1	1	1

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Yes

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

10000

HA No

18

19

Material Description

Vinyl Baseboard Mastic

Drywall

Material

Quantity

3500

Material

Units

LF

SF

Material Location

Throughout 1995 Annex, EXCEPT corridors

Throughout 1995 Annex

Change in Assessment Category

X NO

X NO

YES

20	Drywall Joint Compound	5000	SF	Throughout 1995 Annex		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	J				1							
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

600

HA No

22

Material Description

Terrazzo Floor

2016 - Fall: No Change

Material

Units

SF

Material

Quantity

Material Location

Boys and Girls Toilets,

1957 Bldg

Page 11

Change in Assessment Category

X NO

0040	No Observe				7						
2016 - Fall:	: No Change										
Comments:	•										
2047 Fall	No Change										
	: No Change										
Comments	•										
2017 Spri	ng: No Change										
	· ·										
Comments:	:										
2010 5 11					4						
2018 - Fall:	: No Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

TSI

Asbestos

Type

Material

Category

Friable

Yes

Damage

Туре

Damage

Quantity

0

None

Damage

Units

	· ·		_	
2016 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				
		·		<u> </u>

Material

Quantity

0

Material

Units

LF

Material Location

Boiler Room Storage -

Boiler Room Storage -

1957 Bldg

1957 Bldg

HA No

С

D

Material Description

Cardboard Pipe Insulation

MJP E/F/V on Cardboard

Pipe Insulation

Change in Assessment Category

X NO

X NO

YES

F	Blown-in Insulation	5000	SF	Between Drop Ceiling and Roof throughout, Mechanical Room - 1957		Miscellaneous	Yes	None	0	YES	X NO
2016 - Fall: N	o Change	]									
Comments:											
2017 - Fall: N	o Change										
Comments:	Ğ										
2017 - Spring	: No Change										
Comments:											
2018 - Fall: No Change											
Comments:	Ü										
					J						

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
G	Ceiling Panels	5000	SF	Between Drop Ceiling and Roof - 1957		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2017 - Spring: No Change
Comments:

2017 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

2018 - Fall: No Change Comments: Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	Aircell Pipe Insulation	275	LF	Above Ceiling Tile in Main Corridor & Vestibule East of Clerical Office, Boiler Rm Storage - 1957		TSI	Yes	None	0		YES X NO
2016 - Fall: N Comments:	lo Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	MJP E/F/V on Aircell Pipe Insulation	36	LF	Above Ceiling Tile in Main Corridor & Vestibule East of Clerical Office, Boiler Rm Storage - 1957		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Daniel C Beard Elementary School
Date: 12/10/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 30051

SCHOOL'S ASBESTOS MANAGEMENT PLAN.