Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

30081

Oracle Unit:

Address: 7507 W Birchwood Avenue Region: 01 Mail Room: Asbestos Surveyor: Bartsch, Henry X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/14/2018 Email Address: hbartsch@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other website HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type Rooms 109, 111, YES X NO 112/114 all purpose 01 Acoustical Plaster 1500 SF Surface Yes None 0 room, Corridor -1960 2016 - Fall: No Change Comments:no change 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Frederick Stock Elementary School

School:

5770

Building ID:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
05	12"x12" Tan w/ brown and white streaks VFT	1800	SF	Kitchen, Kitchen Storage, 108, 100, 101, corridor outside kitchen - 1955		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change	•		•			•			•		

2016 - Fall: No Change
Comments:no change
_
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	9"x9" Tan VFT	2500	SF	Room 103, Room 105, Corridor- 1955		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Type	Category		Type	Quantity	Units		
07	12"x12" Tan w/Brown & white streaks VFT Mastic	1800	SF	Kitchen, Kitchen Storage, 100, 108, 101, corridor outside kitchen -1955		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Sprii	ng: No Change				-							
Comments:]							
	No Change											
Comments:					-							
2018 - Sprii	ng : No Change											
Comments:												

Asbestos

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	9"x9" Tan VFT Mastic	2500	SF	Room 103, Room 105, Corridor - 1955		Miscellaneous	No	None	0		YES X NO

2016 - Fall: N	o Change		
Comments:no	change		
2017 - Spring	: No Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2018 - Spring	; : No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			
		•	

HA No

2018 - Fall: No Change

Comments:

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12"x12" Tan VFT	2200	SF	NW Vestibule, Corridor, 114/112 all purpose room, Teachers Break Room -1960 addition		Miscellaneous	No	None	0		YES X NO
					•						

2016 - Fall: No Change	
Comments:no change	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12"x12" Tan VFT Mastic	2200	SF	NW Vestibule, Corridor, 114/112 all purpose room, Teachers Break Room -1960 addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

11/(140	Waterial Description	Quantity	Units	Waterial Education	Туре	Category	Thable	Туре	Quantity	Units	Onange in 7 to coosmone	Catogory
14	Drywall	600	SF	Throughout - 1955 Bldg.		Surface	Yes	None	0		YES X	NO
2016 - Fall: N	lo Change											
Comments:no	o change				_							
	g: No Change											
Comments:					_							
2017 - Fall: N	lo Change				1							
Comments:					4							
2018 - Sprinç	g : No Change				_							
Comments:					4							
2018 - Fall: N	lo Change											
Comments:					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment	Category

Type

Asbestos

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

Damage

Quantity

0

Units

YES

X NO

Damage

15	Baseboard	30	LF	Engineer Office - 1955 Bldg.
0040 5 11 11	01			
2016 - Fall: N				
Comments:no	change			
2017 - Spring	: No Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2018 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				

Quantity

Units

HA No

Material Description

Material

Material

Material Location

Engineer Office - 1955

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Catego	
16	Baseboard Mastic	30	LF	Engineer Office - 1955 Bldg.		Miscellaneous	No	None	0		YES	X NO
	I: No Change s:no change											
	ring: No Change				1							
Comments					1							
2017 - Fal	I: No Change											

2018 - Spring : No Change

Comments:

Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
17	12"x12" Blue VFT	1400	SF	Room 104, Public Office Storage - 1955 Bldg.		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
18	12"x12" Blue VFT Mastic	1400	SF	Room 104, Public Office Storage - 1955 Bldg.		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: No Change Comments:no change												

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
19	12"x12" Blue VFT	1600	SF	Rooms 109 & 111 - 1960 Addition		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
20	12"x12" Blue VFT Mastic	1600	SF	Rooms 109 & 111 - 1960 Addition		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change				1							
Comments	s:no change											
2017 - Spr	ring: No Change											
Comments	S:				-							
2017 - Fall	l: No Change											
Comments	S:			<u> </u>	_							
2018 - Spr	ring : No Change				<u> </u>							

2018 - Fall: No Change

Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
21	9"x9" Brown VFT	40	SF	Hallway outside Room 105 - 1955 Bldg.		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
22	9"x9" Brown VFT Mastic	50	SF	Hallway outside Room 105 - 1955 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]					•		

2016 - Fall: No Change
Comments:no change
<u> </u>
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" White w/Tan specs VFT	1800	SF	Kitchen, Kitchen storage, corridor outside kitchen, Rm 101, 108 -1955 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
24	12"x12" White w/Tan specs VFT Mastic	1800	SF	Kitchen, Kitchen storage, corridor outside kitchen, Rm 101, 108 -1955 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N							•		•	•		
2017 - Spring	: No Change				4							
Comments:												
2017 - Fall: N	o Change											
Comments:]							
2018 - Spring	: No Change											
Comments:					-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" Beige (White w/Tan specs) VFT	2200	SF	NW Vestibule, Corridor, 114/112 all purpose room, Teachers Break Room & Toilet - 1960 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"x12" Beige (White w/Tan specs) VFT Mastic	2200	SF	NW Vestibule, Corridor, 114/112 all purpose room, Teachers Break Room & Toilet - 1960 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 30081

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
27	12"x12" Gray VFT (ABATED)			Engineer Office, Corridor outside Kitchen - 1955		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:n	o change				1							
2017 - Spring	g: No Change				_							
Comments:					 							
2017 - Fall: N	lo Change											
Comments:					-							
	g : No Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					=							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12"x12' Gray VFT Mastic (ABATED)			Engineer Office, Corridor outside Kitchen - 1955		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
29	9"x9" Gray w/ Green VFT	1000	SF	Room 102 -1955 Bldg.		Miscellaneous	No	None	0		YES	X NO
	2016 - Fall: No Change Comments:no change											

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	9"x9" Gray w/ Green VFT Mastic	1000	SF	Room 102 -1955 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12"x12" White VFT	120	SF	Room 112 Storage - 1960 Addition		Miscellaneous	No	None	0		YES X NO
					i						

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12"x12" White VFT Mastic	120	SF	Room 112 Storage - 1960 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
33	MJP E/F/V on Fiberglass Pipe Insulation	55	LF	Crawlspace, Teachers Toilet Pipe Chase - 1960 Addition		TSI	Yes	None	0		YES	X NO
2016 - Fal	I: No Change	·		<u> </u>	1							
Comments	s:no change											
2017 - Spi	ing: No Change				-							
Comments	3:											
2017 - Fal	l: No Change				-							
Comments	S:											
2018 - Spi	ing : No Change				-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	2'x4' Ceiling tiles (REMOVED)			Rooms 109 & 111		Miscellaneous					YES X NO

HA No

Comments:

Comments:

2018 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
35	12"x12" off white w/ beige and gray streaks VFT	1000	SF	Mobile unit		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:no change												

2016 - Fall: No Change
Comments:no change
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35A	12"x12" off white w/ beige and gray streaks VFT MASTIC	1000	SF	Mobile unit		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
36	Acoustical Ceiling with grooves	1000	SF	Mobile unit		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	no change											
2017 - Sprii	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprii	ng : No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Drywall system	2000	SF	Mobile unite		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

Page 17

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12x12 Tan w/White specks VFT	160	SF	Eng. Office, Corridor by kitchen, Corridor outside Rm 101 -1955 bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:no change	
_	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	<u> </u>

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38A	12x12 Tan w/White specks VFT Mastic	160	SF	Eng. Office, Corridor by kitchen, Corridor outside Rm 101 -1955 bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:no change
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12x12 Rust w/White Specks VFT	200	SF	Toilets in rooms 103, 104, 105, 106, JC next to Rm 101 -1955 bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:no change
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39A	12x12 Rust w/White Specks VFT Mastic	200	SF	Toilets in rooms 103, 104, 105, 106, JC next to Rm 101 -1955 bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 19

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assessi	ment Category
40	12x12 Red VFT	600	SF	Main Office -1955 Bldg		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change				1								
Comments:n	o change												
2017 - Spring	g: No Change												
Comments:													
2017 - Fall: N	No Change				-								
Comments:													
2018 - Fall: N	No Change				-								
Comments:	-]								
2018 - Spring	g : No Change				1								
Comments:													

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40A	12x12 Red VFT Mastic	600	SF	Main Office -1955 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 20

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Carpet Mastic	500	SF	Principals office -1955 Bldg		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N											

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	2x2 Smooth Ceiling Tile	150	SF	Toilets in Rms 103, 104, 105, 106 -1955 Bldg		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:no change
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

		Quantity	Units		Type	Category		Type	Quantity	Units		
43	2x4 Ceiling Tle	500	SF	Room 100 -1955 Bldg		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:												
Comments:	no change				-							
	g: No Change											
Comments:					_							
2017 - Fall:	No Change				1							
Comments:												
2018 - Fall:	No Change				-							
Comments:]							
2018 - Sprin	g : No Change				-							
Comments:												
					J							

Asbestos

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	1x1 Ceiling Tile	9500	SF	Rooms 102, 103, 104, 105, 106, 108, Main office, Principals office, Corridor -1955 Bldg		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:no change
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44A	1x1 Ceiling Tile Mastic Pucks	9500	SF	Rooms 102, 103, 104, 105, 106, 108, Main office, Principals office, Corridor -1955 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
•	
Comments:no change	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12x12 Pink w/White & Brown specks VFT	40	SF	Toilet next to gym 112/114 -1960 Addition		Miscellaneous	No	None	0		YES X NO

•	•	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
45A	12x12 Pink w/White & Brown specks VFT Mastic	40	SF	Toilet next to gym 112/114 -1960 Addition		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:no					-							
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					=							
	j : No Change											
Comments:					_							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12x12 Rust w/White Specks VFT	200	SF	Room 109 toilet, Room 111 Toilet, Toilet next to teachers lounge - 1960 addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:no change
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46A	12x12 Rust w/White Specks VFT Mastic	200	SF	Room 109 toilet, Room 111 Toilet, Toilet next to teachers lounge - 1960 addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Oracle Unit: 30081

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	2x2 Smoth Ceiling Tile	180	SF	Room 109 & 111 Toilets, Toilet next to gym 112/114, Toilet by teachers lounge -1960 Bldg		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:no change	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	Cardboard Pipe Insulation	20	LF	Boiler Room, Crawlspace - 1955		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessm	ent Category
В	MJP E/F/V on Card Pipe Insulation	5	LF	Boiler Room, Crawlspace - 1955		TSI	Yes	None	0		YES		X NO
2016 - Fall: N]											
Comments:no	o change												
2017 - Fall: N	lo Change												
Comments:													
2017 - Spring	: No Change												
Comments:													
2018 - Spring	: No Change												
Comments:													
2018 - Fall: N	2018 - Fall: No Change												
Comments:													

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	MJP E/F/V on Fiberglass Pipe Insulation	10	LF	Boiler Room, Crawlspace - 1955		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	Aircell Pipe Insulation	30	LF	Boiler Room, Crawlspace - 1955		TSI	Yes	None	0		YES X NO
2016 - Fall: N	o Change										_

2016 - Fall: No Change	
Comments:no change	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	MJP E/F/V on Aircell Pipe Insulation	5	LF	Boiler Room, Crawlspace - 1955		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
1	Mud Boiler Gaskets	10	LF	Boiler Room - 1955		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall	I: No Change											
Comments	s:no change											
2017 - Fall	2017 - Fall: No Change											
Comments	S:											
2017 - Spr	ring: No Change											
Comments	S:											
2018 - Spr	2018 - Spring : No Change											
Comments	3:											
2018 - Fall	I: No Change				1							

HA No	0	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
J		Mud Packing	2	SF	Boiler Room - 1955		TSI	Yes	None	0		YES X NO	

2016 - Fall: No Change
Comments:no change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Frederick Stock Elementary School
Date: <u>12/15/2018</u>
·
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other. website
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 30081

SCHOOL'S ASBESTOS MANAGEMENT PLAN.