Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

31161

Oracle Unit:

Address: 3500 W. Douglas Region: 03 Mail Room: Asbestos Surveyor: Greason, Daron X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/11/2018 Email Address: dgreason@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type YES 1B Plaster Walls SF X NO 1000 Throughout 1927 Annex Miscellaneous No None 0 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Lawndale Elementary Community Academy

School:

4430

Building ID:

1C	1' x 1' Acoustical Ceiling Tile	20000	SF	1959 Addition		Miscellaneous	Yes	None	0	YES	X NO
2016 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change										
Comments:	, J										
2017 - Fall: N	lo Change										
Comments:	<u> </u>										
2018 - Spring	g : No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:	<u> </u>										

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2B	Plaster Ceilings			Throughout 1927 Annex		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categ	jory
3B	1' x 1' Acoustical Ceiling Tile	2000	SF	Throughout 1927 Annex		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: No Change Comments:												

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
3C1	12" x 12" Brown Floor Tile w/ White Streaks	8000	SF	Kitchen Complex & 1st Floor Hall		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3C2	12" x 12" White Floor Tile w/ Brown Streaks	6000	SF	Kitchen Complex & 1st Floor Hall, Room 330		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Ÿ
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3C3	12" x 12" Gray Floor Tile w/ White & Black Streaks	4820	SF	3rd Floor Teacher's Lounge, 2nd and 3rd Floor Halls		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

3C4	12" x 12" Blue Floor Tile	900	SF	Room 112	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Chango									
	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2018 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4A1	Gray Linoleum			Room 222		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
4A2	Red Linoleum	750	SF	Room 221		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	_											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:	,											
2018 - Fall: N	lo Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4B1	9" x 9" Green Floor Tile - ABATED			Annex		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

	4B2	9" x 9" Brown Floor Tile - ABATED	Washroom, 2nd Floor Hall, Rooms 208 and 211	Miscellaneous			YES	X NO
Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring: No Change	2016 Fal	l: No Chango						
2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change								
Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	Comments	S:						
Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change								
2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	2017 - Spi	ing: No Change						
2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	Comments	S'.						
Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change		**						
Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	2017 - Fal	l: No Change						
Comments: 2018 - Spring : No Change	Comments	S:						
Comments: 2018 - Spring : No Change	2018 - Fal	l: No Change						
2018 - Spring : No Change Comments:								
Comments:	2018 - Spi	ing : No Change						
	Comments	S:						

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4C1	9" x 9" Gray Floor Tile w/Black & White Streaks	11800	SF	Rooms 114, 116-118, 212, 214-218, 220, 312, 314, 315, 317-320, 2nd and 3rd Floor & Halls & Storages		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

										l	
4C2	9" x 9" Light Brown Floor Tile w/Blk & Wh Streaks	3750	SF	Rooms 220, 218, 315, 317, and 319		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	No Change										
Comments:											
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	No Change										
Comments:											
2018 - Spring	g : No Change										
Comments:											
2018 - Fall: N	No Change										
Comments:											
					J						

Type

Material

Category

Miscellaneous

Asbestos

Type

Material

Category

Friable

Friable

No

Damage

Type

None

Damage

Type

Damage

Quantity

Damage

Quantity

0

Damage

Damage

Units

Units

	•	•	
2016 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2018 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			

Material

Quantity

1000

HA No

HA No

5A1

Material Description

Material Description

w/ Brown Streaks

12" x 12" Yellow Floor Tile

Material

Quantity

Material

Material

Units

SF

Units

Material Location

Material Location

Rooms 223-229

Change in Assessment Category

Change in Assessment Category

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5A2	12" x 12" Gray Floor Tile w/ White Streaks	900	SF	Rooms 322		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5A3	12" x 12" Black Floor Tile w/ White Specks	20	SF	Room 329		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
5A4	12" x 12" Orange Floor Tile	2600	SF	Room in Front of Boiler Room and Engineer's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change	•		•	-]	•	•	•	•	•		
Comments:	J											
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:					_							
2018 - Fall: N	No Change											
Comments:					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5A5	12" x 12" Brown Floor Tile	750	SF	Room 227 Wardrobe		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2018 - Spring : No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
5A6	12" x 12" Blue Floor Tile	3500	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:	•											
2017 - Spring	: No Change				1							
Comments:	•											
2017 - Fall: N	lo Change				-							
Comments:	-											
2018 - Spring	: No Change				-							
Comments:												
2018 - Fall: N	lo Change											
Comments:	J											
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5A7	12" x 12" Green Floor Tile	4035	SF	Teachers Lounge (Now Parent Room), Adjacent Hall & Basement Room 01		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

5A8	12" x 12" Brown Floor Tile	175	SF	Hall by Boiler Room	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:	.									
2017 - Fall: N	o Change									
Comments:	Ü									
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:										
2018 - Spring	: No Change									
Comments:	<u> </u>									

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5B	12" x 12" Tan Floor Tile - ABATED			Rooms 104, 105, 107, and 108 Annex Building - DEMOLISHED		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
6A1	9" x 9" Black Floor Tile w/ White Streaks - ABATED			Engineer's Workroom, Room 332, Office left of Pool	71	Miscellaneous		7.			YES	X NO
2016 - Fall: N	lo Change	-	•	•	1	•	•	•	•	•	•	
Comments:	io change											
2017 - Spring	g: No Change											
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6A10	9" x 9" Brown Floor Tile w/ Light Brown Streaks	3400	SF	Rooms 321, 322, 323, 324, 329, and 422		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6A2	9" x 9" Red Floor Tile w/ White Streaks	1200	SF	Engineer's Office 03		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
	·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6A3	9" x 9" Purple Floor Tile	1200	SF	Engineer Office 03		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No Ma	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	" x 9" Brown Floor Tile w/ rown & White Streaks	3000	SF	Rooms 421, 422, 323, 325, 328, 329, 330, 331, and 323		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6A5	9" x 9" Brown Floor Tile w/ White and Red Streaks	3500	SF	Rooms 421, 422, 322, 324, 325, 329, and 331		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6A6	9" x 9" Dark Brown Floor Tile w/ Wh & Brn Streaks	3350	SF	Rooms 322-325, 328- 331, and 421-422		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6A7	9" x 9" Tan Floor Tile	625	SF	Room 221 Pantry		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6A8	9" x 9" Brown Floor Tile w/ White Streaks	950	SF	Rooms 331 and 323		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6A9	9" x 9" Gray Floor Tile w/ Black & White Streaks	1650	SF	Rooms 102/now 122 and 422		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
7A	Stage Curtain	2500	SF	Stage in Auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	ı: No Change											
Comments:	,											
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2018 - Spring	ı : No Change											
Comments:	, <u> </u>											
2018 - Fall: N	lo Change											
Comments:												
_								_			1	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8A	Black and Brown Terrazzo	15000	SF	1st, 2nd, 3rd, and 4th Floor Halls, Engineer's Storage, Lobby and Foyer		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8B	Tan, Black, and Brown Terrazzo	12000	SF	1st, 2nd, 3rd, and 4th Floor Halls, Lobby, Engineer's Storage, Office		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2040 Full No Oleven	
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8C	Tan and Brown Terrazzo	1000	SF	Engineer's Storage Room, Lobby and Foyer		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
9	Blue Ceramic Tile Grout	1300	SF	2nd and 3rd Floor Mens Washrooms and Locker Rooms		Surface	No	None	0		YES	X NO
2016 - Fal	II: No Change]							
Comments	s:											
2017 - Spr	ring: No Change											
Comments	S:											
2017 - Fal	II: No Change											
Comments	s:											
2018 - Spr	ring : No Change											
Comments	S:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	Tan Ceramic Tile Grout	600	SF	Main Building - Shower Rooms and Men's Lounge		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
11	Red Clay Tile (Clay Brick)	2000	SF	Main BldgLocker Rooms, Shower Room, Basement Hall		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change	<u> </u>	<u> </u>	·]							
Comments	:				-							
2017 - Spri	ng: No Change				<u> </u>							
Comments	:				-							
2017 - Fall:	No Change											
Comments	:				4							
2018 - Spri	ng : No Change											
Comments	:				_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Red Clay Tile Mortar (Brick Mortar)	2000	SF	Main BldgLocker Rooms, Shower Room, Basement Hall		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
13	Terrazzo Wall Panels	6000	SF	Main BldgBoys & Girls Washrooms, Showers, Locker Rooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change	•		•	-]	•	•	•	•	•	•	
Comment												
2017 - Sp	ring: No Change				-							
Comment	S:]							
2017 - Fal	I: No Change											
Comment	S:											
2018 - Sp	ring : No Change											
Comment	S:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Fireplace Brick	200	SF	Main Building - Rooms 102/now 122 and 103, 121, 123		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
15	Fireplace Brick Mortar	200	SF	Rooms 122 and 123		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:]							
2017 - Spring	g: No Change				_							
Comments:												
2017 - Fall: N	lo Change				_							
Comments:]							
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change				-							
Comments:	Ţ.											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	Blue Carpet Mastic - ABATED			Room 121		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
17	9" Stone Floor Tile	3500	SF	Room 01 and Basement Hall		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change				1							
Comments	s:											
2017 - Spr	ring: No Change											
Comments	S:											
2017 - Fal	I: No Change											
Comments	S:											
2018 - Spr	ring : No Change											

Ī	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Ī	18	Stone Tile Mortar	2500	SF	Room 01 and Basement Hall		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

Comments:

2018 - Fall: No Change

19	Red Ceramic Tile Grout	1300	SF	2nd and 3rd Floor Girls Washroom, Girls Shower Room	Miscellaneous	No	None	0	YES	X NO
2016 - Fall	: No Change									
Comments	S:									
2017 - Spr	ing: No Change									
Comments	S:									
	: No Change									
Comments	S:									
2018 - Spr	ing : No Change									
Comments	S:									
2018 - Fall	: No Change									
Comments	S:									

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Vibration Collars	50	LF	Fan Rooms-4th Floor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asses	sment Category
21	Block	3000	SF	Boiler Room and Fan Rooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change											
Comments	S:				_							
2017 - Spr	ing: No Change											
Comments	S:				_							
2017 - Fall	: No Change											
Comments	S:											

2018 - Spring : No Change Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Block Mortar	3000	SF	Boiler Room and Fan Rooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Type	Category		Туре	Quantity	Units		
23	12"x12" Gray w/ White Streaks Floor Tile Mastic	1000	SF	Rooms 322		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change											
Commonte	,,											
2017 - Spr	ing: No Change											
Comments	3:											
2017 - Fall	: No Change											
Comments	3:											
2018 - Spr	ing : No Change											
Comments	_ • •											
1					I							

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	9" x 9" Tan Floor Tile Mastic			Room 221 Pantry		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

2018 - Fall: No Change

Comments:

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
25	Black Baseboard	600	LF	Room 04, Mens & Womens Basement Washrooms, Room 221		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change	•	•	•	7	•	•	•	•	•	•	
Comment												
2017 - Spi	ring: No Change											
Comments	S:											
2017 - Fal	I: No Change											
Comment	S:				_							
2018 - Spi	ring : No Change											
Comments	s:	·										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	Black Baseboard Mastic	600	LF	Room 04, Mens & Womens Basement Washrooms, Room 221		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	9"x9" Dk Brn w/ Red & Wh Streaks Floor Tile Mastic	3725	SF	Rooms 422, 322, 324, 325, 329, 331, and 421		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12" x 12" Yellow Floor Tile Mastic	4050	SF	Rooms 223, 224, 225, 226, 227, 228, 229		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
29	12" x 12" Orange Floor Tile Mastic	2600	SF	Engineer's Office & Room Before Boiler Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12" x 12" Ceiling Tiles With Holes	1000	SF	Room 327		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12" x 12" Brown Floor Tile Mastic	750	SF	Room 227 Wardrobe		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12" x 12" Black Floor Tile w/ White Specks Mastic	525	SF	Room 329		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

33	9"x9" Black Floor Tile White Streaks-Mastic-ABATED	Engineer's Work Room, Room 332, and Office Left of Pool	Miscellaneous			YES	X NO
2016 Fall	. No Change	<u> </u>	·]				
	: No Change						
Comments	:						
2017 - Spri	ing: No Change						
Comments	:						
2017 - Fall	: No Change						
Comments	:						
2018 - Spri	ing : No Change						
Comments	:						
2018 - Fall	: No Change						
Comments	:						

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	9" x 9" Red Floor Tile w/ White Streaks Mastic	1200	SF	Engineer Office 03		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	9" x 9" Purple Floor Tile Mastic	1200	SF	Engineer Office 03		Miscellaneous	No	None	0		YES X NO

				·
2016 - Fall: N	lo Change			
Comments:				
2017 - Spring	j: No Change			
Comments:				
2017 - Fall: N	lo Change			
Comments:				
2018 - Spring	j : No Change			
Comments:				
2018 - Fall: N	lo Change			
Comments:				·
·		•	•	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	9" x 9" Dark Brown w/White & Brn Floor Tile Mastic	3500	SF	Rooms 421, 422, 328, 329, 330, 331, and 323		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12" x 12" Green Floor Tile Mastic	8710	SF	Teacher's Lounge (Now Parent Room), Adjacent Hall & Basement Rm. 01		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12" x 12" Blue Floor Tile Mastic	3500	SF	Auditorium		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	9" x 9" Brown w/White & Brown Floor Tile Mastic	5375	SF	Rooms 421, 422, 322, 323, 324, 325, 328, 329, 330 & 331		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	9" x 9" Brown Floor Tile w/ White Streaks Mastic	950	SF	Room 323 and 331		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	9" x 9" Gray Floor Tile w/ Black & White Mastic	1650	SF	Rooms 102/now 122 and 422		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	9" x 9" Brown Floor Tile w/ Brown Streaks Mastic	3400	SF	Rooms 321, 322, 323, 324, 329, and 422		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Туре	Category		Type	Quantity	Units		
43	Ceiling Plaster	4050	LF	Pool Area		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change	•				·						
Comments:	<u> </u>											
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
	g : No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												

Material

Damage

Damage

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	Fire Door Insulation	21	SF	Pool Area-Bleacher Area		TSI	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material Location

Damage Change in Assessment Category

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
45	Brown Ceramic Tile Grout	5000	SF	Pool Floor and Shower Walls		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	g: No Change											
Comments:					_							
2017 - Fall: N	lo Change				_							
Comments:					-							
	g : No Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:												

Material

Damage

Friable

Damage

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	Interior Window Caulk	100	LF	Pool Area		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assessment Category
47	Beige Vinyl Baseboard	108	LF	Office Area Left of Pool		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				Ī							
Comments:	_											
2017 - Spring	g: No Change				1							
Comments:]							
2017 - Fall: N	lo Change				1							
Comments:												
2018 - Spring	g : No Change				1							
Comments:	J											
2018 - Fall: N	lo Change				_							
Comments:	-]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Beige Vinyl Baseboard Mastic	108	LF	Office Area Left of Pool		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
49	Vibration Damper	50	LF	Mechanical Room Left of Pool Equipment Area		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:												
Comments:												
2017 - Sprin	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:	.											
2018 - Sprin	ng : No Change				<u> </u>							
Comments:												
2018 - Fall:	No Change											
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	Paper Insulation	0	LF	Pool Tunnel		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

51	Cementitious Joint Insulation on Paper Wrap Pipes		Pool Tunnel		TSI			YES	X NO
004C F-I	l. N.a. Ob a a sa			1					
	l: No Change								
Comments	S:								
2017 - Spi	ring: No Change								
Comments	S:								
				1					
2017 - Fal	I: No Change								
Comments	S:								
				1					
2018 - Spi	ring : No Change								
Comments									
				1					
2018 - Fal	I: No Change	•	_						
Comments				1					

Type

Material

Category

Material Location

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	Joint Compound	50	LF	C wall (patched area) in Pool Area		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
53	Cinder Block Mortar	3000	SF	Boiler Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change				_							
Comments:												
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:	J											
2018 - Fall: N	o Change				_							
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	Cinder Block	3000	SF	Boiler Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
55 A	Tank Insulation			Boiler Room (Tank Closest to Wall)		TSI					YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	j : No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55 B	Tank Insulation			Boiler Room-Tank Furthest From Wall		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
56	First Layer of Insulation			Boiler Room-(Tank Closest to Wall)		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	White Baseboard	100	LF	Locker Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
58	White Baseboard Mastic	100	LF	Locker Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change				-							
Comments:												
2017 - Fall: N	lo Change											
Comments:	-											
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change				-							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	Stone Baseboard Mastic	4000	SF	Throughout 1927 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
60	Interior Window Grout	500	LF	Throughout Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				7							
Comments:												
2017 - Sprin	g: No Change				-							
Comments:												
2017 - Fall: I	No Change				-							
Comments:												
2018 - Sprin	g : No Change				-							
Comments:												
2018 - Fall: I	No Change				+							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	Interior Window Glazing	500	LF	Throughout Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in As	sessment Categor
		Quantity	Units		Type	Category		Туре	Quantity	Units	1	
62	Black and Brown Carpet Mastic	300	SF	Men's Teachers Lounge, 2nd Floor Landing		Miscellaneous	No	None	0		YES	X NO
	. 0:				1							
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change				-							
Comments:	<u> </u>											
2019 Spring	g : No Change				-							
	g . No Change				1							
Comments:												
	 .				_							
2018 - Fall: N	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	Insulation Inside of Fire Doors		SF	Entrances and Exits		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
64	9" x 9" Green Floor Tile Mastic - ABATED			1929 Annex - 208, 211, 1st Floor Girls Washroom, 2nd Floor Hall - DEMOLISHED		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				7							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:	_											
2018 - Fall: N	No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	9" x 9" Brown Floor Tile Mastic - ABATED			1929 Annex- 208, 211, 1st Floor Girls Washroom, 2nd Floor Hall - DEMOLISHED		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

66	12" x 12" Tan Floor Tile Mastic - ABATED	1929 Annex - F 103, 104, 105, DEMOLISHED	107 -	Miscellaneous			YES	X NO
2016 - Fall	I: No Change							
Comments								
2017 - Spr	ring: No Change							
Comments	S:							
2017 - Fall	I: No Change							
Comments	S:							
2018 - Spr	ring : No Change							
Comments	S:							
2018 - Fall	I: No Change							
Comments	S:							

Type

Material

Category

Miscellaneous

Asbestos

Type

Material

Category

Friable

Friable

No

Damage

Type

None

Damage

Type

Damage

Damage

Units

Units

Damage

Quantity

Damage

Quantity

0

Change in Assessment Category

Change in Assessment Category

YES

X NO

2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

Material

Quantity

420

Material

Units

SF

HA No

HA No

67

Material Description

Material Description

Block Walls

Material

Units

Material

Quantity

Material Location

Material Location

1929 Annex Boiler Room

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
68	Block Mortar	420	SF	1929 Annex- Boiler Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	Brick Walls	420	SF	1929 Annex- Boiler Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

70	Brick Mortar	420	SF	1929 Annex- Boiler Room		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Chongo				1						
	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:	-										
2018 - Spring	: No Change										
Comments:	-										
2018 - Fall: N	o Change										
Comments:											
					1						

Type

Material

Category

Damage Quantity Damage

Units

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	Terrazzo Flooring			1929 Annex- Hallways - DEMOLISHED		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
72	Terrazzo Stall Panels			1929 Annex - DEMOLISHED		Miscellaneous					YES	X NO
2016 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:					_							
2018 - Spring	: No Change											
Comments:					_							
2018 - Fall: N	o Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	Exterior Face Brick - Not AHERA			1929 Annex		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

Page 52

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
74	Exterior Face Brick Mortar - Not AHERA			1929 Annex		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
75	Exterior Brick - Not AHERA			1929 Annex		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

76	Exterior Brick Mortar - Not AHERA		1929 Annex	Miscellaneous			YES	X NO
2016 - Fall: N	o Change							
Comments:	o onango							
2017 - Spring	: No Change							
Comments:								
2017 - Fall: N	o Change							
Comments:								
2018 - Spring	: No Change							
Comments:								
2018 - Fall: N	o Change							
Comments:								

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	Roof and Flashing - Not AHERA			1929 Annex roof		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
78	12" x 12" Tan Floor Tile			Fieldhouse		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	•											
2017 - Spring	ı: No Change				-							
Comments:	,											
2017 - Fall: N	lo Change				-							
Comments:	<u> </u>											
2018 - Spring	ı : No Change				-							
Comments:	<u> </u>											
2018 - Fall: N	lo Change				+							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
79	12" x 12" Tan Floor Tile Mastic			Fieldhouse		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	ent Category
80	Brick Walls			Fieldhouse - DEMOLISHED		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	Ü]							
2017 - Spring	: No Change				1							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:												
2018 - Spring	ı : No Change				-							
Comments:												
2018 - Fall: N	lo Change				-							
Comments:	-]							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
81	Brick Mortar			Fieldhouse Walls - DEMOLISHED		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
82	9"x9" Light Brown FT w/Blk & White Streaks Mastic	3750	SF	Rooms 218, 220, 315, 317, and 319		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:	
Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change	
2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2016 - Fall: No Change
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Spring: No Change
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Fall: No Change
Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Fall: No Change	2019 Caring : No Change
2018 - Fall: No Change	1 0 0
	Comments:
Comments:	2018 - Fall: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
83	12" x 12" White Floor Tile w/ Brown Streaks Mastic	6600	SF	Cafeteria, Kitchen, Serving Room, 1st Floor Hall, Room 330		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
84	12"x12" Gray Floor Tile w/Wh & Blk Streaks Mastic	3350	SF	3rd Floor Teachers Lounge, 2nd and 3rd Floor Halls		Miscellaneous	No	None	0		YES X NO
		•	,	•	1	•	•	•	•	•	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
85	12" x 12" Blue Floor Tile Mastic	75	SF	Room 112 East Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
86	12"x12" White Floor Tile w/ Brown Streaks Mastic	3350	SF	Cafeteria, Kitchen, 1st Floor Hall, Serving Room, Faculty Dining Room		Miscellaneous	No	None	0		YES X NO
	•	•	•		•	•	•	•	•	=	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
87	Aircell Pipe Insulation	2500	LF	Inside Walls Throughout Facility		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
88	Cinder Block Mortar	5000	SF	Throughout Facility		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
89	Gray Baseboard	1000	LF	Throughout Facility		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Page 60

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
90	Gray Baseboard Mastic	600	LF	Throughout Facility		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change											
Comments:												
2018 - Sprin	ng : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
91	Glazed Brick Mortar	30000	SF	Throughout Building		Surface	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
92	Brown Baseboard	600	LF	Faculty Dining Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Spring	g: No Change				-							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:												
2018 - Spring	g : No Change				-							
Comments:												
2018 - Fall: N	lo Change											
Comments:					1							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
93	Brown Baseboard Mastic	600	LF	Faculty Dining Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
94	12" x 12" Ceiling Tile	300	SF	Women's 1st Floor Faculty Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	II: No Change											
Comments												
2017 - Spr	ring: No Change				_							
Comments	S:											
2017 - Fall	II: No Change											

Comments:

2018 - Fall: No Change Comments:

2018 - Spring : No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
95	Gray Baseboard	500	LF	Room 112		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	ment Category
96	Gray Baseboard Mastic	500	LF	Room 112		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change												
Comments:													
2017 - Sprin	g: No Change												
Comments:	<u> </u>												
2017 - Fall: N	No Change												
Comments:	Ŭ												
2018 - Fall: N	No Change												
Comments:													
2018 - Sprin	g : No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
97	Drywall	700	SF	Room 112		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assessi	ment Category
98	Mastic for Wall Tile in Washroom	1500	SF	Room 112		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: Comments:	No Change												
Comments:	No Change												
	ng: No Change												
Comments:	•				_								
2018 - Fall:	No Change												
Comments:													

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99	Ceramic Tile Grout	840	SF	Washrooms and Foyer		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Spring : No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
100	Exterior Brick - Not AHERA			1959 Addition		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	J											
2017 - Spring	ı: No Change				-							
Comments:	,				1							
2017 - Fall: N	lo Change											
Comments:	J											
2018 - Fall: N	lo Change											
Comments:					1							
2018 - Spring	ı : No Change											
Comments:												
					j							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	Exterior Brick Mortar - Not AHERA			1959 Addition		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
102	Roofing and Flashing - Not AHERA			1959 Addition Roof		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:	-											
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	ı : No Change											
Comments:												
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	9" x 9" Gray w/ Black & White Floor Tile Mastic	10100	SF	1959-Rms 114,116-118, 212, 214-218, 220,312, 314,315, 317-320, 2nd and 3rd Floor & Halls & Storages		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

104	12" x 12" White Floor Tile w/Black Flecks	800	SF	Room 121		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
2016 - Fall: No Change Comments:				-								
Comments.												
2017 - Fall: N	lo Change											
Comments:												
0047 0	NI- OL-											
	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:	, ,											
2040 Falls N	la Changa]							
2018 - Fall: N	io Change				-							
Comments:												
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units	atoriai Educatori	Type	Category	. 110010	Type	Quantity	Units	5ango in 7.00000	c.ii Calogory

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

105	12" x 12" White Floor Tile w/Black Flecks Mastic	800	SF	Room 121	Miscellaneous	No	None	0	
2016 - Fall:	No Change								
Comments:									
2017 - Fall:	No Change								
Comments:	-								
2017 - Sprin	g: No Change								
Comments:									
2018 - Fall:	No Change								

2018 - Spring : No Change Comments:

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

Page 68

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
106	4" Black Vinyl Baseboard	130	LF	Room 121		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
107	4" Black Vinyl Baseboard Mastic	130	LF	Room 121		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

108	12" x 12" Beige w/Brown Streaks Floor Tile - REMOVED		Room 324 in the 1927 Building		Miscellaneous				YES	X NO
0040 5 11 1				1		•		•	•	
2016 - Fall: I	No Change									
Comments:										
2017 - Sprin	g: No Change									
Comments:										
2017 - Fall: I	No Change									
Comments:	-									
2018 - Fall: I	No Change									
Comments:	<u> </u>									
2018 - Sprin	g : No Change									
Comments:	<u> </u>									
1				1						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
109	12" x 12" Beige w/Brown Streaks Floor Tile Mastic - REMOVED			Room 324 in the 1927 Building		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
110	12"x12" White Vinyl Floor Tile	1275	SF	Room 330, 121		Miscellaneous	No	None	0		YES X NO

2016 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			
2018 - Spring	ı : No Change		
Comments:			
		•	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
111	12" x 12" White Vinyl Floor Tile - Matic	1275	SF	Room 330, 121		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
112	12" x 12" Brown and Tan Vinyl Floor Tile	425	SF	Room 114, 319, 324		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
113	12" x 12" Brown and Tan Vinyl Floor Tile - Mastic	425	SF	Room 114, 319, 324		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
114	12" x 12" Blue Vinyl Floor Tile	1550	SF	Room 116, 122, 315, 322		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
115	12" x 12" Blue Vinyl Floor Tile - Mastic	1550	SF	Room 116, 122, 315, 322		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

		Quantity	Units		Type	Category	Туре	Quantity	Units		
116	Tank Insulation			Boiler Room Tank #1		TSI	None			YES	X NO
2016 - Fall: I	No Change				7						
Comments:											
2017 - Fall: I	No Change										
Comments:					_						
2017 - Sprin	g: No Change										
Comments:											
2018 - Fall: I	No Change										
Comments:											
2018 - Sprin	g : No Change										
Comments:											

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
117	12"x12" White Vinyl Floor Tile - Patches	80	SF	Parent Room, 04		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
118	12"x12" White Vinyl Floor Tile - Patches - Mastic	80	SF	Parent Room, 04		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
119	Brown Carpet	750	SF	Room 327		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
120	Brown Carpet - Adhesive	750	SF	Room 327		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change							•	•			
Comments:												
2017 - Spring	: No Change											
Comments:	_											
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:	<u> </u>											
2018 - Fall: N	o Change											
Comments:	-											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
121	Drywall	800	SF	New Boiler Room, New Electrical Room in Cafeteria		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
122	Drywall Compound	800	SF	New Boiler Room, New Electrical Room in Cafeteria		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change	-		. —			. —				

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
123	T.S.I.	30	LF	Hanging Tank - Boiler Room Tank #3		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
124	Gray Linoleum Adhesive			Room 222		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	_											
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
125	Red Linoleum Adhesive	750	SF	Room 221		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
126	12"x12" Brown Floor Tile - Mastic	200	SF	Wall by Boiler Room		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2040 0 : N 0
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
130	Tan, Black Terrazo Flooring	875	SF	Main Entrance East Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
131	Blue, White Ceramic Floor Tile Grout	1080	SF	1st, 2nd, 3rd Floors Boys Wash Rooms East Buildings		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change						•	•	•	•		•	

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
132	Blue, White Ceramic Floor Tile Adhesive	1080	SF	1st, 2nd, 3rd Floors Boys Wash Room East Buildings		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
133	White, Grey Ceramic Floor Tile Grout	1080	SF	1st, 2nd, 3rd Floors Girls Wash Room East Buildings		Miscellaneous	No	None	0		YES X NO
2040. Falls Na Ohanna						-			-		

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
134	White Grey Ceramic Floor Tile Adhesive	1080	SF	1st, 2nd, 3rd Floors Girls Wash Room East Buildings		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
135	Brown Ceramic Floor Tile Grout	1800	SF	1st, 2nd, 3rd Floors Girls Wash Rooms West Buildings		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change			•								

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
136	Brown Ceramic Floor Tile Adhesive	1800	SF	1st, 2nd, 3rd Floors Girls Wash Room West Buildings		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
137	Blue Ceramic Floor Tile Grout	1800	SF	1st, 2nd, 3rd Floors Boys Wash Room West Buildings		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
138	Blue Ceramic Floor Tile Adhesive	1800	SF	1st, 2nd, 3rd Floors Boys Wash Room West Buildings		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
139	Black, White, Brown Terrazo Flooring	20000	SF	Throught The West Buildings		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2010 0 1 11 01	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
140	Black Vibration Collars	20	SF	Engineers Office, West Buildings		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assessment Category
141	Red Ceramic Flooring & Grout	5000	SF	West Bldg. Basement		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				1							
Comments:	_											
2017 - Fall: N	No Change											
Comments:	J											
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
142	Red Ceramic Tile Mastic	5000	SF	West Bldg. Basement		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
143	12" X 12" Beige Floor Tile	1025	SF	Rooms 221 (Storage Room) and 222		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
144	Mastic Associated w/ 12" x 12" Beige Floor Tile	1025	SF	Rooms 221 (Storage Room) and 222		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
B1	Joint Insulation off Fiberglass Pipe Insulation	400	LF	Main Building - Throughout		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	-											
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A1	Fiberglass Pipe Insulation			Throughout Facility		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
A2	Fiberglass Pipe Insulation			Throughout Facility		TSI					YES	X NO
2016 - Fall: N	lo Change											
Comments:]							
2017 - Spring	g: No Change				_							
Comments:												
2017 - Fall: N	lo Change				_							
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change				-							
Comments:	•											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A3	Cementitious Pipe Joints Insulation	125	SF	Throughout Facility		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
B1	Hard Joint Compound on Fiberglass Pipe Insulation	200	LF	Throughout Main Building		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change]			•	•			
Comments:					=							
2017 - Spring	g: No Change				-							
Comments:												
2017 - Fall: N	lo Change				=							
Comments:	-											
2018 - Spring	g : No Change				-							
Comments:	<u> </u>											
2018 - Fall: N	lo Change											
Comments:	<u> </u>				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B2	Cementitious Joint Insulation on Fiberglass Lines	30	LF	Throughout Facility		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
C1	Aircell Pipe Insulation	950	LF	Throughout Facility		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change					•	·			•		
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2018 - Sprir	ng : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
C2	Aircell Pipe Insulation	1700	LF	Throughout Facility		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
D1	Cementitious Joint Insulation off Aircell Lines	225	LF	Throughout Facility		TSI	Yes	None	0		YES X NO	
2016 Fall: No Change												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D2	Cementitious Joint Insulation off Aircell Lines	50	SF	Throughout Facility		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
E1	Cardboard Pipe Insulation	50	LF	Boiler Room		TSI	Yes	None	0		YES	X NO
	No Change											
Comments	:											
2017 - Spri	ng: No Change											
Comments	•											
2017 - Fall:	No Change											
Comments	•											
2018 - Fall:	No Change											
Comments	<u>: </u>											
1												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
E2	Cardboard Pipe Insulation	25	LF	T Room		TSI	Yes	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2018 - Spring : No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
EB1	Exterior Brick (Not AHERA)			Main Building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	g: No Change											
Comments:	, <u> </u>											
2017 - Fall: N	lo Change				-							
Comments:	_											
2018 - Fall: N	lo Change				-							
Comments:												
2018 - Spring	g : No Change				-							
Comments:												
					_							
	T			1		1		1	1		1	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
EM1	Exterior Brick Mortar (Not AHERA)			Main Building		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
EWC1	Exterior Window Glazing (Not AHERA)			Main Building		Miscellaneous					YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:	Ü											
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
	T	1		I and a second	T	T	T = · · ·	T =	T =		1 0	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
EWG1	Exterior Window Glazing (Not AHERA)			Main Building		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
F1	Flashing (Not AHERA)			Upper Level Roof Above Gym- Main Building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:]							
2017 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	g: No Change				-							
Comments:												
2018 - Fall: N	lo Change				-							
Comments:												
2018 - Spring	g : No Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F2	Cementitious Joint Insulation off Cardboard Lines	20	LF	Annex T Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
F3	Flashing (Not AHERA)			Lower Level Roof above Gym- Main Building		TSI					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	•											
2017 - Fall: N	lo Change											
Comments:	-				1							
2017 - Spring	ı: No Change				_							
Comments:												
2018 - Spring	ı : No Change											
Comments:												
2018 - Fall: N	lo Change				_							
Comments:												
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F4	Flashing (Not AHERA)			3rd Story Roof- Main Building		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
F5	Flashing (Not AHERA)			4th Story Roof		TSI					YES	X NO
2016 - Fall: N	o Change											
Comments:					_							
2017 - Fall: N	o Change											
Comments:	<u> </u>				1							
2017 - Spring	: No Change											
Comments:					1							
2018 - Spring	: No Change				-							
Comments:]							
2018 - Fall: N	o Change				-							
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G2 T2	Insulation on Large Tank			Boiler Room- 1929 Annex		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
G2B	Boiler Insulation			Boiler Room- 1929 Annex		TSI				YES	X NO
2016 - Fall: N	lo Change										
Comments:											
2017 - Spring	: No Change										
Comments:	•										
2017 - Fall: N	lo Change										
Comments:											
2018 - Spring	ı : No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:	-										

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G2T1	Insulation on Small Tank			Boiler Room- 1929 Annex		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	ment Category
R1	Roofing (Not AHERA)			Upper Level Roof Above Gym		Surface					YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change											
Comments:	-											
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R2	Shingles (Not AHERA)			Shingled Slant Roof- Main Building		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categ	jory
R3	Roofing (Not AHERA)			Lower Level Roof above Gym		Surface					YES X NO	
2016 - Fall: I	No Change]							
Comments:	J											
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
					_							
LIA NI-	Material December Con	NA-t	I Martardal	Material Landin	A -11	Maria de la	I markets	D	I D	I B	0.	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R4	Roofing (Not AHERA)			3rd Story Roof		Surface					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	nt Category
R5	Roofing Material (Not AHERA)			4th Story Roof		Surface					YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	<u> </u>											
2017 - Spring	g: No Change				1							
Comments:	<u>-</u>											
2017 - Fall: N	lo Change				=							
Comments:												
2018 - Spring	g : No Change				-							
Comments:												
2018 - Fall: N	lo Change				=							
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R6	Roofing			Roof Above Pool		Miscellaneous					YES X NO
 	01			1							

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
TP1	Tar Paper (Not AHERA)			3rd Story Roof		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Lawndale Elementary Community Academy
Date: 12/11/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.