Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Ashburn Community Elementary School 32081 Building ID: 7100 School: **Oracle Unit:** Address: 8300 S. St. Louis Region: 05 Mail Room: Asbestos Surveyor: Saldana, Jose X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/26/2018 Email Address: A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Type Quantity MJP E/F/V on Corrugated YES 02 100 LF X NO All Floors in Building TSI Yes None Pipe Insulation 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

03	Corrugated Pipe Cover	500	LF	All Floors in Building		TSI	Yes	None	0	YES	X_NO
2016 - Fall: N	lo Change				1						
Comments:	V										
2017 - Fall: N	lo Change]						
Comments:					1						
	g: No Change										
Comments:					1						
2018 - Fall: N	lo Change										
Comments:					-						

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	MJP E/F/V on Paper Wrapped Pipe Insulation	100	LF	All Floors in Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
05	Paper Wrapped Pipe Insulation	5	LF	All Floors in Building		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	MJP E/F/V on Paper Wrapped Pipe Insulation	2	LF	Basement		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
07	Paper Wrapped Pipe Insulation	10	LF	Basement		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change]							

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	MJP E/F/V on Corrugated Pipe Insulation	100	LF	All Floors in Buidling		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

0040	1. 01										
2016 - Fall: N	lo Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:	io oriango										
2017 - Spring	r. No Change										
Comments:	y. 110 Onlango										
2018 - Fall: N	lo Chango										
	io Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

Type

Type

Material

Category

Category

Miscellaneous

TSI

Friable

Yes

Yes

Damage

Type

None

Type

None

Damage

Quantity

Quantity

0

0

Damage

Units

Units

	_		FIOOI
2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			
		 	 -

Quantity

7000

Units

SF

Material

Units

LF

Material

Quantity

Material Location

All Floors in Building

Basement, 1st and 2nd

HA No

09

10

Material Description

Corrugated Pipe Insulation 600

1'x1' Acoustical Ceiling Tile

Change in Assessment Category

X NO

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	9"x9" Dark Red w/Cream Specks Floor Tile	24200	SF	1st and 2nd Floors Rooms: 101,102, 103, 104, 105, 107, 201, 202, 203, 204, 205, 206, 207, 208, 209, and 211		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	MJP E/F/V on Corrugated Pipe Insulation	100	LF	AllI floors in building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
13	Corrugated Pipe Insulation	600	LF	All Floors in Building		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change]							
	lo Chongo				-							
2017 - Fall: N Comments:	io Change											
2017 - Spring	g: No Change											
Comments:												

НА	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14		1'x1' Acoustical Ceiling Tile Mastic	28400	SF	Basement, 1st and 2nd Floor Hallways		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change		
Comments:		
Comments.		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

2018 - Fall: No Change

Comments:

Page 7

15	9"x9" Black w/Cream Speckled Floor Tile	420	SF	1st Floor Maintenance	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	lo Change									
2017 - Fall: N Comments:	lo Change									
2017 - Spring Comments:	g: No Change									
2018 - Fall: N Comments:	lo Change									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	1'x1' Acoustical Ceiling Tile	100	SF	Throughout Building and Basement		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

Oracle Unit: 32081

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	9"x9" Dark Brown Floor Tile	8058	SF	Under 12"x12" Floor Tile in Basement, 113, 114, 116, 117, Janitor's Closet, 210, 212, 213, 215, 216, and 217		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	1'x1' Acoustical Ceiling Tile Mastic	8058	SF	Throughout Building		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

22	Breeching/Exhaust Packing	320	SF	Boiler Room	TSI	Yes	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2018 - Fall: N	o Change									

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22a	Corrugated Pipe Insulation	65	LF	Boiler Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22b	MJP E/F/V on Corrugated Pipe Insulation	65	LF	Boiler Room		TSI	Yes	None	3		YES X NO
2016 - Fall: N	No Change										
	Comments:										

2016 - Fall. No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Vibration Dampening Cloth	5	SF	Basement Storage		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

2016 - Fall:	No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
2017 - Sprin	g: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

2000

HA No

24

25

2016 - Fall: No Change

Material Description

12"x12" Pink Floor Tile

Vinyl Baseboard and Mastic 376

Material

Quantity

Material

Units

LF

SF

Material Location

Ground Floor

Lunchroom / Gym

Change in Assessment Category

X NO

X NO

YES

26	Mastic	2000	SF	Lunchroom / Gym		Miscellaneous	NO	None	0		YES	X NO
2016 - Fall: N	lo Chango				1							
	io Change				4							
Comments:												
2017 - Fall: N	lo Change											
Comments:]							
2017 - Spring	g: No Change											
Comments:]							
2018 - Fall: N	lo Change											
Comments:												
]							
	_	•	•		_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
27	12'x12" White Floor Tile	1000	SF	Lunchroom / Gym		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Comments:	o Change											

2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change

Material

Quantity

2000

Material

Units

SF

Material Location

Lunchroom / Gym

HA No

Comments:

26

Material Description

12"x12" Pink Floor Tile

Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
28	12"x12" White Floor Tile Mastic	1000	SF	Lunchroom / Gym		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change				7							
Comments	S:											
2017 - Fall	l: No Change											
Comments	S:											
2017 - Spr	ing: No Change											
Comments	S:											
2018 - Fall	l: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Carpet Mastic	3000	SF	Rooms 108, 110, 112, 218, 219, and Library		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

2016 - Fall: N	No Change										
Comments:											
2017 - Fall: N	No Change										
Comments:					4						
2017 - Spring	g: No Change										
Comments:					_						
2018 - Fall: N	No Change										
Comments:					4						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

1000

HA No

30

31

Material Description

12 x 12 Blue Floor Tile

Green and Beige Terrazzo

Material

Units

SF

SF

Material

Quantity

10000

Material Location

Hallways and Stairwells

Rooms 106 and 109

Change in Assessment Category

X NO

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
32	12 x 12 Blue Floor Tile Mastic	1000	SF	Rooms 106 and 109		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12x12 Gray w/specks VFT	3500	SF	Rooms 114, 214, 215, 216, 217 and 210		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 16

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Cate	gory
33B	12x12 Gray w/specks VFT Mastic	3500	SF	Rooms 114, 214, 215, 216, 217 and 210		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: N	lo Change	•		_	1			•	•	•		

016 - Fall: No Change
Comments:
017 - Spring: No Change
Comments:
017 - Fall: No Change
Comments:
018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Carpet Mastic	1500	SF	Room 111, 212, Faculty room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

2016 - Fall:	No Change										
Comments:											
2017 - Fall:	No Change										
Comments:	1										
2017 - Spri	ng: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
					<u> </u>						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
	·	Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Yes

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

HA No

99

100

Comments:

Comments:

Comments:

Comments:

Material Description

Transite Siding

Drywall system

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material

Quantity

100

600

Material

Units

SF

SF

Material Location

Multipurpose room

Ground Floor

Change in Assessment Category

X NO

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessn	nent Category
101	Fire door	1	EA	Electrical room/ gym storage		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 Fall: No Change
2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102	12"x12" white w/ tan and light brown specks VFT	2100	SF	Rooms 202, 210, and 213		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

102A	12"x12" white w/ tan and light brown specks VFT MASTIC	2100	SF	Rm 202, 210, and 213		Miscellaneous	No	None	0		YES	X NO
	. 01	•	•	•	1	•	•	•	•	•		
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	12"x12" white w/ tan specks VFT	700	SF	Room 113		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Ca	itegory
103A	12"x12" white w/ tan specks VFT MASTIC	700	SF	Room 113		Miscellaneous	No	None	0		YES X NO	0
2016 - Fall: N	lo Change]							

[
2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104	12"x12" light & gray w/ gray & white specks VFT	2900	SF	Rooms 216, 215, 217, 214		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104A	12"x12" light & gray w/ gray & white specks VFT Mastic	2900	SF	Rm 246, 215, 217, 214		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Ashburn Community Elementary School
Date: 9/4/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 32081

SCHOOL'S ASBESTOS MANAGEMENT PLAN.