Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

45211 Chicago Academy Elementary School 6670 School: **Oracle Unit: Building ID:** Address: 3400 N. Austin Ave. Region: 01 Mail Room: Asbestos Surveyor: Heramb, Andrew X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/8/2019 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type 1st through 3rd floor YES X NO corridors, auditorium, 01 9" x9" Black Vinyl Floor Tile 8200 SF Miscellaneous No None 0 engineer's office and office vault- 1932 Bldg. 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

02	9" x9" Black Vinyl Floor Tile Mastic	8200	SF	1st through 3rd floor corridors, auditorium, engineer's office and office vault - 1932 Bldg.		Miscellaneous	No	None	0	YES	X NO
2016 - Fa	ıll: No Change]						
Commen	<u> </u>										
2017 - Fa	all: No Change										
Commen	ts:										
2017 - Sp	oring: No Change										
Commen	ts:										
2018 - Fa	III: No Change										
Comment	ts:		·	<u>-</u>							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

1st through 3rd floor

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	9"x 9" Red Vinyl Floor Tile	8200	SF	1st through 3rd Floor Corridors, auditorium, engineer's office and office vault - 1932 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

										1	
04	9" x 9" Red Vinyl Floor Tile Mastic	8200	SF	1st through 3rd Floor Corridors, auditorium, engineer's office and office vault - 1932 Bldg.		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: I	No Change										
Comments:	-										
2017 - Fall: I	No Change										
	to origings				_						
Comments:											
2017 - Sprin	g: No Change										
Comments:											
2018 - Fall: N	No Change				1						
Comments:	<u> </u>										
					=						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	Black Border Vinyl Floor Tile	3300	SF	1st through 3rd Floor Corridors, auditorium (under carpet), engineer's office and office vault - 1932 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
·	

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	Black Border Vinyl Floor Tile Mastic	3300	SF	1st through 3rd Floor Corridors, auditorium (under carpet), engineer's office and office vault - 1932 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	12" x 12" White w/Grey Streaks Vinyl Floor Tile	3500	SF	Room 100A/B, 110 (under the carpet), 110A, 110B, 133, 131, 207A, 223, 301A, 309, Basement Storage J - 1932 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	12" x 12" White w/Grey Streaks VFT Mastic	3500	SF	Room 100A/B, 110, 110A, 110B, 131, 133, 207A, 223, 301A, 309, , Basement Storage J - 1932 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
0040 5 11 N 01	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	9" x9" Green w/Streaks Vinyl Floor Tile (NOT OBSERVED)	1200	SF	Rm 311		Miscellaneous	No	Dist	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

10	9" x 9" Green w/Streaks Vinyl Floor Tile Mastic (NOT OBSERVED)	1200	SF	Room 311		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change]						
Comments:	io onange										
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	ı: No Change										
Comments:											
]						
2018 - Fall: N	lo Change										
Comments:											
]						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	ment Category
11	9" x 9" Beige w/ Red Streaks Vinyl Floor Tile	1650	SF	Room 105 (under HA #47) and Room 308 - 1932 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

12	9" x9" Beige w/Red Streaks Vinyl Floor Tile Mastic	1650	SF	Room 105 (under HA #47) and Room 308 Bldg 1932		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change]						
Comments:											
2017 - Fall: N	lo Change										
Comments:	-										
2017 - Spring	ı: No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:											
					J						

Type

Asbestos

Type

Material

Material

Category

Miscellaneous

Category

Friable

Friable

No

Damage

Damage

Type

None

Type

Damage

Quantity

Damage

Quantity

0

Damage

Damage

Units

Units

13	12" x12" White w/Grey Spots/Streaks VFT	800	SF	Room 101A - 1932 Bldg.
2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				

Material

Quantity

Material

Quantity

Material

Material

Units

Units

Material Location

Material Location

HA No

HA No

Material Description

Material Description

Change in Assessment Category

Change in Assessment Category

X NO

		Quantity	Units		Type	Category		Type	Quantity	Units		
14	12" x12" White w/Grey Spots/Streaks VFT Mastic	800	SF	Room 101A - 1932 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change												
Comments:												
2017 - Fall: N	lo Change											
Comments:	o onango											

Material

Friable

Damage

Damage

Asbestos

2017 - Spring: No Change

Material Description

Comments:

Material

Material Material Location

2018 - Fall: No Change

Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	9"X9" Multi-color VFT	300	SF	3rd Fl. Hall by Room 301- 1932 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Page 8

Damage Change in Assessment Category

16	9"X9" Multi-color VFT Mastic	300	SF	3rd Fl. Hall by Room 301 - 1932 Bldg.	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

3rd Fl. Hall by Room 301

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	9"X9" Beige Mixed VFT	650	SF	3rd & 2nd Floor Hall by stairs and elevator - 1932 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No

Material Description

9"X9" Multi-color VFT

Material

Quantity

Material

Units

18	9"X9" Beige Mixed VFT Mastic	650	SF	elevator and stairs - 1932 Bldg.		Miscellaneous	No	None	0		YES	X NO
				•	_							
2016 - Fall: N	lo Change											
Comments:												
0047 Fall N	la Ohanana											
2017 - Fall: N	io Change											
Comments:												
2017 - Spring	ı: No Change				_							
Comments:	,											
2018 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

2nd Flr & 3rd Hall by

HA No		Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
19		9"X9" Gray w/Spots Vinyl Floor VFT - ABATED			Rm B50		Miscellaneous		None			YES	X NO
_	- Fall: No nents:	o Change											

2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

Material

Quantity

Material

Units

HA No

Material Description

2018 - Fall: No Change Comments:

Change in Assessment Category

20	9"X9" Gray w/Spots Vinyl Floor VFT Mastic - ABATED			Rm B50		Miscellaneous		None			YES	X NO
2016 - Fall: N	Jo Change				1							
Comments:	10 Change				-							
Commonto												
2017 - Fall: N	No Change											
Comments:												
	g: No Change											
Comments:												
22.12 5 11 1					-							
2018 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

Damage

Type

None

Damage

Quantity

Damage

Units

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No

21

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

9"X9" Salmon w/Dots, Vinyl Floor VFT - ABATED Material

Quantity

Material

Units

Material Location

Rms B52

Change in Assessment Category

X NO

22	9"X9" Salmon w/Dots, Vinyl Floor VFT Mastic - ABATED			Rms B52		Miscellaneous		None			YES	X NO
2016 Fall I	No Change	•	•		1	•	•	•	•	•	•	
2016 - Fall: I	vo Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:	-											
		·										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

Damage

Type

None

Damage

Quantity

Damage

Units

HA No

23

Material Description

9"X9" Light Brown w/Dots Vinyl Floor Tiles - ABATED Material

Units

Material

Quantity

Material Location

Rms B49, B52, B50A,

B50B

YES

X NO

	ABATED			BOOB ABATED							
	· · ·	•	•	•	1	•	•	•	•	•	•
	No Change										
Comments:											
					=						
2017 - Fall:	No Change										
Comments:	•										
2017 Spri	ng: No Change				-						
Comments:					-						
2018 - Fall:	No Change				-						
Comments:	<u> </u>				-						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

Damage

Type

None

None

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

Rms B49, B52, B50A,

REOR ARATED

Rm 151

HA No

24

25

Material Description

9"X9" Light Brown w/Dots Vinyl Floor VFT Mastic -

9"X9" Dark Brown w/ Dots

Vinyl Floor Tile - ABATED

Change in Assessment Category

X NO

X NO

YES

26	9"X9" Dark Brown w/ Dots Vinyl Floor Tile Mastic - ABATED	Room 151		Miscellaneous	None		YES	X NO
2016 - Fal	: No Change		, 					
Comments								
2017 - Fal	: No Change							
Comments	S:							
	ing: No Change							
Comments	S:							
	: No Change							
Comments	8:							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
27	9"X9" Burgundy Vinyl Floor Tile	1250	SF	Rm 116 , Rm 120 (under carpet) - 1932 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No	o Change											

2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

HA No

Material Description

9"X9" Dark Brown w/ Dots

Material

Quantity

Material

Units

2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	9"X9" Burgundy Vinyl Floor Tile Mastic	1250	SF	Rm 116, Rm 120 (under carpet) - 1932 Bldg.		Miscellaneous	No	None	0		YES X NO
0040 Fall N	I - Ol				1						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	9"x 9" Cream VFT	2450	SF	Rm 116, Rm 120 (under carpet) - 1932 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
30	9"x 9" Cream VFT Mastic	2450	SF	Rm 116 and 120 (under the carpet) - 1932 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change]							
Comments:	-											
2017 - Fall: I	No Change											
Comments:					-							
2017 - Sprin	g: No Change				-							
Comments:	-											

2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	9"X9" Coffee w/Streak VFT	250	SF	Rm 215A - 1932 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

32	9"X9" Coffee w/Streak VFT Mastic	250	SF	Rm 215A - 1932 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	.o o.nan.go											
2017 - Fall: N	lo Change				-							
Comments:												
2017 - Spring	: No Change				-							
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

Rm 250 North Office

Storage

HA No

33

Material Description

9"X9" Blue w/Streaks VFT -

ABATED

Change in Assessment Category

YES

X NO

34	9"X9" Blue w/Streaks VFT Mastic - ABATED			Rm 250 North Office Storage		Miscellaneous		None			YES	X NO
2016 - Fall: I	No Change											
Comments:	140 Change											
2017 - Fall: I	No Change											
Comments:	140 Change											
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
35	12"x12" White w/ Spots and Streaks VFT - REMOVED			Rm 212A		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

2016 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Page 18

36	12"x12" White w/ Spots and Streaks VFT mastic - REMOVED			Rooms 212A		Miscellaneous		None			YES	X NO
0046 F-II. N	Ja Ohanana	•	•	•	1		•	•	•	•	•	
2016 - Fall: N	vo Change											
Comments:												
0045 5 11 1												
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

Damage

Quantity

0

None

Damage

Units

37	12"X12" Orange VFT (Under HA47+48)	800	SF	Rm 210
		•	•	
2016 - Fall: N	No Change			
Comments:				
2017 - Fall: N	lo Change			
Comments:				
2017 - Spring	g: No Change			
Comments:				
2018 - Fall: N	lo Change			
Comments:				

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12"X12" Orange VFT Mastic (Under HA47+48)	800	SF	Rm 210		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change]						

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12"X12" Beige w/Tan Specks VFT	650	SF	Rms 202, 202A-C - 1932 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

40	12"X12" Beige w/Tan Specks VFT Mastic	650	SF	Rms 202, 202A-C 1932 - 1932 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	II: No Change											
					_							
Comment	is:											
2017 - Fa	II: No Change											
Comment	ts:											
2017 - Sp	ring: No Change											
Comment												
Comment												
2018 - Fa	II: No Change											
					_							
Comment	is:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
	·	Quantity	Units		Type	Category		Type	Quantity	Units		,
		,		Lunchroom Manager's					1			
1	1	1	1	-and in com Manager o		1	1			1		

Type

Material

Category

Friable

No

Miscellaneous

Damage

Туре

None

0

Damage

Quantity

Damage

Units

2500

SF

HA No

41

Material Description

12"X12" Beige w/Tan

12"X12" Black w/ White

Streaks VFL

Material

Quantity

Material

Units

Material Location

Office, 3rd Floor

Lunchroom, Assistant Eng. Office - 1932 Bldg.

Rms 202, 202A-C 1932 -

Change in Assessment Category

VES

YES

X NO

	1	Quantity	Units		Type	Category		Туре	Quantity	Units	•
1 /1 /	12" Black w/ White ks VFL Mastic	2500	SF	Lunchroom Manager's Office, 3rd Floor Lunchroom, Assistant Eng. Office - 1932 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	9"X9" Tan w/Brown Streaks Vinyl Floor Tile (Abated)			Basement Phone Rm Abated		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 22

44	9"X9" Tan w/Brown Streaks Vinyl Floor Tile Mastic (Abated)	i		Basement Phone Rm - Abated		Miscellaneous		None			YES	X NO
0040	Na Ohana	•	•	•	7	•	•	•	•	•	•	
	No Change											
Comments:												
					1							
2017 - Fall:	No Change											
Comments:												
2017 - Spri	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category	1	Type	Quantity	Units		

Type

Material

Category

Miscellaneous

Friable

Damage

Type

None

Damage

Quantity

Damage

Units

45	12"X12" Off-White w/Gray Streaks VFT (Abated)			Basement Rm B7, Rm B19
2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:			•	
		•	•	

HA No

Material Description

9"X9" Tan w/Brown Streaks

Material

Units

Material

Quantity

Material Location

Change in Assessment Category

X NO

46	12"X12" Off-White w/Gray Streaks VFT Mastic (Abated)	Basement Rm B7, Rm B19	Miscellaneous			YES	X NO
2016 - Fal	I: No Change]	·			
Comment			-				
2017 - Fal	I: No Change						
Comment	S:						
	ring: No Change						
Comment	S:		-				
	I: No Change						
Comment	S:		_				
L			J				

Type

Asbestos

Type

Material

Material

Category

Category

Friable

Friable

Damage

Damage

Type

Type

Damage

Quantity

Damage

Quantity

Damage

Damage

Units

Units

47	12"X12" Blue w/White VFT	8750	SF	Rms 105, 107, 107E, 109/109A, 111/113, 115/117, 119/121, 210, 212A - 1932 Bldg.		Miscellaneous	No	None	0	
2016 - Fall: No	Change									
Comments:										
2017 - Fall: No	Change									
Comments:										
2017 - Spring:	No Change									
Comments:					_					

Material Location

HA No

HA No

2018 - Fall: No Change

Comments:

Material Description

Material Description

12"X12" Off-White w/Gray

Material

Quantity

Material

Quantity

Material

Material

Units

Units

Material Location

Change in Assessment Category

Change in Assessment Category

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	12"X12" Blue w/White VFT Mastic	8750	SF	Rms 105, 107, 107E, 109/109A, 111/113, 115/117, 119/121, 210, 212A - 1932 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	12"X12" White w/Tan Spots VFT (NOT OBSERVED)	450	SF	Main Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

	OBSERVED)										
0040	No Ohamas	•	•	•	1	•	•	•	•	•	
2016 - Fall:	No Change				<u> </u>						
Comments:											
2017 Falls	No Changa										
2017 - Fall:	•										
Comments:											
2017 - Sprin	ng: No Change				<u> </u>						
Comments:	<u> </u>										
2018 - Fall:	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	1			1	21	0.7	1	V 1			1

Type

Material

Category

Miscellaneous

Miscellaneous

No

Friable

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

51	Squares Linoleum (NOT 900 SF Rm 313 OBSERVED)									
2016 - Fall: N	o Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Fall: No Change										
Comments:										
	·	·		·						

HA No

50

Material Description

Brown w/Tan Small

12"X12" White w/Tan Spots VFT Mastic (NOT

Material

Quantity

450

Material

Units

SF

Material Location

Main Office

Change in Assessment Category

X NO

X NO

YES

52	Brown w/Tan Small Squares Linoleum Mastic (NOT OBSERVED)	900	SF	Rm 313		Miscellaneous	No	None	0		YES	X NO
0040 5-11 1	. Ol	•	•	•	_	•	•	•	•	•	•	
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												

Type

Asbestos

Type

Material

Material

Category

Miscellaneous

Category

Friable

Friable

Damage

Damage

Type

Type

Damage

Quantity

Damage

Quantity

Damage

Damage

Units

Units

	321A - 1932 Bldg.									
2016 - Fall: No Change										
Comments:										
2017 - Fall: No Change										
Comments:										
2017 - Spring: No Change										
Comments:										
2018 - Fall: No Change										
Comments:	·									

Material

Quantity

Material

Material

Units

Units

Material Quantity Material Location

Material Location

3rd Floor Lunchroom,

Rm 322A-D, 3rd Floor Corridor by 322A-D, 200,

HA No

HA No

53

Material Description

Material Description

Ceiling Tiles

2'X2' White Dot w/Grooves

Brown w/Tan Small

Change in Assessment Category

Change in Assessment Category

YES

X NO

	,	Quantity	Units		Type	Category		Туре	Quantity	Units		3 7
54	2'X2' White Smooth Ceiling Tiles			3rd Floor Lunchroom Serving Area, 3rd Floor kitchen, Lunchroom Manager's Office - 1932 Bldg.		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change											
Comments:												
2018 - Fall:	No Change				_							
Comments:	, and the second											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
55	1'X1' Brown w/Holes, Ceiling Tiles			3rd Floor Small Gymnasium (302), 2nd Floor Gym - 1932 Bldg.		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											

Material

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Comments:

Comments:

Comments:

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	1'X1' Dot Ceiling Tiles			Rms 116, 213B, Gym, 323, 323A-D, 3rd Floor Hallway Between 323A- D, 3rd Floor Lunchroom, Rm 322A-D, 3rd Floor Corridor by 322A-D (Above HA# 53), 3rd Floor Lunchroom Serving Area, 3rd Floor Kitchen, Lunchroom Manager's Office (Above HA# 54) Bldg 1932		Miscellaneous					YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	2'X4' White Dot/Groove Ceiling Tiles			Rm 133, 131, 1st/2nd/3rd Floor North and South Toilets, 107B, 107C, 110, 110A, 110B, 207A, 207B, 207D, 213, 219, 223, 231, 309A, 331, 3rd Floor Janitor's Closet, 323A-D, 329, 321, 309P, 309B, 309, 207C, 229, 221, 209 - 1932 Bldg.		Miscellaneous		None			YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	12"X12" Grooved Ceiling Tiles			107, 114, MainOffice, Principal & Astt Pincipal's Offc, CopyRm 112, 120, 205, 207, 212A, 210, 214, 214A, 300(library), 308, 3rd Fir LunchRm, 322A-D, 3rd Fir Corridor by 322A-D, 3rd Fir LunchRm Serv. Area, 3rd Fir Kitchen,LunchRm Manag. Offc, 200 (In Stairwell),217 - 1932 Bldg.		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2040 Falls No Change
2018 - Fall: No Change Comments:
Comments.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	2'X4' White w/ Deep Grooves, Ceiling Tiles			Rm 100A/B - 1932 Bldg.		Miscellaneous					YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
·	-

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Asses	sment Category
60	2'X2' White w/Dots, Ceiling Tiles			Rm 108 Lounge, 109/109A, 111/113, 115/117, 119/121, 200 (library) - 1932 Bldg.		Miscellaneous					YES	ĺ	X NO
2016 - Fall: N	No Change				7								
Comments:													
2017 - Fall: N	No Change				1								
Comments:	J												
2017 - Sprine	g: No Change				-								
Comments:	<u> </u>												
2018 - Fall: N	No Change				-								
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Asses	sment Category
61	Carpet Mastic			Rm 106, 116, 120, Principal and Astt Principal's Office, Copy Rm, 144, Locker Rm by Engineer's Office, 203, 231, 200(library), 240, 242, 244, 300(library), 133, 112, Auditorium - 1932 Bldg.		Miscellaneous					YES		X NO
2016 - Fall: N	No Change				7								
Comments:	Ü												
2017 - Fall: N	No Change				-								
Comments:	Ü												
2017 - Spring	g: No Change				1								
Comments:													
2018 - Fall: N	No Change				-								

Comments:

	62	Hard Coat Plaster			Hatching Maps) - 1932 Bldg.		Surface		None			YES	X NO
Γ	2016 - Fall: N	o Change		<u> </u>	·								
_	Comments:												
ŀ	2017 - Fall: N	o Change											
Ī	Comments:												
ŀ	2017 - Spring	No Change											
	Comments:												
_	2018 - Fall: N	o Change											
Ľ	Comments:												
_						<u> </u>							
	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
	63	Troweled on Wall Plaster			1st Floor Auditorium 1932		Surface					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

Throughout (See

Bldg

64	Rough-Textured Ceiling Plaster		Rm 150, 150A, 151, 250, 350-352, 3rd Floor Conference Rm - 1960 Bldg.			None		YES	X NO
2016 - Fall: N	o Chango]					
2010 - Fall. IN	o Change								
Comments:									
2017 - Fall: N	o Change								
Comments:									
2017 - Spring	: No Change								
Comments:									
		·	·						
2018 - Fall: N	o Change								
Comments:									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	Aircell Pipe Insulation	7305	LF	Throughout Basement (See Hatching Maps), 207D, 209, 211, 211A, 213, 213B, 242 - 1932 Bldg.		TSI	Yes	Dist	50		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	Mudded Joint Packing Elbow/Fitting/Valve on Aircell Pipe Insulation	752	LF	Throughout Basement (See Hatching Maps), 207D, 209, 211, 211A, 213, 213B Bldg 1932		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	Cardboard Pipe Insulation	5640	LF	Throughout Basement (See Hatching Maps), 207D, 209, 211, 211A, 213, 213B - 1932 Bldg		TSI	Yes	Dist	10		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68	Mudded Joint Packing Elbow/Fitting/Valve on Cardboard Pipe Insulation (Paperwrap)	546	LF	Throughout Basement (See Hatching Maps), 207D, 209, 211, 211A, 213, 213B - 1932 Bldg		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	Mag Block Pipe Insulation	1780	LF	Basement Wood Shop, N. Compressor R, Storage D, N. and S. Tunnel, Main Corridor, SW Tunnel, Storage I, Weight Room - 1932 Bldg		TSI	Yes	Loc	5		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category		
70	Mudded Joint Packing Elbow/Fitting/Valve on Mag Block Pipe Insulation	280	LF	Basement Wood Shop, N. Compressor R, Storage D, N. and S. Tunnel, Main Corridor, SW Tunnel, Storage I, Weight Room - 1932 Bldg.		TSI	Yes	Dist	10		YES X NO		

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	Aircell Duct Insulation	250	LF	Basement Storage G - 1932 Bldg.		TSI	Yes	Loc	20		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
72	Mudded Joint Packing Elbow/Fitting/Valve on Fiberglass Pipe Insulation	705	LF	Throughout Basement (See Hatching Maps) and Attic - 1932 Bldg.		TSI	Yes	Loc	3		YES	X NO
2016 - Fa	ıll: No Change]		•			•	•				

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	_
· ·	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	Boiler Breeching	120	LF	Boiler Rm - 1932 Bldg.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

74	Tank Insulation	300	SF	Boiler Rm - 1932 Bldg.		TSI	Yes	None	0		YES	X NO
2016 - Fall	: No Change				7							
Comments												
2017 - Fall	: No Change											
Comments	S:				4							
	ing: No Change											
Comments	X				4							
2018 - Fall	: No Change											
Comments	:				4							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
75	Hard Coat Plaster			Throughout (See Hatching Maps) - 1960							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

	1											
76	Carpet Mastic			Rm 350-352 - 1960 Bldg.							YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	j: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					l							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
				3rd Floor Lunchroom, 3rd Floor Lunchroom							YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

77	12"X12" White w/Gray VFT	2500	SF	Floor Lunchroom Manager's Office, Assistant Eng. Office - 1932 Bldg.	Miscellaneous	No	None	0	YES
	fall: No Change								
2017 - F	all: No Change								
Commer	nts:								
2017 9	Paring: No Chango								

2017 - Spring: No Change

Comments:

2018 - Fall: No Change

Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
78	12"X12" White w/Gray VFT Mastic	2500	SF	3rd Floor Lunchroom, 3rd Floor Lunchroom Manager's Office, Assistant Eng. Office - 1932 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change				1							
Comments												
2017 - Fal	I: No Change											
Comments												
2017 - Spi	ring: No Change											
Comments	3:											
2018 - Fal	I: No Change											
Comments	S:											
					J							
	1.4.4.1.1.15			T								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
79	Terrazzo	7650	SF	Stairwell Treads Landings, Hallway Border and Room, Entrances, Stairs Upto Gym, Auditorium, Stairs and Vestibules, Stairs in Gym Area, Stairs Near Freight Elevator - 1932 Bldd.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change		
•		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		
	•	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
80	Drywall, Tape, Compound	2300	SF	2nd & 3rd Floor Stair Corridor to Addition, Rm 313, 300, 301, 120 - 1932 Bldg.		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
81	12"X12" White w/Tan Streaks	900	SF	Rm 315, 315A - 1932 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
81A	12"X12" White w/Tan Streaks Mastic	900	SF	Rm 315, 315A - 1932 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - F	Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
82	12"X12" White w/Multi- Color Streaks	700	SF	Rm 313A, 3151A -1932 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Units Units	Change in Assessment Categor	ry
82A	12"X12" White w/Multi- Color Streaks Mastic	700	SF	Rm 313A, 3151A -1932 Bldg.		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
83	Blue-Gray Linoleum	500	SF	Rm 311 and 311 Lab - 1932 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

83A	Blue-Gray Linoleum Mastic	500	SF	Rm 311 and 311 Lab - 1932 Bldg.		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:	·			·							
					_						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

Rm 311 and 311 Lab -

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
84	Blue-White Linoleum	300	SF	Rm 311 and 311 Lab - 1932 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

84A	Blue-White Linoleum Mastic	300	SF	Rm 311 and 311 Lab - 1932 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
					+							
Comments:					4							
2017 - Fall:	No Change				-							
Comments:												
2017 - Sprir	ng: No Change				_							
Comments:												
2018 - Fall:	No Change				-							
Comments:	Ţ.											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Friable

No

Miscellaneous

Damage

Type

None

0

Damage

Quantity

Damage

Units

	by 106 - 1932 Bldg.
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
	·

2500

SF

HA No

85

Material Description

12"X12" Gray w/Streaks

Material

Quantity

Material

Units

Material Location

Rm 108, staff Room, Man

and Women Toilets, Hall

within Room 100, GYM

Change in Assessment Category

X NO

YES

		Quantity	Units		Type	Category		Type	Quantity	Units		
85A	12"X12" Gray w/Streaks VFT Mastic	2500	SF	Rm 108, staff Room, Man and gym by 106, Women Toilets, Hall within Room 100, GYM by 106 - Bldg 1932		Miscellaneous	No	None	0		YES	Х NO
2016 - Fall:	: No Change]							
Comments:	:]							
2017 - Fall:	No Change											
Comments:	:											
2017 - Spri	ng: No Change											

Material

Friable

Damage

Damage

Asbestos

2018	- Fall:	No	Change

Material Description

Material

Material Material Location

Comments:

Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
86	12"X12" Gray w/Streaks VFT	6000	SF	Rm 255, 254, 253, 252, 155, 154, 153, 152; basement B51; 1st, 2nd, 3rd Floor Corridors (1960)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
86A	12"X12" Gray w/Streaks VFT Mastic	6000	SF	Rm 255, 254, 253, 252, 155, 154, 153, 152; Basement B51; 1st, 2nd, 3rd Floor Corridors (1960)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
87	Gray Speckled Linoleum	4500	SF	Room B52 (art room) -1960 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

87A	Gray Speckled Linoleum Mastic	4500	SF	Room B52 (art room) -1960 Bldg.		Miscellaneous	No	None	0	YES	X NO
2016 - Fa	II: No Change]						
Comment	S:				1						
2017 - Fa	II: No Change										
Comment	s:				=						
2017 - Sp	ring: No Change										
Comment	S:				=						
2018 - Fa	II: No Change										
Comment	s:										

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
88	1'X1' White Smooth- Textured Ceiling Tiles	1600	SF	Rm 202, 205 (1932)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Page 49

89	Terrazzo	900	SF	Stairwells (1960)		Miscellaneous	No	None	0	YES	X NO
2016 - Fal	l: No Change]						
Comments	S:				-						
	l: No Change										
Comments	S:										
2017 - Spr	ing: No Change										
Comments	S:				-						
2018 - Fal	l: No Change										
Comments	S:				-						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
90	12 x 12 White with Blue Streaks VFT	200	SF	Room 331(teacher/ staff lounge) -1932 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
90A	12 x 12 White with Blue Streaks VFT Mastic	200	SF	Room 331(teacher/ staff lounge) -1932 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2010 5 11 11 21
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
91	12 x 12 Blue Streaked VFT	200	SF	Room 331(teacher/ staff lounge) -1932 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

91A	12 x 12 Blue Streaked VFT Mastic	200	SF	Room 331(teacher/ staff lounge) -1932 Bldg.		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change]						
Comments:	io Griange										
2017 - Fall: N	lo Change										
Comments:	-										
2017 - Spring	g: No Change										
Comments:											
2018 - Fall: N	lo Change										

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
92	White Linoleum Flooring VFT	900	SF	Room 313 - 1932 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

92A	White Linoleum Flooring VFT Mastic	900	SF	Rooms 313 - 1932 Bldg.		Miscellaneous	No	None	0		YES	X NO
2046 Fall N	Ja Channa				7							
2016 - Fall: N	vo Change											
Comments:												
2017 - Fall: N	No Change				1							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
	_				_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

Yes

Friable

Damage

Туре

None

Damage

Quantity

0

Damage

Units

4500

SF

HA No

93

Material Description

6" x 12" Ceiling Tile White

with Holes

Material

Quantity

Material

Units

Material Location

Auditorium & Balcony

1932 Bldg.

Room, 108 Staff Room -

YES

X NO

94	12 x 12 Dark Beige streaked VFT	800	SF	Main Office (1932)	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	No Change									
Comments:	-									
	g: No Change									
Comments:										
2017 - Fall: N	No Change									
Comments:										
2018 - Fall: N	No Change									

Material

Category

Asbestos

Type

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
94A	12 x 12 Dark Beige streaked VFT Mastic	800	SF	Main Office (1932)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

95	9" x 9" Beige Mixed VFT	600	SF	3rd and 2nd Floor Corridor by Rooms 301 and 201 - 1932 Bldg		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	o Change										
2017 - Spring Comments:	: No Change										
2017 - Fall: N Comments:	o Change				-						
2018 - Fall: N Comments:	o Change										

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
95A	9" x 9" Beige Mixed VFT Mastic	600	SF	3rd and 2nd Floor Corridor by Rooms 301 and 201 - 1932 Bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

										1		
96	12" x 12" Sand VFT	700	SF	Room 301 - 1932 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	2017 - Spring: No Change											
Comments:	<u> </u>											
2017 - Fall: N	o Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
96A	12" x 12" Sand VFT Mastic	700	SF	Room 301 - 1932 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Chicago Academy Elementary School
Date: <u>1/8/2019</u>
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.