## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2018 - Fall

Air Force Academy High School 45231 2010 School: **Oracle Unit: Building ID:** Address: 3630 S. Wells Region: Mail Room: Asbestos Surveyor: Guerrero, Samuel X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/10/2019 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type 12" x 12" Beige Floor Tile YES 006 X NO Material Not Present w/Brown & White Streaks 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

		Quantity	Units		Type	Category		Type	Quantity	Units			
007	12"x12" Lt Brown Floor Tile w/Brn & White Streaks			Material Not Present		Miscellaneous		None			YES	X NO	0
2016 - Fall:	No Change												
Comments:	<u> </u>												
2017 - Sprin	g: No Change												
Comments:	<u> </u>												
2018 - Fall:	No Change												
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Ca	tegory
008	Mastic on 9" x 9" Dark Brown Floor Tile			Material Not Present		Miscellaneous		None			YES	X	)
2016 - Fall:	No Change												
Comments:													
2017 - Sprin	g: No Change												
Comments:													
2018 - Fall:	No Change												
Comments:													

Material

Asbestos

Damage

Friable

Damage

Damage Change in Assessment Category

HA No

Material Description

Material

Material Material Location

		Quantity	Units		Type	Category		Type	Quantity	Units		
009	Mastic on 12x12 Dk Brn w/Brn & Wh Strks Floor Tile			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
010	Mastic on 12x12 Lt. Brown w/Brn & Wh Streaks FT			1953 Building, Room 212A (MDF Room)		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												

Material

Asbestos

Damage

Friable

Damage

Damage Change in Assessment Category

HA No

Material Description

Material

Material Material Location

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
011	Partition Floor Joiner Compound			1946/53 Connection by Room 104				None			YES	X NO
2016 - Fall: N	No Change				7							
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change				_							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asser	ssment Category
012	12"x12" Lt Brown w/Brn & White Streaks Floor Tile			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	No Change				7							
Comments:	-											
2017 - Spring	g: No Change				_							
Comments:												
2018 - Fall: N	No Change				_							
Comments:												

Friable

Material

Asbestos

Damage

Damage

Damage

Change in Assessment Category

Material Material Location

HA No

Material Description

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
013	Mastic on 12 x 12 Lt Brn w/Brn & White Strks FT			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:	<u> </u>											
0040 Falls N	I. Ob				_							
2018 - Fall: N	lo Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
014	Carpet Adhesive			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:	· ·											
0047 0 :	N. O											
2017 - Spring	r: No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
015	Black Vinyl Baseboard			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments.					_							
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Chango											
Comments:	io Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
016	Black Vinyl Baseboard Adhesive			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
0047 On rise	N. Observe											
Comments:	g: No Change				_							
Comments.												
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
017	Sink Bottom Caulking			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
018	Plaster			1946 Building				None			YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	ı: No Change											
Comments:												
2018 - Fall: N	lo Change				-							
Comments:	.c c.iango											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
019	Interior Brick Walls			1946 Building				None			YES	X NO
2016 - Fall: N	lo Change											
2017 - Spring	g: No Change											
Comments:	I. O											
2018 - Fall: N Comments:	lo Change											
			_									
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
020	Interior Brick Walls Mortar			1946 Building				None			YES	X NO
Comments:	g: No Change											
2018 - Fall: N Comments:	io Cnange											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
021	12" x 12" Green Floor Tile			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
2017 - Spring	ı: No Change											
Comments:	,											
2018 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
022	Mastic on 12" x 12" Green Floor Tile			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:	V											
2017 - Spring	ı: No Change				_							
Comments:	,ge											
2018 - Fall: N	lo Change				_							
Comments:	io Oriange											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
023	Tar Paper and Mastic in Vault Closet Areas			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
024	Vibration Isolator			1946 Building, Attic Above 200 and 201				None			YES	X NO
2016 - Fall: N	lo Change											
Comments:	•											
2017 - Spring	ı: No Change											
Comments:	J											
2018 - Fall: N	lo Change				_							
Comments:												

		Quantity	Units		Type	Category		Type	Quantity	Units			
025	Fan Unit Door Lining			1946 Building, Attic above 200 and 201				None			YES	X NO	
2016 - Fall: N	No Change												
Comments:	<u> </u>												
	g: No Change												
Comments:													
2018 - Fall: N	No Change												
Comments:	NO Change												
Comments.													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Catego	ry
026	Dirt on Floor			Material Not Present		TSI		Loc			YES	X NO	
2016 - Fall: N	No Change												
Comments:													
2017 - Spring	g: No Change												
Comments:	•												
2018 - Fall: N	Jo Change				_								
Comments:	NO Oriange												
CClorito.													

Material

Asbestos

Damage

Friable

Damage

Damage Change in Assessment Category

HA No

Material Description

Material

Material Material Location

027	Mastic on 12"x12" Beige w/Brown & White Streaks FT	Material Not Present	Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change		•	•	•	•	•		
Comments:	to onange								
2017 - Spring	g: No Change								
Comments:									
2018 - Fall: N	lo Change								
Comments:									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
028	Partition Wall Joiner Compound	10	LF	1946/1953 Buildings by 104 & 204		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

Mastic on 12"x12" Beige

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
029	12" x 12" Dark Gray w/White & Brown Streaks FT			Material Not Present							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
030	12" x 12" Dark Gray Floor Tile w/Beige Mix			Material Not Present							YES	X NO
2016 - Fall: N	lo Change				$\neg$							
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:	g. 110 Onango											
2018 - Fall: N	lo Change											
Comments:	to oriallye											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
031	Mastic on 12"x12" Dark Gray w/Beige Mix Floor Tile			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	io oriango											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
032	12" x 12" Light Beige Mix Floor Tile			Material Not Present							YES	X NO
2016 - Fall: N	lo Change				$\neg$							
Comments:												
2017 Spring	g: No Change											
Comments:	g. No Change											
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
033	Mastic on 12" x 12" Light Beige Mix Floor Tile			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
034	12" x 12" Dark Pink Floor Tile			Material Not Present							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	<b>-</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
035	Adhesive for 12" x 12" Dark Pink Floor Tile			Material Not Present							YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:	o comen go											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
036	12" x 12" Dark Beige w/ Brown & White Streaks FT			Material Not Present							YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	· No Change											
Comments:	2017 - Spring: No Change Comments:											
0040 F-II. N	a Obasasa											
2018 - Fall: N Comments:	o Change											
Comments.												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
037	Mastic on 12x12 Dk Beige w/Brn & White Strks FT			Material Not Present							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	•											
2018 - Fall: N	lo Change											
Comments:	to change											
<u> </u>		T		1		T = -		T _	T =	1 =	1	_
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
038	12" x 12" Light Gray Mix Floor Tile			Material Not Present							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	g. No Change											
2018 - Fall: N	lo Change											
Comments:					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
039	Mastic on 12" x 12" Light Gray Mix Floor Tile			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	go											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
040	Gray and Yellow Mix Linoleum			Material Not Present							YES	X NO
2016 - Fall: N	lo Change											
Comments:	.o onango											
2017 Spring	g: No Change				_							
Comments:	g. No Change											
2018 - Fall: N	lo Change											
Comments:					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
041	Burlap with Adhesive Under Grey & Yellow Linoleum			Material Not Present							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	Ţ.											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
042	12" x 12" Blue Floor Tile			Material Not Present							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	, <u> </u>											
2018 - Fall: N	lo Change											
Comments:	<del>-</del> <b>g</b>											

		Quantity	Units		Туре	Category		Туре	Quantity	Units	<u> </u>	
043	Mastic on 12" x 12" Blue Floor Tile			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	<i>y</i>											
2018 - Fall: N	No Change				-							
Comments:	-											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
044	Mastic 12x12 Dk. Gray w/White & Brown Streaks FT			Material Not Present		Miscellaneous		Loc			YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change				-							
Comments:	10 01141190											
		•										

Material

Friable

Damage

Damage

Damage

Change in Assessment Category

Material Material Location

HA No

Material Description

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
045	Interior Brick			1953 Building							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
046	Interior Brick Mortar			1953 Building							YES	X NO
2016 - Fall: N	lo Change				$\neg$							
Comments:												
2017 - Spring	g: No Change											
Comments:	<u>-</u>											
2018 - Fall: N	lo Change											
Comments:	J											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
047	Plaster			1953 Building							YES	X NO
2016 - Fall: N	lo Change				$\exists$							
2017 - Spring	g: No Change											
Comments: 2018 - Fall: N	lo Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
048	Light Gray Vinyl Baseboard			Material Not Present							YES	X NO
2016 - Fall: N Comments: 2017 - Spring Comments: 2018 - Fall: N Comments:	g: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
049	9" x 9" Brown Floor Tile			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments.												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	o Change											
Comments.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
050	Mastic on 9" x 9" Brown Floor Tile			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 0 :	N. O.											
	g: No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:	•											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
051	Desk Top Linoleum			Material Not Present							YES	X NO
2016 - Fall: N	lo Change											
	g: No Change											
Comments:												
2018 - Fall: N Comments:	lo Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
052	Desk Top Linoleum Adhesive			Material Not Present							YES	X NO
2016 - Fall: N Comments:	lo Change											
	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments.												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
053	Black Vinyl Baseboard			Material Not Present							YES	X NO
2016 - Fall: N	lo Change				7							
Comments.												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	la Changa				_							
Comments:	io Change											
Comments.					_							
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
054	Black Vinyl Baseboard Adhesive			Material Not Present							YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
	g: No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
055	12x12 Dk Beige w/Brown & White Streaks Floor Tile			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	Ţ.											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asser	ssment Category
056	12" x 12" Blue Floor Tile			Material Not Present							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:	J											
2018 - Fall: N	lo Change											
Comments:	io orialigo											
		•										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
057	12" x 12" Blue Floor Tile Adhesive			Material Not Present							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	o viamige											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
058	Dark Gray Vinyl Baseboard			Material Not Present							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:	,go											
2018 - Fall: N	lo Chango											
Comments:	io Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
059	Dark Gray Vinyl Baseboard Adhesive			Material Not Present							YES	X NO
2016 - Fall: N	lo Change				$\exists$							
Comments:												
2017 - Spring	g: No Change											
Comments:	<u> </u>											
2018 - Fall: N	lo Change				_							
Comments:	io Oriange											
	I	T	T. s. s. s. s. s.	T. A. C. C. C. C.		T	Levis	T.5	T.5	T 5		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
060	12" x 12" Gray Mix Floor Tile			Material Not Present							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı. No Change											
Comments:	J. 140 Orlange				_							
2010 = 11 1												
	lo Change				_							
Comments:	lo Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
061	Mastic on 12" x 12" Gray Mix Floor Tile			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:	o onango											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
TIATIO	Waterial Description	Quantity	Units	Waterial Education	Type	Category	Thabic	Type	Quantity	Units	Orlange in Asso.	33ment Gategory
062	Cork Insulation			Fan Room by 214							YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	· No Change											
Comments:	. No Change											
2018 - Fall: N	o Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
063	Vibration Isolator			Fan Room by 214							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	to onange											
LIIA NI	I.M. C. I.D. C. C.	T	T	T. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.		T. 8. 4. 4. 4.	Levis	T 5	1.5	1.5	T 01	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
064	12" x 12" Beige Floor Tile w/Brown & White Streaks			Material Not Present							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	g. No Change											
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
065	Mastic on 12"x12" Beige FT w/Brn & White Streaks			Material Not Present							YES	X NO
2016 - Fall: N Comments:	lo Change											
Comments.												
2017 - Spring	g: No Change											
Comments:												
2040 Fall N	la Change											
2018 - Fall: N	io Change				_							
Comments.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
066	12" x 12" Light Brown Floor Tile			Material Not Present							YES	X NO
2016 - Fall: N	lo Change											
Comments:	-											
0047 0 0	N. Olasas											
2017 - Spring	g: No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
067	12" x 12" Light Brown Floor Tile Adhesive			Material Not Present							YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:	o comenige											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
068	12" x 12" Dark Pink Floor Tile			Material Not Present							YES	X NO
2016 - Fall: N	o Change				$\neg$							
Comments:												
2017 - Spring	: No Change											
Comments:	. No onange											
2040 Fall N	la Change											
2018 - Fall: N Comments:	o Change											
Comments.												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
069	12" x 12" Dark Pink Floor Tile Adhesive			Material Not Present							YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
070	Fan Unit Door Lining Insulation			1946 Building, Basement							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	<u> </u>				]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
071	9" x 9" Gray Floor Tile			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change				$\exists$							
2017 - Spring	g: No Change											
Comments: 2018 - Fall: N	lo Change											
Comments:	·											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
072	Mastic on 12" x 12" Gray Floor Tile			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
	g: No Change											
Comments:	la Change											
2018 - Fall: N Comments:	io Change											

073	Partition Wall Compound	Between 1 Buildings, Floor Corr	1st and 2nd						YES	X NO
		•		•	•	•	•	•		
2016 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
074	9" x 9" Light Brown Floor Tile	200	SF	1960 Building, Store Room by Engineer's Office		Miscellaneous	No	Loc	10		YES X NO

<b>-</b>	
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

Material Location

Between 1953/60

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
075	Mastic on 9" x 9" Light Brown Floor Tile	200	SF	1960 Building, Store Room by Engineer's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Spring: No Change												
Comments:												
2018 - Fall: No Change												
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
076	Dark Gray Vinyl Baseboard			Material Not Present							YES	X NO
2016 - Fall: N	No Change				$\neg$							
Comments:	•											
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: No Change												
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
077	Dark Gray Vinyl Baseboard Adhesive			Material Not Present							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	io onango											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
	material 2 cooling to	Quantity	Units	material Economic	Туре	Category		Туре	Quantity	Units	onango miritos	comem category
078	Pump Floor/Unit Caulk			1960 Building, Boiler Room							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	g. No Change											
2018 - Fall: N												
	io Change											
Comments:	io Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
079	Boiler Gasket Material			Material Not Present		TSI					YES	X NO
2016 - Fall: N	lo Change											
	g: No Change											
Comments:												
2018 - Fall: N Comments:	lo Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
080	Interior Brick			1960 Building							YES	X NO
2016 - Fall: N Comments: 2017 - Spring Comments: 2018 - Fall: N	g: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
081	Interior Brick Mortar			1960 Building							YES	X NO
2016 - Fall: N	lo Change				]							
Comments:					-							
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage Units	Change in Asses	sment Category
	1011 1011 0 1 5 :	Quantity	Units	4000 B ''   E	Туре	Category		Туре	Quantity	Units		
082	12" x 12" Sandy Beige Floor Tile	250	SF	1960 Building, Engineer's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	J											
2017 - Spring	r. No Change				-							
Comments:	g. 140 Change				-							
	la Changa				1							
2018 - Fall: N	io Change				-							
Comments.					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
083	Mastic on 12" x 12" Sandy Beige Floor Tile	250	SF	1960 Building, Engineer's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments:												
	ng: No Change											
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	ssment Category
11/(140	Waterial Besonption	Quantity	Units	Waterial Ecoation	Type	Category	Thabic	Туре	Quantity	Units	Onlange in Added	oment oatogory
084	9" x 9" Orange Floor Tile	50	SF	1960 Building, Engineer's Office Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				]							
Comments:												
2017 - Sprir	ng: No Change				-							
Comments:												
2018 - Fall:	No Change				†							
Comments:												

085	Mastic on 9" x 9" Orange Floor Tile	50	SF	1960 building, Engineer's Office Corridor		Miscellaneous	No	None	0		YES X	NO
2016 - Fall:	No Change				]							
Comments:	<u> </u>											
2017 - Sprii	ng: No Change											
Comments:	<u> </u>											
2018 - Fall:	No Change											
Comments:												
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment	t Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

TIANO	Material Description	Quantity	Units	Material Location	Type	Category	THADIC	Type	Quantity	Units	Change in Asses	sillerit Gategory
086	12" x 12" Off White Floor Tile	30	SF	1960 Building, Store Room Toilet Across from Engineer's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Comments:	o Change											

Comments: 2018 - Fall: No Change

2017 - Spring: No Change

Material Description

Material

Quantity

Material

Units

Comments:

HA No

087	Mastic on 12" x 12" Off White Floor Tile	30	SF	1960 Building, Store Room Toilet Across from Engineer's Office		Miscellaneous	No	None	0		YES	X NO
					1							
2016 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	<u> </u>											
2018 - Fall: N	No Change											
Comments:	<u> </u>											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Туре	Quantity	Units		0 ,
000	12" x 12" Light Gray Mix			Matarial Nat Dansant								Tv bra
088	Floor Tile			Material Not Present							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
089	12" x 12" Light Gray Mix Floor Tile Mastic			Material Not Present							YES	X NO
2016 - Fall: N	lo Change											
Comments.												
2017 - Spring	g: No Change											
Comments:												
2019 Fall: N	la Changa											
2018 - Fall: N Comments:	io Change											
Comments.												
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
090	Radiator Grill Lining Material			1960 Building							YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
0047 0 0	N. Observe											
Comments:	g: No Change											
Comments.												
2018 - Fall: N	lo Change											
Comments:	•											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
091	Incinerator Gasket Material by Fire Hole			Material Not Present		TSI					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
092	Incinerator Interior Brick			Material Not Present							YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	r. No Change											
Comments:	y. 110 Ondrigo											
2018 - Fall: N	lo Chango											
Comments:	io Change											
2 3												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
093	Incinerator Ash Chamber Brick			Material Not Present							YES	X NO
2016 - Fall: N	lo Change											
Comments:					4							
2017 - Spring	g: No Change				1							
Comments:	•											
2018 - Fall: N	lo Change				-							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
094	Vibration Isolator			1946 Building, Fan Unit							YES	X NO
2016 - Fall: N	lo Change											
Comments:					4							
2017 - Spring	ı: No Change				=							
Comments:	•											
2018 - Fall: N	lo Change											
Comments:	io oriango				1							
					]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
095	White Chalky Material and Soil Mix			1953 Building, Unfinished Pipe Space							YES	X NO
2016 - Fall: N	lo Change				]							
Comments:					1							
2017 - Spring	: No Change				]							
Comments:												
2018 - Fall: N	lo Change				-							
Comments:	-				]							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
096	Vault Door Insulation			Material Not Present		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	<u> </u>											
2017 - Spring	ı: No Change				1							
Comments:	,				]							
2018 - Fall: N	lo Change				-							
Comments:					<u> </u>							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
097	Light Gray Vinyl Baseboard			Material Not Present							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
098	Light Gray Vinyl Baseboard Adhesive			Material Not Present							YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	ı: No Change											
Comments:	<u>-</u>											
2018 - Fall: N	lo Change											
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
099	Beaver Board			Material Not Present							YES	X NO
2016 - Fall: N	lo Change				$\exists$							
	g: No Change											
2018 - Fall: N	lo Change											
Comments.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
100	Exterior Brick			1946 Building							YES	X NO
2016 - Fall: N Comments: 2017 - Spring Comments: 2018 - Fall: N Comments:	g: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
101	Exterior Brick Mortar			1946 Building							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Chango											
Comments:	NO Change											
COMMITTEE:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
102	Exterior Brick			1953 Building							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	g. 140 Orlange											
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
103	Exterior Brick Mortar			1953 Building							YES	X NO
2016 - Fall: N	lo Change											
Comments.												
	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	- Commigue											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Domogo	Domogo	Domogo	Change in Asse	essment Category
HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Damage Type	Damage Quantity	Damage Units	Change in Asse	SSITIETIL Category
104	Exterior Brick			1960 Building							YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 Spring	g: No Change											
Comments:	J. NO Change				_							
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
105	Exterior Brick Mortar			1960 Building							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Chongo											
Comments:	io Change											
Comments.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
106	Exterior Door Caulk (NON AHERA)			1960 Building							YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
0047 On rin a	No Observe											
Comments:	g: No Change											
Comments.												
2018 - Fall: N	lo Change											
Comments:	-											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
107	Roofing Materials (NON AHERA)			1946 Building							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	Ţ											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
108	Roofing Materials (NON AHERA)			1953 Building							YES	X NO
2016 - Fall: N	lo Change											
Comments:	Ü											
2017 - Spring	g: No Change											
Comments:	J. 140 Orlango											
2018 - Fall: N	lo Chango											
Comments:	NO Criange											

		Quantity	Units		Type	Category		Type	Quantity	Units		
109	Roofing Materials (NON AHERA)			1960 Building							YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Spri	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
110	Interior Window Caulk			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Spri	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												

Asbestos

Damage

Friable

Damage

HA No

Material Description

Material

Material Location

Damage Change in Assessment Category

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
111	12" x 12" Lt. Beige w/Brwn & Wt. Streaks FT			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	<u> </u>											
2017 - Spring	ı: No Change				-							
Comments:												
2018 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
112	12" x 12" White w/Off White & Beige Streaks			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:	-											
2018 - Fall: N	lo Change											
Comments:	<u> </u>											

Material

Friable

Damage

Damage

Damage

Change in Assessment Category

Material Material Location

HA No

Material Description

113	Mastic for HA 111 & HA 112 Checkerboard FT Pattern			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	o Change				1							
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:	-											
2018 - Fall: N	o Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
114	12" x 12" Red Floor Tile			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	o Change				]							
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
115	12" x 12" Red Floor Tile Mastic			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	to change											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Domogo	Domogo	Domogo	Change in Assa	ssment Category
TIA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Damage Type	Damage Quantity	Damage Units	Change in Asses	SSITIETII Calegory
116	12" x 12" Blue Floor Tile			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:	<b>9</b>											
2017 Spring	g: No Change				_							
Comments:	g. No Change											
2018 - Fall: N	lo Change											
Comments:					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
117	12" x 12" Blue Floor Tile Mastic			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: No	o Change											
Comments:												
2017 - Spring:	: No Change											
Comments:	<u> </u>											
2018 - Fall: No	n Change											
Comments:	o change											
HA No	Material Description	Matarial	Matarial	Matarial Lagation	A ala a ata a	Material	Triable	Damana	D	Damasa	Change in Assa	
HA NO	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
118	Green Carpet Adhesive			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: No	o Change											
Comments:	J											
2017 - Spring:	· No Change											
Comments:	. No Change											
2018 - Fall: No	o Change											
Comments:												

		Quantity	Units		Type	Category		Type	Quantity	Units		
119	Acoustical Ceiling	1600	SF	Throughout Hallways of the 1960 Building		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall	: No Change				7							
Comments												
2017 - Spr	ing: No Change				-							
Comments												
2018 - Fall	: No Change				-							
Comments	· ·											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
120	12x12 beige mix floor tile			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall	: No Change				7							
Comments					=							
2017 - Spr	ing: No Change				-							
Comments												
2018 - Fall	: No Change											
Comments					_							
					_							

Asbestos

Damage

Friable

Damage

Damage Change in Assessment Category

HA No

Material Description

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
121	mastic associated with 12x12 beige mix floor tile			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	_											
2018 - Fall: N	lo Change											
Comments:	io Change											
<u> </u>	T	1	T	1	1		1		T_	T	T =	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
122	Red Carpet Adhesive			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	g. 140 Onange											
2018 - Fall: N	lo Change											
Comments:												
L												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
123	Black Board/ Marker Board Adhesive	5000	SF	Classrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	ı: No Change				=							
Comments:	,g											
2018 - Fall: N	lo Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
124	Grey and Black Mix Terrazzo Flooring	4000	SF	East Enterances and Stairwells		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	<u>-</u> -											
0047 0 :	N. O.											
2017 - Spring	g: No Change				_							
Comments:					4							
2018 - Fall: N	lo Change				7							
Comments:	Ŭ											

125	12" X 12" Tand w/Brown and White Streaks Floor Tile	Material Not Present	Miscellaneous		None			YES	X NO
2016 - Fall:	No Change		]	•	•	•	•		
Comments									
2017 - Spri	ng: No Change		_						
Comments									
2018 - Fall:	No Change								
Comments									
			_						

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No Ma	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
126 an	2" X 12" Tand w/Brown nd White Streaks Floor ile Mastic			Material Not Present		Miscellaneous		None			YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

12" X 12" Tand w/Brown

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
127	Cork Board Adhesive			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
2017 - Spring	g: No Change											
Comments: 2018 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
128	Green Carpet Adhesive			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N Comments: 2017 - Spring Comments: 2018 - Fall: N Comments:	g: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessr	ment Category
129	12"x12" White Mottled Floor Tile			Thtoughout Corridors, Classrooms, and Offices		Miscellaneous					YES		X NO
2016 - Fall: N	lo Change												
Comments:					-								
2017 - Spring	: No Change												
Comments:					_								
2018 - Fall: N	lo Change				-								
Comments:													
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessr	ment Category
130	12"x12" White Mottled Floor Tile Mastic			Thtoughout Corridors, Classrooms, and Offices		Miscellaneous					YES		X NO
2016 - Fall: N	lo Change												
Comments:													
2017 - Spring	: No Change												
Comments:					1								
2018 - Fall: N	lo Change				-								
Comments:													
					_								

		Quantity	Units		Type	Category		Type	Quantity	Units		
131	12"x12" Blue Mottled Floor Tile			Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules		Miscellaneous					YES	X NO
2016 - Fall	No Change				7							
Comments												
Comments	ng: No Change											
Comments	•											
2018 - Fall:	No Change											
Comments												
			1	1	T		T =		T =	T _		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
132	12"x12" Blue Mottled Floor Tile Mastic			Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules		Miscellaneous					YES	X NO
2016 - Fall	No Change				7							
Comments												
0047 Cm#	na. Na Changa				-							
Comments	ng: No Change											
Comments	•				-							
2018 - Fall	No Change				1							

Friable

Damage

Asbestos

Damage

Damage Change in Assessment Category

HA No

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
133	2'x2' Lay-in Ceiling Tile			First Floor Corridor		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change				-							
Comments:	gc											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
134	2'x4' Lay-in Ceiling Tile			Rooms 112A, 126, and 226		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	-											
2017 - Spring	ı: No Change				-							
Comments:	, J											
2018 - Fall: N	lo Change				-							
Comments:	io chango											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
135	4" Gray Baseboard			Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunch Room, and 2nd Floor Store Room.		Miscellaneous					YES X NO
-					-						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
136	4" Gray Baseboard Mastic			Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunch Room, and 2nd Floor Store Room.		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
137	Gray Sink Undercoating			Rooms 128, 130, and 133		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	<u> </u>											
2018 - Fall: N	lo Chango											
Comments:	io Change											
Commonto.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
138	Carpet Mastic			Rooms 134 and 212		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	y: No Change											
Comments:	g. No Change											
2018 - Fall: N	lo Change											
Comments:												

		Quantity	Units		Туре	Category		Туре	Quantity	Units	<u> </u>	
139	Transite Laboratory Countertop	400	SF	Rooms 109 and 226		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:	•											
2018 - Fall: N	No Change				-							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
140	Wood Pattern Sheet Flooring			Gymnasium		Miscellaneous					YES	X NO
2016 - Fall: N	No Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change				-							
Comments:												

Friable

Material

Asbestos

Damage

Damage

Damage

Change in Assessment Category

Material Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
141	Wood Pattern Sheet Flooring Mastic			Gymnasium		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
142	Blue Sheet Flooring	650	SF	Room 126		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	<u> </u>											
2017 - Sprin	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	<u> </u>											

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
143	Blue Sheet Flooring Mastic	650	SF	Room 126		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:					<u> </u>							
2017 - Spring	: No Change				-							
Comments:	-											
2018 - Fall: N	o Change				<u> </u>							
Comments:												
					]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
144	Transite Electrical Panel	200	SF	Basement Electrical Vault		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:												
2017 - Spring	: No Change											
Comments:	. 140 Onango											
2018 - Fall: N	o Chango											
Comments:	o change				-							
					]							

		Quantity	Units		Type	Category		Type	Quantity	Units		
145	Electrical Wiring Associated with Wall Mounted Clocks	150	LF	Throughout Building		Miscellaneous	No	Unknown	0		YES	X NO
2016 - Fall:	No Change											
Comments:	U											
2017 - Sprin	ıg: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	ito onango											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
В	Distributed Pipe Insulation on Floor			Material Not Present		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:	U											
2017 - Sprin	ig: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												

Asbestos

Damage

Friable

Damage

Damage Change in Assessment Category

HA No

Material Description

Material

		Quantity	Units		Type	Category		Type	Quantity	Units		
С	Aircell Pipe Insulation			1946 Building, Walls and Pipe Chases		TSI					YES	X NO
2016 - Fall: N	No Change				1							
Comments:	J											
2017 - Spring	g: No Change				1							
Comments:	<i>y y</i> -				]							
2018 - Fall: N	No Change				_							
Comments:					]							
					]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
D	Joint Compound off Fiberglass Pipe Insulation			Material Not Present		TSI		None			YES	X NO
2016 - Fall: N	No Change				1							
Comments:												
2017 - Spring	g: No Change				-							
Comments:												
2018 - Fall: N	No Change				1							
Comments:	<u> </u>				]							
					]							

Asbestos

Damage

Friable

Damage

HA No

Material Description

Material

Material Location

Damage Change in Assessment Category

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
Е	Joint Compound Off Fiberglass Pipe Insulation			Material Not Present		TSI		None			YES	X NO
2016 - Fall: N	o Change											
Comments:	J											
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
F	Distributed Pipe Insulation in Dirt on Floor			Material Not Present		TSI		Dist			YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	-											

Material

Friable

Damage

Damage

Damage

Change in Assessment Category

Material Material Location

HA No

Material Description

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
G	Distributed Pipe Insulation in Dirt on Floor			Material Not Present		TSI		Dist			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
Н	Aircell Pipe Insulation			Material Not Present		TSI		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	·											

Material

Friable

Damage

Damage

Damage

Change in Assessment Category

Material Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
1	Aircell Pipe Insulation			Material Not Present		TSI		None			YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Spring	ı: No Change											
Comments:	. No change											
2018 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
J	Paperwrap Pipe Insulation			1946 Building, Pipe Chases							YES	X NO
2016 - Fall: N Comments:	lo Change						·					
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
K	Hard Joint Compound off Paperwrap Pipe Insulation	75	LF	1946 Building, Walls and Pipe Chases		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:												
2017 - Spring	: No Change											
Comments:	<b>.</b>											
2018 - Fall: N	o Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
L	Hard Joint Compound off Aircell Pipe Insulation			Material Not Present		TSI		Dist			YES	X NO
2016 - Fall: N	o Change				]							
Comments:												
2017 - Spring	· No Change											
Comments:	. Ho onango											
2018 - Fall: N	o Change											
Comments:	o Change											
-					]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
L-1	Hard Joint Compound off Aircell Pipe Insulation			1946 Building, Walls and Pipe Chases		TSI					YES	X NO
2016 - Fall: N	o Change				]							
Comments:	<u> </u>				1							
2017 - Spring	: No Change				=							
Comments:					1							
2018 - Fall: N	lo Change											
Comments:	<b>.</b>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
М	Hard Joint Compound off Aircell Pipe Insulation			Material Not Present		TSI		None			YES	X NO
2016 - Fall: N	o Change				1							
Comments:	•											
2017 - Spring	: No Change				1							
Comments:	,											
2018 - Fall: N	o Change											
Comments:												
					]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
N	Hard Joint Compound off Aircell Pipe Insulation			Material Not Present		TSI		None			YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
0	Duct Interior Insulation			1960 Building, Boiler Room							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:	<b>y</b> -											

		Quantity	Units		Туре	Category		Туре	Quantity	Units	<u> </u>	
Р	Magblock Pipe Insulation			Material Not Present		TSI		Loc			YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring: No Change												
Comments:												
2018 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
Q	Magblock Pipe Insulation Joint Compound			Material Not Present		TSI		None			YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring: No Change												
Comments:												
2018 - Fall: N	lo Change											
Comments:	<u> </u>											

Friable

Material

Asbestos

Damage

Damage

Damage

Change in Assessment Category

Material Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
R	Water Tank Insulation			Material Not Present		TSI		None			YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Spring Comments:	g: No Change											
2018 - Fall: No Change Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
S	Aircell Duct Insulation			Material Not Present		TSI					YES	X NO
2016 - Fall: N Comments: 2017 - Spring Comments: 2018 - Fall: N Comments:	g: No Change											

Т	Magblock Insulation	15	LF	1946 Building, Coal/Ash Room Abandoned Mech. Unit		TSI	Yes	None	0		YES	X NO
2016 - Fall	: No Change	•	•		 ]	•	•	•	•	•		
Comments												
2017 - Spr	ing: No Change											
Comments	:											
2018 - Fall	: No Change											
Comments	:											
LIA No	Motorial Description	Motorial	Motorial	Motorial Logation	Achaetae	Motorial	Erioblo	Domogo	Domogo	Domogo	Change in Assess	mont Cotogony

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

	HA NO	Material Description	Quantity	Units	iviaterial Location	Type	Category	Friable	Type	Quantity	Units	Change in Asses	sment Category
	U	Duct Insulation - Black Tar Like Adhesive			1953 Building, Unfinished Pipe Spaces		TSI					YES	X NO
2016 - Fall: No Change Comments:													

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Air Force Academy High School
Date: 1/15/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 45231

SCHOOL'S ASBESTOS MANAGEMENT PLAN.