Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

William J Bogan High School 46041 1230 School: **Oracle Unit: Building ID:** Address: 3939 W. 79th St. Region: 05 Mail Room: Asbestos Surveyor: Lowe, Jeffrey X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/7/2019 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type Office store Room . YES X NO A80 9x9 Green VFT 107,105, 2nd flr W. Miscellaneous corridor, nurses office 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08B	9x9 Brown VFT-material not observed			kitchen, office		Miscellaneous		None			YES X NO
2016 - Fall:	No Change										
Comments:											
2017 - Sprin	ng: No Change										
Comments:	g g-										
2017 - Fall:	No Change										
Comments:	<u> </u>										
2018 - Sprin	ng : No Change										
Comments:											
2018 - Fall:	No Change										
Comments:	J										
LIA Na	Material Decemention	Matarial	Matarial	Matarial Lagation	Ashastas	Mariania	Luiabla	Damasa	Damana	D	Change in Assessment Catagoni

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08C	9x9 gray VFT	1450	SF	S. stairwell near auditorium, N/W basement entry stairwell, and auditorium		Miscellaneous	No	Dist	25		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

08D	9x9 red VFT			1st flr W. corridor, 2nd flr, East corridor center - ABATED		Miscellaneous					YES	X NO
2016 Fall:	No Change			•	1		•	•	•	•	•	
Comments:												
Comments.	•				1							
2017 - Fall:	No Change											
Comments:												
2017 - Sprii	ng: No Change				1							
Comments:	:											
2018 - Fall:	No Change				_							
Comments:	•]							
2018 - Sprii	ng : No Change				1							
Comments:	•											
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

Damage

Type

Туре

None

Damage

Quantity

Quantity

Units

YES

X NO

Damage

Units

2016 - Fall: No	Change		
Comments:	<u> </u>		
2017 - Spring:	No Change		
Comments:			
2017 - Fall: No	Change		
Comments:			
2018 - Spring :	: No Change		
Comments:			
2018 - Fall: No	Change		
Comments:	•		

Quantity

Units

113

HA No

08E

Material Description

9x9 tan and blue VFT

Material

Quantity

Material

Units

Material Location

09A	12x12 off white w/ speckles	3760	SF	Rm 102, Main office, social room	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2017 - Fall: N	o Change									
Comments:	-									
2018 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10A	Baseboard			Throughout		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No

Material Description

Material

Quantity

Material

Units

		Quantity	Units		Type	Category	Type	Quantity	Units		
11A	Mastic beneath baseboard			Throughout		Miscellaneous	None			YES	X NO
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12A	Mastic 9x9 Green Floor tile			Office store rm, 107,105, 2nd flr W. corridor, nurses office		Miscellaneous					YES X NO

016 - Fall: No Change	
Comments:	
017 - Fall: No Change	
Comments:	
017 - Spring: No Change	
Comments:	
018 - Fall: No Change	
Comments:	
018 - Spring : No Change	
Comments:	

HA No

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessn	nent Category
12B	Mastic under 9x9 Brown VFT			See HA 8B		Miscellaneous					YES	X NO
2016 - Fall: N	o Change]							
Comments:	<u> </u>				1							
2017 - Spring	: No Change											
Comments:	-				1							
2017 - Fall: N	o Change				=							
Comments:					-							
2018 - Spring	: No Change				_							
Comments:												
2018 - Fall: N	o Change				=							
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12C	Mastic beneath 9x9 gray	1450	SF	S. stairwell near auditorium, N/W basement entry stairwell, and auditorium		Miscellaneous	No	Dist	25		YES X NO

016 - Fall: No Change
Comments:
017 - Fall: No Change
Comments:
017 - Spring: No Change
Comments:
018 - Fall: No Change
Comments:
018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
12D	mastic 9x9 red VFT	2950	SF	1st flr W. corridor, 2nd flr, East corridor center		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	_											
2017 - Fall: N	lo Change											
Comments:	•]							
2017 - Spring	ı: No Change				-							
Comments:]							
2018 - Fall: N	lo Change				-							
Comments:	<u> </u>											
2018 - Spring	ı : No Change				_							
Comments:	, <u> </u>											
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12E	Mastic 9x9 tan VFT			113		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

Page 7

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
13A	Mastic 12x12 off white w/speckles	3760	SF	Rm 102, Main office, social room		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change											
Comments												
2017 - Spr	ring: No Change											
Comments	S:											
2017 - Fal	II: No Change											
Comments	s:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12x12 blue flr tile	57	SF	Main office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Spring : No Change

Comments:

		-							_		
14A	Tan linoleum w/blue trim	32600	SF	Throughout classrooms, nurses office, cafeteria, library, counselors office, RM. 113		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change]						
Comments:	<u> </u>										
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
	g : No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:											

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12x12 white w/blue specks flr tile	20100	SF	Throughout corridors, 139, 141, 143, kitchen, office		Miscellaneous	No	None	0		YES X NO

HA No

Material Description

Material

Quantity

Material

Units

15A	Mastic Beneath Tan Linoleum	32000	SF	Throughout classrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	•				-							
2017 - Spring	g: No Change				_							
Comments:												
2017 - Fall: N	lo Change											
Comments:					=							
	g : No Change				-							
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
16	Transite table tops	300	SF	lab rooms		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Units

Damage

Quantity

Change in Assessment Category

HA No

Material Description

Material

Units

Material

Quantity

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
16A	Mastic under 12x12 white w/blue specks	20100	SF	Throughout corridors, 139, 141, 143, kitchen, office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change			· · · · · · · · · · · · · · · · · · ·								

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	Transite counter tops	900	SF	Lab rooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
17A	Mastic under 12x12 blue flr tile	57	SF	Main office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	Transite fume hood	300	SF	Rm 221		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
19	1'x1' White with Holes Ceiling Tile	15000	SF	Throughout		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	1'x1' White with Holes Ceiling Tile Mastic	15000	SF	Throughout		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

		Quantity	Units		Type	Category		Type	Quantity	Units		
21	Baseboard	180000	SF	Throughout School		Miscellaneous	No	None	0		YES	X NO
	II: No Change											
Comment	is:				_							
2017 - Sp	ring: No Change											
Comment	s:											
2017 - Fa	II: No Change											
Comment	ts:											
2018 - Sp	ring : No Change				=							
Comment	ts:											
2018 - Fa	II: No Change											
Comment												

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Baseboard Mastic	180000	SF	Throughout School		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
23	Burgundy Carpet Mastic	3000	SF	Principal's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	2' x 4' Ceiling Tile, White, Spaghetti Pattern	30000	SF	1st and 2nd Floor Hallways		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	2' x 4' Ceiling Tile, White Spaghetti Pattern Mastic	30000	SF	1st and 2nd Floor Hallways		Miscellaneous	No	None	0		YES X NO
					i						

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	9" x 9" Black Floor Tile	10000	SF	Auditorium		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
27	9" x 9" Black Floor Tile Mastic	10000	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change											
Comments												
2017 - Spr	ing: No Change											
Comments	S:											
2017 - Fall	: No Change				=							
Comments	S:											
2018 - Spr	ing : No Change											
Comments	S:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Acoustical Ceiling Tile	2000	SF	143 Band Room		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Acoustical Ceiling Tile Mastic	2000	SF	143 Band Room		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	2' x 4' White Ceiling Tile	4000	SF	Rooms 142, 239, 110, and 144		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	2' x 4' White Ceiling Tile Mastic	4000	SF	Rooms 142, 239, 110, and 144		Miscellaneous	No	None	0		YES X NO
2016 Falls No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Ceiling Plaster	10000	SF	Auditornium		Surface	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	ment Category
А	Millboard-material not observed			Boiler room& basement		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change]							
Comments:												
2017 - Spring	j: No Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					_							
2018 - Spring	ı : No Change											
Comments:												
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Fire curtain	640	SF	Auditorium		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
СМ	tan carpet mastic	300	SF	engineers office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:					1							
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	Light fixture insulators			1st flr north wing		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Mudded fittings on Fiberglass lines	300	LF	Chases & basement		TSI	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Breeching	350	SF	Boiler room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
Н	Tank insulation			Boiler room		TSI		None			YES	X NO
2016 - Fall: N	lo Change]							
Comments:]							
2017 - Spring	g: No Change				-							
Comments:	-]							
2017 - Fall: N	lo Change				-							
Comments:												
2018 - Spring	j : No Change				-							
Comments:												
2018 - Fall: N	lo Change				-							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-100	2'x4' white celing tiles with holes	100	SF	engineer office		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
1	Cardboard fittings	280	LF	Throughout		TSI	Yes	None	0		YES	X NO
2016 - Fall	I: No Change											
Comments	S:											
2017 - Spr	ring: No Change											
Comments	3:											
2017 - Fall	l: No Change											
Comments	S:											
2018 - Fall	l: No Change											
Comments	S:											
2018 - Spr	ring : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Fire Doors	20	EA	Throughout		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

Page 24

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
К	Cardboard pipe insulation	1525	LF	Throughout		TSI	Yes	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
0	Incinerator insulation	400	SF	Boiler room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

Р	Boiler Gaskets	100	LF	Boiler room	TSI	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:	o onango									
2047 Fall N	o Change									
2017 - Fall: N Comments:	o Change									
2017 - Spring	: No Change									
Comments:										
2018 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:	y -									

Type

Material

Category

Damage Quantity Damage

Units

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Q	Tank insulation			Pool filter room - abated		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R	Aircell Pipe Cover	3000	SF	Unexcavated Area in Basement		TSI	Yes	Dist	50		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
S	Aircell Pipe Fitting Insulation	3000	SF	Un-Excavated Area in Basement		TSI	Yes	Dist	50		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: William J Bogan High School
Date: <u>1/7/2</u> 019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.