

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2018 - Fall

**School:** Hyde Park Academy High School  
**Address:** 6220 S. Stony Island

**Oracle Unit:** 46171  
**Region:** 05

**Building ID:** 1390  
**Mail Room:** 46

**Asbestos Surveyor:** Collins, Michael  
**Survey Date:** 1/10/2019  
**Email Address:** \_\_\_\_\_

**CHECK HERE IF NO CHANGE TO ASBESTOS**

A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

*Each child's backpack*    
 *Notice printed in school's newsletter*    
 *Notice printed in school's calendar*    
 *Other* | *Report made available*

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 01    | plaster              | 140000            | SF             | building 1911     |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 02    | hard plaster         | 140000            | SF             | building 1937     |               | Surface           | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 03    | hard plaster         | 140000            | SF             | building 1970     |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description    | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 04    | 12x12 ceiling tile text | 700               | SF             | 1937 building room 142 |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 05    | 12x12 ceiling tile   | 10000             | SF             | 1937 building     |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 06    | 2x2 ceiling tile     | 34500             | SF             | 1911 building     |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 07    | 2x4 pinhole ceiling tile | 34500             | SF             | 1911 building     |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description        | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 08    | 2x4 perforated ceiling tile | 1500              | SF             | 1911 building     |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description  | Material Quantity | Material Units | Material Location                                     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 09    | ceiling tectum panels | 13000             | SF             | 1911 buildings (50 ft. in air inaccessible to sample) |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10    | 9x9 light brown F.T. | 16800             | SF             | 130, 132, 136, 138, 140, 142-145, 210, 232, 236, 238, 240, 303, 305, 307, 309, 310, 332, 334, 336, 338, 340, 344, 345, 346 |               | Miscellaneous     | No      | Dist        | 500             |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11    | 12x12 tan F.T.       | 99000             | SF             | 130, 132, 136, 138, 140, 142-145, 210, 232, 236, 238, 240, 303, 305, 307, 309, 310, 332, 334, 336, 338, 340, 344, 345, 346 |               | Miscellaneous     | No      | Dist        | 100             |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description     | Material Quantity | Material Units | Material Location                          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 12    | 12x12 metal ceiling tile | 3750              | SF             | 1911 natatorium ( ceiling is inaccessible) |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 13    | transite table tops  | 1000              | SF             | Science labs      |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|  |
|--|
| 2016 - Fall: No Change<br>Comments:    |
| 2017 - Spring: No Change<br>Comments:  |
| 2017 - Fall: No Change<br>Comments:    |
| 2018 - Spring : No Change<br>Comments: |
| 2018 - Fall: No Change<br>Comments:    |

| HA No | Material Description    | Material Quantity | Material Units | Material Location     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 14    | transite panel material | 2500              | SF             | Science labs 312, 316 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|  |
|--|
| 2016 - Fall: No Change<br>Comments:    |
| 2017 - Spring: No Change<br>Comments:  |
| 2017 - Fall: No Change<br>Comments:    |
| 2018 - Spring : No Change<br>Comments: |
| 2018 - Fall: No Change<br>Comments:    |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description                   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 15    | accoustical ceiling tile (no material) |                   |                | 1911 building     |               |                   |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                            | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 16    | 12x12 ceiling tile text (material not observed) |                   |                | 1937 building     |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location                            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 17    | spray-on fireproofing | 45000             | SF             | BLDG 1911 above 2nd & 3rd floor ceiling tile |               | Surface           | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description        | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 18    | 9x9 light brown F.T. mastic | 16800             | SF             | 130, 132, 136, 138, 140, 142-145, 210, 232, 236, 238, 240, 303, 305, 307, 309, 310, 332, 334, 336, 338, 340, 344, 345, 346 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 19    | 9x9 tan F.T. mastic  | 11400             | SF             | 1st, 2nd & 3rd floor south hallways |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |           |
|---------------------------|-----------|
| 2016 - Fall: No Change    | Comments: |
| 2017 - Spring: No Change  | Comments: |
| 2017 - Fall: No Change    | Comments: |
| 2018 - Spring : No Change | Comments: |
| 2018 - Fall: No Change    | Comments: |

| HA No | Material Description      | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 20    | 9x9 med. Brn. F.T. mastic | 21000             | SF             | SEE COMMENTS FOR ROOM LOCATIONS |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |           |
|---------------------------|-----------|
| 2016 - Fall: No Change    | Comments: |
| 2017 - Spring: No Change  | Comments: |
| 2017 - Fall: No Change    | Comments: |
| 2018 - Spring : No Change | Comments: |
| 2018 - Fall: No Change    | Comments: |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 21    | 12x12 tan F.T. mastic | 99000             | SF             | SEE COMMENTS FOR ROOM LOCATIONS |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description  | Material Quantity | Material Units | Material Location                                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22    | 12x12 tan F.T. mastic | 900               | SF             | 1937 building, patched areas of 1st, 2nd flr hallway |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description       | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23    | 12x12 lt. Brn. Tile mastic | 1700              | SF             | 1970 building, weight room |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 24    | 2' ceiling tile      | 14000             | SF             | 1937 building     |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location                           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 25    | 2' ceiling tile      | 1200              | SF             | 1970/ rear of rm. 143 2nd flr. S/W corridor |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 26    | 9x9 tan F.T.         | 11400             | SF             | 1st, 2nd & 3rd floor south hallways |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 27    | 9x9 med.brn. F.T.    | 21000             | SF             | SEE COMMENTS FOR ROOM LOCATIONS |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location                                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 28    | 12x12 tan F.T.       | 900               | SF             | 1937 building, patched areas of 1st, 2nd flr hallway |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 29    | 12x12 lt. Brn. F.T.  | 1700              | SF             | 1970 building, weight room |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 30    | 9x9 med. Brn. F.T.   | 2500              | SF             | Room 246, southeastern hall on 2nd floor |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 31    | 9x9 tan F.T.         | 1300              | SF             | Room 210, 311     |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 32    | 12x12 beige F.T.     | 750               | SF             | Small hallways leading to library on 2nd and 3rd floors. |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 33    | 12x12 brown F.T.     | 4000              | SF             | Locker rooms 1st floor |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34    | 12x12 lt. Brn. F.T.  | 11000             | SF             | 1911 building     |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 35    | 12x12 dark tan F.T.  | 800               | SF             | 1911 building, patched areas |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 36    | 12x12 lt. Grn. F.T.  | 1600              | SF             | Room 133          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 37    | 12x12 off-white F.T. | 1825              | SF             | Engineer's office |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 38    | 12x12 white F.T.     | 2500              | SF             | Rooms 135, 137    |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description    | Material Quantity | Material Units | Material Location                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 39    | 12x12 Tan speckled F.T. | 490               | SF             | Patched areas of 1st flr north hallway |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 40    | 9x9 brown F.T.       | 950               | SF             | 1937 building, patched areas of 1st, 2nd, 3rd flr hallways |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 41    | 9x9 drk.brn. F.T.    | 75                | SF             | 1937 building, patched areas of 1st, 2nd, 3rd flr hallways |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 42    | 12x12 lt. Brn. F.T.  | 1500              | SF             | 1937 building, patched areas of 1st, 2nd & 3rd floor south hallways |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location                          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 43    | 9x9 med. Brn. F.T.   | 1800              | SF             | Team, Visitor, Boy's & Girl's Locker Rooms |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 44    | 9x9 tan F.T.         | 425               | SF             | 1937 building     |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 45    | 9x9 brown F.T.       | 3100              | SF             | SEE COMMENTS FOR ROOM LOCATIONS |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location                                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 46    | 9x9 brown F.T.       | 600               | SF             | Patched areas of 1st, 2nd & 3rd floor south hallways |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description      | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 47    | 9x9 med. brn. F.T. mastic | 2500              | SF             | Room 246, southeastern hall on 2nd floor |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 48    | 9x9 tan F.T. mastic  | 1300              | SF             | Room 210, 311     |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description    | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 49    | 12x12 beige F.T. Mastic | 750               | SF             | Small hallways leading to library on 2nd and 3rd floors. |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description    | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 50    | 12x12 brown F.T. mastic | 4000              | SF             | Locker rooms 1st floor |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 51    | 12x12 lt. Brn. F.T. mastic |                   |                | Auditorium        |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description       | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 52    | 12x12 dark tan F.T. mastic | 800               | SF             | 1911 building, patched areas |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 53    | 12x12 lt. Grn. F.T. mastic | 1600              | SF             | Room 133          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description        | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 54    | 12x12 off-white F.T. mastic | 1825              | SF             | Engineer's office |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 55    | 12x12 white F.T. mastic | 2500              | SF             | Rooms 135, 137    |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description           | Material Quantity | Material Units | Material Location                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 56    | 12x12 Tan speckled F.T. mastic | 490               | SF             | Patched areas of 1st flr north hallway |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 57    | 9x9 brown F.T. mastic | 950               | SF             | 1937 building, patched areas of 1st, 2nd, 3rd flr hallways |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description     | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 58    | 9x9 drk.brn. F.T. mastic | 75                | SF             | 1937 building, patched areas of 1st, 2nd, 3rd flr hallways |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description       | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 59    | 12x12 lt. Brn. F.T. mastic | 1500              | SF             | 1937 building, patched areas of 1st, 2nd & 3rd floor south hallways |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description      | Material Quantity | Material Units | Material Location                          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 60    | 9x9 med. Brn. F.T. mastic | 1800              | SF             | Team, Visitor, Boy's & Girl's Locker Rooms |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 61    | 9x9 tan F.T. mastic  | 425               | SF             | 1937 building     |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description  | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 62    | 9x9 brown F.T. mastic | 3100              | SF             | SEE COMMENTS FOR ROOM LOCATIONS |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description     | Material Quantity | Material Units | Material Location                                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 63    | 9x9 ft. Brn. F.T. mastic | 600               | SF             | Patched areas of 1st, 2nd & 3rd floor south hallways |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 64    | 12x12 ceiling tile text | 25000             | SF             | 1911 building     |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description           | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 65    | 12x12 ceiling tile text mastic | 25000             | SF             | 1911 building     |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 66    | ceiling/tile system  | 15000             | SF             | 1911 building     |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description      | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 67    | 12x12 ceiling tile matsic | 1300              | SF             | 1937 building     |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 68    | 2'x4' ceiling tile   | 800               | SF             | 1937 building     |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 69    | drop-in ceiling tile | 8500              | SF             | 1937 building     |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 70    | 2'x4' ceiling tile   | 1200              | SF             | 1970 building     |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 71    | black trim vinyl baseboard | 18000             | LF             | 1911 building     |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 72    | black trim vinyl baseboard mastic | 18000             | LF             | 1911 building     |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description      | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 73    | blk. Trim vinyl baseboard | 275               | LF             | 1937 building     |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description             | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 74    | blk. Trim vinyl baseboard mastic | 275               | LF             | 1937 building     |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 75    | black trim vinyl baseboard | 300               | LF             | 1970 building     |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 76    | black trim vinyl baseboard mastic | 300               | LF             | 1970 building     |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 77    | transite wind/sill   | 3000              | SF             | 1911 building     |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 78    | transite windowsill  | 550               | SF             | 1937 building     |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 79    | grey carpet mastic   | 950               | SF             | 1911 building     |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 80    | green carpet mastic  | 1900              | SF             | 1911 building     |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 81    | brown carpet mastic  | 1200              | SF             | 1911 building     |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 82    | dr. orange carpet mastic | 15000             | SF             | 1911 building     |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 83    | orange carpet mastic | 21000             | SF             | 1911 building     |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description                       | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 84    | 12" x 12" Light gray with white floor tile | 3600              | SF             | Auditorium, Rm 142 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                                  | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 85    | Mastic for 12" x 12" Light gray with white floor tile | 3000              | SF             | Auditorium        |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 86    | Gray mix Terrazzo    | 5000              | SF             | Entrance and stairwells |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                        | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 87    | 12" x 12" White w/gray and black floor tile | 3200              | SF             | Room 114 and patches in room 210 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                                      | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 88    | Mastic for 12" x 12" white with gray and black floor tile | 500               | SF             | Room 114 and patches in Room 210 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                         | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 89    | 12" x 12" white with blue and red floor tile | 1800              | SF             | Room 117          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description                                    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 90    | Mastic for 12" x 12" white with Blue and Ref floor tile | 1800              | SF             | Room 117          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 91    | Black Chalk boards   | 13000             | SF             | Classrooms        |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 92    | Black Chalk Board Adhesive | 13000             | SF             | Classrooms        |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description         | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 93    | 2' x 2' Carpet Square Mastic | 2000              | SF             | Library           |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description      | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 94    | 12" x 12" Gray Floor Tile | 8000              | SF             | Rooms 142, 341, 344, 345, and Stage 107A |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description                           | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 95    | Mastic Associated w/ 12" x 12" Gray Floor Tile | 8000              | SF             | Rooms 142, 341, 344, 345, and Stage 107A |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| A     | Mag block            |                   |                | boiler            |               | TSI               |         | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| B     | mag block            |                   |                | garage            |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| C     | mag block            |                   |                | suspended in pump room |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| D     | mag block ABATED     |                   |                | pump rm.          |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| E     | mag block            |                   |                | boiler room       |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| F     | preform pipe         |                   |                | boiler room & tunnel |               | TSI               |         | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| G     | preform fittings     |                   |                | basement & tunnels |               | TSI               |         | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description      | Material Quantity | Material Units | Material Location                                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| H     | cardboard pipe insulation |                   |                | compressor rm./ pump rm. Absorption rm./ tunnels |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No   | Material Description                           | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|---------|--|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| HA-1000 | Glue for 1'x1' white ceiling tile with grooves | 34500             | SF             | Rm. 301, 303, 305, 307, 309, 311 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No   | Material Description         | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|---------|------------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| HA-1001 | new 2'x2' white ceiling tile | 35000             | SF             | throughout 1st and 3rd floor |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No   | Material Description         | Material Quantity | Material Units | Material Location             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|---------|------------------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| HA-1002 | new 2'x4' white ceiling tile | 35000             | SF             | throughout 1st and 3rd floors |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No   | Material Description    | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|---------|-------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| HA-1003 | Black sink undercoating | 15                | SF             | Art rooms 401, 402, 406 |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| I     | cardboard fittings   | 40                | LF             | tunnels/compressor rm. |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| J     | fiberglass fittings  | 1800              | LF             | 1911 building     |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| K     | aircell duct insulation | 30                | SF             | tunnels           |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| L     | aircell pipe insulation | 2240              | LF             | pump rm. Tunnels  |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| M     | fittings on aircell  | 140               | LF             | pump room 1911    |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| N     | fiber glass fittings | 400               | LF             | 1937 building     |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| O     | fiberglass fittings  |                   |                | 1970bldg          |               | Miscellaneous     |         | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description     | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| P     | 2'x2' WHITE CEILING TILE | 69000             | SF             | THROUGHOUT 1911 BLDG |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                 | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| Q     | LINOLEUM FLOORING<br>Grey with white | 2000              | SF             | ROOM 245, and 343 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| Q-1   | LINOLEUM FLOORING-MASTIC | 950               | SF             | ROOM 245, and 343 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| R     | 12x12 BROWN VFT      | 2300              | SF             | ROOMS 341, 333    |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| R-1   | 12x12 BROWN VFT-MASTIC | 2300              | SF             | ROOMS 341, 333    |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location                                       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| S     | 12x12 BLUE VFT       | 3250              | SF             | EAST STAIRWELL, FRONT OF AUDITORIUM & ALL OF AUDITORIUM |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location                                       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| S-1   | 12x12 BLUE VFT-MASTIC | 3250              | SF             | EAST STAIRWELL, FRONT OF AUDITORIUM & ALL OF AUDITORIUM |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description      | Material Quantity | Material Units | Material Location                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| T     | 12x12 ORANGE W/ GREEN VFT | 450               | SF             | BACK STAGE OF AUDITORIUM W/ HALLWAY |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| T-1   | 12x12 ORANGE W/<br>GREEN VFT-MASTIC | 450               | SF             | BACK STAGE OF<br>AUDITORIUM W/<br>HALLWAY |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*



---

Robert Christlieb

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***



NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Hyde Park Academy High School  
Date: 1/10/2019

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other. Report made available
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.