Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

46201

Oracle Unit:

Address: 6325 W. 56th St. Region: Mail Room: Asbestos Surveyor: Szczepanik, Margaret X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/10/2019 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type 1st.2nd.3rd corridors. YES X NO 13A 12x12 pink speckled flr tile 47790 SF 101,102,104,105,106,108 Miscellaneous No None 0 ,109,112-115,117,201-211,214,215,222 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

John F Kennedy High School

School:

Oracle Unit: 46201

1420

Building ID:

13B 12x12 taupe flr tile 9000 SF 1st,2nd flr corridors, Rm 218,219,222,M&F gym office,1st,2nd flr dr ways to class rms,Lunchroom	YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13C	12x12 dark biege flr tile	8230	SF	Lunch rm, 3rd flr corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

13D	12x12 crème w/brwn blotch flr tile	5760	SF	lunchroom	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:	-									
2017 - Spring	: No Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:										

Type

Asbestos

Type

Material

Category

Material

Category

Miscellaneous

Friable

Friable

No

Damage

Damage

Туре

None

Туре

Damage

Quantity

Damage

Quantity

0

Damage

Damage

Units

Units

13E	12x12 rust VFT	300	SF	3rd flr. NE Corridor
		•		
2016 - Fall: N	lo Change			
Comments:				
2017 - Fall: N	lo Change			
Comments:				
2017 - Spring	յ։ No Change			
Comments:				
2018 - Fall: N	lo Change			
Comments:	·			·
			·	

Material

Quantity

Material

Quantity

Material

Material

Units

Units

Material Location

Material Location

HA No

HA No

Material Description

Material Description

Change in Assessment Category

Change in Assessment Category

X NO

YES

13F	12x12 crème w/ tan flr tile	150	SF	3rd flr NW corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Changa				1							
	vo Change											
Comments:												
					_							
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: N	No Changa											
	NO Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage Units	Change in Assess	ment Category
		Quantity	Units	1	Type	Category		Туре	Quantity	UTIILS		

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

14A	mastic under 12x12 pink speckled flr. Tile	Rms, 101,102,103,104,105,106 ,108,109,112- 115,117,201- 211,214,215,222	Miscellaneous			YES
2016 - Fa	II: No Change					
Comment						
2017 - Fa	II: No Change					
Comment	S:					
2017 - Sp	ring: No Change					

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No

Comments:

Comments:

2018 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

X NO

14C	Mastic under 12x12 dark beige flr. Tile	8230	SF	linked area (220A,220B, 220C)		Miscellaneous	No	None	0		YES	X NO
0040 5-11	N. Oleana	•			7							
	: No Change											
Comments	:											
2017 - Spri	ng: No Change											
Comments	:											
2017 - Fall:	: No Change											
Comments												
2018 - Fall:	: No Change											
Comments	:											
					=							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

No

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

X NO

	Biotorios Mastis		
2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			

Quantity

5760

Units

Lunchroom

SF

HA No

14D

Material Description

12x12 crème w/brwn.

Blotches Mastic

Material

Units

Material

Quantity

Material Location

lunch rm, 3rd flr corridor,

14E	12x12 rust VFT Mastic	300	SF	3rd flr. NE corridor		Miscellaneous	No	None	0	YES	X NO
004C Fall N	- Ob]						
2016 - Fall: N	o Cnange										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											
]						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14F	Mastic under 12x12 crème w/ tan flr. Tile	150	SF	3rd flr NW corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

15A	12x12 pink flr tile	2330	SF	2nd, flr middle(220A, 220B,220C) off. 1970 bldg., Link hall		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change				1						
Comments:	<u> </u>										
2017 - Spring	: No Change				-						
Comments:											
2017 - Fall: N	lo Change				_						
Comments:											
2018 - Fall: N	lo Change										
Comments:											
					J						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
15B	12x12 taupe flr tile	2330	SF	1970 bldg. 2nd flr. Middle office (220A, 220B, 220C) Link hall		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

2016 Falls	No Changa										
2016 - Fall:											
Comments:											
2017 - Sprir	ng: No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
	_		•	_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Surface

Miscellaneous

Friable

No

Damage

Type

None

None

Damage

Quantity

0

Damage

Units

Change in Assessment Category

X NO

X NO

YES

YES

16B	Mastic under 12x12 taupe flr tilesee HA14C		1970 bldg, 2nd flr. Middle office
2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			

Material

Quantity

290

Material

Units

SF

Material Location

Room 206

HA No

15D

Material Description

12x12 Reddish Orange with

Speckles VFT-See HA 13A

17A	Black Baseboard			3rd flr classrms and weight room		Miscellaneous		None			YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Sprin	ng: No Change				-							
Comments:	<u> </u>											
2017 - Fall:	No Change				1							
Comments:	-											
2018 - Fall:	No Change				=							
Comments:	-											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
17B	Black Baseboard			Main office and rm 314	71.7	Miscellaneous		None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

18A	Black Baseboard Mastic			3rd flr. Class Rms and weight rm		Miscellaneous		None			YES	X NO
2016 - Fall	: No Change				7							
Comments												
2017 - Spr	ing: No Change											
Comments												
2017 - Fall	: No Change				1							
Comments	<u> </u>											
2018 - Fall	: No Change				+							
Comments	S:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
18B	Black Baseboard Mastic			main office		Miscellaneous		None			VES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

19	6 in. Black Baseboard			1970 Bldg. Classrms		Miscellaneous		None			YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Fall:	No Change				_							
Comments:					-							
	ng: No Change											
Comments:					-							
2018 - Fall:	No Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
20	Mastic under 6 in.Black			1970 Bldg. Classrooms		Miscellaneous		None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Baseboard

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
21A	popcorn acoustical spray on			Lunchroom		Miscellaneous		None			YES	X NO
2016 - Fall	: No Change				1							
Comments												
2017 - Spr	ing: No Change				1							
Comments												
2017 - Fall	: No Change											
Comments	:											
2018 - Fall	: No Change				-							
Comments	:											
					<u>.</u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
21B	acoustical spray on			Butler Hall, main off., teachrs lounge,2nd flr asst princ off., 2nd flr aud exit,principals off.		Surface		None			YES	X NO
2016 - Fall	: No Change]							
Comments					1							

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

21C	Acoustic Wall Tile	1500	SF	Butler hall	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
2017 - Spring Comments:	g: No Change									
2017 - Fall: N Comments:	lo Change									
2018 - Fall: N Comments:	lo Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
	22	Acoustical Spray on	3500	SF	Rm 220a,220b,220c and corridor 1970 bldg.		Surface	Yes	None	0		YES	X NO
_	2016 - Fall: N Comments:	o Change											
-	2017 - Fall: N	o Change											

Comments:

2017 - Spring: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

2018 - Fall: No Change Comments:

23	1x1 ceiling tile mastic			classrms, offices.		Miscellaneous		None			YES	X NO
2016 - Fall:	No Change				1							
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
24	Fire Door insulation (All doors abated)			throughout (no destructive sampling		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Units

Material

Quantity

Material Location

performed)

Page 14

25 Vibration cloth Basement/Boller rm, Fan rms		None	YES X NO
2016 - Fall: No Change			
Comments:			
2017 - Fall: No Change			
Comments:			
2017 - Spring: No Change			
Comments:			
2018 - Fall: No Change			
Comments:			
	Material Friable Category	Damage Damage Type Quantity	Damage Units Change in Assessment Category

Type

Material

Surface

No

Category

Friable

Damage

Type

None

Damage

Quantity

0

Damage

Units

Material Location

Basement/Boiler rm, Fan

240

HA No

26

Material Description

Drywall

2016 - Fall: No Change

Material

Quantity

Material

Units

SF

Rm 116

YES

Change in Assessment Category

X NO

27	Lab table tops	900	SF	Rms. 214, 215, 313, 314		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:	•											
2017 - Fall:	No Change											
Comments:												
	g: No Change											
Comments:					-							
2018 - Fall:	No Change]							
Comments:					_							
HA No	Material Description	Material	Material	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Categor

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30A	9x9 light biege, flr. Tile	9881	SF	3rd Flr.corrs,rm303,307- 309, 312, 313,2nd lr.corr. Store rms.1st flr.shop str rm,bsmnt stor rm/bthrm, grl gym, vault in main office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

30B	9x9 mauve flr tile	3000	SF	3rd flr. Corridor, girls gym corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	J											
2017 - Fall: N	lo Change				-							
Comments:	J											
2017 - Spring	ı: No Change				-							
Comments:												
2018 - Fall: N	lo Change				-							
Comments:	<u> </u>											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

Damage

Quantity

Damage

Units

2016 - Fall: I	No Change		
Comments:			
2017 - Sprin	g: No Change		
Comments:			
2017 - Fall: I	No Change		
Comments:			
2018 - Fall: I	No Change		
Comments:			
		•	

1525

SF

rm 300

Material

Quantity

Material

Units

Material Location

HA No

30C

Material Description

9x9 tan VFT

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
31A	9x9 light biege flr tile mastic	9881	SF	3rd Flr.corrs, rm 303, 307-309, 312,313,315,2 nd Flr.corr store rms.1st flr.shop store rm.Lndry, grl gym		Miscellaneous	No	None	0		YES	х мо

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31B	Mastic under 9x9 Marker	3000	SF	3rd flr. Corridor, girls gym corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

2016 - Fall:	No Change										
Comments											
	ng: No Change										
Comments	:										
2017 - Fall:	No Change										
Comments	•										
2018 - Fall:	No Change										
Comments	:										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
<u> </u>			+	ļ		-		+	+	+	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Damage

Type

None

None

Damage

Quantity

0

Damage

Units

Material

Quantity

1525

Material

Units

SF

Material Location

boys gym, girls gym

rm 300,312

HA No

31C

32

Material Description

9x9 tan flr tile Mastic

2x2 ceiling tiles

Change in Assessment Category

X NO

X NO

YES

YES

33A	Mastic green carpet			Butler Hall		Miscellaneous		None			YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:					_							
2018 - Fall: I	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
33B	Mastic Green carpet			rm 111, band rm		Miscellaneous		None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
33C	Mastic Dk Blue Carpet	500	SF	rm 304, 306, 308		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprii	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:	·	<u> </u>										
2018 - Fall:	No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34A	9x9 mauve VFT	1055	SF	1970 Bldg. 2nd flr. Corridor NE end		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	·
<u> </u>	

Comments:

34B	9x9 lt. Biege VFT	1600	SF	1970 bldg, 2nd flr corridor NE end, café locker rm.	Miscellaneous	No	Loc	200	YES	X NO
2016 - Fall: N	No Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2017 - Spring	g: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:										

Type

Material

Category

Material Location

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35A	9x9 mauve VFT mastic	1055	SF	1970 bldg, 2nd flr corridor NE end		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

2016 - Fall:	No Changa				\neg						
Comments:											
2017 - Fall:	No Change										
Comments:											
2017 - Sprir	ng: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Damage

Type

Loc

None

Damage

Quantity

200

Damage

Units

Material

Quantity

1400

Material

Units

SF

Material Location

1970 bldg, 2nd flr corridor

NE end, café locker rm.

1970 bldg. Throughout

addition

HA No

35B

36

Material Description

9x9 lt. Biege VFT Mastic

1x1 ceiling tile

Change in Assessment Category

X NO

X NO

YES

YES

38	Drywall compound	50	SF	rm 116		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: I	No Change				1							
Comments:	go]							
2017 - Fall: I	No Change				1							
Comments:	<u> </u>]							
2017 - Sprin	g: No Change											
Comments:					-							
2018 - Fall: I	No Change]							
Comments:					_							
					<u>.</u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
20	interior window gloze			rm 223 1970 bldg		Missellaneous					Dvro I	V No

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

39

2016 - Fall: No Change

Material Description

interior window glaze

Material

Quantity

Material

Units

Material Location

abated

YES

X NO

40	interior window caulking			1970 bldg. Rm 223 - abated		Miscellaneous					YES	X NO
2016 - Fall: N	No Change											
Comments:	10 0.1.a.1.go											
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
41	2x4 ceiling tile			rm 223 1970 bldg.		Miscellaneous		None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Page 25

42	lab topsNew lab tops	35	SF	1970 addition store rm., rm 314, 215,216 - Removed		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	No Change				1						
Comments:											
2017 - Fall: N	No Change				-						
Comments:]						
	g: No Change										
Comments:											
2018 - Fall: N	No Change										
Comments:					_						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42A	Lab tops	35	SF	1970 addition room 314,215,216		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

45	Drywall			1970 bldg. Classrooms		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change]							
Comments:] -							
2017 - Fall: N	lo Change											
Comments:					-							
2017 - Spring: No Change												
Comments:					1							
2018 - Fall: N	lo Change				Ī							
Comments:					_							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
46	Drywall compound	200	SF	1970 bldg. Classrooms		Miscellaneous	Yes	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

2016 - Fall: No Change

Material Description

Material

Quantity

Material

Units

47	1x1 acoustical ceiling tile (Removed 2011)			court, old rifle range in basement		Miscellaneous					YES	X NO
2016 - Fall:	No Change				7							
Comments:	.											
2017 - Sprin	ng: No Change				_							
Comments:]							
2017 - Fall:	No Change											
Comments:					-							
2018 - Fall:	No Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
48	1x1 ceiling tile glue dots			court, old rifle range in		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2018 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Units

Material Quantity Material Location

basement

49	9x9 tan floor tile (Abated)			basement rifle room and hallways		Miscellaneous		None			YES	X NO
2016 - Fall:	No Change				1							
Comments:	. to onango											
2017 - Sprin	g: No Change				-							
Comments:	g. 110 Ghango											
2017 - Fall:	No Change				_							
Comments:	<u> </u>]							
2018 - Fall:	No Change				_							
Comments:	<u> </u>]							
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
50	9x9 tan floor tile mastic			basement rifle room and		Miscellaneous		None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No

Material Description

(Abated)

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material

Quantity

Material

Units

Material Location

hallways

Change in Assessment Category

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
51	blue linoleum	2300	SF	rooms 109, 215, 216, 314, 316, 320		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: No Change												

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
52	2x2 ceiling tile, worm pattern	1400	SF	Rms. 215,216 (dropped ceiling)		Miscellaneous	Yes	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

60	12" x 12" dark gray and tan checked VFT and mastic	2000	SF	3rd Floor Hallway	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	Gray Carpet Mastic	1248	SF	Rm. 310		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

62	Blue Carpet Mastic	3040	SF	Rm. 212, 111		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change										
Comments:											
2017 - Spring	j: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	0	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
63		Blue Designed Carpet Mastic	12000	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
	2016 - Fall: No Change Comments:												
2017	2017 - Fall: No Change												

Comments:

2017 - Fall: No Change

Comments:

2018 - Fall: No Change

Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	12" x 12" Tan Multicolor VFT	1600	SF	Rm. 111, 212		Miscellaneous	No	None	0		YES X NO
2010 = 11 11		1									

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
	·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
65	12" x 12" Tan Multicolor VFT Mastic	1600	SF	Rm. 111, 212		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

66	12" x 12" Yellow/Brown Checkerboard Pattern VFT	5000	SF	Library	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:	_									
2017 - Spring	g: No Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2018 - Fall: N	lo Change	•								
Comments:										

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	12" x 12" Yellow/Brown Checkerboard Pattern VFT Mastic	5000	SF	Library		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

68	6" Blue Baseboard	2500	LF	Rm. 212, 111, Library, Throughout Basement		Miscellaneous	No	None	0	YES	X NO
2016 - Fal	l: No Change]						
Comments	S:]						
2017 - Fal	l: No Change]						
Comments	S:				1						
2017 - Spr	ing: No Change										
Comments	S:										
2018 - Fal	l: No Change										
Comments	S:				_						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	6" Blue Baseboard Mastic	2500	LF	Rm. 212, 111, Library, Throughout Basement		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

Α	Joints and fiberglass and acm runs	150	FITTING	Boiler rm, Basement, Pipe chases throughout		TSI	Yes	None	0	YES	X NO
					İ						
2016 - Fall: N	lo Change										
Comments:	comments:										
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	ı: No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:											
					•						

Type

Asbestos

Type

Material

Material

Category

Category

Friable

Friable

Damage

Damage

Type

Type

Damage

Quantity

Damage

Quantity

		-			 • .			-	
В	Boiler Gaskets	60	LF	Boilers	TSI	No	None	0	
2016 - Fall: N	o Change								
Comments:									
2017 - Spring	: No Change								
Comments:									
2017 - Fall: N	o Change								
Comments:									

2018 - Fall: No Change Comments:

HA No

HA No

Α

Material Description

Material Description

Material

Material

Units

Units

Material

Quantity

Material

Quantity

Material Location

Material Location

Change in Assessment Category

Change in Assessment Category

YES

X NO

Damage

Damage

Units

Units

С	Boiler Gaskets	15	LF	Boilers		TSI	No	None	0	YES	X NO
2016 - Fall: No Change Comments:											
2017 - Spring: No Change Comments:											
2017 - Fall: No Change Comments:											
2018 - Fall: No Change											

Material

Category

Friable

Damage

Type

Asbestos

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Boiler tank insulation	500	SF	boilers		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

E	Incenerator insul partially abated			Boiler rm.		TSI					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	io onango											
2047 Fall N	la Change											
2017 - Fall: N Comments:	io Change											
2017 - Spring	: No Change											
Comments:												
2018 - Fall: No Change												
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
F	Fire BrickINCINERATOR			Incinerator		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: John F Kennedy High School
Date: 1/10/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.