Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Kenwood Academy High School 46361 Building ID: 1710 School: **Oracle Unit:** Address: 5015 S. Blackstone Region: Mail Room: Asbestos Surveyor: Collins, Michael X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/10/2019 Email Address: mdcollins5@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type Building. C - Rooms 2nd YES X NO Floor Boy's Gym, 1st 15 Tectum Tile 18200 SF Miscellaneous No None 0 Floor Girl's Gym. Building. A - Room 127 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

16	Transite Table Tops	500	SF	Building B - Rooms 315, 301, 303, 325, 310		Miscellaneous	No	None	0	YES	X NO
0040 = 11 11					1						
2016 - Fall: N	lo Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:	-										
2018 - Spring	ı: No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:	<u> </u>										
					1						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	Transite Counter Tops	500	SF	Building B Rooms 305, 315, 315 Storage, 301, 303, 303 Storage, 325, 325 Office, 306, 310		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
18	6" Black Baseboard			District Superintendent's Office							YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Sprir	ng: No Change				<u> </u>							
Comments:												
2017 - Fall:	No Change				<u> </u>							
Comments:	<u> </u>											
2018 - Sprir	ng : No Change				<u> </u>							
Comments:												
2018 - Fall:	No Change				<u> </u>							
Comments:												
		T	T		1	1		1				

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	6" Black Baseboard Mastic			District Superintendent's Office							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
20	4" Beige Baseboard			Building D							YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	: No Change				-							
Comments:												
2018 - Spring	ı : No Change				-							
Comments:	<u> </u>											
2018 - Fall: N	lo Change				\dashv							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20.1	4" Brown Basebaord			Building D - Security Office							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Ca	ategory
21	4" Beige Baseboard Mastic			Building D							YES X N	0
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change				_							
Comments:												
2017 - Spring	: No Change											
Comments:	•											
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change				-							
Comments:	J											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21.1	4" Brown Baseboard Mastic			Building D - Security Office							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 5

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	nent Category
22	Roofing Material - Not AHERA			Roof, Building A, B, C, D							YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change				-							
Comments:												
2018 - Spring	j : No Change				-							
Comments:												
2018 - Fall: N	lo Change				-							
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Roof Flashing - Not AHERA			Roof Building A, B, C, D							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
24	Interior Brick			Building A,B,C,D Throughout							YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	•											
2017 - Spring	: No Change				1							
Comments:												
2017 - Fall: N	lo Change				1							
Comments:												
2018 - Spring	: No Change				1							
Comments:												
2018 - Fall: N	lo Change				1							
Comments:	<u> </u>											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Interior Brick Mortar			Building A,B,C,D - Throughout							YES X NO
0040 5 11 11	01	1									

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

26	Exterior Brick - Not AHERA	Building A,B,C,D Exteriors				YES	X NO
			1				
2016 - Fall: N	o Change						
Comments:							
2017 - Spring	: No Change						
Comments:			1				
			1				
2017 - Fall: N	o Change						
Comments:							
2018 - Spring	: No Change						
Comments:							
2018 - Fall: N	o Change						
Comments:							
]				

Type

Material

Category

Damage Quantity Damage

Units

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Exterior Brick Mortar-Not AHERA			Building A,B,C,D Exteriors							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Page 8

28	Maroon Carpet Mastic			Building B - Principal's Office, Guidence Counselor's Office, Hall							YES	X NO
2016 - Fall: N	la Chango				1							
	NO Criarige				-							
Comments:					-							
2017 - Spring	g: No Change				_							
Comments:					1							
2017 - Fall: N	No Change				1							
Comments:	Ţ ,				-							
2018 - Spring	g : No Change				1							
Comments:					1							
2018 - Fall: N	No Change											
Comments:	Ţ.											
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Asbestos

Type

Material

Category

Category

Friable

Damage

Type

Туре

Damage

Quantity

Quantity

Units

YES

X NO

Damage

Units

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Quantity

Units

HA No

30

Material Description

Blue Carpet Mastic

Material

Units

Material

Quantity

Material Location

Building B - Main Office,

1st & 2nd Floor Media

Centers

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
31	1' x 1' Ceiling Tile			Building D							YES	X NO
2016 - Fall: N	No Change											
Comments:	J											
2017 - Fall: N	No Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
				1				_	1		т	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31.1	1' x 1' Ceiling Tile Mastic			Building D							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

32	2' x 4' White Worm Pinhole Ceiling Tile	Science Rooms (321, 324)				YES	X NO
2016 - Fall: N	o Change		1				
Comments:]					
2017 - Spring	: No Change		1				
Comments:]				
2017 - Fall: N	o Change		1				
Comments:							
2018 - Spring	: No Change		1				
Comments:	•						
2018 - Fall: N	o Change		1				
Comments:	~						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	2' x 4' White Worm Pinhole Ceiling Tile			Building B - Rooms 323, 316, 221, 220, 219, 218, and 123							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
34	Blue Baseboard			Science Rooms (321, 324)							YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change				1							
Comments:	, J											
2017 - Fall: N	lo Change				1							
Comments:	Ü											
2018 - Spring	g : No Change											
Comments:	,											
2018 - Fall: N	lo Change											
Comments:]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Drywall			Science Room (321, 324)							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
36	Drywall Joint Compound			Science Rooms (321, 324)							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					_							
2018 - Spring	ј : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Light Blue w/Dark Blue & White Streaks Linoleum			Science Rooms (321, 324)							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
37.1	Lt Blue w/Dk Blue & White Streaks Linoleum Mastic			Science Rooms (321, 324)							YES	X NO
2016 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:					_							
2018 - Fall: N	o Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Lab Table Tops	100	SF	Building B Rooms 305, 315, 301, 303, 303 Storage, 306, 310, 321 & 324		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
39	Lab Hood	20	SF	Science Rooms (324, 321)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change				-							
Comments:												
2018 - Sprir	ng : No Change				-							
Comments:	-											
2018 - Fall:	No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Plaster Ceiling	90000	SF	Throughout Bathrooms		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
41	Drywall	2000	SF	Throughout		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprin	ng : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:		<u> </u>		·								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Drywall Joint Compound	2000	SF	Throughout		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
43	Transite Ceiling	10	SF	Building D Stairwell 13		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments:	v											
2017 - Sprir Comments:	ng: No Change											
2047 Falls	No Change				-							

2017 - Fall: No Change Comments:

2018 - Spring : No Change Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	Transite Walls, Chalkboard	800	SF	Building D Lunchroom,		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
45	Vibration Gasket	100	LF	Throughout Mechanical Rooms, MDF Room 123		TSI	Yes	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	Lab Hood	50	SF	Building B - Rooms 310, 305, and 315		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
47	Blue Baseboard Mastic			Building B - Science Rooms (324, 321)							YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
1												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	12" x 12" Cream w/Brown Specks Floor Tile	1500	SF	Building A Rooms 227 & 234, Building B		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
49	12" x 12" Cream w/Brown Specks Floor Tile Mastic	1500	SF	Building A Rooms 227 & 234, Building B		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments	:											
2017 - Spri	ng: No Change											
Comments	:											
2017 - Fall:	: No Change											
Comments	:											
2018 - Spri	ng : No Change											
Comments	:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	12" x 12" White w/Reddish Specks Floor Tile			Building A Room 134		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
51	12" x 12" White w/Reddish Specks Floor Tile Mastic			Building A Room 134		Miscellaneous					YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	Sink Coating	43	SF	Building A Rooms 234 & 225		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
53	12" x 12" Gray w/Gray Specks Floor Tile	900	SF	Building B Rooms 121		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	12" x 12" Gray w/Gray Specks Floor Tile Mastic	900	SF	Building B Rooms 121		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
55	Gray Carpet Mastic			Building B 2nd Floor Faculty Commons		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change]							
Comments:					1							
2017 - Spring	g: No Change				=							
Comments:												
2017 - Fall: N	lo Change				_							
Comments:					_							
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:					-							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	12x12 Blue Floor Tile	1700	SF	ROOMS 321, 324		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
57	12x12 blue floor tile mastic	1700	SF	rm 321, 324		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	12x12 white ft w/ tan mottle	950	SF	rm 128, 128A		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 24

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	Mastic for 12x12 white floor tile w/ tan mottle	950	SF	rm 128, 128A		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:	
Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change	
2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2016 - Fall: No Change
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Spring: No Change
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Fall: No Change
Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Fall: No Change	2019 Caring : No Change
2018 - Fall: No Change	1 0 0
	Comments:
Comments:	2018 - Fall: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	2x4 Ceiling tile w/ divots & dots	2100	SF	rm 128, 128A, 234		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
61	12x12 Brown Mottle floor tile			rm 134 H		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	Mastic for 12x12 Brown mottle floor tile			rm 134 H		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	12x12 Cream floor tile w/ brown specks	1200	SF	rm 234		Miscellaneous	No	None	0		YES X NO
					-						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	Mastic for 12x12 Cream floor tile w/ brown specks	1200	SF	rm 234		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
65	12"x12" Peach VFT	500	SF	Faculty Commons		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	J											
2018 - Spring	g : No Change											
Comments:	<i>y</i>											
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	12"x12" Peach VFT Mastic	500	SF	Faculty Commons		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	12" x 12" Bright White Floor Tile	15100	SF	1st Floor Hallways		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68	Mastic Associated w/ 12" x 12" Bright White Floor Tile	1500	SF	1st Floor Hallways		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	12" x 12" Blue Floor Tile	9900	SF	1st Floor Hallways, Rooms 106, 107, 108, 109, 110, 116, 117, 118, 119, 120, and 126		Miscellaneous	No	None	0		YES X NO

2010 Falls No Change	
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70	Mastic Associated w/ 12" x 12" Blue Floor Tile	9900	SF	1st Floor Hallways, Rooms 106, 107, 108, 109, 110, 116, 117, 118, 119, 120, and 126		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

	material Description	Quantity	Units		Type	Category		Туре	Quantity	Units	onango my toosot	omoni Galogory
71	12" x 12" Yellowish Floor Tile	800	SF	Main Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:					_							
2018 - Spring	g : No Change											
Comments:					_							
2018 - Fall: N	No Change											
Comments:												

Material

Friable

Damage

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72	Mastic Associated w/ 12" x 12" Yellowish Floor Tile	800	SF	Main Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
73	12" x 12" White Floor Tile	2280	SF	2nd Floor Lunchroom, Kitchen Faculty, Room 127		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
74	Mastic Associated w/ 12" x 12" White Floor Tile	2280	SF	2nd Floor Lunchroom, Kitchen Faculty, Room 127		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
75	12 x 12" Light Blue Floor Tile	9000	SF	Lunchroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
76	Mastic Associated w/ 12 x 12" Light Blue Floor Tile	9000	SF	Lunchroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
77	Blue Carpet Mastic	700	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change											
Comments	<u> </u>											
2017 - Spri	ng: No Change											
Comments	:											
2017 - Fall	: No Change											
Comments	:											
2018 - Fall	: No Change											
Comments	:											
2018 - Spri	ing : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
78	12" x 12" Blue, White, and Beige Floor Tile	2000	SF	Rooms 133 and 134		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
79	Mastic Associated w/ 12" x 12" Blue, White, and Beige Floor Tile	2000	SF	Rooms 133 and 134		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change						•				•	•	

2016 - Fall: No Change	
Comments:	
2017 7 11 11 21	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
80	Carpet Tile Mastic	3600	SF	Room 122 and Main Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 35

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-1	2' x 4' Acoustical Ceiling Tiles	9400	SF	Throughout Building A - Offices, Hallways, Classrooms, 325 & 325 Office		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 46361

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-3	Spray-on Fireproofing	10610	SF	Bldg.D-Rm224,223, Lunchroom,Kitchen,Halls, Boy's/GirlsToliet,Bldg C- East Mech.Rm,237,238, 266, Bldg.A Fan Rm		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		
2018 - Fall: No Change		
Comments:	 	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-6	12" x 12" Black Floor Tile	2160	SF	Building B - 1st Floor Passageways		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
A-6.1	12" x 12" Beige Floor Tile	1900	SF	Building D - District Superintendent's Office & Faculty Service Line		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	· No Change											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2040 Fall Na Obana	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-6.2	12" x 12" Blue Floor Tile	220	SF	Building B - Room 123/MDF Room 121/Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
A-6.3	12" x 12" Beige w/Brown Specks Floor Tile	1710	SF	Building D-Engineer's Office, Rm. 227		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
	·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-6.4	12" x 12" Tan Floor Tile	3885	SF	Building A - Corridors, Rooms 232 and 233, Passageways 1,2,3,4		Miscellaneous	No	None	0		YES X NO

016 - Fall: No Change	
Comments:	
017 - Fall: No Change	
Comments:	
017 - Spring: No Change	
Comments:	
018 - Fall: No Change	
Comments:	
018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-7	12" x 12" Black Floor Tile Mastic	2160	SF	Building B - Passage ways 1 & 2		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2010 0 1 11 01	
2018 - Spring : No Change	
Comments:	

HA N	0	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-7.	1	12" x 12" Beige Floor Tile Mastic	1900	SF	Building D-District Superintendent's Office & Faculty Service Line		Miscellaneous	No	None	0		YES X NO

Page 40

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
A-7.2	12" x 12" Blue Floor Tile Mastic			Building B - Room 121/MDF Room 121/Office							YES	X NO
2016 - Fall: N Comments:	lo Change											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-7.3	12" x 12" Beige w/ Brown Specks Floor Tile Mastic	1710	SF	Building D-Engineer's Office, Rm. 227		Miscellaneous	No	None	0		YES X NO

016 - Fall: No Change	
Comments:	
017 - Fall: No Change	
Comments:	
017 - Spring: No Change	
Comments:	
018 - Fall: No Change	
Comments:	
018 - Spring : No Change	
Comments:	

A-7.4	12" x 12" Tan Floor Tile Mastic	3885	SF	Building A - Halls, and Rooms 232 and 233		Miscellaneous	No	None	0	YES	X NO
204C Fall N	a Change				1						
2016 - Fall: N	o Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:	<u> </u>										
					1						
2018 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											
Commonto					1						
L					1						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-8	9" x 9" Beige Floor Tile Mastic	21000	SF	Buildings D - Hall, A4 Building - Throughout Classrooms, Labs, Offices, Throughout Bldg. B Classrooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-8.1	9" x 9" Brown Floor Tile Mastic	22600	SF	Hallways Throughout Facility, Building A - Room 225		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-9	9" x 9" Beige Floor Tile	21000	SF	Building D-Hall, A4 Building-Throughout FacilityClassrooms, Offices,Labs,Throughout Bldg.B Classrooms		Miscellaneous	No	None	0		YES X NO

	3
<u>r</u>	
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-9.1	9" x 9" Brown Floor Tile	21000	SF	Hallways Throughout Facility, Building A - Room 225, Room 226		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

A-C	Pipe Insulation			Building A - Penthouse		TSI		None			YES	X NO
2016 - Fal	I: No Change				1							
Comment												
2017 - Spring: No Change												
Comment	S:											
2017 - Fal	I: No Change											
Comment	S:											
2018 - Sp	ring : No Change											
Comment	S:											
	I: No Change											
Comment	S:											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
A-E	Pipe Insulation			Building A - Pipe chases		TSI		None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

2016 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B(A-2)	Tank Insulation	300	SF	Building B - 4th Floor Boiler Room		TSI	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B(A-3)	Cementitious Insulation (Joint)	250	SF	Building B - 4th Floor Boiler Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
B-1	2' x 4' Acoustical Ceiling Tile w/Pinholes	2250	SF	RM 234, 315, 325		Miscellaneous	Yes	Dist	208		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	•											
2017 - Spring	g: No Change				1							
Comments:	•											
2017 - Fall: N	lo Change				1							
Comments:												
2018 - Spring	g : No Change				1							
Comments:	<u> </u>				1							
2018 - Fall: N	lo Change				-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B-1.1	2' x 4' Acoustical Ceiling Tile/White Worm Pinhole			Building A - Hall, Rooms 232, 233, 234, 237 & 225							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

Comments:

		Quantity	Units		Type	Category		Туре	Quantity	Units		
B-D	Pipe Insulation	400	SF	Building B - Boiler Room		TSI	Yes	None	0		X YES	NO
2016 - Fall: A	bated ater pumps for chillers											
2017 - Spring	յ։ No Change											
Comments:												
2017 - Fall: A	bated											
Comments:Chilled water pumps and piping too and from pumps were abated and re -insulated												

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Туре	Category		Type	Quantity	Units	
С-В	Cemetitious Insulation (Joint)			Building C - Roof Drains		TSI		None			YES X NO

Material

Material Description

2018 - Spring : No Change

2018 - Fall: No Change

Comments:

Comments:

Material

Material Location

HA No

C-C	Pipe Insulation			Building C - Throughout Building and Crawlspaces		TSI					YES	X NO
0040 F.U	I No Observe				1							
	l: No Change											
Comments	S:											
2017 - Fal	l: No Change											
Comments												
	-				1							
2017 - Spr	ing: No Change				1							
Comments					1							
	-				1							
2018 - Fal	I: No Change				1							
Comments	S:				1							
					1							
2018 - Spr	ing : No Change				1							
Comments					1							
					1							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

TSI

Friable

Damage

Туре

Туре

None

Damage

Quantity

Quantity

Units

YES

X NO

Damage

Units

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Quantity

Units

HA No

C-D

Material Description

Cementitious Insulation on

Pipe Joint

Material

Units

Material

Quantity

Material Location

Throughout Building C

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment	Category
C-E	Tank Insulation	245	SF	Building C - 3rd Floor Mechanical Room		TSI	Yes	None	0		YES	NO
2016 - Fall: No Change Comments:												

2016 Falls No Change
2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CK-DC	Joint Insulation	500	LF	Building D - Equipment Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
CK-DE	Aircell Pipe Insulation			Building D - Cafeteria Pipe Chase		TSI		None			YES	X NO
0040 5-11	NI- Ol-				7							
2016 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall:	No Change				+							
Comments:												
2018 - Sprin	g : No Change				-							
Comments:	<u> </u>											
2018 - Fall:	No Change				+							
Comments:	y -				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CK-DF	Lag & Joint Cement	50	LF	Building D - Mechanical Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CK-DG	Tank Insulation	300	SF	Building D - Mechanical Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E-B	Fiberglass Pipe Insulation Hard Elbows	896	LF	Buildings A, B, C, D		TSI	Yes	Loc	15		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
E-C	Tank Insulation	400	SF	Building D - 1st Floor Mechanical Room		TSI	Yes	Loc	5		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												

Material

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Р	Incinerator Stack Insulation			Building D - Mechanical Room		TSI		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

2018 - Fall: No Change

Comments:

Material Description

Material

Material

Material Location

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Kenwood Academy High School
Date:	1/11/0219
the Asbest	notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of tos Management Plan is available at each school during school hours by appointment. to review the Asbestos Management Plan must be made at least 24 hours in advance.
The last in	se be advised that CPS conducts asbestos inspections of all Schools every three years. espection was completed in 2016. surveillances are conducted every six months.
CHECK O	<u>NE</u>
A c	opy of this notice was sent home in each child's backpack.
A c	opy of this notice was printed in the school's newsletter and sent home with each child
A c	opy of this notice was printed in the school's calendar and sent home with each child
Oth	ner.
	Y OF THIS NOTICE MUST BE PLACED IN THE HOOL'S ASBESTOS MANAGEMENT PLAN.