Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Dr Martin Luther King Jr College Prep HS 46371 Building ID: 1760 School: **Oracle Unit:** Address: 4445 S. Drexel Region: Mail Room: Asbestos Surveyor: Johnson, Lance X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/10/2019 Email Address: ljohnson207@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type Wood Fire Doors without YES 100 SF X NO **Throughout School** Miscellaneous No None 0 Labels 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
4A	Mastic for Carpeting			Office and Library, Auditorium							YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	Wood Fire Doors with Labels	220	SF	2nd and 3rd Floor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
6	24" x 24" Blue Floor Tile			Lunch and Dining Room		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
	T						1	_	_		1 01 1 1	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6A	24" x 24" Orange Floor Tile			Lunch and Dining Room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	ment Category
7	12" x 12" Brown Floor Tile	8900	SF	1st floor corridor		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change]								
Comments:													
2017 - Fall: N	lo Change				1								
Comments:	Ţ												
2017 - Spring	g: No Change				1								
Comments:	, J												
2018 - Fall: N	lo Change												
Comments:	go				Ī								
2018 - Spring	j : No Change				_								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8	Tectum	2600	SF	Auditorium and Band Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
10	1' x 1' Glue on Ceiling Tile			Auditorium							YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:	-											
r								1			1	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10A	Mastic for 1' x 1' Ceiling Tile (HA 10)			Auditorium							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
11	2' x 5' Ceiling Tile			Throughout School							YES	X NO
2016 - Fall:	No Change											
Comments												
2017 - Spri	ng: No Change											
Comments	:											
2017 - Fall:	No Change											
Comments	:											
2018 - Spri	ng : No Change											
Comments	:											
2018 - Fall:	No Change											
Comments	:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11A	2' x 5' Lay-in Ceiling Tile with Small Fissure			Throughout School							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

12	Hard-coat Plaster	Washrooms, Storage Rooms, and Classroom Entrance Ways				YES	X NO
2016 - Fall	: No Change		1				
			4				
Comments	:						
	: No Change						
Comments	:						
			1				
2017 - Spri	ng: No Change						
Comments							
2018 - Fall	: No Change						
Comments	:						
2018 - Spri	ng : No Change						
Comments							
			1				

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12" x 12" Brown Granite Looking Floor Tile-MASTIC	8900	SF	1st floor corridors		Miscellaneous	No	None	0		YES X NO
					1						_

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
·

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
14	24" x 24" Floor Tile Mastic			Lunch and Dining Rooms on HA 6 & 6A							YES	X NO
2016 - Fall: N	lo Change]							
Comments:	J											
2017 - Fall: N	lo Change				-							
Comments:												
2017 - Spring	g: No Change											
Comments:					1							
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:]							
					J							
	T			1	1		1	1	1	1		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Grey Covebase			Throughout							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 8

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
16	Mastic for Grey Covebase			Throughout School							YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change				1							
Comments:	V											
2017 - Spring	g: No Change				1							
Comments:	,											
2018 - Fall: N	lo Change											
Comments:	Ţ.											
2018 - Spring	g : No Change											
Comments:	,											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	Cinder Block			Throughout School							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 9

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
18	Cinder Block Mortar			Throughout						YES	X NO
2016 - Fall: N	lo Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:	<u> </u>										
2017 - Spring	ı: No Change										
Comments:	J. NO Change										
2018 - Fall: N	lo Change										
Comments:											
2018 - Spring	ı : No Change										
Comments:	1. 110 Onlango										

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	Window Caulk Interior	80000	LF	Throughout School		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
20	Window Caulk - Exterior- Not AHERA			Exterior of School							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12" x 12" Off-White Floor Tile w/Brn & Wht Streaks	44656	SF	2nd & 3rd floor corridors and all stairway platforms, Rms. 116, 117		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

22	Mastic for 12" x 12" Off- white Floor Tile (HA 21)	2nd & 3rd floor co and all stairway platforms, Rms.				YES	X NO
0040	Na Ohanana	<u> </u>					
2016 - Fall: I	No Change						
Comments:							
2017 - Fall: I	No Change						
Comments:	-						
2017 - Sprin	g: No Change						
Comments:							
2018 - Fall: I	No Change						
Comments:	<u> </u>						
2018 - Sprin	g : No Change						
Comments:	<u> </u>						
- Commonwor							
L							

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Black Mastic for Cove Base (HA 24)			Throughout School							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
24	Black Covebase			Throughout School						YES	X NO
2016 - Fall: N	lo Change										
Comments:					_						
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change				-						
Comments:	<u> </u>										
2018 - Fall: N	lo Change				1						
Comments:	Ŭ										
2018 - Spring	g : No Change				_						
Comments:	,										
	·			·	_						
_											

Material

Friable

Damage

Damage

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Grout for 1" x 1" Ceramic Tile (HA 26)			Restrooms							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
26	1" x 1" Dark Grey Ceramic Tile			Restrooms							YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>				1							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:					_							
2018 - Spring	j : No Change											
Comments:					_							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Mastic for 1" x 1" Ceramic Tile (HA 25)			Restrooms							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
28	Ceramic Blocks			Base of Walls							YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
2018 - Sprir	ng : No Change											
Comments:	-											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Linoleum over Tan Floor Tile			Room #327							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
30	Mastic for Linoleum (HA 29)			Room 327						YES	X NO
2016 - Fall: N	o Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:	_										
2018 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:											

Material

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12" x 12" Tan Floor Tile w/ Grey Speckles	936	SF	Hall by Rm. 302		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
32	Mastic for 12" x 12" Tan Floor Tile (HA 31)	936	SF	Hall by Room 302		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
2017 - Fall: N	lo Change											
2017 - Spring Comments:	g: No Change											
2018 - Fall: N	lo Change											
	g : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	6" Black Cove Base			Auditorium							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessn	nent Category
34	Mastic for 6" Cove Base (HA 33)			Auditorium							YES	X NO
2016 - Fall: N	o Change				7							
Comments:												
2017 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	: No Change											
Comments:					_							
2018 - Fall: N	o Change											
Comments:					_							
2018 - Spring	: No Change]							
Comments:					_							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Mastic for Stair (Skid)			Stairs							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
36	4" Black Cove Base			Library							YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
r			1							,		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Mastic for 4" Black Cove Base (HA 036)			Library							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	ent Category
38	Sheet Rock			Between Rooms 220 & 222							YES	X NO
2016 - Fall: N	lo Change]							
Comments:					1							
2017 - Fall: N	lo Change				_							
Comments:												
2017 - Spring	j: No Change				_							
Comments:												
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	ı : No Change											
Comments:					-							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Joint Compound for Sheet Rock			Between Rooms 220 & 222							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
40	6" x 6" Ceramic Tile	600	SF	Food Prep in Kitchen and Dining Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Grout for Ceramic Tile (HA 40)	600	SF	Food Prep in Kitchen and Dining Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
42	Grout for 6" x 12" White Ceramic Block (HA 42A)			Kitchen		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	ј : No Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42A	6" x 12" White Ceramic Block			Kitchen		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 22

HA No	Material Description	Material	Material Units	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage Units	Change in Asse	essment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
43	Window Glazing (exterior) - NON AHERA			Exterior		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:	<u> </u>											
2017 - Fall:	No Change											
Comments:	<u> </u>											
2017 - Sprir	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
2018 - Sprir	ng : No Change											
Comments:	-											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43A	Transite	350	SF	in Hood Rm 350, Rm. 230, 232, 346		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

44 In x 1° Ceramic Tile - White will ack Speckles Pool Area In x 1° Ceramic Tile - White will ack Speckles X No In x 10° Ceramic Tile - White will ack Speckles X No 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Spring : No Change Comments:	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring: No Change	44				Pool Area							YES	X NO
Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring: No Change	2016 - Fall: N	lo Change				1							
Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change		V											
2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	2017 - Fall: N	lo Change											
Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	Comments:												
2018 - Fall: No Change Comments: 2018 - Spring : No Change	2017 - Spring	g: No Change											
Comments: 2018 - Spring : No Change	Comments:												
2018 - Spring : No Change	2018 - Fall: N	lo Change											
	Comments:												
Comments:	2018 - Spring	g : No Change											
	Comments:												
						J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Grout for 1"x1" Ceramic Tile (HA 44)			Pool Area							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	ent Category
46	Mastic (Brown) for 1"x1" Ceramic Tile (HA 44)			Pool Area							YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	•				1							
2017 - Fall: N	lo Change				_							
Comments:]							
2017 - Spring	j: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
					_							

HAI	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47		1" x 2" White Ceramic Tile			Basement Shower Area							YES X NO
201	6 Fall: N	o Chango				1						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
48	Grout for 1" x 2" White Ceramic Tile (HA 47)			Basement Shower Area							YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:	V											
2017 - Spring	g: No Change											
Comments:	-											
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
					_							
r	T			1	1				1	1		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	Mastic for 1" x 2" White Ceramic Tile (HA 47)			Basement Shower Area							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
50	Stage Light Wiring (not Accessible)			Stage		Miscellaneous		None			YES	X NO
2016 - Fall: I	No Change											
Comments:	<u> </u>											
2017 - Fall: I	No Change											
Comments:	<u> </u>											
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:	-											
2018 - Sprin	g : No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	Fittings			in Sealed Pipe Chases (not Accessible)		TSI		Unknown			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	12" X 12" Lt. Beige Floor Tile	55400	SF	Rooms 111, 111A, 110, 107, 116A, 117A, 105, 106, 108 and 2nd & 3rd Floor Classrooms & Teacher's Offices, 102		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	12" X 12" Lt. Beige Floor Tile-MASTIC	55400	SF	Rooms 111, 111A, 110, 107, 116A, 117A, 105, 106, 108 and 2nd & 3rd Floor Classrooms & Teacher's Offices, 102		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
OOAO Falli Na Obaa sa
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	12" X 12" Gray w/White Specks Floor Tile	3200	SF	Basement Corridor, Rooms 012, 013, 014, 016		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	12" X 12" Gray w/White Specks Floor Tile-MASTIC	3200	SF	Basement Corridor, Rooms 012, 013, 014, 016		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	Brown Carpet Mastic	10000	SF	Main Office, Rooms 100E, H, F, K, C, B, P, R, Computer Room 243B, C, and 116		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

57	12" x 12" Light Pink w/ White Streaks VFT	6150	SF	Room 119 (Cafeteria), 120A		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	Comments:											
2017 - Fall: No Change												
Comments:												
2017 - Spring: No Change												
Comments:		_										
2018 - Fall:	No Change											
Comments:					-							
	ng : No Change											
Comments:					4							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
58	12" x 12" Light Pink w/ White Streaks VFT- MASTIC	6150	SF	Room 119 (Cafeteria), 120A		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	Change in Assessment Category	
59	Brown Covebase	500	LF	Room 119 (Cafeteria)		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall:	No Change				7								
Comments:													
2017 - Fall:	No Change												
Comments:													
2017 - Sprin	ng: No Change												
Comments:													
2018 - Fall:	No Change												
Comments:													
2018 - Sprin	ng : No Change												
Comments:													

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	Brown Covebase Adhesive	500	SF	Room 119 (Cafeteria)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	2' x 2' White Ceiling Tile	66000	SF	Rooms 119D, C, 202- 210, 212-220, 240-248, 324-340		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
62	12" x 12" White w/Blue Specks VFT	550	SF	Room 226, 226E		Miscellaneous	No	Loc	2		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	12" x 12" White w/Blue Specks VFT Mastic	550	SF	Room 226, 226E		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:	
Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:	
2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:	2016 - Fall: No Change
Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:	Comments:
Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:	
2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:	2017 - Fall: No Change
Comments: 2018 - Fall: No Change Comments:	Comments:
Comments: 2018 - Fall: No Change Comments:	
2018 - Fall: No Change Comments:	2017 - Spring: No Change
Comments:	Comments:
Comments:	2040. Falls No Charage
	2018 - Fail: No Change
2018 - Spring : No Change	Comments:
2018 - Spring · No Change	
2010 Opining : 110 Onlango	2018 - Spring : No Change
Comments:	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
64	12" x 12" Maroon VFT	400	SF	Room 226		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
65	12" x 12" Maroon VFT Mastic	400	SF	Room 226		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change]							
Comments:					-							

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
66	Maroon Covebase	100	LF	Room 226		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
67	Maroon Covebase Adhesive	100	LF	Room 226		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change]							
Comments:												
2017 Fall: No Chango												

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68	12" x 12" Sky Blue w/ White Specks VFT	3000	SF	Room 343A		Miscellaneous	No	Loc	50		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	12x12 Sky Blue w/ White Specks VFT Mastic	3000	SF	Room 343A		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70	Mastic for 2' X 2' Grey Rubber Floor	2800	SF	Rm. 011, 005, 030 and 018		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	12'X12' Lt. Green Floor Tile	3100	SF	Rm. 222, 224, and Practice Rooms		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2010 5 11 11 21
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72	12"X12" Lt Green Tile Mastic	3100	SF	Room 222, 224, & Practice Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	12"x12" Dark Green Floor Tile	1350	SF	Room 222		Miscellaneous	No	Loc	3		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
74	12"X12" Dark Green Floor Tile Mastic	1350	SF	Room 222		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
75	Linoleum	4240	SF	Rm 346, 348, 350		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments												
2017 - Fall:	: No Change											
Comments												
2017 - Spri	ng: No Change											
Comments												
2018 - Fall:	: No Change											
Comments												
2018 - Spri	ng : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
76	Linoleum Mastic	4240	SF	Rm 346, 348, 350		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	Lab Benches & Counter Tops	3008	SF	Rm 352, 350, 348, 346, 230, 232, & Science Storage Room		Miscellaneous	No	None	0		YES X NO
	•				·	•	-	•	-		

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
78	12" X 12" Dark Gray VFT	225	SF	Basement Rm. 003		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
79	12" X 12" Dark Gray VFT Mastic	225	SF	Basement Rm. 003		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	_											
2017 - Fall: N	lo Change											
Comments:					1							
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
80	4" Brown Baseboard	10000	LF	1st Floor Corridor & Classrooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2018 - Spring : No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
81	4" Brown Baseboard Adhesive	10000	LF	1st Floor Corridor & Classrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	·											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
82	Vault Door Insulation	36	SF	Main Office		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2018 - Spring : No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
83	12" x 12" Light Blue VFT	3132	SF	Rm. 118		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
84	12" x 12" Light Blue VFT Mastic	3132	SF	Rm. 118		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
85	Blue Carpet Mastic	400	SF	Rm. 101		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	g: No Change											
Comments:	, <u> </u>											
2018 - Fall: N	lo Change											
Comments:	<u> </u>											
2018 - Spring	g : No Change				<u></u>							
Comments:	,											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
86	12"x12" Green VFT			Room 118, Restroom		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 45

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
87	12"x12" Green VFT Mastic			Room 118, Restroom		Miscellaneous				YES	X NO
2016 - Fall: N	o Change]						
Comments:											
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change				-						
Comments:					-						
2018 - Fall: N	o Change										
Comments:					1						
2018 - Spring	: No Change										
Comments:					-						
					J						

Material

Friable

Damage

Damage

Damage

Change in Assessment Category

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
88	1' x 1' Ceiling Tile	3000	SF	Rooms 343 and 343A		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	nent Category
89	Mastic Associated w/ 1' x 1' Ceiling Tile	3000	SF	Rooms 343 and 343A		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				1							
Comments:	Ü]							
2017 - Fall: N	lo Change				-							
Comments:	-]							
2017 - Spring	: No Change											
Comments:					-							
2018 - Fall: N	o Change											
Comments:					_							
2018 - Spring	: No Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	Boiler Packing			Boiler Room							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 47

		Quantity	Units		Type	Category	Туре	Quantity	Units	1	
В	Breeching on Boiler			Boiler Room		TSI	None			YES	X NO
2016 - Fall: N	o Change]						
Comments:					 						
2017 - Fall: N	o Change										
Comments:					-						
2017 - Spring	: No Change										
Comments:					1						
2018 - Fall: N	o Change										
Comments:					<u> </u>						
2018 - Spring	: No Change										
Comments:	·			<u> </u>	 -						
					J						

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Tank Insulation 3' x 5' - 30	100	SF	Boiler Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Tank Insulation 3' x 5' - 30	150	SF	Boiler Room		TSI	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	Tank Insulation 3' x 5' (grey)	150	SF	Boiler Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
F	Tank Insulation 3' x 5' (Blue)	120	SF	Boiler Room		TSI	Yes	None	0		YES	X NO
2016 - Fall: I Comments:	No Change									•		
Comments.												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:	-											
2018 - Fall: I	No Change											
Comments:	<u> </u>											
	g : No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Tank Insulation (Large Yellow/Orange) Heat Exchanger			Boiler Room		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 50

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	nent Category
Н	Vibration Dampers on Air Duct System			2nd and 3rd Floors							YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	Ţ.											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	Duct Liner			Ceiling of Auditorium							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
J	Boiler Jacket - Fiberglass Wrap			Boiler Room							YES	X NO
2016 - Fall: N	lo Change				7							
Comments:					=							
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change				_							
Comments:					_							
	: No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:					4							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	12"x12" Dark Green Floor Tile			Univents in Classroom, Lunchroom, Office		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

		Quantity	Units		Type	Category		Type	Quantity	Units		
L	Joint on Fiberglass Pipe (see HA P)	2500	LF	1st Floor throughout Shops, Offices, Boiler Room, Tunnels		TSI	Yes	None	0		YES	X NO
204C Falls	No Change	•	•	•	7	•	•	•	•	*	•	
	No Change											
Comments:												
2017 - Sprin	ng: No Change											
Comments:												

Material

Friable

Damage

Damage

Asbestos

2017 - Fall: No Change Comments:

Material Description

Material

Material Location

2018 - Fall: No Change

Comments:

HA No

2018 - Spring : No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
М	Jacket Covering on Fiberglass Duct Insulation			Throughout							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
N	Duct Insulation (Foil & Fiberglass)			Ceiling of 1,2, & 3rd Floors							YES	X NO
2016 - Fall: N	No Change											
Comments:	<u> </u>											
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:	_											
2018 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change				-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
0	White Air Duct Insulation	1500	SF	Above Ceiling in Kitchen Serving Area		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Р	Joints on Fiberglass Pipe Insulation, Boiler Room	2500	LF	Boiler room, Tunnels, Rm 126, 129		TSI	Yes	Dist	14		X YES NO

2016 - Fall: Deteriorated
Comments:insulation at hot water tank
2017 - Spring: Abated
Comments:tunnel area, boiler room
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Q	Fiberglass Pipe Insulation			Throughout School							X YES NO

2016 - Fall: Deteriorated
Comments:pipe insulation elbows front vestibule area
2017 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:tunnel area
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
R	Tank Insulation	200	SF	Boiler Room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	g: No Change											
Comments:												

2017 - Fall: No Change

Comments:

2018 - Fall: No Change

Comments:

2018 - Spring : No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
S-1	12x12 black w/ white specs	4100	SF	Stage, Room 116		Miscellaneous	No	Loc	25		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
S-2	12x12 black w/ white specs-mastic	4100	SF	Stage, Room 116		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 57

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Dr N Date: 1/14/2	Martin Luther King Jr College Prep HS 019
the Asbestos Ma	you in accordance with Illinois and Federal Asbestos Regulations, that a copy of inagement Plan is available at each school during school hours by appointment. ew the Asbestos Management Plan must be made at least 24 hours in advance.
The last inspection	dvised that CPS conducts asbestos inspections of all Schools every three years. on was completed in 2016. lances are conducted every six months.
CHECK ONE	
A copy of	this notice was sent home in each child's backpack.
X A copy of	this notice was printed in the school's newsletter and sent home with each child
A copy of	this notice was printed in the school's calendar and sent home with each child
Other.	
4 CODY OF 7	THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Oracle Unit: 46371 Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.