Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Benito Juarez Community Academy High School 46421 1890 School: **Oracle Unit: Building ID:** Address: 2150 S. Laflin Region: 03 Mail Room: Asbestos Surveyor: Soto, Leonardo **CHECK HERE IF NO CHANGE TO ASBESTOS** Survey Date: 1/8/2019 Email Address: lsoto34@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter X Other NTO was not release Each child's backpack Notice printed in school's calendar Change in Assessment Category HA No Material Description Material Location Asbestos Friable Damage Material Material Damage Quantity Units Category Quantity Type Type 1st Floor Corridor & 2nd YES X NO Hard Spray-on Fireproofing Surface Floor Gym 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
2	Soft Spray-on Fire Proofing			Throughout 2nd Floor		Surface					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	J											
2017 - Spring	ı: No Change											
Comments:	,											
2017 - Fall: N	lo Change											
Comments:	3											
2018 - Spring	ı : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3	2' x 2' Ceiling Tile			1st Floor Corridor & Swimming Pool Area		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
4	2' x 4' Ceiling Tile			Throughout 2nd Floor and Office		Miscellaneous					YES	X NO
2016 - Fall: N	o Change				1							
Comments:	•											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	2' x 4' Ceiling tile			3rd Floor Corridors, Classrooms 312, 332, 333 & 335		Miscellaneous					YES X NO

Page 3

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
6A	12" x 12" Crème w/White Speck Floor Tile			Basement		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
	g : No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6B	12" x 12" Speckled Red Floor Tile			2nd & 3rd Floor Stairwells & Basement		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

										l	
6C	12" x 12" Speckled Brown Floor Tile	16800	SF	Throughout 1st & 2nd Floors & Engineer's Office in Basement., Lunch Room		Miscellaneous	No	Dist	12	YES	X NO
2016 - Fall	: No Change				7						
					4						
Comments	S:										
2017 - Spr	ing: No Change										
Comments											
Comment	<i>,</i>				+						
2017 Fall	lı Na Changa										
	: No Change				4						
Comments	S:										
					1						
2018 - Fall	: No Change										
Comments	<u> </u>										
Comments).				+						
0040 0	' N. Ol				4						
	ing : No Change				1						
Comments	S:										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6D	12" x 12" Reddish Brown Floor Tile			1st Floor Corridor & Room 102		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
6E	12" x 12" Green Floor Tile			1st Floor Stairwell		Miscellaneous					YES	X NO
2016 - Fall: N	No Change						•		•			
Comments:	J											
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
L												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6F	12" x 12" Yellow Floor Tile	15500	SF	1st & 3rd Floor Corridors, Throughout 2nd Floor & Rooms 312 & 320		Miscellaneous	No	Dist	3100		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Page 6

6G	12" x 12" Crème w/Black Spots Floor Tile	1st & 2nd Floor Corridors & Rooms 125, 312, 312, 330, 332 & 333	Miscellaneous		YES	X NO
2016 - Fall:	No Change]			
Comments:						
2017 Coris	ay No Chongo					
	ng: No Change		_			
Comments:						
2017 - Fall:	No Change					
Comments:]			
2018 - Sprir	ng : No Change					
Comments:]			
2018 - Fall:	No Change					
Comments:			1			
			1			
			-			

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6H	12" x 12" Speckled Black Floor Tile			1st, 2nd & 3rd Floor Corridors, 230, 248, 207, and 226		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

61	12" x 12" Crème w/Brown Speck Floor Tile	8000	SF	Rooms 250, 248, 224, 214, E and W Corridor Hallways		Miscellaneous	No	None	0	YES	X NO
2016 - Fall	No Change				1						
Comments					1						
Comments	•				1						
2017 - Spri	ng: No Change										
Comments											
	No Change										
Comments											
2018 - Spri	ng : No Change										
Comments											
2018 - Fall:	No Change										
Comments	:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6J	12" x 12" Crème w/Gray Specks Floor Tile			Throughout 2nd Floor		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Rooms 250, 248, 224,

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
6K	12" x 12" Pepper Floor Tile			Classrooms 342, 340, and 338		Miscellaneous					YES	X NO
2016 - Fall: N	No Change]							
Comments:					1							
2017 - Spring	g: No Change				_							
Comments:					1							
2017 - Fall: N	No Change				-							
Comments:					1							
2018 - Spring	g : No Change				-							
Comments:												
2018 - Fall: N	No Change											
Comments:					1							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6L	12" x 12" Mottled Brown Floor Tile			2nd and 3rd Floor Corridors		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 9

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
6M	12" x 12" Blue Floor Tile			MDF Room (205)		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:					-							
2017 - Spring	g: No Change				_							
Comments:					_							
2017 - Fall: N	lo Change											
Comments:					=							
2018 - Fall: N	lo Change											
Comments:					_							
2018 - Spring	g : No Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7	Lab Tables and Counter Tops	800	SF	Classrooms 319 & 354		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8A	12" x 12" Crème w/White Speck Floor Tile Mastic	100	SF	Basement Womens Restroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change Comments:	
Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	
2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	2016 - Fall: No Change
Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	Comments:
Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	
2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	2017 - Fall: No Change
Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	Comments:
Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	
2018 - Fall: No Change Comments: 2018 - Spring : No Change	2017 - Spring: No Change
Comments: 2018 - Spring : No Change	Comments:
Comments: 2018 - Spring : No Change	
2018 - Spring : No Change	2018 - Fall: No Change
	Comments:
Comments:	2018 - Spring : No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8B	12" x 12" Speckled Red Floor Tile Mastic	300	SF	2nd & 3rd Floors Stairwells & Basement		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
8C	12" x 12" Speckled Brown Floor Tile Mastic	16800	SF	Throughout 1st & 2nd Floors & Engineer's Office in the Basement, Lunch Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change		1									

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8D	12" x 12" Reddish Brown Floor Tile	6500	SF	Room 102, 124, and 1st floor hallway		Miscellaneous	No	Dist	1300		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
8E	12" x 12" Green Floor Tile Mastic	200	SF	1st Floor Stairwell		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												
2017 - Spring: No Change Comments:												

2017 - Fall: No Change Comments:

Comments.

2018 - Fall: No Change

Comments:

2018 - Spring : No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8F	12" x 12" Yellow Floor Tile Mastic	15500	SF	1st & 3rd Floor Corridors, Throughout 2nd Floor & Rooms 312 & 320		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
8G	12" x 12" Crème w/Black Spots Floor Tile Mastic			1st & 2nd Floor Corridors & Rooms 125, 312, 312, 330, 332 & 333		Miscellaneous					YES	X NO
2016 - Fall: N	o Change			•								

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8H	12" x 12" Speckled Black Floor Tile Mastic	150	SF	1st, 2nd & 3rd Floor Corridors, 230, 248, 207, and 226		Miscellaneous	No	None	0		YES X NO

81	12" x 12" Crème w/Brown Speck Floor Tile Mastic	8000	SF	Throughout 2nd Floor		Miscellaneous	No	None	0	YES	X NO
0040 5 11 11	01				1						
2016 - Fall: N	o Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:											
1											

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8J	12" x 12" Crème w/Gray Specks Floor Tile Mastic			Throughout 2nd Floor		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8K	12" x 12" Mottled Brown Floor Tile Mastic	80	SF	2nd and 3rd Floor Corridors		Miscellaneous	No	None	0		YES X NO
•											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8L	12" x 12" Pepper Floor Tile Mastic	3000	SF	Classrooms 342, 340, and 338		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
8M	12' x 12" Blue Floor Tile Mastic			MDF Room (205)		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	•											
2017 - Spring	ı: No Change				-							
Comments:	.											
2017 - Fall: N	lo Change				-							
Comments:												
2018 - Spring	: No Change				-							
Comments:												
2018 - Fall: N	lo Change				-							
Comments:	<u> </u>											
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9	Sink			3rd Floor Corridors, Classrooms 312, 332 & 335		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

10	Drywall Tape		3rd Floor Corridors, Classrooms 312, 332 & 335		Miscellaneous					YES	X NO
2016 - Fall	: No Change	<u> </u>	<u> </u>						·		
Comments											
2017 - Fall	: No Change										
Comments	:										
	ing: No Change										
Comments	:										
	ing : No Change										
Comments	:										
	: No Change										
Comments	:										
LIA NI-	Material Described	Martin del Martin de	A Market and a Library of the second	A - I 1	NA = (= v' = 1	Estable.	D	D	D	Ola	

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10A	Drywall Mud			3rd Floor Corridors, Classrooms 312, 332 & 335		Miscellaneous					YES X NO

016 - Fall: No Change	
Comments:	
017 - Fall: No Change	
Comments:	
017 - Spring: No Change	
Comments:	
018 - Spring : No Change	
Comments:	
018 - Fall: No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
11	Roof Flashing - Not AHERA			Roof Top Deck		Miscellaneous				YES	X NO
2016 - Fall: N	lo Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:	<u> </u>										
2017 - Spring	v: No Change										
Comments:	g. No Change										
Commonto.											
2018 - Spring	g : No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:	io onango										

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Roof Field - Not AHERA			Roof		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

13	Carpet Mastic	1st Floor Corridors, 126 & Scattered Throughout 2nd Floor	Miscellaneous			YES	X NO
0040	Na Obassa						
2016 - Fall: I	No Change						
Comments:							
2017 - Sprin	g: No Change						
Comments:							
2017 - Fall: I	No Change						
Comments:							
2018 - Fall: I	No Change						
Comments:							
2018 - Sprin	g : No Change						
Comments:	<u> </u>						
1							

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Troweled on Sink Covering	8	SF	Room 337 (Faculty Lunch Room)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

		Quantity	Units		Type	Category	Туре	Quantity	Units		
15	Exterior Brick - Not AHERA			Exterior of Building		Miscellaneous				YES	X NO
2016 - Fall: N	No Change										
Comments:											
2017 - Fall: N	No Change										
Comments:	· ·										
2017 Cprine	a. No Chango										
	g: No Change										
Comments:											
2018 - Spring	g : No Change										
Comments:	<u> </u>										
2019 Falls N	Jo Changa										
2018 - Fall: N	No Change										
Comments:											

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	Exterior Brick Mortar (Non_AHERA)			Exterior of Building		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

		Quantity	Units		Type	Category	Туре	Quantity	Units		
17	Cinder Block			Throughout 3rd Floor		Miscellaneous				YES	X NO
2016 - Fall: N	lo Change				1	•					
Comments:											
2017 - Fall: N	lo Change				1						
Comments:					1						
2017 - Spring	g: No Change										
Comments:											
	g : No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:					_						
					1						
	14 1 1 1 5 1 1 1						 1	1	_	<u> </u>	

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	Cinder Block Mortar			Throughout 3rd Floor		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
19	Plaster Ceiling			Exterior of Building at Entrances		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	-											
2017 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	g: No Change				-							
Comments:												
2018 - Spring	g : No Change				_							
Comments:												
2018 - Fall: N	lo Change											
Comments:	<u> </u>											
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Fume Hood	15	SF	Classrooms 319		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
21	Concrete Floor			Throughout 3rd Floor		Miscellaneous				YES	X NO
2016 - Fall: I	No Change										
Comments:					-						
2017 - Fall: I	No Change										
Comments:											
2017 - Sprin	g: No Change										
Comments:											
2018 - Sprin	g : No Change										
Comments:											
2018 - Fall: I	No Change				-						
Comments:					=						

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Black Baseboard			Scattered Throughout 2nd Floor		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

		Quantity	Units		Type	Category	Type	Quantity	Units		
22D	Black Baseboard Adhesive			Scattered Throughout 2nd Floor		Miscellaneous				YES	X NO
2016 - Fall: N	lo Change				1						
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change										
Comments:					_						
2018 - Fall: N	lo Change										
Comments:					_						
2018 - Spring	g : No Change										
Comments:											

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Kilns	2	EA	0115		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
24	Gray Linoleum w/Black, White, Gray Spots			Room 344		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	J]							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												
2018 - Spring	j : No Change											
Comments:												
2018 - Fall: N	lo Change				_							
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Gray Linoleum w/Black, White, Gray Spots Mastic			Room 344		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
26	New Drywall	1500	SF	Cafeteria, Front Breezeway Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	l: No Change											
Comments	5:											
2017 - Fal	l: No Change											
Comments	3:											
2017 - Spr	ring: No Change											

Comments:

2018 - Spring : No Change Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	New Drywall Compound	1500	SF	Cafeteria, Front Breezeway Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Light Brown Ceramic Flooring & Grout	7500	SF	Patio		Miscellaneous	No	Dist	25		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2010 Caring Ala Changa
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Light Brown Tile Mastic	7500	SF	Patio		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Blue Grey Carpet Mastic	10000	SF	2nd Floor Media Center		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Abated		
Comments:spring 2013		
·		
2017 - Fall: No Change		
Comments:		
2017 - Spring: Abated		
Comments:place spring 2013		
· · · · -		
2018 - Spring : Other		
Comments:Replace 2013		
·		
2018 - Fall: Other		
Comments:replaced 2013		
·		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Grey Ceramic Flooring & Grout	160	SF	1st Floor Womens Bathroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Grey Ceramic Flooring Mastic	160	SF	1st Floor Womens Bathroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change Comments:	
Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2016 - Fall: No Change
Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Fall: No Change
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Spring: No Change
Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Fall: No Change	
2018 - Fall: No Change	2018 - Spring : No Change
	Comments:
Comments:	2018 - Fall: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Brown & Gold Ceramic Flooring & Grout	200	SF	1st Floor Boys Bathroom		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Abated
Comments:replace summer 2011
2017 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:replace tile in 2011 project
2018 - Spring : Other
Comments:replace in 2011 project
2018 - Fall: Other
Comments: replaced in 2011 project
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Brown & Gold Ceramic Flooring Mastic	200	SF	1st Floor Boys Bathroom		Miscellaneous	No	None	0		X YES NO

2016 - Fall: A	2016 - Fall: Abated											
Comments:replace summer 2011												
2017 - Fall: N	2017 - Fall: No Change											
Comments:	Comments:											
2017 - Spring	: Abated											
Comments:re	place tile in 2011 proje	ect										
2018 - Spring	: Other											
Comments:re	place in 2011 project											
2018 - Fall: O	2018 - Fall: Other											
Comments: replaced in 2011 project												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Brown & White Ceramic Flooring & Grout	200	SF	1st Floor Girls Bathroom		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Abated
Comments:replace summer 2011
2017 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:replace tile in 2011 project
2018 - Spring : Other
Comments:replace in 2011 project
2018 - Fall: Other
Comments: replaced in 2011 project

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Brown & White Ceramic Floor Mastic	200	SF	1st Floor Girls Bathroom		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Al	2016 - Fall: Abated									
Comments:re	Comments:replace summer 2011									
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: Abated									
Comments:re	place tile in 2011 proje	ect								
2018 - Spring	: Other									
Comments:re	place in 2011 project									
2018 - Fall: O	ther									
Comments: re	Comments: replaced in 2011 project									

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Black Ceramic Flooring and Grout	720	SF	2nd, 3rd Floor Bpys Bathroom and 3rd Floor SW Rooms		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Abated
Comments:replace summer 2011
2017 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:replace tile in 2011 project
2018 - Spring : Other
Comments:replace in 2011 project
2018 - Fall: Other
Comments: replaced in 2011 project

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Black Ceramic Flooring Mastic	720	SF	2nd, 3rd, Floor Boys Bathroom and 3rd Floor SW Rooms		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Abated	
Comments:replace summer 2011	
2017 - Fall: No Change	
Comments:	
2017 - Spring: Abated	
Comments:replace tile in 2011 project	
2018 - Spring : Other	
Comments:replace in 2011 project	
2018 - Fall: Other	
Comments: replaced in 2011 project	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Brown Ceramic Flooring & Grout	1800	SF	1st, 2nd Mens Bathroom, 2nd, 3rd Womens and Girls Bathroom		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Abated
Comments:replace summer 2011
2017 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:replace tile in 2011 project
2018 - Spring : Other
Comments:replace in 2011 project
2018 - Fall: Other
Comments: replaced in 2011 project

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Brown Ceramic Flooring Mastic	1800	SF	1st, 2nd Mens Bathroom 2nd, 3rd Womens and Girls Bathroom		Miscellaneous	No	None	0		X YES NO

				Onio Batinooni	
•	•	•	•		
2016 - Fall: Al	bated				
Comments:re	place summer 2011				-
2017 - Fall: N	o Change				
Comments:					
2017 - Spring	: Abated				
Comments:re	place tile in 2011 proje	ect			
2018 - Spring	: Other				
Comments:re	place in 2011 project				
2018 - Fall: O	ther				
Comments: re	eplaced in 2011 projec	t		_	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100	12"x12" VFT Dark Orange	1200	SF	Room 100		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	12"x12" VFT Dark Orange Mastic	1200	SF	Room 100		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102	12"x12" Gold VFT	400	SF	Room 100		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
103	12"x12" Gold VFT Mastic	400	SF	Room 100		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
104	12"x12" White Multi Specks VFT	4500	SF	Clinic		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
105	12"x12" White Multi Specks VFT Mastic	4500	SF	Clinic		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change					7							
Comments:												
2017 - Fall: I	No Change											
Comments:					_							
2017 - Spring: No Change												
Comments:	Comments:											

2018 - Fall: No Change Comments:

2018 - Spring : No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
106	12"x12" Green VFT	450	SF	Clinic		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
107	12"x12" Green VFT Mastic	450	SF	Clinic		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall: I	2018 - Fall: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
108	12"x12" Orange/Brown VFT	450	SF	Clinic		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 38

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
109	12"x12" Orange/Brown VFT Mastic	450	SF	Clinic		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change											
Comments	S:											
2017 - Spi	ring: No Change											
Comments	S:											
2017 - Fal	II: No Change											
Comments	s:											
2018 - Spi	ring : No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
110	Joint Compound	1500	LF	Clinic		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
111	Drywall	8000	SF	Clinic		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	J											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
112	2x2 Ceiling Tile	5500	SF	Clinic		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
113	12"x12" Dark Orange VFT	2500	SF	Medical Lab		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
114	12"x12" Dark Orange VFT Mastic	2500	SF	Medical Lab		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
115	12"x12" Maroon VFT	500	SF	Medical Lab		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				1							
Comments]							
2017 - Spri	ing: No Change											
Comments	:											
2017 - Fall	: No Change											
Comments	:											
2018 - Spri	ing : No Change											
Comments	Comments:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
116	12"x12" Maroon VFT Mastic	500	SF	Medical Lab		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	ment Category
117	12"x12" Dull White VFT	500	SF	Medical Lab		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change]								
Comments:	_												
2017 - Spring	g: No Change				1								
Comments:	,												
2017 - Fall: N	lo Change				1								
Comments:													
2018 - Spring	g : No Change				-								
Comments:	,												
2018 - Fall: N	lo Change				-								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
118	12"x12" Dull White VFT Mastic	500	SF	Medical Lab		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
119	12"x12" Brown Blotted VFT	600	SF	Main Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	¥											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
120	12"x12" Brown Blotted VFT Mastic	600	SF	Main Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2018 - Fall: No Change

Comments:

Page 44

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
121	12"x12" Darkyellow VFT	600	SF	Main Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
	Comments:											
2017 - Fall:	: No Change											
Comments	:											
2017 - Spri	ing: No Change											
Comments	:											
2018 - Fall:	: No Change											
Comments).		<u>-</u>									

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
122	12"x12" Darkyellow VFT Mastic	600	SF	Main Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2018 - Spring : No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
123	12"x12" Pinkish Red VFT	600	SF	Main Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments: 2017 - Fall: N Comments:												

2017 - Spring: No Change Comments:

2018 - Fall: No Change Comments:

2018 - Spring : No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
124	12"x12" Pinkish Red VFT Mastic	600	SF	Main Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
125	Brake Shoes	5	EA	Elevators		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change											
Comments	S:											
2017 - Spr	ring: No Change											
Comments	S:											
2017 - Fall	l: No Change											
Comments	S:											
2018 - Fall	l: No Change											
Comments	S:											
2018 - Spr	ring : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
126	Gaskets	10	EA	Generator Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
127	Grey Multicolored Carpet	3200	SF	Auditorium, Band Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change											
Comments	S:											
2017 - Fall	l: No Change											
Comments	S:											
2017 - Spr	ing: No Change											
Comments	S:											
2018 - Fall	I: No Change											
Comments	S:											
2018 - Spr	ring : No Change				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
128	12x12" White/Brown Specks VFT	2200	SF	2nd Floor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
129	12x12" White/Brown Specks VFT Mastic	2200	SF	2nd Floor		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
130	12"x12" Bright Orange VFT	800	SF	Rooms 275-280		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	ment Category
131	12"x12" Bright Orange VFT Mastic	800	SF	2nd Floor		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change]								
Comments:	-				=								
2017 - Fall: N	lo Change				1								
Comments:	Ü												
2017 - Spring	ı: No Change				1								
Comments:	J												
2018 - Fall: N	lo Change												
Comments:													
2018 - Spring	j : No Change				_								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
132	12"x12" Bright Blue VFT	800	SF	Rooms 275-280		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
133	12"x12" Bright Blue VFT Mastic	800	SF	2nd Floor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
134	12"x12" Bright Green VFT	800	SF	Rooms 275-280		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
135	12"x12" Bright Green VFT Mastic	800	SF	2nd Floor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

136 2x2 Ceiling Tile 12000 SF 2213, 1118, 1123, 1126, E Hall Stairs, Boys/Girls Miscellaneous Yes None 0	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Dressing Rooms, 1st Floor Corridor	136	2x2 Ceiling Tile	12000	SF	275-280, 2221-2224, 2213, 1118, 1123, 1126, E Hall Stairs, Boys/Girls Dressing Rooms, 1st		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
137	Window Caulk	6000	SF	Throughout 2nd Floor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	<u> </u>											
2017 - Fall: N	lo Change				+							
Comments:	<u> </u>											
2017 - Spring	g: No Change				+							
Comments:												
2018 - Fall: N	lo Change				+							
Comments:	Ğ											
2018 - Spring	g : No Change				-							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
138	Door Caulk	4000	SF	Throughout 2nd Floor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
139	Spray on Fire Proofing	50000	SF	Throughout 2nd Floor		Surface	Yes	None	0		YES	X NO
	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
2018 - Sprir	ng : No Change											
Comments:	·											
	·											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
140	Red Sealant	10000	LF	Throughout 2nd Floor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

		Quantity	Units		Туре	Category		Type	Quantity	Units		
141	2x2 Black Ceiling Tile	1200	SF	Control Room Auditorium		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:	3 · ·											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
<u> </u>					J							

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
142	12'x8' Acoustic Panels	3000	SF	Auditorium		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Material

Material Location

Page 56

				Type	Category	Friable	Damage Type	Damage Quantity	Damage Units	0.181.g0 11.7.000	ssment Category
ight Blue Acoustic Panels	500	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
Change]							
Change				_							
lo Change				+							
Change				+							
Ŭ											
No Change				+							
g •											
	Change Change O Change	Change Change Change Change Change	Change Change Co Change Change	Change Change Co Change Change	Change Change Change Change	Change Change Change Change	Change Change Change Change Change				

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
144	Orange Acoustic Panels	500	SF	Auditorium		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

		Quantity	Units		Type	Category		Туре	Quantity	Units	1	
145	4'x4' Ceiling Tile	7500	SF	Auditorium, Room 281 Choir Room		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:												
2017 - Fall: N	o Change				-							
Comments:												
2017 - Spring	: No Change				-							
Comments:												
2018 - Fall: N	o Change				1							
Comments:												
2018 - Spring	: No Change				-							
Comments:	-											

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
146	Baseboard	8000	LF	Throughout School		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
147	Mastic Associated w/ Baseboard	8000	LF	Throughout School		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	•											
2017 - Fall:	No Change											
Comments:	•											
2017 - Sprii	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
2018 - Sprii	ng : No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	Fittings on Fiberglass Pipe Insulation			Boiler Room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
В	Canvas Wrap Over Breeching			Boiler Room		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	ı: No Change											
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	ı : No Change											
Comments:	<u> </u>											
2018 - Fall: N	lo Change											
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Fiberglass Boiler Insulation			Boiler Room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 60

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
D	Boiler Breeching			Boiler Room		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:					-							
	g: No Change				-							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					 							
2018 - Spring	g : No Change											
Comments:			•									

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	Canvas Wrap Over Water Tank			Boiler Room		Miscellaneous					X YES NO

2016 - Fall: Other
Comments:water tank removed
2017 - Spring: Deteriorated
Comments:has damage
2017 - Fall: No Change
Comments:
2018 - Spring : Deteriorated
Comments:damaged
2018 - Fall: Deteriorated
Comments:Damaged

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Cementitious Pipe Fittings			Throughout 1st Floor and Pool Equipment Room		Miscellaneous					X YES NO
2016 - Fall: Damaged											

2016 - Fall: Damaged
Comments:some damage
2017 - Spring: Deteriorated
Comments:has damage
2017 - Fall: No Change
Comments:
2018 - Spring : Other
Comments:damaged
2018 - Fall: Damaged
Comments:Damaged

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Cementitious Pipe Fittings			Auto Shop (on Heater) /Throughout 1st Floor		Miscellaneous					X YES NO

2016 - Fall: Damaged
Comments:some damage
2017 - Fall: No Change
Comments:
2017 - Spring: Other
Comments:has damage
2018 - Fall: Damaged
Comments:Damaged
2018 - Spring : Other
Comments:damaged

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	Gasket on Oven	10	LF	Classroom 334		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Other									
Comments:no	Comments:no oven in 334								
2017 - Fall: N	o Change								
Comments:									
2017 - Spring									
Comments:no	oven in room								
2018 - Spring	: Other								
Comments:no	oven								
2018 - Fall: O	ther								
Comments:no	oven								
				·					

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	Boiler Gasket	60	LF	Boiler Room		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Other
Comments:no gasket
2017 - Spring: Other
Comments:no gaskets
2017 - Fall: No Change
Comments:
2018 - Spring : Other
Comments:no gaskets
2018 - Fall: Other
Comments:no gaskets

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Benito Juarez Community Academy High School
Date:1/8/2019

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
X Other. NTO was not released
A COPY OF THIS NOTICE MUST BE PLACED IN THE

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.