Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Bowen High School 46491 Building ID: 1240 School: **Oracle Unit:** Address: 2710 E. 89th St. Region: Mail Room: Asbestos Surveyor: Gordon, Sandra X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/12/2018 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type Annex Rooms: 312, 240, YES X NO 12x12 Tan w/Brown Specks 224, 225, 230, 231, 242, 01 6400 SF Miscellaneous No None 0 Floor Tile 234, 235, 129, Dean's Office, Library 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments:

01AFT	12X12 green w/green specks VFT	1400	SF	Rooms 229, 241, 261		Miscellaneous	No	None	0		YES		X NO
2017 - Spring	ı: No Change			·	7								
Comments:	J												
2017 - Fall: N	lo Change												
Comments:	Comments:												
2018 - Spring	ı : No Change												
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessm	ent Category
01AM	12x12 green w/ grwwn specks VFT MASTIC	1400	SF	Rooms 229, 241, 261		Miscellaneous	No	None	0		YES		X NO
2017 - Fall: N	lo Change				1								
Comments:													
2017 - Spring	ı: No Change												
Comments:	, 9-												
2018 - Spring	2018 - Spring : No Change												

Category

Asbestos

Type

Damage

Type

Friable

Damage

Quantity

Damage

Units

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

01CM	12x12 dark gray w/specks VFT MASTIC	300	SF	261 Lunchroom		Miscellaneous	No	None	0		YES	X NO
2017 - Sprin Comments:	g: No Change											
2017 - Fall: Comments:	No Change											
2018 - Sprin	ig : No Change				-							
]			1			,	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

4300

Material

Quantity

Material

Units

SF

Material Location

Rooms 229, 241, 229A,

HA No

1BFT

Material Description

12x12 light gray w/ gray and white specks VFT

Page 3

Change in Assessment Category

X NO

YES

1BM	12x12 gray w/gray and white specks VFT MASTIC	4300	SF	Rooms 229, 241, 229A, 261	Miscellaneous	No	None	0	YES	X NO
2017 - Fall: N Comments:	lo Change									
2017 - Spring Comments:	: No Change									
2018 - Spring Comments:	j : No Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1CFT	12x12 dark gray w/specks VFT	300	SF	261 Lunchroom		Miscellaneous	No	None	0		YES X NO

2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Material

Quantity

Material

Units

HA No

1CM	Carpet Mastic	6400	SF	Rooms 144, 140C, 140H, 140E, 140D, 140, 140A, 140J, 200N, 240		Miscellaneous	No	None	0	YES	X NO
	•		•		1	•	•	•			
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:	-										
2018 - Spring	g : No Change										

Category

Friable

Damage

Type

Asbestos

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1DS	Drywall System		SF	Rms. 231, 2nd fl. breezeway, 1st fl. breezeway		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

02	9x9 Floor Tile - Not observed	0	SF	Main building 2nd and 3rd Floor Classrooms	Miscellaneous	No	None	0	YES	X NO
2017 - Fall: N Comments:	o Change									
2017 - Spring	: No Change									
Comments:										
2018 - Spring Comments:	: No Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

Main building 2nd and

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02FT1	9x9 Dark Brown Floor Tile NOT OBSERVED IN ROOM 211	1200	SF	Main Building Rooms 210, 211, 212 NOT OBSERVED IN ROOM 211		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

02FT2	9x9 Light Gray Floor Tile (NOT OBSERVED)	900	SF	Main Building Room 312	Miscellaneous	No	None	0	YES	X NO
<u> 2017 - Spring</u>	g: No Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2018 - Spring	g : No Change									
Comments:										

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03FT14	12x12 Cream Floor Tile	60000	SF	Teachers lounge, 1st, 2 nd, 3rd, and 4th Floor Hallways, 1st Floor Women's Bathroom, 3rd Floor Men's bathroom, Rms 490, 314, 204, 285A; 2nd floor handicap toilet		Miscellaneous	No	None	0		YES X NO

2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

03FT3	12x12 Green Floor Tile	800	SF	Main Building Principals Office, Conference Room Corridor	Miscellaneous	No	None	0	YES	X NO
2017 - Fall: N Comments:	o Change									
2017 - Spring Comments:	: No Change									
2018 - Spring Comments:	: No Change									

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
03FT4	9x9 White w/ Green Specks Floor Tile	900	SF	Main Building Room 202		Miscellaneous	No	None	0		YES	X NO
2017 - Spring Comments:	: No Change											

2017 - Fall: No Change Comments: 2018 - Spring : No Change

Material

Quantity

Material

Units

HA No

Material Description

2018 - Spring : No Change Comments:

03FT6	12x12 Brown Floor Tile	800	SF	Main Building 1st Floor hallway Trim, room 410	Miscellaneous	No	None	0	YES	X NO
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Spring	: No Change									
Comments:										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03FT7	12x12 Light Brown Speckled Floor Tile REMOVED FROM ROOMS 306 & 310	15000	SF	Main Building Rooms 300, 310, 314, 315, 316, 306, 1st and 3rd Floor Faculty Bathrooms, 208A, 207, Main Office, and 2nd fl. Corridor. REMOVED FROM ROOMS 306 & 310		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
03FT8	12x12 Beige Speckled Floor Tile	400	SF	Main Building Room 308		Miscellaneous	No	None	0		YES	X NO
2017 - Spring	: No Change]							
Comments:												
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:	<u> </u>											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
04	Tectum Celing	5000	SF	Main building Gymnasium		Miscellaneous	Yes	None	0		YES	X NO
2017 - Spring	: No Change]							
Comments:	<u> </u>											
2017 - Fall: N	o Change				-							
Comments:	.											
2018 - Spring	: No Change				<u> </u>							
Comments:												

		Quantity	Units		Type	Category		Type	Quantity	Units		
05	9x9 Floor Tile-removed 1991			Annex 1st and 2nd Floor		Miscellaneous			0		YES	X NO
2017 - Spring	g: No Change]							
Comments:	<u> </u>											
2017 - Fall: N	Vo Change				1							
Comments:	10 Griange				1							
2012 0 :												
	g : No Change											
Comments:												
]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	essment Category
TIANO	Material Description	Quantity	Units	Material Location	Type	Category	Thable	Type	Quantity	Units	Change in Asse	essinent Category
06	Linoleum Floor	950	SF	main building Stairways		Miscellaneous	No	None			YES	X NO
2017 - Spring	g: No Change				1							
Comments:	<u>g</u>]							
2017 - Fall: N	No Change				-							
Comments:	10 Orlange											
2010 Caria	a . No Change											
	g : No Change											
Comments:					-							
					J							

Asbestos

Damage

Friable

Damage

Damage Change in Assessment Category

HA No

Material Description

Material

Material Location

06FT11	12x12 Gray Floor Tile	14000	SF	Annex Rooms: 222, 223, 226, 227, 232, 233, 236, 237, 124, 125, 137, 138, 139, 136		Miscellaneous	No	None	0		YES X NO
2017 - Sprin	g: No Change]						
Comments:	<u> </u>]						
2017 - Fall:	No Change				_						
Comments:											
2018 - Sprin	g : No Change]						
Comments:					_						
					1						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06FT12	12x12 Light Blue Floor Tile	2000	SF	Annex 1st Floor Offices, 2nd Floor Faculty		Miscellaneous	No	None	0		YES X NO

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage Quantity Damage

Units

Change in Assessment Category

X NO

YES

06FT12	12x12 Light Blue Floor Tile Mastic	2000	SF	2nd Floor Faculty Lounge, 140-A-J
2017 - Spring	g: No Change			
Comments:				
2017 - Fall: N	No Chango			
Comments:	NO Change			
Comments.				
2018 - Spring	g : No Change			
Comments:				

Material

Quantity

Material

Units

Material Location

HA No

06FT13	12x12 White w/ Tan Specks Floor Tile	1800	SF	Annex Rooms 126 and 127		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change				1							
Comments:	<u> </u>]							
2017 - Spring	g: No Change				_							
Comments:												
2018 - Spring	g : No Change				-							
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
06FT14	12x12 Cream Floor Tile	1850	SF	Annex 1st and 2nd Floor Hallways		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change]							
Comments:	J											
2017 - Spring	g: No Change			1								
Comments:	,]								
2018 - Spring	g : No Change				_							
Comments:												

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

HA No

Material Description

Material

Units

Material

Quantity

Material Location

06FT5	12x12 Dark Brown and Cream Speckled Floor Tile	7200	SF	Annex Rooms: 241, 240, 229, 242, 129, 229A		Miscellaneous	No	None	0	YES	X NO
					1						
2017 - Fall: N	No Change										
Comments:											
2017 - Spring	g: No Change										
	g. 140 Onlange										
Comments:											
2018 - Spring	g : No Change										
zoro opini	g . 110 Onango										

Type

Material

Category

Damage

Type

Damage

Quantity

Damage Units

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06FT7	12x12 Light Brown Floor Tile	17100	SF	Annex Rooms: 224, 225, 230, 231, 239, 122, 123, 134, 135, 136, 238		Miscellaneous	No	None	0		YES X NO

2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

07FT9	12x12 Red Floor Tile NOT OBSERVED	3000	SF	Main Building Lunchroom NOT OBSERVED		Miscellaneous	No				YES	X NO
2017 - Spring	r. No Change											
Comments:	g. He change											
2017 - Fall: N	lo Change											
Comments:	•											
2018 - Spring	g : No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

10/140	Waterial Description	Quantity	Units	Waterial Education	Type	Category	Thabic	Type	Quantity	Units	Change in 7.05050	ment oatogory
09	12x12 Tan w/Brown Specks Floor Tile Mastic	6400	SF	Annex Rooms: 241, 240, 224, 225, 229, 230, 231, 242, 234, 235, 129, dean's office, and library		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: No Comments:	o Change											

2017 - Spring: No Change
Comments:

2018 - Spring : No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

09FT12	12x12 Light Blue Floor Tile	2500	SF	Annex 1st Floor Offices, 2nd Floor Faculty Lounge, Rm 140-AJ	Miscellaneous	No	None	0	YES	X NO
2017 - Fall: N Comments:	lo Change									
2017 - Spring Comments:	g: No Change									
2018 - Spring Comments:	g : No Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09FT13	12x12 White w/ Tan Specks Floor Tile Mastic	750	SF	Annex Rooms 126 and 127		Miscellaneous	No	None	0		YES X NO

2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

09FT14	12x12 Cream Floor Tile Mastic	1850	SF	Annex 1st and 2nd Floor Hallways		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	No Change				7							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:	J											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
09FT5	12x12 Dark Brown and Cream Speckled FT Mastic	7200	SF	Annex rooms 240, 242, 129, 229A		Miscellaneous	No	None	0		YES	X NO
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change				_							
Comments:												
2018 - Spring : No Change												

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

HA No

Comments:

Material Description

Material

Units

Material

Quantity

Material Location

		Quantity	Units		Туре	Category		Туре	Quantity	Units	3	,
09FT7	12x12 Light Brown Floor Tile Mastic	17100	SF	Annex Rooms: 224, 225, 230, 231, 239, 122, 123, 134, 135, 136, 238		Miscellaneous	No	None	0		YES	X NO
2017 - Fall:	No Change				1							
Comments:	J				- -							
2017 - Sprin	g: No Change											
Comments:												

Friable

Damage

Damage

Damage

Asbestos

Material Location

237, 124, 125, 137, 138,

]						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9FT11	12x12 Gray Floor Tile	13500	SF	Annex Rooms: 222, 223, 226, 227, 232, 233, 236,		Miscellaneous	No	None	0		YES X NO

Miscellaneous

No

None

0

acar	139, 136
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

13500

SF

Material

Material

HA No

Material Description

2018 - Spring : No Change

Mastic

Comments:

9FT11

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
14	Transite Panels-abated.			Swimming Pool and Locker Rooms							YES	X NO
2017 - Spring	: No Change]							
Comments:					-							
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
16	12x12 Floor Tile Mastic	162000	SF	Main Building, 2nd, 3rd and 4th Floor Classrooms		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change]							
Comments:	•											
2017 - Spring	: No Change				-							
Comments:												
2018 - Spring	: No Change				-							
Comments:	v											
					j							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16FT-2	12x12 Cream Floor Tile Mastic	60000	SF	1st, 2nd, 3rd, and 4th Floor Hallways, 3rd Floor Mens Bathroom, 1st Floor Womens Bathroom, 2nd fl. handicap toilet, Rms. 490, 314, 204, 285A		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16FT10	12x12 Orange and White Floor Tile Mastic	100	SF	Main Building Engineers Office		Miscellaneous	No	None	0		YES X NO

·	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

16FT3	12x12 Green Floor Tile Mastic	600	SF	Main Building, Principals Office, Conference Room Corridor		Miscellaneous	No	None	0	YES	X NO
2017 - Fall: N	No Change	·									
Comments:											
2017 - Spring	g: No Change										
Comments:											
2018 - Spring	g : No Change										
Comments:											
					j						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16FT4	9x9 White with Green Specks Floor Tile Mastic	900	SF	Main Building, Room 202		Miscellaneous	No	None	0		YES X NO

2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

16FT6	12x12 Brown Floor Tile Mastic	800	SF	Main Building, 1st Floor Hallway Trim, Room 410	Miscellaneous	No	None	0	YES	X NO
2017 - Spring Comments:	: No Change									
2017 - Fall: N	o Change									
Comments:										
2018 - Spring	: No Change									
Comments:										

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16FT7	12x12 Light Brown Floor Tile Mastic	16000	SF	Main Building, Rooms: 300, 310, 314, 315, 316, 306, 3rd & 1st Floor Faculty Bathroom, 208A, 207, Main Office, and 2nd fl. Corridor. (310, and 306 Removed)		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		

Material

Quantity

Material

Units

Material Location

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
16FT8	12x12 Beige Speckled Floor Tile	1000	SF	Main Building, Room 308		Miscellaneous	No	None			YES	X NO
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
16FT9	12x12 Red Floor Tile Mastic (NOT OBSERVED)	3000	SF	Main Building, Lunchroom		Miscellaneous	No	None	0		YES	X NO
2017 - Spring	g: No Change]							
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2018 - Spring	g : No Change											

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
17	9x9 Maroon and Tan Floor Tile Mastic	900	SF	Main Building Swimming Pool and Corridors		Miscellaneous	No	None	0		YES	X NO
2017 - Sprir	ng: No Change]							
Comments:												
2017 - Fall:	No Change				_							
Comments:												
2018 - Sprir	ng : No Change				-							
Comments:	· ·											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
19	Linoleum Mastic	950	SF	1908 Stairways		Miscellaneous	No	None	0		YES	X NO
2017 - Sprir	ng: No Change]							
Comments:												
2017 - Fall:	No Change				-							
Comments:					=							
2018 - Sprir	ng : No Change											
Comments:					1							
]							

HA No

20	9x9 Floor Tile Mastic	0	SF	Main Building 2nd and 3rd Floor Classrooms		Miscellaneous	No	None	0		YES	X NO
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
20FT1	9x9 Dark Brown Floor Tile Mastic	1800	SF	Main Building rooms 200, 212-211 NOT OBSERVED		Miscellaneous	No	None	0		YES	X NO
	g: No Change	<u> </u>]							
Comments:												

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2017 - Fall: No Change

2018 - Spring : No Change

Comments:

Comments:

Material Description

Material

Units

Material

Quantity

Material Location

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
20FT2	9x9 light Gray Floor Tile Mastic (NOT OBSERVED)	900	SF	Main Building room 312		Miscellaneous	No	None	0		YES	X NO
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	j : No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
21	9x9 Floor Tile Mastic- material removed.			Annex Room and Office							YES	X NO
2017 - Spring	g: No Change				1							
Comments:	<u>-</u>											
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	j : No Change											
Comments:												
					_							

Friable

Material

Asbestos

Damage

Damage

Damage

Change in Assessment Category

Material Material Location

HA No

Material Description

Material

22	12x12 Beige w/White Streaks Floor Tile	200	SF	Main Building - Room 211 and 211A	Miscellaneous	No	None	0	YES	X NO
2017 - Sprin Comments:	g: No Change									
2017 - Fall: Comments:	No Change									
2018 - Sprin Comments:	ig : No Change									

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12x12 Beige w/White Streaks Floor Tile Mastic	200	SF	Main Building - Room 211 and 211A		Miscellaneous	No	None	0		YES X NO

2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
24	Turquois Carpet Mastic	400	SF	Main Building - Assembly Hall		Miscellaneous	No	None	0		YES	X NO
2017 - Sprin	g: No Change]							
Comments:					_							
2017 - Fall: I	No Change				<u> </u>							
Comments:					_							
	g : No Change]							
Comments:					_							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
25	12x12 Gray Floor Tile	600	SF	Main Building - Gym Corridor		Miscellaneous	No	None	0		YES	X NO
2017 - Sprin	g: No Change				1							
Comments:												
2017 - Fall: I	No Change											
Comments:					_							
2018 - Sprin	g : No Change											
Comments:					_							
L					_							

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
26	12x12 Gray Floor Tile Mastic	1000	SF	Main Building - Gym Corridor		Miscellaneous	No	None	0		YES	X NO
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:	•											
2018 - Sprind	g : No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
28	Gray Carpet Mastic	600	SF	Main Building - Room 400		Miscellaneous	No	None	0		YES	X NO
2017 - Spring	g: No Change											
Comments:	•											
2017 - Fall: N	No Change											
Comments:	To Omango											
2018 - Spring	g : No Change											
Comments:	g . 140 Onlange				7							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
29	Gray Linoleum	700	SF	Main Building - Room 306		Miscellaneous	No	None	0		YES	X NO
2017 - Spring	: No Change											
Comments:					_							
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:	· · · · · · · · · · · · · · · · · · ·											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
30	Gray Linoleum Mastic	700	SF	Main Building - Room 306		Miscellaneous	No	None	0		YES	X NO
2017 - Spring	: No Change											
Comments:	<u> </u>											
2017 - Fall: N	o Change											
Comments:	o Onlange											
2010 Chring	. No Change											
2018 - Spring Comments:	. No Change											
Commonto.												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
31	Brown Baseboard	60	LF	Main Building - Room 306		Miscellaneous	No	None	0		YES	X NO
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
32	Brown Baseboard Mastic	60	LF	Main Building - Room 306		Miscellaneous	No	None	0		YES	X NO
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	•											
2018 - Spring	: No Change											
Comments:	· · ·											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
33	Black Baseboard	75	LF	Main Building - Boys Gym, 2nd floor		Miscellaneous	No	None	0		YES	X NO
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:	<u> </u>											
2018 - Sprin	g : No Change											
Comments:	g : ::o oago											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
34	Black Baseboard Mastic	75	LF	Main Building - Boys Gym, 2nd floor		Miscellaneous	No	None	0		YES	X NO
2017 - Sprin	g: No Change											
Comments:	0											
2017 - Fall: I	No Change											
Comments:	ito chango											
2018 - Sprin	g : No Change											
Comments:	ig . No Change											
23												

35	9x9 Brown Floor Tile	15	SF	Main Building - Gym Vestibule, 2nd floor		Miscellaneous	No	None	0		YES	X NO
2017 Cn	ring, No Changa				\neg							
	ring: No Change											
Comments	S:											
2017 - Fal	I: No Change											
Comments	 S:											
2018 - Spi	ring : No Change											
Comments	3:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
	·	Quantity	Units		Type	Category		Type	Quantity	Units		
20	Mastic for 9x9 Brown, 9x9	45	SF	Main Building - Gym		N 4: II	N-	N				[v.h.a
36	Tan, and 9x9 Dark Brown	15	SF	Vestibule, 2nd floor		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
37	9x9 Tan Floor Tile	15	SF	Main Building - Gym Vestibule, 2nd floor		Miscellaneous	No	None	0		YES	X NO
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: No Change												
Comments:												
2018 - Spring : No Change												
Comments:	,											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damaga	Domogo	Change in Asses	esmont Catagory
HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Damage Type	Damage Quantity	Damage Units	Change in Asses	Sment Category
38	9x9 Dark Brown Floor Tile	15	SF	Main Building - Gym Vestibule		Miscellaneous	No	None	0		YES	X NO
2017 - Spring	ı: No Change											
Comments:	•											
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	ı · No Change											
2018 - Spring : No Change Comments:												
					┪							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
39	Brown Carpet Mastic	450	SF	Annex - Child Care Room		Miscellaneous	No	None	0		YES	X NO
2017 - Sprin	ng: No Change]							
Comments:												
2017 - Fall: No Change												
Comments:	-											
2018 - Sprin	ng : No Change											
Comments:												
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
40	Brown Carpet w/Dots	250	SF	Annex - Child Care Room		Miscellaneous	No	None	0		YES	X NO
2017 - Sprin	ng: No Change]							
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprin	ng : No Change											
Comments:	.g : ::e ege											
]							

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
41	Blue Carpet Mastic	750	SF	Annex - Library (228)		Miscellaneous	No	None	0		YES	X NO
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: No Change												
Comments:												
2018 - Spring : No Change												
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
42	Gray carpet, Gray Carpet Mastic	600	SF	Annex - Room 238		Miscellaneous	No	None	0		YES	X NO
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: No Change												
Comments:												
2018 - Spring : No Change												
Comments:												

HA No

42A	2'X2' Smooth Ceiling Tile	5000	SF	Rooms 241, 261, 229A, 229, 231, 140J, 140A, 140, 140D, 140E, 140H, 140G		Miscellaneous	Yes	None	0		YES	X NO
2017 - Fall:	: No Change				7							
Comments	;				1							
2017 - Spri	ng: No Change				=							
Comments	:											
2018 - Spri	ng : No Change				_							
Comments	:				-							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
42B	Rubber Floor Mastic	1400	SF	231 Annex		Miscellaneous	No	None	0		YES	X NO
2017 - Spri	ng: No Change			<u>-</u>	1		<u> </u>	•	•	•	•	
Comments					- -							
2017 - Fall:	: No Change				-							

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

2018 - Spring : No Change

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
43	Light Brown Baseboard	675	LF	Annex - Corridor		Miscellaneous	No	None	0		YES	X NO
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	ı : No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asser	ssment Category
44	Light Brown Baseboard Mastic	675	LF	Annex - Corridor		Miscellaneous	No	None	0		YES	X NO
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2018 - Spring	ı : No Change											
Comments:	, -											

45	12x12 Gray w/Green Spots Floor Tile	1800	SF	Annex - Rooms 126 and 127	Miscellaneous	No	None	0	YES	X NO
2017 - Spring	· No Change									
Comments:	. No Change									
2017 - Fall: N	o Change									
Comments:										
2018 - Spring	: No Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
46	12x12 Gray w/Green Spots Floor Tile Mastic	1800	SF	Annex - Rooms 126 and 127		Miscellaneous	No	None	0		YES	X NO
2017 - Sprir	ng: No Change											

2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	Gray Baseboard	2000	LF	Annex - Rooms: 222, 223, 226, 227, 232, 233, 235, 234, 236, 237, 124, 125, 137, 138, 139		Miscellaneous	No	None	0		YES X NO
2017 - Fall: N	lo Change										

2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Gray Baseboard Mastic	2000	LF	Annex - Rooms: 222, 223, 226, 227, 232, 233, 235, 234, 236, 237, 124, 125, 137, 138, 139		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

49	Black Baseboard	450	LF	Annex - Rooms 240, 241, 229, 238		Miscellaneous	No	None	0		YES	X NO
2017 - Fal	I: No Change]							
Comments												
2017 - Spr	ring: No Change											
Comments	s:											
2018 - Spr	ring : No Change											
Comments	S:											
					I							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
50	Black Baseboard Mastic	450	LF	Annex - Rooms 240, 241, 229, 238		Miscellaneous	No	None	0		YES	X NO
2017 - Fal	I: No Change											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

2017 - Spring: No Change

2018 - Spring : No Change

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
51	Blue Baseboard	125	LF	Annex - Childcare Area		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change											
Comments:					4							
2017 - Spring	g: No Change											
Comments:	<u> </u>											
2010 Carina	r - No Changa				4							
Comments:	g : No Change				+							
Comments.					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
52	Blue Baseboard Mastic	125	LF	Annex - Childcare Area		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change				7							
Comments:	<u> </u>											
0047 0 :	N. O.											
	g: No Change				4							
Comments:					+							
2018 - Spring	g : No Change											
Comments:	-											
					_							

HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
	a.a 2 ccop.iici.	Quantity	Units	material 200ation	Туре	Category		Туре	Quantity	Units	onange m rissessment sategory
53	Turquois Baseboard	450	LF	Annex - Rooms 228, Womens 2nd Floor Faculty Lounge, West Office Corridor and Offices		Miscellaneous	No	None	0		YES X NO
2017 - Fall:	No Change				7						
Comments:	ito onango										
2017 - Sprin	ıg: No Change										
Comments:											
2018 - Sprin	g : No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	Turquois Baseboard Mastic	450	LF	Annex - Rooms 228, Womens 2nd Floor Faculty Lounge, West Office Corridor and		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
55	Tan Linoleum	800	SF	Annex - Childcare Room, Rm 133		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	No Change]							
Comments:					_							
2017 - Spring	g: No Change				-							
Comments:	V											
2018 - Spring	g : No Change				1							
Comments:	g . No Change				-							
]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
1,,,,,,	Waterial Becompiler	Quantity	Units	Material Education	Туре	Category	Thabia	Туре	Quantity	Units	Change in Acces	oment category
56	Tan Linoleum, Mastic	800	SF	Annex - Childcare Room, RM 133		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	No Change				1							
Comments:	V											
2017 - Spring	g: No Change				1							
Comments:	g. No Change				-							
	N. O.				1							
Comments:	g : No Change				-							
Comments.					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessn	ment Category
57	Brown Baseboard	200	LF	Annex - Childcare Room and YMCA Office		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	No Change				7							
Comments:	<u> </u>]							
2017 - Spring	g: No Change				-							
Comments:												
2018 - Spring	g : No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessn	ment Category
58	Brown Baseboard Mastic	200	LF	Annex - Childcare Room and YMCA Office		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	No Change				7							
Comments:	V				1							
2017 - Spring	g: No Change				-							
Comments:												
2018 - Sprine	g : No Change				-							

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
59	Blue Linoleum	300	SF	Annex - Childcare Room		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: I	No Change]							
Comments:												
2017 - Sprin	g: No Change				-							
Comments:												
2018 - Sprin	g : No Change				1							
Comments:												
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
60	Blue Linoleum Mastic	300	SF	Annex - Childcare Room		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: I	No Change				1							
Comments:	V											
2017 - Sprin	g: No Change				1							
Comments:	J J											
2018 - Sprin	g : No Change				-							
Comments:	<u> </u>]							
					_							

HA No

					. 71			. 7 -				
61	Tan Baseboard	1200	LF	Annex - Rooms 224, 225, 230, 231, 239, 122, 123, 126, 135, 136, 134, Infant Room		Miscellaneous	No	None	0		YES	X NO
2017 - Fall	I: No Change]							
Comments	Ţ											
2017 - Spr	ring: No Change											
Comments	3:											
2018 - Spr	ring : No Change											
Comments	S:											
					I							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
62	Tan Baseboard Mastic	1200	LF	Annex - Rooms 224, 225, 230, 231, 239, 122, 123, 126, 135, 136, 134, Infant Room		Miscellaneous	No	None	0		YES	X NO
2017 - Fall	I: No Change]							
Comments	Ţ											
2017 - Spr	ring: No Change											
<u>-0 Opi</u>	ing. 110 Chango				4							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Comments:

Comments:

2018 - Spring : No Change

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
63	2x4 Ceiling tile	304571	SF	Throughout main/annex building		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asser	ssment Category
64	blue carpet	1500	SF	main bldg social room		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change				7							
Comments:	J											
2017 - Spring	g: No Change											
Comments:	g. 140 Chango											
2018 - Spring	g : No Change											
Comments:	g . No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos	Material	Friable	Damage	Damage Quantity	Damage Units	Change in Asse	ssment Category
		Quantity	UTIILS		Туре	Category		Туре	Quantity	UTIILS		
65	Blue Carpet Mastic	1500	SF	Main Building- Social Room		Miscellaneous	No	None	0		YES	X NO
2017 - Fal	l: No Change				7							
Comments	S:											
2017 - Spi	ing: No Change				1							
Comments												
2018 - Spi	ing : No Change				+							
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
66	Beige linoleum	2500	SF	main building room 211, 307, 308, 310, 310A		Miscellaneous	No	None	0		YES	X NO
2017 - Fal	l: No Change				7							
Comments												
2017 - Spi	ing: No Change				+							
Comments												
2018 - Spi	ing : No Change				=							
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
67	vibration collar	25	LF	annex mechanical rm		TSI	Yes	None	0		YES	X NO
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:					_							
	j : No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
75	12 x 12 lt. Vanilla VFT	4000	SF	Lunchroom		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												
	j : No Change											
Comments:					_							

HA No

76	TSI on HVAC ducts	60	LF	Annex 2nd Floor Fan Room	TSI	Yes	None	0	YES	X NO
2017 - Fall: N	lo Change									
Comments:										
2017 - Spring	g: No Change									
Comments:										
2018 - Spring	g : No Change									
Comments:										

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	Harp packed fittings on fibergalss insulated pipes	50	LF	Auto Shop		TSI	Yes	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

78	Linoleum and associated adhesive	3600	SF	206, 207, 209, 306, 310, 205A, 211	Miscellaneous	No	None	0	YES	X NO
2017 - Fall: N	lo Change									
Comments:	Ü									
2017 - Spring	ı: No Change									
Comments:	J									
2018 - Spring	ı : No Change									

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Ī	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	79	12x12 beige VFT/12x12 brown VFT checkere w/glue	1000	SF	238 and 239		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

		Quantity	Units		Туре	Category		Туре	Quantity	Units	<u></u>	
80	Plaster	304571	SF	Throughout Main Building		Surface	No	None	0		YES	X NO
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	g. 110 Onango											
	g : No Change											
Comments:												
LIA NI-	Maradal Basadaria	Matadal	I Maria dal	Material Landin	A -11	NA-1-2-1	Legan	D	D	D	Observation Asse	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
81	Plaster	25000	SF	Throughout Annex Building		Surface	No	None	0		YES	X NO
2017 - Fall: N	No Change											
Comments:	io onango											
2017 Carina	a. No Chango											
	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:	· · · · · ·											

Material

Friable

Damage

Damage

Damage

Change in Assessment Category

Material Material Location

HA No

Material Description

Material

82	12x12 Orange and White Floor Tile	100	SF	Main Building - Engineer's Office	Miscellaneous	No	None	0	YES	X NO
2017 - Fall	: No Change									
Comments	:									
2017 - Spri	ng: No Change									
Comments	:									
2018 - Spri	ng : No Change									
Comments	:									

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
83	12 x 12 Orange and White Floor Tile Mastic	100	SF	Main Building - Engineer's Office		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

84	12x12 Orange Floor Tile	200	SF	Main Building - Cafeteria Office		Miscellaneous	No	None	0		YES	X NO
2017 - Fal	I: No Change				1							
	· ·				_							
Comment	S:											
2017 - Sp	ring: No Change											
Comment	S:											
2018 - Sp	ring : No Change]							
Comment	s:											
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
	material Decemption	Quantity	Units	material Eccation	Туре	Category		Туре	Quantity	Units		omoni Galogoly
0.5	12x12 Orange Floor Tile			Main Building - Cafeteria			1	1				
85	Mastic	200	SF	Office		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Material

Quantity

Material

Units

Office

Material Location

HA No

Material Description

Mastic

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
86	12x12 Light Vanilla Floor Tile Mastic	4000	SF	Main Building - Lunchroom		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:	.											
2018 - Spring	ı : No Change											
Comments:	,											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
87	Carpet Mastic	5000	SF	Main Building - Conference Room		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	ı: No Change											
Comments:	J. 140 Ondrige											
2019 Spring	ı : No Chango											
Comments:	j : No Change											
Comments.					\dashv							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
88	Linoleum	700	SF	Room 211		Miscellaneous	No	None	0		YES	X NO
	: No Change											
Comments) :											
2017 - Spr	ing: No Change											
Comments												
2018 - Spr	ing : No Change											
Comments	· ·											
			_	_	1	_	_	•	•			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
89	Lab counter-tops	1400	SF	Rms 310, 308, 307, 306, 206, and 211 - Main Bldg		Miscellaneous	No	None	0		YES	X NO
2017 - Fall	: No Change											
Comments												
0047 0	in an Nia Ohanana											
Comments	ing: No Change											
Comments) .				1							
2018 - Spr	ing : No Change											

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
90	9X9 gray with white streaks, VFT	700	SF	Rm 311 - Main Bldg		Miscellaneous	No	None	0		YES	X NO
2017 - Spri	ing: No Change											
Comments	:											
2017 - Fall	: No Change											
Comments												
2018 - Spri	ing : No Change											
Comments	· ·											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
91	9X9 gray with white streaks, Mastic	500	SF	Rm 311 - Main Bldg		Miscellaneous	No	None	0		YES	X NO
2017 - Fall	: No Change							•				
Comments												
2017 - Spri	ing: No Change											
Comments												
0040 0												
	ing : No Change											
Comments): :											

		Quantity	Units		Type	Category		Type	Quantity	Units		
92	12" X 12" light cream mixed speckled, VFT	950	SF	Rms 205, 105A, B, C, D, E, and F - Main Bldg		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N Comments:	o Change											

Material

Friable

Damage

Damage

Damage

Change in Assessment Category

2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Material Material Location

Material Description

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
93	12" X 12" light cream mixed speckled, Mastic	950	SF	Rms 205, 105A, B, C, D, E, and F - Main Bldg		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Units Units	Change in Assessment Categ	jory
94	12" X 12" vanilla mixed speckled, VFT	1300	SF	Rms 300 and 207, elevator vestibule - Main Bldg		Miscellaneous	No	None	0		YES X NO	
2017 - Fall: N	lo Change	•	-]			•				

2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
95	12" X 12" vanilla mixed speckled, Mastic	1300	SF	Rms 300 and 207, elevator vestibule - Main Bldg		Miscellaneous	No	None	0		YES X NO

-	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

96	12" X 12" white with blue specks, VFT	550	SF	Rm 209 - Main Bldg		Miscellaneous	No	None	0		YES	X NO
2017 - Spi	ring: No Change											
Comments												
2017 - Fal	II: No Change											
Comments	S:											
	ring : No Change											
Comments	S:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
97	12" X 12" white with blue specks, Mastic	550	SF	Rm 209 - Main Bldg		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

98	12" X 12" light tan with streaks, VFT	2800	SF	1st floor corridor - 1939 Bldg	Miscellaneous	No	None	0	YES	X NO
2017 - Fall: N	lo Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Spring	ı : No Change									
Comments:		•								

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99	12" X 12" light tan with streaks, Mastic	2800	SF	1st floor corridor - 1939 Bldg		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

100	2' X 4' ceiling tile, white with pin-holes	4100	SF	Throughout 1939 Bldg		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change]							
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
101	Terrazo	2000	SF	Stairwell and Baseboard - 1939 Bldg		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change]							
Comments:	V											
2017 - Spring	g: No Change											
Comments:	, <u> </u>											
2018 - Spring	g : No Change											
Comments:	· ·											

Category

Asbestos

Type

Damage

Type

Damage

Quantity

Damage

Units

Friable

HA No

Material Description

Material

Quantity

Material

Units

Material Location

		Quantity	Units		Type	Category		Type	Quantity	Units	
102	Plaster	17000	SF	Throughout 1939 Bldg		Surface	No	None	0		YES X NO
2017 - Spri	ng: No Change	•]	•					
Comments	:				_						
2017 - Fall	: No Change				<u> </u>						
Comments	:				_						
	ng : No Change										
Comments	:				1						
					1						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	Air Cell	100	LF	1939 Bldg: boys bathroom in locker room, basement vault, boiler room		TSI	Yes	None	0		YES X NO
					1						

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

Material

Material Description

HA No

Material

Material Location

104	2' X 4' ceiling tile	10000	SF	Throughout Annex		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	No Change				7							
Comments:	<u> </u>]							
2017 - Spring	g: No Change				_							
Comments:]							
2018 - Spring	g : No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
105	12" X 12" light purple mixed speckled, VFT	400	SF	Lobby to gym (Annex)		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	No Change				7							
Comments:	<u> </u>]							
2017 - Spring	g: No Change				<u> </u> 							

Category

Asbestos

Type

Damage

Type

Damage

Quantity

Damage

Units

Friable

HA No

Material Description

2018 - Spring : No Change

Comments:

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
106	12" X 12" light purple mixed speckled, Mastic	400	SF	Lobby to gym (Annex)		Miscellaneous	No	None	0		YES	X NO
2017 - Spring	: No Change											
Comments:					_							
2017 - Fall: N	o Change				_							
Comments:	-											
2018 - Spring	: No Change				-							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
107	12X12 Lt. Vanilla floor tile Mastic	4000	SF	Main Bldg. Lunchroom		Miscellaneous	No	None			YES	X NO
2017 - Fall: N	o Change				7							
Comments:	J											
2017 - Spring	· No Change				-							
Comments:	. No Gridings											
2018 - Spring	· No Change				-							
Comments:	. 140 Ondinge				-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
108	Spray On	1200	SF	1st and 2nd Floor Entrance and breezeway		Surface	Yes	None	0		YES	X NO
2017 - Fall: N	No Change]							
Comments:												
2017 - Spring	g: No Change											
Comments:	J											
2018 - Spring	g : No Change											
Comments:	g . He Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
109	Lab Tables	400	SF	Annex 229		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	No Change				7							
Comments:	J											
2017 - Spring	g: No Change											
Comments:	g. 140 Ondrigo											
2019 Spring	g : No Change											
Comments:	g . No Change											
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
А	Tank Insulation-material removed.			Annex Boiler Room							X YES	NO
2017 - Fall: A	bated]							
Comments:10)/2017]							
2017 - Spring	: No Change											
Comments:					 							
2018 - Spring	: No Change											
Comments:					 							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
A(#2)	Aircell Pipe Insulation- material removed.			Main Building Mechanical Area, Classrooms, Lunchroom							YES	X NO
2017 - Fall: N	o Change]							
Comments:	<u> </u>											
2017 - Spring	: No Change				-							
Comments:												
2018 - Spring	: No Change				-							
Comments:	J]							
					j							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
В	Boiler Breaching-material abated.			Annex Boiler Room							YES	X NO
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	; No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
С	Cardboard Insulation- material abated.			Main Building Classrooms and Mechanical Areas							YES	X NO
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	o Change											
0040 0 1	N. Observe											
Comments:	g : No Change											
Comments.												

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
D	Pipe Fitting Insulation	130	LF	Throughout Annex		TSI	Yes	None	8		YES	X NO
2017 - Fall: N	lo Change]							
Comments:												
2017 - Spring	j: No Change				1							
Comments:												
2018 - Spring	j : No Change											
Comments:					1							
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
D(#2)	Cementitious Joints on Cardboard-material abated.			Main Building, Classrooms, Mechanical Area							YES	X NO
2017 - Spring	j: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
	j : No Change											
Comments:												
					_							

Friable

Material

Asbestos

Damage

Damage

Damage

Change in Assessment Category

Material Material Location

HA No

Material Description

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessr	ment Category
F	Joints and Elbows on Fiberglass Runs-abated			Main Building, Classrooms, Mechanical Areas, 1st, 2nd, and 3rd Floor		TSI					YES		X NO
2017 - Fall: I	No Change				7								
Comments:					1								
2017 - Sprin	g: No Change												
Comments:					1								
2018 - Sprin	g : No Change												
Comments:													
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessr	ment Category
G	Pre-Form Pipe Insulation- abated.			Main Building							YES		X NO
2017 - Fall: I	No Change				7								
Comments:	<u> </u>												
2017 - Sprin	g: No Change				-								
Comments:	 												

2018 - Spring : No Change

Comments:

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
Н	Elbows on Pre-Formed Pipe Insulation-abated			Main Building							YES	X NO
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:	J											
2018 - Spring	g : No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
HA-1000	1'x1' white ceiling tile with random and reg.holes NOT OBSERVED	1000	SF	Kitchen NOT OBSERVED		Miscellaneous	Yes	None	0		YES	X NO
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:	J											
2018 - Sprine	g : No Change											
Comments:	<u> </u>											

Material

Friable

Damage

Damage

Damage

Change in Assessment Category

Material Material Location

HA No

Material Description

Material

HA-1001	Glue for 1'x1' white ceiling tile with holes NOT OBSERVED	1000	SF	Kitchen NOT OBSERVED	Miscellaneous	No	None	0	YES	X NO
2017 - Spring Comments:	: No Change					•				
2017 - Fall: N Comments:	o Change									
2018 - Spring Comments:	: No Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-1002	Mudded Pipe Fittings	20	LF	1908 bldg boiler room		TSI		None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
HA-1003	Mudded Pipe Fittings	30	LF	1953 bldg AHU by GYM, GYM		TSI	No	None	0		YES	X NO
2017 - Fall: No Change												
Comments:												
2017 - Spring: No Change												
Comments:					 							
2018 - Spring	: No Change											
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
N	Cardboard Pipe Insulation- abated.			Main Building Mechanical Room							YES	X NO
2017 - Fall: No Change]							
Comments:]							
2017 - Spring: No Change					-							
Comments:]							
2018 - Spring : No Change					-							
Comments:					1							
]							

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
0	Cementitious Joints-abated.			Main Building Mechanical Rooms		TSI					YES	X NO
2017 - Fall: N	lo Change]							
Comments:												
2017 - Spring	: No Change											
Comments:												
	ı : No Change											
Comments:												
					I							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
Р	Cementitious Fittings on Fiberglass-abated.			Main Building Unexcavated Area and Boiler Room							YES	X NO
2017 - Fall: N	lo Change]							
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
					J							

Material

Friable

Damage

Damage

Damage

Change in Assessment Category

Material Material Location

HA No

Material Description

Material

X	Paper Wrap Pipe Insulation-abated.			Main Building throughout 1st Floor Corridor Above Plaster Celing							YES	X NO
		•	•	•	<u>. </u>	•	•	•	•			
2017 - Fall: No Change												
Comments:												
2017 - Spring	a: No Change											
2017 - Spring: No Change												
Comments:												
2018 - Spring	g : No Change											
Comments:												
·	·			·								
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Friable

Damage

Type

Type

Damage

Quantity

Quantity

Damage

Units

Units

YES

X NO

Y	Insulation-abated.	Plaster Celing	
2017 - S	Spring: No Change		
	Fall: No Change		
Comme			
2018 - \$	Spring : No Change		
Comme	ents:		

Units

Material

Units

Material

Quantity

Quantity

Material Location

Main Building Throughout

HA No

Material Description

Joints on Cardboard Pipe

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Bowen High School
Date: 12/12/2018
·
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.