Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

46641

Oracle Unit:

Richard T Crane Medical Preparatory HS

School:

Building ID: Address: 2245 W. Jackson Region: Mail Room: Asbestos Surveyor: Ruiz, Luis X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/10/2019 Email Address: silver0392@gmail.com A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Other E-mail Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar HA No Material Description Material Location Friable Damage Change in Assessment Category Material Asbestos Material Damage Damage Quantity Units Category Quantity Type Type Throughout Facility (Auto YES X NO Shop Hall, Room next to 001 12" x 12" Beige Floor Tile 7000 SF Miscellaneous No None 0 the pool, engineer office, hall outside 260) 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments:

1270

001M	12" x 12" Beige Floor Tile Mastic	7000	SF	Throughout Facility (Auto Shop Hall, Room next to the pool, engineer office, hall outside 260)	Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change									
Comments:										
2017 - Fall:	No Change									
Comments:										
2017 - Sprii	ng: No Change									
Comments:										
2018 - Fall:	No Change									
Comments:										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

Throughout Facility (Auto

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
002A	9" x 9" Reddish Brown Floor Tile			Corridors		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

002A-M	9" x 9" Reddish Brown Floor Tile Mastic			Corridors		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:					1							
2017 - Spring	g: No Change				-							
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
002B	9" x 9" Black Floor Tile			Corridors		Miscellaneous		None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2018 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

002B-M	9" x 9" Black Floor Tile Mastic			Corridors		Miscellaneous		None			YES	X NO
2016 Fall N	la Changa				1							
2016 - Fall: N	io Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	-											
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					1							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Туре	Quantity	Units		
	+	1					1			1		

Type

Material

Category

Miscellaneous

No

None

0

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Library 207

3000

SF

HA No

003

Comments:

2016 - Fall: No Change

Material Description

Red Carpet Mastic

Material

Quantity

Material

Units

YES

X NO

004	Brown Carpet Mastic			Rooms 321, 206, and 413 Office, Police, and Washroom		Miscellaneous					YES	X NO
2016 Falls	No Changa				٦							
2016 - Fall:												
Comments:												
2017 - Fall:	No Change											
Comments:	-											
2017 - Sprir	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
l				1	71	3-17		211 -				

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

0

None

Damage

Units

2000

SF

Gymnasium

HA No

005

2016 - Fall: No Change

Material Description

Wood Floor Underlayment

Material

Units

Material

Quantity

Material Location

Rooms 321, 206, and

Change in Assessment Category

X NO

YES

											l	
006	Matting			Running track		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:					= - -							
2017 - Spring	ı: No Change				-							
Comments:	,				1							
2017 - Fall: N	lo Change				1							
Comments:					1							
2018 - Fall: N	lo Change											
Comments:	-				1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
006M	Adhesive Beneath Matting			Running Track		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

007	Painted Concrete - NOT AHERA					Surface					YES	X NO
2016 - Fall	: No Change											
Comments												
2017 - Fall	: No Change											
Comments	:											
	ng: No Change											
Comments	:	_										
	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
800	Black/Gray Carpet Mastic			Clinic		Miscellaneous					YES	X NO
2016 - Fall	: No Change				7							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

009	Grayish Brown Ceramic Tile Grout			Washrooms		Miscellaneous					YES	X NO
2016 - Fall:	No Chango				1							
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprii	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	·											
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
11/(140	Material Description	Quantity	Units	Waterial Education	Type	Category	THADIO	Type	Quantity	Units	Change in 7.0000	oment oategory
		+ '			7.	,		1	+	1	<u> </u>	
010	2' x 4' Random Dot Lay In			Throughout Facility		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

011	Plaster Patch	100	SF	Outside of Cafeteria		Surface	Yes	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:]							
2017 - Fall:	No Change				1							
Comments:	<u> </u>											
2017 - Sprir	ng: No Change]							
Comments:					_							
2018 - Fall:	No Change											
Comments:					_							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
012	1' x 1' Ceiling Tile			Pool Area		Miscellaneous					VES	V NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

Material

Quantity

Material

Units

2016 - Fall:	No Change										
Comments											
2017 - Fall:	No Change										
Comments	•										
2017 - Spri	ng: No Change										
Comments	•										
2018 - Fall:	No Change										
Comments	•										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

Yes

Yes

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

HA No

013

014

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

1' x 1' Fissured Ceiling Tile

1' x 1' Smooth Ceiling Tile

Material

Quantity

8000

Material

Units

SF

SF

2000

Material Location

Gym & Library

Canteen & Kitchen

Change in Assessment Category

X NO

X NO

YES

YES

015	1' x 1' Dot Ceiling Tile	1500	SF	Band & Canteen		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	<u> </u>											
2017 - Fall:	No Change											
Comments:												
	ıg: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
016	Zinc			First Floor Hall		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

017	2' x 2' Ceiling Tile	200000	SF	Pool, Throughout Class Rooms and Hallways		Miscellaneous	Yes	None	0		YES	X NO
0010 = 11 1					٦							
2016 - Fall: N	No Change											
Comments:												
]							
2017 - Fall: N	No Change											
Comments:]							
2017 - Spring	g: No Change											
Comments:					1							
2018 - Fall: N	No Change											
Comments:	•				1							
					1							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

Yes

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

Change in Assessment Category

X NO

YES

	-	_		
2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				<u> </u>

2' x 2' Lay In Ceiling Panels 500

Quantity

Units

Clinic (110)

SF

Material

Quantity

Material

Units

Material Location

HA No

019

Material Description

	·	Quantity	Units		Type	Category		Туре	Quantity	Units		
020	Paint (Not Textured)			Throughout Facility		Miscellaneous					YES	X NO
2016 - Fall	: No Change											
Comments	i:											
2017 - Fall	: No Change											
Comments	:											
2017 - Spr	ing: No Change											
Comments	SI:											
	: No Change											
Comments	SI:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
021	Wall Plaques			Band Practice Room - Removed Before 1998							YES	X NO
2016 - Fall	: No Change											
Comments	<u> </u>											

Material

Friable

Damage

Damage

Damage

HA No

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material Description

Material

Material

Material Location

022	4" Baseboard			Throughout Original Building		Miscellaneous					YES	X NO
2016 - Fall	: No Change				1							
Comments												
2017 - Spri	ng: No Change				-							
Comments			_									
2017 - Fall	: No Change				-							
Comments:												
2018 - Fall	: No Change				-							
Comments	•											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
022M	4" Baseboard Adhesive			Throughout Original		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

Material

Quantity

Material

Units

023M	6" Baseboard Mastic			Throughout Original Building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	3.											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:					_							
					<u></u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
23	6" Baseboard			Throughout Original		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

024	90 de. Baseboard			Auditorium		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				1							
Comments:					_							
	g: No Change]							
Comments:					-							
2017 - Fall: N	No Change											
Comments:		1										
	2018 - Fall: No Change											
Comments:					_							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
024M	90 de. Baseboard Mastic			Auditorium		Miscellaneous					YES	X NO
2016 - Fall: N	No Change]										

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Units

Material

Quantity

Material Location

025	4" Brown Baseboard			New Addition Gym and Corridor		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				1							
Comments:	to onange											
2017 - Sprine	g: No Change				_							
Comments:	grave canalys											
2017 - Fall: N	No Change				1							
Comments:												
2018 - Fall: N	No Change]							
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
025M	4" Brown Baseboard Mastic			New Addition - Gym and Corridor		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

026	6" Brown Baseboard			Hall and Room 106		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:					1							
2017 - Spring	: No Change				-							
Comments:					-							
2017 - Fall: N	lo Change				-							
Comments:												
2018 - Fall: N	lo Change				-							
Comments:					1							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
026M	6" Brown Baseboard Mastic			Hall and Room 106		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

2016 - Fall: No Change

Material Description

027	Interior Brick			Building		Miscellaneous					YES	X NO
2016 - Fall	No Change				7							
Comments:												
2017 - Sprii	ng: No Change				1							
Comments:												
2017 - Fall:	No Change											
Comments:					_							
2018 - Fall:	No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
027M	Interior Brick Mortar			Throughout Original		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

028	Cinder Block			Throughout Original Building		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change				_							
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
028M	Cinder Block Mortar			Throughout Original		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

029	Glazed Brick			Original Building - Gym, 2nd Floor Fan Room		Miscellaneous					YES	X NO
2016 - Fall:	No Change				1							
Comments:					1							
2017 - Sprin	g: No Change											
Comments:	grine enamge											
2017 - Fall:	No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
029M	Glazed Brick Mortar			Original Building - Gym and 2nd Floor Fan Room		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

Page 21

030	Water Tank			Pool Maintenance Area		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:]							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:				1								
2018 - Fall: N	lo Change											
Comments:					-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
031	Terrazzo Basins			1st, 2nd & 3rd Floor Maintenance Rooms		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

Comments:

Material Description

Material

Units

Material

Quantity

Material Location

032	White Terrazzo Flooring			1st, 2nd, and 3rd Floor Corridors		Miscellaneous					YES	X NO
2016 - Fall: N	No Change]							
Comments:	Ü											
2017 - Fall: N	No Change											
Comments:	10 0ago											
2017 - Sprine	g: No Change											
Comments:					= 							
2018 - Fall: N	No Change											
Comments:					1							
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
033	Red Border Terrazzo			Corridors		Miscellaneous					YES	X NO
2016 - Fall: N	No Change		•]	•	•					
Comments:	J											

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material Description

Material

Units

Material

Quantity

Material Location

034	Multi-Brown Ceramic Tile Grout			4th Floor Women's Washroom		Miscellaneous					YES	X NO
2016 - Fall	: No Change											
Comments												
2017 - Fall	: No Change											
Comments												
2017 - Spr	ing: No Change											
Comments	<u> </u>											
2018 - Fall	: No Change											
Comments	S:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
035	Orange Carpet Mastic			Rooms 307, 310, 313, and 413		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Units

Material Quantity Material Location

and 413

036	Gray Carpet Mastic			Principal's Office, Main Office, and Security		Miscellaneous					YES	X NO
2016 - Fa	I: No Change											
Comment												
	I: No Change											
Comment	S:											
2017 - Sp	ring: No Change											
Comment												
2018 - Fa	I: No Change											
Comment												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
037	Cementitious Gaskets			2nd Floor Fan Room		TSI					YES	X NO
2016 - Fa	I: No Change	•	•		<u>. </u>	•	•	•		•		

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

038	Ceiling Tile Under Metal 1' x 1' Ceiling Tile			Above Pool Bleachers		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				7							
Comments:	go											
2017 - Fall: N	No Change				_							
Comments:												
2017 - Spring	g: No Change				1							
Comments:												
2018 - Fall: N	No Change				_							
Comments:]							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
039	2' x 4' Random Dot Replacement Ceiling Panels	Quantity	Office	Fan Room #2	Турс	Miscellaneous		Турс	Quantity	Office	YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
040	Transite Sink Tops	200	SF	Rooms 315, 316, 317, 201, 210, 215, and 216		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
041	Black Material Coating Sink Bottoms	14	SF	Rooms 315, 316, 317, 201, 210, 215, and 216		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

042	Lab Table Tops			Rooms 300, 301, 315, 316, and 317		Miscellaneous					YES	X NO
2016 - Fall: N	o Change				1							
Comments:					1							
2017 - Fall: N	o Change				_							
Comments:					-							
2017 - Spring	: No Change											
Comments:					-							
2018 - Fall: N	o Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
043	Terrazzo Flooring			New Addition		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

044	Blue Carpet Mastic			Auditorium		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>]							
2017 - Fall: No Change												
Comments:												
2017 - Spring	j: No Change											
Comments:					 							
2018 - Fall: N	lo Change											
Comments:					1							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
045	Pink Carpet Mastic			Rooms 213 and 214, and Upper Library	75-	Miscellaneous		77-			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Units

Material

Quantity

Material Location

	·	Quantity	Units		Туре	Category		Туре	Quantity	Units		
046	Cinder Block			New Addition - Gym		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Spri	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
047	Cinder Block Mortar			New Addition - Gym		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:												

Material

Damage

Damage

Damage

Friable

HA No

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material Description

Material

Material

Material Location

048	Adhesive Behind Mirrors	100	SF	Washrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	.											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
049	Gray and White Linoleum			Rooms 201, 217, 300, and 301		Miscellaneous		None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

YES

		Quantity	Units		Туре	Category		Type	Quantity	Units		
050	Grey and White Linoleum Mastic	3375	SF	Rooms 200, 201, 217, 300, and 301		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	II: No Change											
Comment	Comments:				-							
2017 - Fall: No Change												
Comment	is:											

Material

Friable

Damage

Damage

2017 - Spring: No Change

Material Material Location

Material Description

2018 - Fall: No Change

Comments:

Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
051	12"x12" Light Gray Floor Tile	1900	SF	Room 106		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Damage Change in Assessment Category

052	12" x 12" Light Gray Floor Tile Mastic	1900	SF	Room 106		Miscellaneous	No	None	0	YES	X NO
2016 - Fall	: No Change]						
Comments]						
2017 - Fall	: No Change										
Comments	:] -						
2017 - Spr	ing: No Change]						
Comments	X				1						
2018 - Fall	: No Change]						

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
053	Fume Hood Interior Backing	25	SF	Rooms 316 and 317		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

054	Kiln Gasket			Room 103		TSI					YES	X NO
2016 - Fall:	No Change]							
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Spring: No Change					_							
Comments:					_							
	No Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
055	Non Skid Strips			2nd Floor Ramp		Miscellaneous					YES	X NO
2016 - Fall:	No Change											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

056	Interior Caulk	20	LF	Pool Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>				1							
2017 - Fall: N	lo Change											
Comments:					- -							
2017 - Spring	: No Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
057	Drywall			Cat Walk		Surface					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

058	Doors	320	SF	Throughout Facility		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:					1							
2017 - Fall:	No Change											
Comments:					-							
	ng: No Change				_							
Comments:					-							
2018 - Fall:	No Change											
Comments:					4							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
059	Block			New Addition		Surface					VES	Y NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Insulation Inside of Fire

Material

Quantity

Material

Units

Material Location

060	Block Mortar			New Addition		Surface					YES	X NO
2016 - Fall:	No Change				7							
Comments												
2017 - Fall:	No Change											
Comments	:				4							
	ng: No Change											
Comments	:				4							
2018 - Fall:	No Change											
Comments	:				_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
062	Black Duct Sealant	150	LF	Tunnel		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

063	Chalkboard Adhesive			Running Track		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	•											
2017 - Fall: N	lo Change]							
Comments:												
2017 - Spring	g: No Change]							
Comments:												
2018 - Fall: N	lo Change				-							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
064	12" X 12" Brown Speckled Floor Tile			Rooms 426 and 430		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

064M	12" x 12" Brown Speckled Floor Tile Mastic			Rooms 426 and 430		Miscellaneous					YES	X NO
2016 - Fall: N	lo Chongo]							
	io Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u>-</u>											
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					•							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
-		Quantity	Units		Туре	Category		Туре	Quantity	Units	J J	
065	12" x 12" Black Floor Tile			Kitchen Office		Miscellaneous		None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2018 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

065M	12" x 12" Black Floor Tile Mastic			Kitchen Office		Miscellaneous		None			YES	X NO
2016 - Fall: I	No Change											
Comments:	10 Change											
2017 - Fall: I	No Change				-							
Comments:	To Change											
2017 - Sprin	g: No Change				-							
Comments:					=							
2018 - Fall: I	No Change				-							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
066	12" x 12" Dark Brown Floor			Kitchen Office		Miscellaneous		None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material Quantity

Material Location

HA No

Material Description

066M	Tile Mastic			Kitchen Office		Miscellaneous		None			YES	X NO
2016 - Fall:	No Change				1							
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change											
Comments:					_							
2018 - Fall:	No Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
067	12" x 12" Pink Floor Tile			Kitchen Pump Room		Miscellaneous		None			VES	Y NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2018 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

12" x 12" Dark Brown Floor

Material

Quantity

Material

Units

Material Location

067M	12" x 12" Pink Floor Tile Mastic			Kitchen Pump Room		Miscellaneous		None			YES	X NO
2016 - Fall:	No Change				1							
Comments:												
2017 - Fall:	No Change				_							
Comments:	U]							
2017 - Sprir	ng: No Change				_							
Comments:												
2018 - Fall:	No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

Damage

Quantity

0

Damage

Units

1800

Material

Quantity

Material

Units

SF

Material Location

Rooms 105, 315, 316,

HA No

068

Material Description

12" x 12" Gray Floor Tile

YES

X NO

068M	12" x 12" Gray Floor Tile Mastic	3600	SF	Rooms 105, 315, 316, and 317	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
2017 - Fall: N	lo Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:	io onange									
Commonto.										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
069	12" x 12" Cream Colored Floor Tile	5400	SF	Rooms 433, 435, 401, 443, 433, 440, 441, 420, 416, 414b, 437, 438, 439, 119, 426, 430, 402, 404, 432, 427, 431, 429, 450, 424, 419, 417, 410, 436, 153, 425, 421, 415, 414A, 400, 119b, 415, 103, 101, 115, 116, 117, 118, 406, 409, 420, 422, and 423, and Stage		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
069M	12"x12" Cream Colored Floor Tile Mastic	5400	SF	Rooms 433, 435, 401, 443, 433, 440, 441, 420, 416, 414b, 437, 438, 439, 119, 426, 430, 402, 404, 432, 427, 431, 429, 450, 424, 419, 417, 410, 436, 153, 425, 421, 415, 414A, 400, 119b, 415, 103, 101, 115, 116, 117, 118, 406, 409, 420, 422, and 423, and Stage		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
070	9" x 9" Tan Floor Tile w/Brown Streaks			3rd Floor Southeast Storage		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

070M	9" x 9" Tan Floor Tile w/Brown Streaks Mastic			3rd Floor Southeast Storage		Miscellaneous					YES	X NO
2016 - Fall: I	No Change]							
Comments:	J .				-							
2017 - Fall: I	No Change											
Comments:												
	g: No Change											
Comments:					-							
2018 - Fall: I	No Change											
Comments:					-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
071	Adhesive Backing on Fiberglass Insulation Panels			Hall, Rooms 51A and 51B		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
072	12" x 12" Tan Floor Tile w/White Specks	400	SF	Room 104		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
072M	12" x 12" Tan Floor Tile w/White Specks Mastic	400	SF	Room 104		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

073	Floor Tile Beneath 12"x12" Floor Tile			Room 317		Miscellaneous					YES	X NO
2016 - Fall	No Change											
Comments												
2017 - Spri	ng: No Change				-							
Comments												
2017 - Fall:	No Change											
Comments	:				-							
2018 - Fall:	No Change											
Comments	:				_							
					_1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

0

None

Damage

Units

728

SF

Material

Units

Material Quantity Material Location

Room 317

HA No

073M

Material Description

Mastic on Floor Tile

Beneath 12"x12" Floor Tile

Floor Tile Beneath 12"x12"

Change in Assessment Category

YES

YES

X NO

074	Linoleum (Beneath Carpet)			Room 321		Miscellaneous					YES	X NO
2016 - Fall: N	o Change]							
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	-]							
2018 - Fall: N	o Change											
Comments:	-]							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
074M	Linoleum Mastic			Room 321		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

Comments:

Material Description

Material

Units

Material

Quantity

Material Location

075	Terrazzo			Stairway, 1-2, 2-3, 3-4		Miscellaneous					YES	X NO
2016 - Fall	: No Change											
Comments	:											
2017 - Fall	: No Change											
Comments	:											
2017 - Spr	ing: No Change											
Comments	:											
2018 - Fall	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
076	Material Under Carpet			Room 413		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

076M	Adhesive For Material Under Carpet			Room 413		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				7							
Comments:	J				1							
2017 - Fall: N	No Change											
Comments:												
2017 - Sprin	g: No Change				-							
Comments:												
2018 - Fall: N	No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
077	Interior Brick			New Addition Corridor		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				7							
Comments:					1							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material

Units

Material

Quantity

Material Location

		Quantity	Units		Type	Category		Туре	Quantity	Units		
077M	Interior Brick Mortar			New Addition Corridor		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				7							
Comments:	Ü				1							
2017 - Fall: N	No Change				-							
Comments:												
2017 - Spring	g: No Change											
Comments:					_							
2018 - Fall: N	No Change				_							
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
078	Glazed Brick			Pool Room Walls		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				7							
Comments:												

Material

Friable

Damage

Damage

Damage

HA No

Material Description

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material

Material

Material Location

		Quantity	Units		Type	Category		Type	Quantity	Units		
078M	Glazed Brick Mortar			Pool Room Walls		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	10 Onange											
2017 - Fall: N	No Change											
Comments:												
2047 Corio	n. No Change											
Comments:	g: No Change											
Comments.												
2018 - Fall: N	No Change											
Comments:												
	T		T	T	1		1		T =	T	T	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
	BlackTar on Outside of	Quantity	Office		1,750	Calogory		1,700	Quantity	OTITO		
079	Duct Insulation - Not AHERA			Roof							YES	X NO
2016 - Fall: N	lo Chango											
Comments:	No Change											
Comments.												
2017 - Fall: N	No Change											

Material

Friable

Damage

Damage

HA No

Comments:

Comments:

Comments:

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Material Location

Damage Change in Assessment Category

080	9" x 9" Reddish Brown Floor Tile			ROTC		Miscellaneous		None			YES	X NO
2016 - Fall:	No Change				7							
Comments:	rto Oriango											
2017 - Fall:	No Change				-							
Comments:	go											
2017 - Sprin	ng: No Change				+							
Comments:												
2018 - Fall:	No Change				=							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
081	9" x 9" Reddish Brown			ROTC		Miscellaneous		None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Floor Tile Mastic

Material

Quantity

Material

Units

Material Location

082	Caulk - NOT AHERA			North Main Entrance							YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change				1							
Comments:	:											
2017 - Sprii	ng: No Change											
Comments:	:											
2018 - Fall:	No Change											
Comments:	:											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
000	Interior Transom Window								1.			

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

300

LF

HA No

082

083

Material Description

Exterior Transom Window

Material

Quantity

Material

Units

Material Location

North Main Entrance

North Main Entrance

Change in Assessment Category

X NO

X NO

YES

YES

084	Plaster Soffit	120	SF	South Entrance of New Addition		Surface	Yes	None	0		YES	X NO
2016 - Fal	I: No Change				7							
Comments												
2017 - Spr	ring: No Change				-							
Comments												
2017 - Fal	I: No Change				_							
Comments	S:				1							
2018 - Fal	I: No Change				-							
Comments	S:				1							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
085	Roof Flashing - Layer 1 - NOT AHERA			New Addition Roof							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

086	Roof Flashing - Layer 2 - Not AHERA			New Addition Roof							YES	X NO
2016 - Fall: N	No Change]							
Comments:	10 Ondrigo				-							
0017 0 :												
	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:	10 Onango		-									
0040 5.11	Al- Ol-											
2018 - Fall: N	No Change											
Comments:												
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
087	Roof Flashing - Layer 3 - NOT AHERA			New Addition Roof							YES	X NO
2016 - Fall: N	No Change]							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Units

Material

Quantity

Material Location

088	Roofing Material - NOT AHERA			New Addition Roof							YES	X NO
2016 - Fall: I	No Change				1							
Comments:												
2017 - Sprin	g: No Change				_							
Comments:	<u>g </u>											
2017 - Fall: I	No Change				1							
Comments:	<u> </u>											
2018 - Fall: I	No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
089	Roofing Material - NOT AHERA			Original Building							YES	X NO
2016 - Fall: I	No Change]							
Comments:	<u> </u>				1							

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

HA No

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material Description

Material

Units

Material

Quantity

Material Location

090	AHERA			Original Building		Surface					YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Sprir	ng: No Change											
Comments:					_							
2017 - Fall:	No Change											
Comments:					_							
2018 - Fall:	<u> </u>											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
091	Decorative Columns - NOT AHERA			Roof		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Roof Flashing - NOT

Material

Quantity

Material

Units

Material Location

092	Decorative Column Mastic/Mortar - NOT AHERA			Roof		Miscellaneous					YES	X NO
2016 - Fall	: No Change			<u> </u>	7						•	
Comments	<u> </u>											
2017 - Fall	: No Change				=							
Comments	<u> </u>											
2017 - Spr	ing: No Change				-							
Comments					<u> </u>							
2018 - Fall	: No Change				1							
Comments					-							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
093	Exterior Red Face Brick - NOT AHERA			Roof		Surface					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Decorative Column

Material

Quantity

Material

Units

Material Location

Page 59

094	Mortar - NOT AHERA			Roof		Surface					YES	X NO
2016 - Fall	: No Change				7							
Comments												
2017 - Fall	: No Change				1							
Comments	:											
2017 - Spri	ng: No Change				1							
Comments	:											
	: No Change											
Comments	:				4							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
095	Interior Brick - NOT AHERA			Roof		Miscellaneous					YES	X NO
2016 - Fall	: No Change	<u>'</u>			7							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

096	Interior Brick Mortar - NOT AHERA			Roof		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				1							
Comments:					- - -							
2017 - Fall: N	No Change											
Comments:					1							
2017 - Spring	g: No Change				1							
Comments:			1									
2018 - Fall: N	No Change				=							
Comments:					1							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
097	Roof Caulking - NOT AHERA			New Addition							YES	X NO
2016 - Fall: N	No Change]										
Comments:	J				1							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material

Units

Material

Quantity

Material Location

098	Roofing Material - NOT AHERA			New Addition		Miscellaneous					YES	X NO
2016 - Fal	I: No Change]							
Comment												
2017 - Fal	I: No Change											
Comment												
2017 - Sp	ring: No Change											
Comment												
2018 - Fal	I: No Change											
Comment	<u>~</u>											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
099	Brick Mortar - NOT AHERA			New Addition		Miscellaneous					YES	X NO
2016 - Fal	I: No Change	1										
Comment					1							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material

Units

Material

Quantity

Material Location

100	Exterior Window Caulk - Not AHERA			Building Exterior		Miscellaneous					YES	X NO
2016 - Fall:	No Change]							
Comments:	V				1							
2017 - Fall:	No Change											
Comments:					=							
	ng: No Change				-							
Comments:					-							
2018 - Fall:	<u> </u>											
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
101	Exterior Door Caulk - NOT AHERA			Building Addition Exterior		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2018 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

103	Tar Paper Over Roof Ducts			Roof NOTAHERA							YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Fall:	No Change											
Comments:					_							
	ng: No Change											
Comments:												
2018 - Fall:	<u> </u>											
Comments:					1							
					<u></u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
104	12" x 12" Beige Floor Tile w/Brown Streaks	900	SF	Room 415		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

-

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

2016 - Fall: N	No Change										
Comments:											
2017 - Fall: No Change											
Comments:											
2017 - Spring	g: No Change										
Comments:											
2018 - Fall: N	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

Material

Units

SF

Material Quantity

900

Material Location

Room 415

Room 416

HA No

105

106

Material Description

12" x 12" Beige Floor Tile

Floor Tile Beneath 12"x12"

w/Brown Streaks Mastic

Change in Assessment Category

X NO

X NO

YES

YES

2016 - Fall:	No Change										
Comments:											
2017 - Fall:	2017 - Fall: No Change										
Comments:	1										
2017 - Spri	ng: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
					<u> </u>						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
	·	Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Damage

Type

None

None

Damage

Quantity

0

Damage

Units

HA No

107

108

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Floor Tile Mastic

Floor Tile Beneath 12"x12"

Floor Tile Beneath 12"x12"

Material

Quantity

750

Material

Units

SF

Material Location

Room 416

Room 421

Change in Assessment Category

X NO

X NO

YES

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
109	Floor Tile Beneath 12"x12" Floor Tile Mastic	750	SF	Room 421		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change												
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring: No Change												
Comments:												

2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
110	Floor Tile Beneath 12"x12" Floor Tile	4000	SF	Cafeteria/Lunchroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 67

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
111	Floor Tile Beneath 12"x12" Floor Tile Mastic	2000	SF	Lunchroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change											
Comments:												
2017 - Fall	: No Change											
Comments	:											
2017 - Spr	ng: No Change											
Comments	:											
2018 - Fall	· No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
112	12" x 12" Aqua Floor Tile (Blue linoleum)	400	SF	Room 218		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

113	12" x 12" Aqua Floor Tile Mastic (Blue Linoleum mastic)	400	SF	Room 218		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	No Change										
Comments:											
2017 - Fall: No Change											
Comments:											
2017 - Spring	g: No Change										
Comments:											
2018 - Fall: No Change											
Comments:											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
114	Floor Tile Beneath 12"x12" Floor Tile	1550	SF	Rooms 210 & 212		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
115	Floor Tile Beneath 12"x12" Floor Tile Mastic	1550	SF	Rooms 210 and 212		Miscellaneous	No	None	0		YES	X NO
2016 -	Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
116	Tan Linoleum	2450	SF	Rooms 315-316, 302, 301, 201 storage 215		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
117	Tan Linoleum Mastic	2450	SF	Rooms 315-316, 302, 301, 201 storage 215		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

016 - Fall: No Change	
Comments:	
017 - Fall: No Change	
Comments:	
017 - Spring: No Change	
Comments:	
018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
118	Brown Ceramic Flooring and Grout	8000	SF	1, 2, 3, 4, Floors Boys & Girls Bathrooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

		,			· ·	0 ,		* .	,		
119	Brown Ceramic Flooring Mastic	8000	SF	1, 2, 3, 4, Floors Boys and Girls Bathroom		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change]						
Comments:]						
2017 - Sprir	ng: No Change				_						
Comments:											
2017 - Fall:	No Change]						
Comments:					1						
2018 - Fall:	No Change]						

Material

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
120	2X4 White Ceiling Tile	200000	SF	Throughout School		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
	121	2X4 White Smooth Ceiling Tile	12300	SF	Cafeteria		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: No Change Comments:													

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
124	12" X 12" Off Beige VFT	900	SF	Room 119		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
125	12" X 12" Off Beige VFT Mastic	900	SF	Room 119		Miscellaneous	No	None	0		YES X NO
0040 5 11 11	01	ſ									

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
126	12"X12" Old Blotted Beige VFT	3000	SF	Room 116, 117, 118, Band Hall		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
127	12"X12" Old Blotted Beige VFT Mastic	3000	SF	Room 116, 117, 118, Band Hall		Miscellaneous	No	None	0		YES X NO
					i						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
128	12"X12" New Blotted Beige VFT	29000	SF	Room 116, 117, 118		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	·
<u> </u>	

Page 75

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessmer	nt Category
129	12"X12" New Blotted Beige VFT Mastic	29000	SF	Room 116, 117, 118		Miscellaneous	No	None	0		YES	NO
2016 - Fall: No Change												

016 - Fall: No Change
comments:
017 - Spring: No Change
Comments:
017 - Fall: No Change
Comments:
018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
130	12" X 12" White W/Grey Speckles VFT	500	SF	Gym Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor
131	12" X 12" White W/Grey Speckles VFT Mastic	500	SF	Gym Office		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
132	12" X 12" White W/Brown VFT	500	SF	Choral Room 119		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Ca	tegory
133	12" X 12" White W/Brown VFT Mastic	500	SF	Choral Room 119		Miscellaneous	No	None	0		YES X NO)
2016 - Fall: N	o Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
134	12" X 12" Off White W/Brown VFT	300	SF	Choral room 119 Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

135	12" X 12" Off White W/Brown VFT Mastic	300	SF	Choral Room 119 Office	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	Jo Chango									
2010 - 1 all. 1	NO Change									
Comments:										
Commonto.										
2017 - Spring	g: No Change									
	g. 110 Change									
Comments:										
2017 - Fall: N	No Change									
Comments:										
2019 Fall: N	la Changa									
2018 - Fall: N	NO Change									

Material

Category

Friable

Damage

Type

Asbestos

Type

Damage

Quantity

Damage Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
136	Blue Linoleum	800	SF	Room 109, 110		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Assess	sment Category
137	Blue Linoleum Adhesive	800	SF	Room 109, 110		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 0 1 11 01												

2010 I dill 110 Orlango
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
138	12" X 12" Brown Texture VFT	500	SF	Ramp Outside the Library		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

139	12" X 12" Brown Texture VFT Mastic	500	SF	Ramp Outside the Library	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	No Change									
Comments:										
	g: No Change									
Comments:										
2017 - Fall: N	No Change									
Comments:										
2018 - Fall: N	No Change									
Comments:										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
140	12" X 12" Red VFT	65000	SF	2nd, 3rd, and 4th Floors Corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
141	12" X 12" Red VFT Mastic	65000	SF	2nd, 3rd, and 4th Floor Corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	2017 - Fall: No Change											

Comments:

2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
142	12" X 12" Mustard VFT	1000	SF	Room 206		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
143	12" X 12" Mustard VFT Mastic	1000	SF	Room 260		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	all: No Change											
Commen	ts:											
2017 - Sp	oring: No Change											
Commen	ts:											
2017 - Fa	all: No Change											

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

2018 - Fall: No Change
Comments:

Material

Material

Material Location

Material Description

HA No

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
144	White Sink Insulation	2	EA	Room 210		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 83

145	Trapezoid Lab Counters	80	EA	Room 215, 216, 315, 316		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change]							
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

YES

2016 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			

20

Room 318

EΑ

Material

Quantity

Material

Units

Material Location

HA No

146

Material Description

3' X 5' Lab Counter

Change in Assessment Category

X NO

	147	4'X8' Lab Counters	20	EA	Room 103, 102	Miscellaneous	No	None	0	YES	X NO
	2016 - Fall: N Comments:	o Change									
	2017 - Spring Comments:	: No Change									
	2017 - Fall: N Comments:	o Change									
- 1	2018 - Fall: N Comments:	o Change									

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
148	12" X 12" Multicolored VFT	2000	SF	Room 411, 412, 413		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

									t	
149	12" X 12" Multicolored VFT Mastic	2000	SF	Room 411, 412, 413	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
	o Change									
Comments:										
2017 - Spring	g: No Change									
Comments:										
2017 - Fall: N	lo Change									
	to enange									
Comments:										
2018 - Fall: N	lo Change									

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
150	Green Carpet Adhesive	800	SF	Room 108		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
151	12" x 12" Brown w/ Light Spots Floor Tile	5000	SF	West Elevator Lobby, 1st Floor MDF Room, Rooms 403, 405, 205, 205A, 200, West Med Room, 2nd Floor Hallway, Lecture Hallway, 440A, 219, Storage Across Room 400, 3rd Floor Kitchen Staff Washroom, 2nd Floor Storage by West Elevators		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
152	Mastic Associated w/ 12" x 12" Brown w/ Light Spots Floor Tile	5000	SF	West Elevator Lobby, 1st Floor MDF Room, Rooms 403, 405, 205, 205A, 200, West Med Room, 2nd Floor Hallway, Lecture Hallway, 440A, 219, Storage Across Room 400, 3rd Floor Kitchen Staff Washroom, 2nd Floor Storage by West Elevators		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
153	12" x 12" Light Brown w/ Spots Floor Tile	8000	SF	Rooms 312, 313, 300, 303-306, 201, 211, 213, 214, 250, 216, 217, 251, 200, 201-204		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
154	Mastic Associated w/ 12" x 12" Light Brown w/ Spots Floor Tile	8000	SF	Rooms 312, 313, 300, 303-306, 201, 211, 213, 214, 250, 216, 217, 251, 200, 201-204		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
155	12" x 12" Turquoise Floor Tile	250	SF	Room 206A		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
156	Mastic Associated w/ 12" x 12" Turquoise Floor Tile	250	SF	Room 206A		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2047 Caring No Change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
157	12" x 12" Blue w/ Streaks Floor Tile	300	SF	Room 101 Kitchen		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

158	Mastic Associated w/ 12" x 12" Blue w/ Streaks Floor Tile	300	SF	Room 101 Kitchen	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:	<u> </u>									
2017 - Spring	g: No Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
159	2' x 2' Gray Carpet Square Glue	700	SF	Rooms 103 and 105		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

A	Fiberglass Duct Cement - REMOVED			Attic							YES	X NO
2016 - Fall: N	o Change											
Comments:	o onange											
2017 - Fall: N	o Change											
Comments:												
2017 2												
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:	o onango											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Туре	Quantity	Units		
AA	Hard Joint Compound on			Boiler Room, Pump Room, Old Glass Shop &		TSI					YES	X NO
, , ,	Fiberglass Pipe Runs			Throughout Basement		-						

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

AB	Hard Joint Compound Off 15" Steam Line			Boiler Room		TSI					YES	X NO
2016 - Fall:	No Change											
Comments												
2017 - Fall:	No Change											
Comments	:											
	ng: No Change											
Comments	:											
2018 - Fall:	No Change											
Comments	:				_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
AC	Hard Joint Compound Off			Auto Shop		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Steam Supply

Hard Joint Compound Off

AD	Hard Joint Compound on Fiberglass Piping			Kitchen		TSI					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	o Chango											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
AE	Boiler Breeching			Boiler Room		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

AF	Paper Wrap on Fiberglass Pipe Insulation			New Addition Locker Room		TSI					YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	io Change				+							
Comments.					+							
2017 - Spring	: No Change											
Comments:												
0047 5 11 1	. 01				4							
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
AG	Insulation Wrap			2nd Floor Fan Room		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2018 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Paper Wrap on Fiberglass

Material

Quantity

Material

Units

Material Location

АН	Cementitious Joint Insulation			See HA - AK		TSI					YES	X NO
2016 - Fal	I: No Change											
Comments												
2017 - Spi	ring: No Change											
Comments	S:											
	I: No Change											
Comments	S:				_							
	I: No Change											
Comments	S:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
A.I.	Cementitious Joint			New Addition Locker								

TSI

Asbestos

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

Room

HA No

ΑI

Material Description

Cementitious Joint

YES

Change in Assessment Category

X NO

		Quantity	Units		Type	Category		Type	Quantity	Units		
AJ	Internal Duct Liner			Basement		TSI		None			YES	X NO
2016 - Fall: I	No Chango				7							
	No Change				1							
Comments:												
2017 - Fall: I	No Change											
Comments:												
					1							
2017 - Sprin	g: No Change				1							
Comments:	<u> </u>											
2018 - Fall: I	No Change											
Comments:												
]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	ssment Category
		Quantity	Units		Type	Category		Туре	Quantity	Units		
	0 111 111			Basement of New								X NO
AK	Cementitious Joint Insulation			Addition and Girls Washroom Plumbing		TSI					YES	X NO
				Wall, 1sr, 2nd, 3rd Floors								
2016 - Fall: I	No Chango				1							
Comments:	ino Criarige				-							
I Comments.					1							

Material

Asbestos

Damage

Friable

Damage

Damage

Material

Material Description

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

HA No

Material

Material Location

В	Cement			Attic							YES	X NO
2016 - Fall: N	No Change				7							
Comments:	<u> </u>											
2017 - Fall: N	No Change											
Comments:					-							
	g: No Change											
Comments:					_							
2018 - Fall: N	No Change											
Comments:					_							
					_]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
С	Preformed Pipe Insulation (Mag Block)			Boiler Room & Gym		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

Material Description

Fiberglass Insulation

Material

Quantity

Material

Units

Material Location

D	Aircell Pipe Insulation	7000	LF	Basement wall chaese		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	<u> </u>				1							
2017 - Sprin	g: No Change											
Comments:					_							
2017 - Fall:	No Change											
Comments:					_							
2018 - Fall:	No Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
Е	Stored Cardboard Pipe Insulation - REMOVED			Basement							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

F	Spray-on Fireproofing	1000	SF	2nd Floor Fan Room		Surface	No	None	0		YES	X NO
2016 - Fal	I: No Change											
Comments												
2017 - Fal	I: No Change											
Comments	3:											
	ring: No Change											
Comments	S:											
	l: No Change											
Comments	S:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
G	Vault Door Liners	160	SF	Throughout Facility Including: Coach's Office, 2nd & 3rd Floor		TSI	Yes	None	0		YES	X NO

Asbestos

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Н	Coated Screens - REMOVED			Lab Rooms							YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	J											
2017 - Spring	ı: No Change				_							
Comments:	,g											
2017 - Fall: N	lo Change				_							
Comments:]									
2018 - Fall: N	lo Change				_							
Comments:	J]							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
I	Kiln Liner			Art Room		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	y -]							

Material

Category

Asbestos Type Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

J	Boiler Insulation Under Metal Jackets			Boiler Room		TSI					YES	X NO
2016 - Fall: N	o Change				7							
Comments:												
2017 - Spring	: No Change											
Comments:	go]							
2017 - Fall: N	o Change				_							
Comments:]										
2018 - Fall: N	o Change				1							
Comments:	<u> </u>]							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
К	Boiler Rope			Boiler Room		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

L	Hard Fittings on Aircell Pipe Insulation	500	LF	Basement		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	o onango											
2017 - Spring	· No Change											
Comments:	. 110 Change											
2017 - Fall: N	o Change		-									
Comments:	-]										
2018 - Fall: N	o Change				-							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
М	Stored Insulation			Basement							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

N	Insulation Beneath Shell of Incinerator			Boiler Room		TSI					YES	X NO
2016 - Fall	: No Change											
Comments												
2017 - Fall	: No Change											
Comments												
2017 - Spri	ing: No Change											
Comments	:											
	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
0	Incinerator Fire Brick			Boiler Room		TSI					YES	X NO
2016 - Fall	: No Change				7							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

Р	Insulation Beneath Shell of Sellers Tank			Boiler Room		TSI					YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Fall: N	lo Change				_							
Comments:												
2017 - Spring	g: No Change		1									
Comments:												
2018 - Fall: N	lo Change				-							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
Q	Vibration Collars			Basement		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

R	Black Backing on Fiberglass Filters - ABATED			Plenum Chamber		TSI					YES	X NO
2016 - Fall: N	lo Change	•		•	7							
Comments:	vo Orlange				1							
Commonto.					1							
2017 - Fall: N	lo Change				1							
Comments:					1							
	g: No Change											
Comments:												
2010 5 11 1					4							
2018 - Fall: N	lo Change				_							
Comments:												
					<u></u>							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
		Quantity	Units		Type	Category		Туре	Quantity	Units		
S	Hard Joint Compound Off Absorption Chiller Piping			2nd Floor Fan Room		TSI					YES	X NO

Asbestos

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

Material

Quantity

Material

Units

Page 106

Change in Assessment Category

Т	Fittings Off Chiller Pumps Piping			2nd Floor Fan Room		Miscellaneous					YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Sprin	ng: No Change				-							
Comments:					1							
2017 - Fall:	No Change				-							
Comments:												
2018 - Fall:	No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
U	Vibration Collars (Cloth)			2nd Floor Fan Room		Miscellaneous					YES	X NO
2016 - Fall:	No Change]							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Units

Material

Quantity

Material Location

V	Canvas Cloth Off Fan Units			2nd Floor Fan Room		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	J-				-							
2017 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	g: No Change											
Comments:		_										
2018 - Fall: N	lo Change				1							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
W	Hard Joint Compound on Water Cooler Piping			2nd Floor Fan Room		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Units

Material

Quantity

Material Location

Х	(Interior) Boiler Packing			Boiler Room		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:												
	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:		_										
2018 - Fall:	<u> </u>											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
Υ	Hard Joint Compound on Valve Pump Piping			Boiler Room		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Z	Hard Joint Compound on Fiberglass Reheat Piping			Plenum Chamber		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 46641 Page 110 ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Richard T Crane Medical Preparatory HS
Date:	1/28/2019
the Asbest	notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of cos Management Plan is available at each school during school hours by appointment. To review the Asbestos Management Plan must be made at least 24 hours in advance.
The last in	e be advised that CPS conducts asbestos inspections of all Schools every three years. spection was completed in 2016. surveillances are conducted every six months.
CHECK ON	<u>NE</u>
A co	opy of this notice was sent home in each child's backpack.
A co	opy of this notice was printed in the school's newsletter and sent home with each child
A co	opy of this notice was printed in the school's calendar and sent home with each child
X Oth	er. E-mail
A COPY	OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile

Oracle Unit: 46641

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Page 112

SCHOOL'S ASBESTOS MANAGEMENT PLAN.