Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

William Jones College Preparatory High School 47021 1060 School: **Oracle Unit: Building ID:** Address: 606 S. State Region: 03 Mail Room: Asbestos Surveyor: Casasanto, Daniel X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/8/2019 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type 3rd Through 5th Floor YES Hard Plaster X NO Surface Corridors 2016 - Fall: No Change Comments:good condition 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:good 2018 - Fall: No Change Comments:D dcasasanto

	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
;	5A	12"x12" Brown w/Beige Floor Tile	6600	SF	Performing Arts Foyer, 221 & Office, 224, Lecture Hall & Stage, Theater,		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:good condition	
2017 - Spring: No Change	
Comments:good	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:D Casasanto	
_	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5B	12" x 12" White Floor Tile			Corridors Throughout		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:good
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:good
2018 - Fall: No Change
Comments:D Casasanto

	11001 1110										
2016 - Fall: N	No Change										
Comments:g											
2017 - Spring	g: No Change										
Comments:g	ood										
2017 - Fall: N	No Change										
Comments:											
2018 - Fall: N	No Change										
Comments:D) Casasanto										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

HA No

5E

6

Material Description

12" x 12" White & Gray

9" x 9" Tan Floor Tile

Floor Tile

Material

Quantity

990

Material

Units

SF

Material Location

Classrooms 600

North Stair Landings

Change in Assessment Category

X NO

X NO

YES

YES

10	9" x 9" White Floor Tile Mastic			Basement Corridor and Elevator Lobby		Miscellaneous					YES	X NO
004C Fall N	la Ohanana				7							
2016 - Fall: N	•											
Comments:g	ood											
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:o	k											
2018 - Fall: N	No Change											
Comments:D) Casasanto											
	_	•	•	_	-							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Rooms 600, 601, and

Material

Quantity

Material

Units

HA No

11

Material Description

2' x 4' White (Wormy) Ceiling Tile

YES

X NO

12	Brown Baseboard			Throughout School		Miscellaneous					YES	X NO
2016 - Fall:	No Change				1							
Comments:	good											
2017 - Fall:	No Change											
Comments:												
	g: No Change											
Comments:	ok											
2018 - Fall:	No Change											
Comments:	O Casasanto											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
13	Brown Baseboard Mastic			Throughout Building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

14	Black Baseboard			Room 403 and 402		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:g	ood]							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	•											
Comments:o	k											
2018 - Fall: N	lo Change											
Comments:D	Casasanto											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
15	Black Baseboard Mastic			Classrooms 402 & 403		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Material

Units

Material

Quantity

Material Location

HA No

Material Description

Change in Assessment Category

Damage

Units

16	Carpet Mastic			Faculty Lunchroom, Library Room (500), Rooms 604 & 606		Miscellaneous					YES	X NO
2016 - Fall	No Change		<u> </u>	•	1						·	
	good condition											
	9											
2017 - Fall:	No Change											
Comments:												
	ng: No Change											
Comments:	:ok											
	No Change											
Comments:	:D Casasanto											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
17	Brown Linoleum			Under Lockers on the 1st, 2nd, 3rd, 4th, 5th & 6th Floor & Locker Alcoves 504A & 604A		Miscellaneous					YES	X NO
2016	Fall: No Chango]							

2016 - Fall: No Change	
Comments:good condition	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:ok	
2018 - Fall: No Change	
Comments:D Casasanto	

HA No

Material Description

Material

Quantity

Material

Units

Material Location

18	Brown Linoleum Mastic	Under Lockers on the 1st, 2nd, 3rd, 4th, 5th & 6th Floor & Locker Alcoves 504A & 604A		Miscellaneous			YES	X NO
2016 - Fall:]					
Comments:	good condition							
2017 - Fall:	No Change							
Comments:								
2017 - Sprin	ng: No Change							
Comments:	ok							
2018 - Fall:	No Change							
	D Casasanto							
]					

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	Drywall			Throughout School		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:good condition
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:ok
2018 - Fall: No Change
Comments:D Casasanto

HA No

Material Description

Material

Quantity

Material

Units

Material Location

20	Exterior Brick - Not AHERA			Throughout Exterior of Building		Miscellaneous					YES	X NO
2016 - Fall: N	No Change											
	ood condition											
2017 - Fall: N	Jo Chango											
Comments:	NO Criange											
2017 Spring	g: No Change											
Comments:0	•											
2018 - Fall: N	· ·											
Comments:D) Casasanto											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
21	Exterior Brick Mortar - Not			Exterior of Building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

AHERA

22	Exterior Joint Compound			Exterior of School		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:go	ood conditon											
2017 - Fall: N	lo Change											
Comments:					1							
2017 - Spring	<u> </u>											
Comments:ol	Κ				_							
2018 - Fall: N	<u> </u>											
Comments:D	Casasanto				_							
					<u></u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
23	Roof Flashing - Not AHERA			Roof, 6th Floor		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

24	Roof Core - Not AHERA			Roof Above Rooms 600- 608		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:g												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:o	k											
2018 - Fall: N	lo Change											
Comments:D	Casasanto											
					I							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

0

None

Damage

Units

Material Location

Throughout School

Material

Units

Material Quantity

2750

SF

HA No

25

Material Description

Insulation Inside Fire Doors

YES

X NO

26	Vibration Damper	100	SF	7th Floor Mechanical Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
	good condition											
2017 - Fall: I	No Change											
Comments:	No change											
2017 - Sprin	g: No Change											
Comments:	<u> </u>											
2018 - Fall: I	No Change											
Comments:I	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
		Quantity	Office		турс	Category		Турс	Quantity	Office		

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Above the 7th Floor

Material

Quantity

Material

Units

HA No

27

Material Description

Roof Flashing - Not AHERA

YES

X NO

28	Roof Core - Not AHERA			Above the 7th Floor Mechanical Room		Miscellaneous					YES	X NO
2016 - Fall: I	No Change											
Comments:					1							
0045 5 11 1												
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:	ok											
					1							
2018 - Fall: 1	No Change				1							
Comments:E	O Casasanto											
					1							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

No

Friable

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

X NO

			000	
				1
2016 - Fall: No	o Change			
Comments:go	ood			
•				
2017 - Fall: No	o Change			
Comments:				
2017 - Spring:	: No Change			
Comments:ok	(
2018 - Fall: No	o Change			
Comments:D	Casasanto			

Quantity

4500

Units

SF

Material

Quantity

Material

Units

Material Location

Rooms 601, 604, and

HA No

29

Material Description

Linoleum

30	Linoleum Mastic	4500	SF	Rooms 600, 601, 608, 604, and 605		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change	<u> </u>		<u> </u>]							
Comments					1							
2017 - Fall:	: No Change				_							
Comments	:				1							
2017 - Spri	ng: No Change											
Comments	:ok				 							
2018 - Fall:	: No Change											
Comments	:D Casasanto				-							
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

Damage

Type

Type

Damage

Quantity

Quantity

Damage

Units

Units

YES

X NO

31	12" x 12" Brown Floor Tile w/White & Brown Specks		Room 606
2016 - Fall: N	lo Change		
Comments:go	ood		
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:ol	(
2018 - Fall: N	o Change		
Comments:D	Casasanto		
	_	•	

Quantity

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

32	12" x 12" Brn Floor Tile w/Wh & Brn Specks Mastic	Room 606	Miscellaneous		YES	X NO
			7			
2016 - Fal	I: No Change					
Comments	s:good					
			1			
2017 - Fal	I: No Change					
Comments	3:		1			
			1			
2017 - Spi	ring: No Change		1			
Comments			1			
2018 - Fal	I: No Change		1			
Comments	s:D Casasanto		1			

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Brown Linoleum	5600	SF	Classrooms 601 - 606		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:ok
2018 - Fall: No Change
Comments:D Casasanto

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Brown Linoleum Adhesive	5600	SF	Classrooms 601 - 606		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N											

2016 - Fall: No Change	
Comments:good	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:good	
2018 - Fall: No Change	
Comments:D Casasanto	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Black Lab Counters and Sinks	800	SF	Classrooms 603 - 606		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:good
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Black Lab Tables	340	SF	Classrooms 604 - 606		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N											

2016 - Fall: No Change	
Comments:good	
2017 - Spring: No Change	
Comments:good	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:D Casasanto	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Fume Hood Interior Materials	120	SF	Classrooms 601A, 604A, 605A		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:good
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Gray Lab Counters and Sinks	480	SF	Classrooms 601 - 602		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:good	
2017 - Spring: No Change	
Comments:good	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:D Casasanto	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Gray Lab Tables	260	SF	Classrooms 601 - 602		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:good	
2017 - Spring: No Change	
Comments:good	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:D Casasanto	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12" x 12" White w/Brown Streaks Floor Tile	26750	SF	Classrooms and Offices 200 - 207, 214A, 214B, 217, 218, 300 - 307, 400 - 407, 500 - 507 and 2, 3, 4, 5, 6,d		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:good
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12" x 12" White w/Brown Streaks Floor Tile Mastic	26750	SF	Classrooms and Offices 200 - 207, 214A, 214B, 217, 218, 300 - 307, 400 - 407, 500 - 507,1,2, 3, 4, 5, 6		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:good
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor
42	12" x 12" Brown Mix Floor Tile	5152	SF	Classrooms and Offices 201 - 202, 204 - 207, 302 - 303, 304 - 307, 401- 403, 405 - 407, 501 - 507 and 1,2, 3, 4, 5, 6		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:good
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12" x 12" Brown Mix Floor Tile Mastic	5152	SF	Classrooms and Offices 201 - 202, 204 - 207, 302 - 303, 304 - 307, 401- 403, 405 - 407, 501 - 507, and 2, 3, 4, 5, 6		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:good
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12" x 12" Yellow Mix Floor Tile	1500	SF	Classrooms and Offices 201 - 202, 204 - 207, 302 - 303, 304 - 307, 401- 403, 405 - 407, 501 - 507		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:good
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12" x 12" Yellow Mix Floor Tile Mastic	1500	SF	Classrooms and Offices 201 - 202, 204 - 207, 302 - 303, 304 - 307, 401- 403, 405 - 407, 501 - 507		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:good
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12" x 12" Beige w/Brown Streaks Floor Tile	16	SF	221 Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:good
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	12" x 12" Beige w/Brown Streaks Floor Tile Mastic	16	SF	221 Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:good
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

48	12" x 12" White w/Medium Brown Specks Floor Tile	500	SF	AuditoriumExits by stairs, Café.Mgr.Off.	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:go										
2017 - Spring										
Comments:go	ood									
2017 - Fall: N	o Change									
Comments:										
2018 - Fall: N										
Comments:D	Casasanto									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	12" x 12" White w/Medium Brown Specks FT Mastic	500	SF	AuditoriumExits by stairs, Cafeteria/Foyer, KitchenCorridor/LwerStair s,Perf.ArtsStairway,Café. Mgr.Off.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:good
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	12" x 12" Brown w/Specks Floor Tile	2700	SF	Auditorium and Stage, Kitchen Office		Miscellaneous	No	None	0		YES X NO
0040 5 11 1	1 01				1						

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:good
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	12" x 12" Brown w/Specks Floor Tile Mastic	2700	SF	Auditorium and Stage & Kitchen Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:good
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	12" x 12" Beige w/Gray Floor Tile	1200	SF	Corridor to Performing Arts Wing		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:good	
2017 - Spring: No Change	
Comments:good	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:D Casasanto	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	12" x 12" Beige w/Gray Floor Tile Mastic	600	SF	Corridor to Cafeteria, Stair Landings, Corridor to Performing Arts Wing		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:good
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

Page 25

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	12" X 12" Dark Gray w/Light Gray Floor Tile	1150	SF	Engineer's Office, 105I, 105J		Miscellaneous	No	None	0		YES X NO
2212 5 11					1						

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:good
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	12" X 12" Dark Gray w/Light Gray Floor Tile Mastic	1150	SF	Engineer's Office, 105I, 105J		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:good
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

	I .											
56	12" x 12" White w/Gray Patches Floor Tile	554	SF	As Patches in Cafeteria, Kitchen Storage and Elevators		Miscellaneous	No	None	0		YES	X NO
004C F-II-I	Na Obasasa	•	•		7	•	•	•	•	•	•	
2016 - Fall: I					1							
Comments:	jood											
2017 - Sprin	g: No Change]							
Comments:	jood											
2017 - Fall: I	No Change											
Comments:	-											
					1							
2018 - Fall: I	No Change				1							
	O Casasanto				1							
	-				1							

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	12" x 12" White w/Gray Patches Floor Tile Mastic	554	SF	As Patches in Cafeteria, Kitchen Storage and Elevators		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:good
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	4" Gray Vinyl Baseboard	116	LF	Engineer's Office		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:good
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto
_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	4" Gray Vinyl Baseboard Adhesive	116	LF	Engineer's Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:good
2018 - Fall: No Change
Comments:D Casasanto

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	4" Brown Vinyl Baseboard	68	LF	605A		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N											

2016 - Fall: No Change
Comments:good
_
2017 - Spring: No Change
Comments:ok
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	4" Brown Vinyl Baseboard Adhesive	68	LF	605A		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:ok
2018 - Fall: No Change
Comments:D Casasanto

Page 29

62	4" Beige Vinyl Baseboard	950	LF	Classrooms 600, 604, 604A		Miscellaneous	No	None	0	YES	X NO
2016 - Fall	: No Change	•		·	7						
					4						
Comments	s:good										
2017 - Spr	ing: No Change										
Comments	::ok										
					1						
2017 - Fall	: No Change				1						
Comments	:				1						
					1						
2018 - Fall	: No Change				1						
	:D Casasanto				1						
					1						
					⊒						

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
63	4" Beige Vinyl Baseboard Adhesive	950	LF	Office Area and Classrooms 600, 604, 604A		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No	o Change											

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:ok
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

Material

Quantity

Material

Units

Material Location

HA No

Material Description

		Quantity	Units		Type	Category		Type	Quantity	Units		
64	4" Yellow Vinyl Baseboard	280	LF	Classrooms 601, 602		Miscellaneous	No	None	0		YES	X NO
2016 - F	all: No Change											
2017 - S	pring: No Change											
	all: No Change											
Comme	nts:	•	•	_								

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	4" Yellow Vinyl Baseboard Adhesive	280	LF	Classrooms 601, 602		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:ok
2018 - Fall: No Change
Comments:D Casasanto

Material

Material Location

HA No

2018 - Fall: No Change Comments:D Casasanto

Material Description

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	4" Cream Vinyl Baseboard	4100	LF	Library, Classrooms & Offices 200-207, 214A, 214B, 217, 218, 300-308, 400-403, 405-407, 500-507, 1, 2, 3, 4, 5, 6		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
0047 Fall No Observe
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:ok
2018 - Fall: No Change
Comments:D Casasanto

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	4" Cream Vinyl Baseboard Adhesive	4100	LF	Library, Classrooms & Offices 200-207, 214A, 214B, 217, 218, 300-308, 400-403, 405-407, 500- 507, 1, 2, 3, 4, 5, 6		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:ok
2018 - Fall: No Change
Comments:D Casasanto

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
68	4" Gray Vinyl Baseboard	400	LF	2nd-6th Floor Corridors, Classroom 404		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:good												
2017 - Spring Comments:ol	•											

2017 - Fall: No Change Comments:

2018 - Fall: No Change Comments:D Casasanto

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	4" Gray Vinyl Baseboard Adhesive	400	LF	2nd-6th Floor Corridors, Classroom 404		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:good	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:ok	
2018 - Fall: No Change	
Comments:D Casasanto	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70	Marker Board Adhesive	1000	SF	Classrooms 201, 301, 304-308, 401-407, 501-507, 601, 602, 604-606		Miscellaneous	No	None	0		YES X NO
2016 - Fall:]						

016 - Fall: No Change
comments:good
017 - Spring: No Change
comments:ok
017 - Fall: No Change
comments:
018 - Fall: No Change
comments:D Casasanto

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	Poster Board Adhesive	440	LF	Classrooms 201, 202, 204-207, 307, 308, 604, 605 and the 3rd and 6th Floor Corridors, 601, 602		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:good	
2017 - Spring: No Change	
Comments:ok	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:D Casasanto	

72	Stair Treads	630	SF	Rear Stairway	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change	·		·						
Comments:go	ood									
2017 - Spring	: No Change									
Comments:ol										
2017 - Fall: N	o Change									
Comments:										
2018 - Fall: N										
Comments:D	Casasanto									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
73	Stair Tread Adhesive	630	SF	Rear Stairway		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:go												

2017 - Fall: No Change
Comments:

2017 - Spring: No Change
Comments:ok

2018 - Fall: No Change
Comments:D Casasanto

Material

Quantity

Material

Units

HA No

Material Description

		Quantity	Units		Type	Category		Type	Quantity	Units		
74	2' x 4' Lay-in Ceiling Panels	87000	SF	1st - 6th Floor Classrooms, Library, Offices, Corridors		Miscellaneous	Yes	None	0		YES	X NO
2016 - E	all: No Change				7							
					4							
Commen	nts:good											
2017 - Fa	all: No Change											
Commen	nts:	•	•									

Material

Friable

Damage

Damage

Asbestos

Comments:

2017 - Spring: No Change
Comments:ok

Material

Material Location

2018 - Fall: No Change Comments:D Casasanto

Material Description

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
75	Gray Rubber Flooring Adhesive	600	SF	Shipping/Receiving Dock		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:ok
2018 - Fall: No Change
Comments:D Casasanto

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
76	Gray Carpet Adhesive	1144	SF	Classroom 404		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change	
Comments:good	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:ok	
2018 - Fall: No Change	
Comments:D Casasanto	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	Brown/Gray Carpet Adhesive	7000	SF	1st Floor Offices, Library		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:ok
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

78	Drywall	12000	SF	1st - 6th Floor Classrooms, Library, Offices, Corridors		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: I Comments:g		·									
	g: No Change										
Comments:c	ok				1						
2017 - Fall: I	No Change										
Comments:											
2018 - Fall: I											
Comments:E) Casasanto										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
79	Drywall Compound	12000	SF	1st - 6th Floor Classrooms, Library, Offices, Corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:ok
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

HA No

Material Description

Material

Quantity

Material

Units

Material Location

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
80	Chalk Board Adhesive	700	SF	Classrooms 201, 202, 204-207		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:go					1							
Comments.ge	,											
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:ok	(·								

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102	12" x 12" Blue and White Tile	6400	SF	Kitchen Supply Room, Cafeteria, Stair Landing & Entrance		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:good	
2017 - Spring: No Change	
Comments:ok	-
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:D Casasanto	

HA No

2018 - Fall: No Change Comments:D Casasanto

Material Description

Material

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
102M	12 x 12 Blue & White Tile Mastic	6400	SF	Kitchen Supply Room, Cafeteria, Stairs, Entrance, Stair Landing		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:g	0											
2017 - Fall: N	No Change											
Comments:	-											
2017 - Spring	g: No Change											
Comments:o	ok				_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	Terrazo Floor	18500	SF	Throughout Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:ok
2018 - Fall: No Change
Comments:D Casasanto

2018 - Fall: No Change Comments:D Casasanto

104	Ceramic Tile and Grout	3072	SF	All Bathroom Walls and Floors		Miscellaneous	No	None	0	YES	X NO
2016 - Fa	all: No Change]						
Commen	ts:good										
2017 - Fa	all: No Change										
Commen	ts:										
2017 - Sp	oring: No Change										
Commen	ts:ok										
2018 - Fa	all: No Change										
Commen	ts:D Casasanto										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104M	Ceramic Tile Mastic	3072	SF	All Bathrooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:ok
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
105	12 x 12 White w/ Specs Floor Tile	108	SF	Kitchen Storage		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:good	
00.47 5 11 11 01	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:ok	
OOAO Fall No Observe	
2018 - Fall: No Change	
Comments:D Casasanto	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
105M	12 x 12 White w/Specs Floor Tile Mastic	108	SF	Kitchen Storage		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:ok
2018 - Fall: No Change
Comments:D Casasanto

106	Window Expansion Caulk	15000	LF	Throughout Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change											
Comments	s:good											
2017 - Fal	l: No Change				_							
Comments	S:				_							
2017 - Spr	ing: No Change											
Comments	s:ok				_							
	l: No Change											
Comments	s:D Casasanto				_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
8B	12" x 12" White Floor Tile			1st Floor Corridor & Locker Room, 3rd & 5th		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

HA No

Material Description

Mastic

Material

Quantity

Material

Units

Material Location

Floors Lobby Areas, 304A & 504A (Alcove) Change in Assessment Category

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Cateo	gory
8D	12" x 12" Gray w/White Floor Tile Mastic	500	SF	Classroom 504		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: I	No Change	•		_]					•		

2016 - Fall: No Change	
Comments:good	
0047 O. d. N. Obasa	
2017 - Spring: No Change	
Comments:good	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:D Casasanto	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8E	12"x 12" White w/Gray Floor Tile Mastic	500	SF	Classrooms 600		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:good
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:ok
2018 - Fall: No Change
Comments:D Casasanto

8F	12" x 12" Orange Floor Tile Mastic			Gymnasium		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:	good				-							
	ng: No Change											
Comments:	ok				_							
2017 - Fall:												
Comments:					-							
2018 - Fall:	No Change											
Comments:	D Casasanto											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
9	9" x 9" Tan Floor Tile			North Stair Landings		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Material

Units

Material

Quantity

Material Location

HA No

Material Description

Mastic

2016 - Fall: No Change Comments:good

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change Comments:D Casasanto

Comments:

Comments:ok

Change in Assessment Category

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	Elbows on Fiberglass Pipe Runs	65	LF	7th Floor Mechanical Room		TSI	Yes	None	0		YES X NO
0040 = 11.1	. 01				1						

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:ok
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Elbows on Fiberglass Pipe Runs	250	LF	Throughout School		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:good	
2017 - Spring: No Change	
Comments:ok	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:D Casasanto	

E	Breeching Duct Insulation		Boiler Room and Chiller Area		TSI					YES	X NO
2016 - Fall: N	No Change										
Comments:g				- -							
2017 - Spring	g: No Change			1							
Comments:o				1							
2017 - Fall: N	No Change										
Comments:				=							
2018 - Fall: N											
Comments:D	Casasanto			-							
				1							
HA No	Material Description	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
	T 11 12 (T 5)		Boiler Room and Chiller							П I	

TSI

Asbestos

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

G

2016 - Fall: No Change Comments:good

Material Description

Tank Insulation (Tar Paper)

Material

Quantity

Material

Units

YES

X NO

Change in Assessment Category

H	Pipe Insulation Tar Paper		Boiler Room		TSI					YES	X NO
2016 - Fall: N	lo Change			1							
Comments:g				-							
2017 - Fall: N	lo Change			1							
Comments:	<u> </u>			1							
2017 - Spring	g: No Change										
Comments:o	k										
2018 - Fall: N	lo Change										
Comments:D	Casasanto			-							
				1							
LIA NIa	Material Description	Matarial	Material Material Leasting	A = b = = 4 = =	Matarial	Detailed	Damas	D	D	Change in Assess	+

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
HA-100	1'x1' grooved splined white Ceiling Tile	2000	SF	Two floors of the building		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:good
2017 - Spring: No Change
Comments:ok
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:D Casasanto

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA-101	Gray coating inder the Kitchen sink	5	SF	Kitchen and Office Area		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:g												
2017 - Spring	g: No Change											
Comments:o	k				1							
2017 - Fall: N	lo Change				-							
Comments:					-							
2018 - Fall: N	lo Change				-							
Comments:D	Casasanto											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
I	Boiler Gasket Insulation			Boiler Room		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Material

Quantity

Material

Units

HA No

Material Description

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Tank Insulation			Mechanical Area by Kitchen		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:good
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:ok
2018 - Fall: No Change
Comments:D Casasanto

Oracle Unit: 47021

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: William Jones College Preparatory High School
Date: 10/22/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 47021

SCHOOL'S ASBESTOS MANAGEMENT PLAN.