Chicago Public Schools

6 Month Asbestos Surveillance

2018 - Fall

	School: Address:	Emil G Hirsch Metropolitan High School 7740 S. Ingleside		Oracle Unit: Region:	47031 05	Building ID: Mail Room:	1380 46
Х СНЕСК Н	ERE IF N	O CHANGE TO ASBESTOS	Asbestos Surveyor: Survey Date: Email Address:	Williams, Mandel 12/18/2018 mwilliams270@cps.edu			

	Each child's backp	ack	Notice	printed in school's new	sletter	Notice pri	nted in sch	ool's calenda	r Ot	her		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
01A	9x9 brown w/streaks	3140	SF	Rm 328's vault and rm 227 1st flr corridor		Miscellaneous	No	None	0		YES	XNO
2016 - Fall: Comments:	No Change											
2017 - Sprir Comments:	ng: No Change				-							
2017 - Fall: Comments:	No Change				-							
	No Change				-							
2018 - Sprir	ng : No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
01B	9x9 tan VFT	2320	SF	1st flr corridor		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02A	12x12 Light olive green VFT	2489	SF	Kitchen, 315, 221, 211, 235, 206, 127, 205, 231, 233, 105		Miscellaneous	No	Dist	16		

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02B	12x12 brn VFT	14725	SF	2nd,3rd flr hall, 236,237,234,217,215,229 , 210,209,207,205,110,122 , 124,125,135,139,141,106 /106A		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02C	12x12 tan VFT	14725	SF	2nd,3rd flr hall, 236,237,234,217,215,229 , 210,209,207,205,110,122 , 124,125,135,139,141,213 ,123		Miscellaneous	No	Loc	30		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02D	12x12 light gray	5715	SF	Main office,library office, Rm 320,321, 220, 223, 126, 130, PE office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
0040 Carina Na Change	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02E	12x12 drk green vft	1420	SF	Rm 235, 206,211,137		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	Duct vibration sleeve	15	SF	Band room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change								
Comments:								
2017 - Fall: No Change								
Comments:								
2017 - Spring: No Change								
Comments:								
2018 - Spring : No Change								
Comments:								
2018 - Fall: No Change								
Comments:								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	firewall	12000	SF	Assembly hall		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change							
Comments:							
2017 - Spring: No Change							
Comments:							
2017 - Fall: No Change							
Comments:							
2018 - Fall: No Change							
Comments:							
2018 - Spring : No Change							
Comments:							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14A	Mastic beneath 9x9 brown VFT	2190	SF	Rm 328's vault and rm 227 1st flr corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change							
Comments:							
2017 - Spring: No Change							
Comments:							
2017 - Fall: No Change							
Comments:							
2018 - Spring : No Change							
Comments:							
2018 - Fall: No Change							
Comments:							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14B	Mastic under 9x9 tan VFT	2320	SF	1st flr corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change							
Comments:							
2017 - Spring: No Change							
Comments:							
2017 - Fall: No Change							
Comments:							
2018 - Spring : No Change							
Comments:							
2018 - Fall: No Change							
Comments:							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15A	Mastic 12x12 light olive VFT - Abated			Kitchen, 315,221,211, 235,206,127		Miscellaneous					YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
15B	Mastic 12x12bm VF	14725	SF	2nd,3rd fir hall, 236,237,234,217,215,229 , 210,209,207,205,110,122 , 124,125,135,139,141,106 /106A		Miscellaneous	No	None	0		YES	XNO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15C	Mastic under 12x12 tan VFT	14725	SF	2nd,3rd flr hall, 236,237,234,217,215,229 , 210,209,207,205,110,122 , 124,125,135,139,141,213 .123		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15D	Mastic beneath 12x12 light gray	5715	SF	Main office,library office, Rm 320,321, 220, 223, 126, 130		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15E	mastic beneath 12x12 lt. green	1420	SF	Rm 235,206,211,137		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16A	Gray linoleum w/blue streaks	5705	SF	Rm 222,225		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ł	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	17A	Mastic under gray linoleum	5705	SF	Rm 222,225		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12x12 vft off-white			room 321		Miscellaneous					YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20M	mastic			room 321		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	pipe fittings	35	LF	warm air tunnel and unfinished crawlspace		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	plaster			1st, 2nd & 3rd floors throughout. Vestibule 12 Stair Well Area		Surface					

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24A	whit w/tan streaks flooring	1700	SF	rooms 221, 211, 235, 206, 127, 322		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24B	white w/tan streaks mastic	1700	SF	room 322, 221, 211, 235, 206, 127		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104	Transit Lab tables	25	SF	Room 322, 326, 322 Office, 328		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change							
Comments:							
2017 - Fall: No Change							
Comments:							
2017 - Spring: No Change							
Comments:							
2018 - Spring : No Change							
Comments:							
2018 - Fall: No Change							
Comments:							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
105	Transit Panels	30	SF	Room 322 Hood Fume		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
106	Beige Linoleum	1266	SF	Room 321		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
107	Beige Linoleum Mastic	1266	SF	Room 321		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
108	Transite Counter Top	263	SF	322, 326, 328		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change							
Comments:							
2017 - Fall: No Change							
Comments:							
2017 - Spring: No Change							
Comments:							
2018 - Fall: No Change							
Comments:							
2018 - Spring : No Change							
Comments:							

Ī	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	109	Transite Chalk Board	2000	SF	1st, 2nd, 3rd floor Classrooms		Miscellaneous	No	Dist	23		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CM-1	Green carpet mastic			Rm 230		Miscellaneous		None			YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CM-2	Blue carpet mastic			Rm 109,128,204		Miscellaneous		None			YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2019 Folly No Change	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CM-3	Red carpet mastic			social room, room 131		Miscellaneous		None			YES XNO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-100	2'x4' white ceiling tile	150000	SF	hallways and classrooms		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 Spring: No Change
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-101	1'x1' white ceiling tile	3000	SF	Kitchen		Miscellaneous	Yes	None	0		YES XNO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-102	Glue for 12"X12" white ceiling tile	3000	SF	Kitchen		Miscellaneous	No	None	0		YES X NO

2010 Fally No Change
2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-103	Spray applied ceiling coating	7000	SF	Pool		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
М	Boiler gasket	140	LF	boiler room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	Boiler door insulation	250	SF	boiler room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
0	12x12 off white w/streaks	3560	SF	ROOMs 321,322, 325, 326		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
O-1	12x12 off white w/streaks MASTIC	3560	SF	ROOMs 321, 322, 325, 326		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	12x12 WHITE W/ BLACK STREAKS VFT	9300	SF	Rm 210,209,206,235,232,234 ,237,236,141,230 /227/223		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

VFT = *Vinyl Floor Tile Friable* = *Can be crumbled, pulverized, or reduced to powder by hand pressure.*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
P-1	12x12 WHITE W/ BLACK STREAKS VFT-MASTIC	9300	SF	Rm 210,209,206,235,232,234 ,237,236,141,230 /227/223		Miscellaneous	No	None	0		

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2019 Fally No Change	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Q	12x12 LIGHT PINK (BEIGE) VFT	750	SF	ROOM 128/COUNSELORS OFFICE		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Q-1	12x12 LIGHT PINK (BEIGE) VFT-MASTIC	750	SF	ROOM 128/COUNSELORS OFFICE		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Alunha /2

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Emil G Hirsch I	Metropolitan	High School
---------	-----------------	--------------	--------------------

Date: 12/18/2018

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016.

Asbestos surveillances are conducted every six months.

CHECK ONE

A copy of this notice was sent home in each child's backpack
--

A copy of this notice was printed in the school's newsletter and sent home with each child

A copy of this notice was printed in the school's calendar and sent home with each child

Other.

A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.