## **Chicago Public Schools**

### 6 Month Asbestos Surveillance

2018 - Fall

		e Learning Ce Bryn Mawr	nter High So	chool				acle Unit: gion:	4902 01	21	Buildin Mail Ro		00	
х снеск	HERE IF NO CH	ANGE TO	) ASBE	STOS	Asbestos Survey D	s Surveyor: ate:	<u>Sanchez,</u> 12/17/201	<u>Alexander</u> 8						
					Email Ad		sanchez- alexander com	@aramark.						
	A copy of the2016/20	17 notice to	parents and	staff regardi	ing the asbe	estos manag	ement plan noti	fications w	as distributed	d via:				
	Each child's backp	ack	Notice	printed in sch	hool's news	letter	Notice prin	nted in scho	ool's calendai	r Ot	her			
HA No	Material Description	Material Quantity	Material Units	Material Loc	cation	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change ir	Asses	sment Category
06	12"x12" White w/ Brown Specks VFT	60000	SF	Throughout			Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N Comments:sa 2017 - Spring Comments:sa 2017 - Fall: N Comments: 2018 - Spring Comments:	ame : No Change ame o Change : No Change													
2018 - Fall: N Comments:	o Change													

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	Rubber Vinyl Flooring	3500	SF	Multipurpose Room		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:same	
2017 - Spring: No Change	
Comments:same	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12"x12" White w/ Brown Specks VFT Mastic	60000	SF	Throughout		Miscellaneous	No		0		YES X NO

2016 - Fall: No Change	
Comments:same	
2017 - Spring: No Change	
Comments:same	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Rubber Vinyl Flooring Mastic	3500	SF	Multipurpose Room		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:same	
2017 - Spring: No Change	
Comments:same	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12"x12" Gold VFT	80	SF	Engineers Hall, & North Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:same
2017 - Spring: No Change
Comments:same
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HAN	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14		12"x12" Gold VFT Mastic	80	SF	Engineers Hall, & North Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:same	
2017 - Spring: No Change	
Comments:same	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" Brown w/ Black Specks VFT	64	SF	North and South Corridor Corners, Room 126 Vestibule		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:same
2017 - Spring: No Change
Comments:same
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"x12" Brown w/ Black Specks VFT Mastic	64	SF	North and South Corridor Corners, Room 126 Vestibule		Miscellaneous	No	None	0		

· · · · · · · · · · · · · · · ·
2016 - Fall: No Change
Comments:same
2017 - Spring: No Change
Comments:same
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"x12" Blue VFT	70	SF	Room 112 Vestibule, Room 113 Vestibule, Room 120 Vestibule, Room 121 Vestibule		Miscellaneous	No	None	0		

2016 - Fall: No Change	
Comments:same	
2017 - Spring: No Change	
Comments:same	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12"x12" Blue VFT Mastic	70	SF	Room 112 Vestibule, Room 113 Vestibule, Room 120 Vestibule, Room 121 Vestibule		Miscellaneous	No	None	0		

2016 - Fall: No Change	
Comments:same	
2017 - Spring: No Change	
Comments:same	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12"x12" Green VFT	25	SF	North Corridor, Room 124 Vestibule		Miscellaneous	No	None	0		

2016 - Fall: No Change	
Comments:same	
2017 - Spring: No Change	
Comments:same	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Oracle Unit: 49021 Page 6

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12"x12" Green VFT Mastic	25	SF	North Corridor, Room 124 Vestibule		Miscellaneous	No	None	0		

2016 - Fall: No Change
Comments:same
2017 - Spring: No Change
Comments:same
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12"x12" Orange VFT	40	SF	Room 110 Vestibule, Room 116 Vestibule, Room 117 Vestibule		Miscellaneous	No	None	0		

2016 - Fall: No Change	
Comments:same	
2017 - Spring: No Change	
Comments:same	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12"x12" Orange VFT Mastic	40	SF	Room 110 Vestibule, Room 116 Vestibule, Room 117 Vestibule		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:same
2017 - Spring: No Change
Comments:same
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Red VFT	30	SF	Room 114 Vestibule, Room 115 Vestibule		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:same	
2017 - Spring: No Change	
Comments:same	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12"x12" Red VFT Mastic	30	SF	Room 114 Vestibule, Room 115 Vestibule		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:same	
2017 - Spring: No Change	
Comments:same	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" Yellow VFT	70	SF	Multipurpose Room North & South Vestibules		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:same	
2017 - Spring: No Change	
Comments:same	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HAI	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26		12"x12" Yellow VFT Mastic	70	SF	Multipurpose Room North & South Vestibules		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:same	
2017 - Spring: No Change	
Comments:same	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

ſ	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	27	2 x 2 ft Dot/Wave Ceiling Tiles	2300	SF	Corridors, Main Office		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:same
2017 - Spring: No Change
Comments:same
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	2 x 4 ft Dot/Wave Ceiling Tiles	6300	SF	Rooms 110, 113, 114, 115, 116, 119- 121, 124, Stage in MP Room, Old Storage Library		Miscellaneous	Yes	None	0		YES XNO

2016 - Fall: No Change
Comments:same
2017 - Spring: No Change
Comments:same
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	1 x 1 ft Dot/Wave Ceiling Tiles	1000	SF	Conference Room, Main Office		Miscellaneous	Yes	None	0		YES XNO

2016 - Fall: No Change	
Comments:same	
2017 - Spring: No Change	
Comments:same	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	2 x 2 ft Rough Texture Ceiling Tiles	1200	SF	Lunch Room		Miscellaneous	Yes	None	0		YES XNO

2016 - Fall: No Change	
Comments:same	
2017 - Spring: No Change	
Comments:same	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12 x 12 inch Gray Speckled VFT	1200	SF	Lunch Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:same
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:same
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31 A	12 x 12 inch Gray Speckled VFT Mastic	1200	SF	Lunch Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:same
2017 - Spring: No Change
Comments:same
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	16 x 16 inch Black VFT	300	SF	Room 100		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:same
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:same
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32 A	16 x 16 inch Black VFT Mastic	300	SF	Room 100		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:same	
2017 - Spring: No Change	
Comments:same	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Spray on Fireproofing	4000	SF	Receiving, electrical, car wash, art room, mechanical room, engineer's office		Surface	Yes	None	0		YES XNO

2016 - Fall: No Change	
Comments:same	
2017 - Spring: No Change	
Comments:same	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Carpet Mastic	2000	SF	Rooms 110,111, 119, 124 A, Entry Way, Old Storage, Hall Way, Eng. Office, Main Office and Associated Rooms		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:same	
2017 - Spring: No Change	
Comments:same	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	2x2 ft Ceiling tile with random pinholes	400	SF	Throughtout the building used as replacement tiles		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:same
2017 - Spring: No Change
Comments:same
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 49021 Page 15

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Tectum Tiles	1500	SF	Multipurpose room		Miscellaneous	No	None	0		

2016 - Fall: No Change
Comments:same
2017 - Spring: No Change
Comments:same
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ł	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	37	Curtain wall	1600	SF	Between POD #1 & POD #2		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:same
2017 - Spring: No Change
Comments:same
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Drywall System	300	SF	Student Lounge		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:same	
2017 - Spring: No Change	
Comments:same	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

ſ	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	39	MJP on fiberglass runs	10	LF	Receiving Rm		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:same	
2017 - Spring: No Change	
Comments:same	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12"x12" Pink w/White & Tan Specks VFT	3500	SF	Rms 1, 2, 3, 4, and Closets, JC, Hallway - Mobile Unit		Miscellaneous	No	None	0		

2016 - Fall: No Change
Comments:same
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:same
2010 Caring No Oberge
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40A	12"x12" Pink w/White & Tan Specks VFT Mastic	3500	SF	Rms 1, 2, 3, 4, Closets, JC, Hallway - Mobile Unit		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:same
2017 - Spring: No Change
Comments:same
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	2' x 2' Ceiling Tiles	3200	SF	Rms 1, 2, 3, 4, and Closets, JC, Hallway - Mobile Unit		Miscellaneous	Yes	None	0		

· · · ·	
2016 - Fall: No Change	
Comments:same	
2017 - Spring: No Change	
Comments:same	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Drywall System	10000	SF	Throughout Mobile Unit		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:same	
2017 - Spring: No Change	
Comments:same	
2017 - Fall: No Change	
Comments:	
Onto During No Olivers	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	Vinyl Baseboard Mastic	1100	LF	Throughout Mobile Unit EXCEPT Boys and Girls		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:same
2017 - Spring: No Change
Comments:same
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	Textured Ceiling	400	SF	Boys and Girls Toilets- Mobile Unit		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:same
2017 - Spring: No Change
Comments:same
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Vinyl Flooring Mastic	350	SF	Boys and Girls Toilets- Mobile Unit		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:same	
2017 - Spring: No Change	
Comments:same	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2049 Folly No Change	
2018 - Fall: No Change	
Comments:	

ALL LEA Responsibilities, for this school, will be met.

Alunha /2

Robert Christlieb

#### NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Northside Learning Center High School
Date:	1/7/2019

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016.

Asbestos surveillances are conducted every six months.

#### CHECK ONE

A copy of this notice was sent home in each child's back	ack.
--	------

A copy of this notice was printed in the school's newsletter and sent home with each child

A copy of this notice was printed in the school's calendar and sent home with each child

Other.

# A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.