## **Chicago Public Schools**

## **6 Month Asbestos Surveillance** 2018 - Fall

Chicago Vocational Career Academy High School 53011 Building ID: 1010 School: **Oracle Unit:** 2100 E. 87th St. Address: Region: Mail Room: Asbestos Surveyor: Gordon, Sandra X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/12/2018 Email Address: A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type 9x9 Tan Floor Tile YES X NO 13A 1939 - Rooms 206, 218 Miscellaneous (ABATED) 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments:

13B	9x9 Dark Beige w/ Brown Streaks Floor Tile ABATED			Rooms 250 and 280		Miscellaneous					YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Fall:	No Change				_							
Comments:					-							
	g: No Change											
Comments:					-							
	g : No Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
13D	9x9 White with Gray Streaks Floor Tile ABATED			Rooms 255 and 273		Miscellaneous	No				YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Spring : No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Units

Material

Quantity

Material Location

13E	9x9 Beige With Streaks and Green Checkerboard Patterned Floor Tile	200	SF	Main Office (Vault)		Miscellaneous	No	None	0	YES	X NO
2016 Fall N	o Chango			•	1						
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:					]						
2018 - Spring	: No Change				]						
Comments:	-				1						
					]						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13F	9x9 Black w/Cream and Green Streaks Floor Tile	2900	SF	Auditorium 1st Floor (Foyer)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

13G	9x9 Cream with Black Streaks Floor Tile (MATERIAL REMOVED)			Rooms 021, 013, 012 MATERIAL REMOVED		Miscellaneous					YES	X NO
004C F-II	No Observe	•	•	•	1	•	•	•	•	•	•	
2016 - Fall:												
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2018 - Sprir	ng : No Change											
Comments:												
					]							
HA No	Material Description	Material	Material	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

Page 4

Material Location

HA NO	Material Description	Quantity	Units	iviaterial Location	Type	Category	Filable	Type	Quantity	Units	Change in Assess	sment Category
13H	9x9 Beige with Multi- Colored Streaks Floor Tile	260	SF	1st Floor Women's Restroom and Corridor (West End)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

14B	Black Linoleum (Not Observed)			Room 130		Miscellaneous					YES	X NO
2016 - Fall: I	No Chango				7							
Comments:	ino Change				-							
Comments.					-							
2017 - Fall: I	No Change											
Comments:	<u> </u>											
_												
	g: No Change											
Comments:												
2010 0					4							
	g : No Change				_							
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
15A	12 x 12 Beige and Purple Checker Board Patterned	500	SF	Room 002		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Floor Tile

Material

Quantity

Material

Units

Material Location

15B	12 x 12 Cream and Tan Checker Board Patterned Floor Tile Mastic	500	SF	Room 002		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change	•	•	•	_ _	·					•	
					-							
Comments:												
2017 - Fall:	No Change				-							
Comments:	Ţ											
2017 - Sprir	ng: No Change											
Comments:												
2018 - Sprir	ng : No Change											
Comments:												
	1					1		_	1 -	I -		

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asses	sment Category
15D	12x12 Reddish Orange with Speckles Floor Tile (MATERIAL REMOVED)			room 206 MATERIAL REMOVED		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				]							
Comments:					]							
2017 - Spring	g: No Change											

Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change

Comments:

HA No

Material Description

12 x 12 Cream and Tan

Material

Quantity

Material

Units

Material Location

Page 6

15E	12x12 Cream Floor Tile (MATERIAL REMOVED)			room 214 MATERIAL REMOVED		Miscellaneous	No				YES	X NO
2016 - Fal	: No Change				1							
Comments	0				1							
2017 - Fal	: No Change				1							
Comments												
2017 - Spr	ing: No Change				1							
Comments	S:											
2018 - Spr	ing : No Change				_							
Comments	S:											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
15F	12x12 Brown Multi-Color Beige Floor Tile (MATERIAL REMOVED)			Room 013, 206 MATERIAL REMOVED	7.	Miscellaneous		, , , , , , , , , , , , , , , , , , ,			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Material

Quantity

Material

Units

HA No

Material Description

15G	12x12 Gray Floor Tile			Rooms 260, 261, 265, 268, 269, 270A and 271		Miscellaneous	No				YES	X NO
2016 - Fal	I: No Change											
Comments												
2017 - Fal	I: No Change				+							
Comments												
2017 - Spr	ring: No Change				-							
Comments	S:				=							
2018 - Spr	ring : No Change											
Comments	3:											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
	12x12 Burnt Orange Floor			Room 206, 2nd Floor								

Type

Material

Category

Miscellaneous

Friable

Damage

Type

None

Damage

Quantity

Damage

Units

Material Location

Rooms 260, 261, 265,

Teacher's Room

MATERIAL REMOVED

Material

Units

Material

Quantity

HA No

15H

Material Description

Tile (MATERIAL

REMOVED)

Change in Assessment Category

X NO

VES

151	speckles floor tile (REMOVED MATERIAL)			room 206, 208 MATERIAL REMOVED		Miscellaneous					YES	X NO
004C F-II	No Observe		-	•	7							
	: No Change											
Comments												
					1							
2017 - Spri	ng: No Change											
Comments	:				1							
	-											
2017 - Fall:	: No Change											
Comments	:											
2018 - Spri	ng : No Change											
Comments												
<u>'</u>												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

0

None

Damage

Units

1600

Material

Units

SF

Material

Quantity

Material Location

Rooms 214B, 104

HA No

15J

Material Description

12x12 black with white

12x12 red floor tile

Change in Assessment Category

X NO

15K	12x12 Cream with Red Streaks Floor Tile (Not Observed)			Room 208 NOT OBSERVED		Miscellaneous					YES	X NO
2016 - Fall:	No Change	•	<u>*</u>	•			•	•	•	•	•	
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprir	ng : No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		zaregory
	12x12 White with Brown	+										

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

main office, Rm 010

Material

Units

Material Quantity

HA No

15L

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Spring: No Change

Material Description

Speckles Floor Tile (Not Observed)

Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15M	12x12 Black Floor Tile As Edging	115	SF	Room 212		Miscellaneous	No	None	0		YES X NO
2016 - Fall:	: No Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
150	12x12 Tourquoise With Light Gray Checkerboard Floor Tile	1500	SF	Rooms 023, 009, 023, 009, 105		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

15P	12x12 Black and Maroon Checkerboard Floor Tile	400	SF	Auditorium Pit		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall	No Change				1							
Comments												
2017 - Spri	ng: No Change											
Comments					1							
2017 - Fall:	No Change											
Comments	:											
2018 - Spri	ng : No Change											
Comments												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
15Q	12x12 Reddish Brown with White Streaks (Not			room 256 NOT		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Observed)

Material

Quantity

Material

Units

Material Location

OBSERVED

15R	12x12 Purple With White Checkerboard Floor Tile (Not Observed)			Room 002		Miscellaneous					YES	X NO
2016 - Fall:	No Chango			•								
Comments:												
2017 - Fall:	No Change											
Comments:												
Committee												
2017 - Sprir	ng: No Change											
Comments:												
Comments.					_							
2040 Cmris	ar . No Change				_							
	ng : No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
11/(140	Waterial Besonption	Quantity	Units	Waterial Education	Type	Category	THADIC	Type	Quantity	Units	Change in 7 toocot	smort oatogory
		Lucinity	00		.,,,,,	Calogory		.,,,,,	a a a . itity	00		
	12x12 peach with cream					1		1			l <del></del>	

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

room 104

Material

Quantity

Material

Units

HA No

15U

Material Description

speckles checkerboard floor tile (NOT OBSERVED) Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15V	12x12 Dark and Light Blue Checkerboard Floor Tile	500	SF	Room 105		Miscellaneous		None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:	
2047 Fall Na Obarra	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15W	12x12 Gray/Light Blue Speckled Floor Tile	2000	SF	Rooms 109 and 112-114		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

15X	12x12 Gold and Multi-Color Dark Blue Checkerboard Floor Tile (Not Observed)			Rooms 115 and 118 NOT OBSERVED		Miscellaneous					YES	X NO
		•		•	1		·			•	•	
2016 - Fall: N	No Change											
Comments:												
					1							
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
1		Quantity	Units		Type	Category	1	Type	Quantity	Units	1	

Type

Material

Category

Miscellaneous

Friable

Damage

Туре

Damage

Quantity

Damage

Units

15Z	12x12 multicolor light blue floor tile (Not Observed)			room 014 NOT OBSERVED					
2016 - Fall:	No Change								
Comments:									
2017 - Fall:	No Change								
Comments:									
2017 - Sprir	ng: No Change								
Comments:									
2018 - Sprir	ng : No Change								
Comments:	Comments:								

Material

Units

Material

Quantity

Material Location

HA No

Material Description

12x12 Gold and Multi-Color

Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
18A	Mauve Carpet Mastic	3500	SF	Rooms 231, 252A, 166, 135, 134A, 126, and 125		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	l: No Change											
Comments	S:											
2017 - Fall	l: No Change											
Comments	S:											
2017 - Spri	2017 - Spring: No Change											
Comments	Comments:											
2018 - Spri	2018 - Spring : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18B	Blue-Speckled Carpet Mastic	500	SF	room 200		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

18C	Blue Carpet Mastic	750	SF	Room 200		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change				]						
Comments:											
2017 - Spri	ng: No Change										
Comments:											
2017 - Fall:	No Change										
Comments:					-						
2018 - Spri	ng : No Change										
Comments:											

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18D	Beige Carpet Mastic	3000	SF	Rooms 231, 252A, 166, 135, 134A, 126, and 125		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

18E	Burgandy Carpet Mastic (MATERIAL REMOVED)	1300	SF	Room 126 MATERIAL REMOVED		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				1							
	No Change											
Comments:					1							
2017 - Fall: N	No Change				-							
Comments:												
					1							
2017 - Sprin	g: No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category		Туре	Quantity	Units		

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

18F

2016 - Fall: No Change

Material Description

Orange Carpet Mastic (MATERIAL REMOVED)

Material

Quantity

Material

Units

Material Location

room 231

Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
21	Transite	3830	SF	shower area, old garage siding, kitchen receiving, room 167 and interior of old garage		Miscellaneous	No	None	0		YES	X NO
2016 - Fal Comments	II: No Change s:											
2017 - Spr	ring: No Change											
Comments	s:				=							
2017 - Fal	II: No Change											

Comments: 2018 - Spring: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21A	Corragated Transite Panels (MATERIAL REMOVED)			Greenhouse MATERIAL REMOVED		Miscellaneous	No				YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
·	_

Page 19

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
28	9x9 brown floor tile	2800	SF	1943 - room 262 and hallway		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28C	9 x 9 Pink floor tile (MATERIAL REMOVED)	2800	SF	1943 - Room 282		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28D	9 x 9 Light Gray Floor Tile	1800	SF	1943 - Rooms 021 and (288 Abated)		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28E	9 x 9 Gray floor tile (MATERIAL REMOVED)	2800	SF	1943 - Room 286		Miscellaneous	No	None	0		YES X NO

0040 5 11 N1 O1	
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categ	ory
28F	9 x 9 Beige with Brown and White Streaks	1000	SF	1943 - Rooms 280, 282 (Back Room), and 250		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: N	lo Change				]							

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28G	9 x 9 Maroon with Beige Checkerboard Floor Tile (MATERIAL REMOVED)	2375	SF	1943 - Room 273, 279, 281, 265, 267		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28H	9 x 9 Tan Speckled Floor Tile	1600	SF	1943 - Rooms 281 and 299		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
28J	9 x 9 Red with Speckles Floor Tile	800	SF	1943 - Rooms 256 and 279		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
28K	9 x 9 Gray with Dark Gray Streaks Flor Tile (MATERIAL REMOVED)	2100	SF	1943 - Room 286 (Front) (Back), 285, 287 MATERIAL REMOVED		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change			•								
Comments:												
2017 - Fall: No Change												
Comments:												

2017 - Spring: No Change Comments:

2018 - Spring : No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
28L	9x9 dark gray with black and white streaks floor tile (MATERIAL REMOVED)	1175	SF	1943 - 288		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28N	9 x 9 White with Black Streaks Floor Tile	1000	SF	1943 - Rooms 255, 273, and 288		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
29	12x12 red with black and white blotches floor tile	3500	SF	1943 - rooms 019, 022, 020, 117		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

29A	12 x 12 Cream with Multicolor Beige Cherckerboard Floor Tile	2600	SF	1943 - Room 259, 008, 024, 106, 135, 136, 326, 338		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change				7							
Comments					]							
2017 - Spr	ring: No Change											
Comments	3:											
	I: No Change											
Comments	S:											
2018 - Spr	ring : No Change											
Comments	S:				_							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessn	nent Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

Damage

Type

Type

Damage

Quantity

Quantity

Damage

Units

Units

YES

(ABATED)		
2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:	•	

Quantity

Units

Material

Units

Material

Quantity

Material Location

1943 - Room 260

1943 - Room 259, 008,

HA No

29B

Material Description

12 x 12 Light and Dark Gray Multicolor Floor Tile

12 x 12 Cream with

Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29C	12 x 12 Dark Gray with Black and Orange Streaks Floor Tile (MATERIAL REMOVED)	2855	SF	1943 - Room 260, 268, 271, 269, 270A MATERIAL REMOVED		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29D	12 x 12 Maroon Floor Tile (MATERIAL REMOVED)	2800	SF	1943 - Room 262 MATERIAL REMOVED		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

12 x 12 Cream with Tan 1943 - Women's Restroom 2nd Floor New Tile (MATERIAL) 1500 SE Restroom 2nd Floor	
29E Floor Tile (MATERIAL REMOVED) 1500 SF RESCION ATERIAL REMOVED Miscellaneous No None 0	X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29G	12 x 12 White Floor Tile (ABATED)			1943 - Room 271		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

				(							
2016 - Fall:	: No Change				]						
Comments:					_						
2017 - Sprir	ng: No Change										
Comments:	· ·				_						
2017 - Fall:	: No Change										
Comments:	· ·				_						
2018 - Sprir	ng : No Change										
Comments:	<u>:</u>				_						
					]						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

Asbestos

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

		Quantity	Units		Type	Category		Type	Quantity	Units	
291	12 x 12 Beige Floor Tile (ABATED)			1943 - Room 272, 276, 285, 286, and Corridor		Miscellaneous	No				YES
2016 - Fa	all: No Change				]						
Commen	ts:										
2017 - Fa	all: No Change										
Commen	ts:										
	oring: No Change										
Common	to:										

Comments: 2018 - Spring: No Change Comments:

HA No

29H

Material Description

12 x 12 Multicolor Beige

Floor Tile

Material

Units

SF

Material

Quantity

Material Location

1943 - Room 2047 Men's

Restroom (abated 288)

Page 29

Change in Assessment Category

X NO

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29K	12 x 12 Tourquise with Gray Speck Checkerboard Pattern Floor Tile (Not Observed)	2400	SF	1943 - Rooms 009, 023, 156, and 277		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	9 x 9 Grey Floor Tile Mastic (NOT OBSERVED)	2900	SF	1939 - Room 010, 222, 103, 013, 011, 012, 021		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

30A	9 x 9 Tan Floor Tile Mastic (ABATED)	1939 - Room 218 and 206	Miscellaneo	s No		YES	X NO
2016 - Fall:	No Change		7				
			=				
Comments:							
2017 - Sprir	ng: No Change						
Comments:							
			7				
2017 - Fall:	No Change						
Comments:	-		]				
			7				
2018 - Sprir	ng : No Change						
Comments:	-		]				
			1				
			<del>_</del>				

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

1939 - Room 218 and

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30B	9 x 9 Dark Beige with Brown Streaks Floor Tile Mastic	1000	SF	Rooms 250 and 280		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

9 x 9 Tan Floor Tile Mastic

Material

Quantity

Material

Units

30D	9 x 9 White with Gray Streaks Floor Tile Mastic	600	SF	Rooms 255 and 273		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Chango										
	NO Change										
Comments:											
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2018 - Spring	g : No Change										
Comments:	<u> </u>										
	Tara da la companya d	1		Tana and a	T	T		1 -	T =		

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
30E	Beige with Green Checkerboard Floor Tile Mastic	200	SF	Main Office (vault)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

30F	9 x 9 Black with Cream and Green Streaks Floor Tile Mastic	85	SF	Auditorium 1st Floor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change		•	•	]	•	•	•	•	•	•	
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
	ng : No Change											
Comments:												
					J							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30G	White and Black Streaks Floor Tile Mastic (MATERIAL REMOVED)	280	SF	Room 021, 013, 012 MATERIAL REMOVED		Miscellaneous	No	None	0		YES X NO

_	
2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

30H	9 x 9 Beige with Multicolor Streaks Floor Tile Mastic	260	SF	Restroom and Corridor (West End)		Miscellaneous	No	None	0		YES	X NO
0040 F.II	NI OL TOTAL				1							
2016 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprin	ng : No Change											
Comments:	-											
					=							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

No

Damage

Type

Type

Damage

Quantity

Quantity

Damage

Units

Units

YES

X NO

	Madio ABATE			rianway							
2016 - Fall: No Change											
Comments:											
2017 - Fall: N	2017 - Fall: No Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2018 - Spring	: No Change										
Comments:	Comments:										

Quantity

Units

HA No

31

Material Description

9 x 9 Brown Floor Tile

Mastic ABATED

Material

Units

Material

Quantity

Material Location

1st Floor Women's

1943 - Room 262 and

Hallway

Page 34

31C	9 x 9 Pink Floor Tile Mastic (MATERIAL REMOVED)	2800	SF	1943 - Room 282 MATERIAL REMOVED		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: No Change											
Comments:											
	ring: No Change										
Comment	S:										
2017 - Fa	II: No Change										
Comment	S:										
2018 - Sp	ring : No Change										
Comment	s:			·							

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31D	9 x 9 Light Gray Floor Tile Mastic (ABATED)			1943 - Rooms 021 and 288		Miscellaneous	No				YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
31E	9 x 9 Gray Floor Tile Mastic (MATERIAL REMOVED)	2800	SF	1943 - Room 286 MATERIAL REMOVED		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31F	12 X 12 Beige with Brown and White Streaks Floor Tile Mastic	500	SF	1943 - Rooms 250 and 280		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31G	9 x 9 Maroon with Beige Checkerboard Patterned Floor Tile Mastic (Not Observed)	2375	SF	1943 - Room 273, 279, 281, 265, 267		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
31H	9 x 9 Tan Speckled Floor Tile Mastic			1943 - Rooms 279 and 281		Miscellaneous	No				YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Catego	ory
31J	9 x 9 Red with Speckles Floor Tile Mastic	800	SF	1943 - Rooms 256 and 279		Miscellaneous	No	None	0		YES X NO	
2016 - Fall:	Vo Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31K	9 x 9 Gray with Dark Gray Streaks Floor Tile Mastic (MATERIAL REMOVED)	900	SF	1943 - Room 286 (Front) (Back), 285, 287		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

31L	9 x 9 Dark Gray w/Black Streaks Floor Tile Mastic (MATERIAL REMOVED)	900	SF	Room 288 MATERIAL REMOVED		Miscellaneous	No	None	0	YES	X NO
2016 - Fa	ıll: No Change				7						
Comment											
2017 - Fa	ıll: No Change				1						
Comment	ts:										
2017 - Sp	oring: No Change										
Comment	ts:										
2018 - Sp	oring : No Change										
Comment	ts:										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31N	White with Black Streaks Floor Tile Mastic	600	SF	1943 - Rooms 255, 273, and 288		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

9 x 9 Dark Gray w/Black

Material

Quantity

Material

Units

Page 39

32	12 x 12 Beige Floor Tile	370	SF	Rooms 175, 216, hanger		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				1							
Comments:	<u> </u>											
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:					1							
2018 - Spring	g : No Change											
Comments:					_							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Friable

No

Miscellaneous

Damage

Туре

None

0

Damage

Quantity

Damage

Units

IVIASTIC		
2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		

500

SF

Room 002

HA No

32A

Material Description

12 x 12 Beige and Purple Checkerboard Floor Tile Material

Quantity

Material

Units

Material Location

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
32AA	12 x 12 Tan with Multicolor Gloor Tile Mastic	2690	SF	1st, 2nd Floor Engineer Office, 008, Teacher's Lounge, 136, Aud., East Dressing Rm, Football Storage		Miscellaneous	No	None	0		YES	X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32B	12 x 12 Cream and Tan Checkerboard Floor Tile Mastic	500	SF	Room 145		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

32D	12 x 12 Reddish Orange Floor Tile Mastic (NOT OBSERVED)		Room 206		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change	<u> </u>	·	]					·		
Comments:	V										
2017 - Fall: N	No Change										
Comments:	<u> </u>										
2017 - Sprin	g: No Change										
Comments:											
2018 - Sprin	g : No Change										
Comments:	<u> </u>										
				J							

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32E	12x12 cream floor tile mastic (NOT OBSERVED)	800	SF	room 214		Miscellaneous	No	None	0		YES X NO
0040 5 11 11	01				1						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

32F	12 x 12 Brown (Multicolored Beige) Floor Tile Mastic (NOT OBSERVED)	11265	SF	Room 010 NOT OBSERVED	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:	go									
2017 - Fall: N	o Change									
Comments:	o Change									
	N. O.									
2017 - Spring	: No Change									
Comments:										
2018 - Spring	: No Change									
Comments:	<u> </u>									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
32G	12 x 12 Gray Floor Tile Mastic ABATED			Rooms 260, 261, 265, 268, 269, and 270A		Miscellaneous					YES	X NO
2016 - Fall: N Comments:	lo Change											

2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments:

Material

Quantity

Material

Units

HA No

Material Description

2018 - Spring : No Change Comments:

32H	12 x 12 Burnt Orange Floor Tile Mastic NOT OBSERVED		Room 2nd Floor Teacher's Room NOT OBSERVED		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change	·	•	7				•		
	O Change			_						
Comments:				_						
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Spring	: No Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

12 x 12 Black with White Room 206, 208, Material	
32I Speckles Floor Tile Mastic (Not Observed) Miscellaneous No None 0	X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Oracle Unit: 53011

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
32J	12 x 12 Red Floor Tile Mastic	2000	SF	Rooms 104, 241B, 256, and 258		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments:	<u> </u>											
2017 - Fall: Comments:												

2017 - Spring: No Change Comments:

2018 - Spring : No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32K	12 x 12 Cream with Red Streaks Floor Tile Mastic (Not Observed)		SF	Room 208		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

32L	White and Brown Speckles Floor Tile Mastic (Not Observed)	1400	SF	Room 208, Main Office		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Chango				]						
	o Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2018 - Spring	: No Change										
Comments:	-										

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
32M	12 x 12 Black Floor Tile Mastic as an Edging	115	SF	Room 212		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

2018 - Spring : No Change Comments:

HA No

Material Description

Material

Quantity

Material

Units

320	12 x 12 Tourquise and Light Gray Checkerboard Floor Tile Mastic	2000	SF	Rooms 009, 023, 105, 156		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Chango	•	•		· ]	•	-	•	•	•	•	
Comments:												
2017 - Sprin	ng: No Change											
Comments:												
Comments.												
00.45 5 11					-							
2017 - Fall:	No Change											
Comments:												
2018 - Sprin	ng : No Change				1							
Comments:												
	_	•			1							
					_							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
32P	Black and Maroon Checkeboard Floor Tile Mastic	400	SF	Auditorium Pit		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

32Q	White Streak Floor Tile Mastic (Not Observed)			Room 256		Miscellaneous	No	None	0		YES	X NO
0040 5 11	N. O.			•	_							
	: No Change											
Comments	s:											
2017 - Spr	ing: No Change											
Comments	;											
2017 - Fall	: No Change											
Comments	::											
2018 - Spr	ing : No Change											
Comments												
					<u> </u>							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

Friable

No

Damage

Туре

None

Damage

Quantity

0

Damage

Units

32R	Checkerboard Floor Tile Mastic (Not Observed)		Room 020
2016 - Fall: N	o Change	•	
	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2018 - Spring	: No Change		
Comments:			
	·		

HA No

Material Description

12 x 12 Purple/White

12 x 12 Reddish Brown w/

Material

Quantity

Material

Units

Material Location

YES

Change in Assessment Category

X NO

32U	Peach and Cream Speckles Floor Tile Mastic (Not Observed)	3		Room 108		Miscellaneous	No	None			YES	X NO
004C Fall N	In Ohaman	•	•	•	1	•	•	•	•	•	•	
2016 - Fall: N	io Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
					1							
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:	-				]							
			•		<del>-</del>							
HA No	Material Description	Material	Material	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

TIATO	Waterial Description	Quantity	Units	Waterial Education	Type	Category	THADIC	Туре	Quantity	Units	Change in Asses	Sameric Category
32V	Dark and Light Blue Checkerboard Floor Tile Mastic	500	SF	Room 105		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				]							
Comments:												
2017 - Sprir	ng: No Change				-							

Comments:

2017 - Fall: No Change

Comments:

2018 - Spring : No Change

HA No

Comments:

Material Description

Material

Quantity

Material

Units

32W	12 x 12 Gray/Light Blue Speckled Floor Tile Mastic	2000	SF	Rooms 112, 113, 114, and 109		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	Vo Change				1							
Comments:	10 Onango											
2017 Spring	g: No Change											
Comments:	g. No Change											
2017 - Fall: N	No Change											
Comments:												
2018 - Spring	g : No Change				1							
Comments:												
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
TIATIO	Material Description	Quantity	Units	Waterial Education	Type	Category	THADIC	Type	Quantity	Units	Onange in Assess	ancin Calegory

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

JZX	Tile Mastic (Not Observed)		1100110 110, 110
2016 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2018 - Spring	: No Change		
Comments:		 	

Material

Quantity

Material

Units

Material Location

Rooms 115, 118

HA No

32X

Material Description

Gold and Multicolor Dark

Blue Checkerboard Floor

Change in Assessment Category

X NO

YES

32Z	12 x 12 Multicolor Light Blue Floor Tile Mastic (Not Observed)			Room 014		Miscellaneous	No			YES	X NO
2016 - Fall: N	lo Change			•				·		•	
	Comments:										
Comments:											
2017 - Spring: No Change											
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2018 - Spring	g : No Change										
Comments:											
					<u>-</u> '						

Type

Material

Material

Category

Friable

Friable

Damage

Damage

Type

Damage

Quantity

Damage

		Quantity	Units		Туре	Category		Type	Quantity	Units		
33	12 x 12 Red w/White and Black Blotches Floor Tile Mastic	3500	SF	1943 - Rooms 217, 117, 022, 020, and 019		Miscellaneous	No	None	0		YES	
2016 - Fa	all: No Change				]							
	Comments:											
2017 - S	pring: No Change											
Commer	nts:											

Asbestos

2017 - Fall: No Change
Comments:

2018 - Spring : No Change
Comments:

HA No

HA No

Material Description

Material Description

Material

Material

Units

Material

Quantity

Material

Material Location

Material Location

Change in Assessment Category

Change in Assessment Category

X NO

Damage

Damage

Units

33A	Beige Checkerboard Patterned Floor Tile Mastic	8000	SF	1943 - Room 008, 024, 135, 136, 259, 266, 338		Miscellaneous	No	None	0		YES X NO
					7						
2016 - Fa	II: No Change										
Comment	s:										
2017 - Sp	ring: No Change										
Comment	s:										
2017 - Fa	II: No Change										
Comment	s:										
2018 - Sp	ring : No Change										
Comment	S:										
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

Damage

Type

Type

Damage

Quantity

Quantity

Damage

Units

Units

YES

33B	Gray Floor Tile Mastic (Not Observed)	1943 - Room 260
204C Falls	No Change	
2016 - Fall:	No Change	
Comments:		
2017 - Fall:	No Change	
Comments:		
2017 - Sprir	ng: No Change	
Comments:		
2018 - Sprir	ng : No Change	
Comments:		

Quantity

Units

HA No

Material Description

12 x 12 Light and Dark

12 x 12 Creme w/Mulitcolor

Material

Units

Material

Quantity

Material Location

Change in Assessment Category

X NO

33C	12x12 Dark Gray w/Black and Orange Streaks Floor Tile Mastic (Not Observed)	1943 - Room 260, 268, 271, 269,	Miscellaneous			YES	X NO
2016 - Fal	: No Change						
Comments							
	•						
2017 - Fal	: No Change						
Comments	<b>:</b>						
2017 - Spr	ing: No Change						
Comments	S:						
	ing : No Change						
Comments	S:						
	_	·					

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33D	12 x 12 Maroon Floor Tile Mastic (Not Observed)	2800	SF	1943 - Room 262		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No

Material Description

12x12 Dark Gray w/Black

Material

Quantity

Material

Units

33E	12 x 12 Cream with Tan Floor Tile Mastic (Not Observed)	2335	SF	1943 - Women's Restroom 2nd Floor (2043), 270	Miscellaneous	No	None	0		YES	X NO
	II: No Change			·				·	•		
Commen											
	oring: No Change										
Commen	IS:										
2017 - Fa	II: No Change										
Commen	ts:										
2018 - Sp	oring : No Change										
Commen	ts:										

Type

Asbestos

Type

Material

Material

Surface

Category

Category

Friable

Friable

Damage

Damage

Type

Type

Damage

Quantity

Damage

Quantity

Damage

Damage

Units

Units

Observed)		
2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:	•	

Material

Quantity

Material

Material

Units

Units

Material Quantity Material Location

1943 - Women's

Material Location

1943 - Room 271

HA No

HA No

33G

Material Description

12 x 12 Cream with Tan

Material Description

Mastic Beneath 12 x 12

White Floor Tile Mastic (Not

Page 54

Change in Assessment Category

Change in Assessment Category

X NO

YES

331	12 x 12 Beige Floor Tile Mastic			1943 - Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				]							
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:					 							
2018 - Sprin	g : No Change											
Comments:					 							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

Damage

Quantity

Damage

Units

		-									
33J	Dark, Light Beige/Gray Checkerboard Petterned Floor Tile Mastic (ABATED)			1943 - Room 282 (Back Room)							
2016 - Fall: N	lo Change										
Comments:											
2017 - Spring	2017 - Spring: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2018 - Spring : No Change											
Comments:											
	_		•								

HA No

Material Description

12 x 12 Beige Floor Tile

Material

Quantity

Material

Units

Material Location

Page 55

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33K	12 x 12 Tourquise with Gray Floor Tile Mastic	2400	SF	1943 - Rooms 009, 023		Miscellaneous	No	None	0		YES X NO
0040 5 11					1						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Mastic Beneath Linoleum (NOT OBSERVED)	5600	SF	Gym (Room 251) 253		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

34A	Red, Black, Brown, and Tan Linoleum Pattern Mastic (Not Observed)			Auditorium 1st and 2nd Floor Foyer		Miscellaneous					YES	X NO
		•	•	•	- -	•	•	•	•	•	•	
2016 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:	•											
2017 - Fall:	No Change											
Comments:												
2018 - Sprir	ng : No Change											
Comments:												
					_							
HA No	Material Description	Material	Material Units	Material Location	Asbestos	Material	Friable	Damage Type	Damage	Damage	Change in Assess	sment Category
1	1	Quantity	UTILS	1	Type	Category	1	I I VDE	Quantity	Units		

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

Damage

Quantity

Damage

Units

34B	Black Linoleum Mastic (NOT OBSERVED)			Room 130								
2016 - Fall: No Change												
Comments:												
2017 - Spring	2017 - Spring: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring : No Change												
Comments:												

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Red, Black, Brown, and

YES

X NO

35	Dark Blue Linoleum (NOT OBSERVED)	1600	SF	Room 208	Miscellaneous			YES	X NO
2016 - Fall: N	o Change								
Comments:	o onange								
Comments.									
2017 - Spring	: No Change								
Comments:	<b>-</b>								
2015 5 11 11									
2017 - Fall: N	o Change								
Comments:									
2018 - Spring	: No Change								
Comments:									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
36	9x9 Gray Tiles (NOT OBSERVED)		SF	Room 288		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
37	9x9 Brown Floor Tile (NOT OBSERVED)	720	SF	286A		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												
2017 - Spring: No Change												

2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12 x 12 Beige Floor Tile	5600	SF	3rd floor Hallway, Rooms 28, 100, 120, 127, and Lunchroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

38M	12 x 12 Beige Floor Tile Mastic	5600	SF	3rd floor Hallway, Rooms 28, 100, 120, 127 and Lunchroom	Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change	•		·						
Comments:	10 Orlange									
	g: No Change									
Comments:										
2017 - Fall:	No Change									
Comments:	J. J. J. J.									
2018 - Sprin	g : No Change									
Comments:	g . Ho onango									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

3rd floor Hallway, Rooms

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12 x 12 White with Beige Specks Floor Tile	123000	SF	Rooms 010, 011, 012, 113, 116, 145A, 134, 209C, 212, 214, 218, 222, 248, and 318		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39M	12 x 12 White with Beige Specks Floor Tile Mastic	123000	SF	Rooms 010, 011, 012, 113, 116, 145A, 134, 209C, 212, 214, 218, 222, 248, and 318		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12 x 12 Yellow with White Floor Tile	10000	SF	Rooms 103A, 103B, 103C, 103D, 204, 205, 205A, 206, 213A, 213B, 213D, and Hallway		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40M	12 x 12 Yellow with White Floor Tile Mastic	10000	SF	Rooms 103A, 103B, 103C, 103D, 204, 205, 205A, 206, 213A, 213B, 213D, and Hallway		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12 x 12 Beige Speckled Floor Tile	300	SF	Rooms 216 (abated 175)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

41M	12 x 12 Beige Speckled Floor Tile Mastic	300	SF	Rooms 216 (175 Abated)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				1							
Comments												
2017 - Spri	ing: No Change				-							
Comments					-							
2017 - Fall	: No Change				-							
Comments	i:				1							
2018 - Spri	ing : No Change				=							
Comments	:											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
	12 x 12 Red and White	1 2 2 2 3			71	J - 7		,,				

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

42

Comments:

Comments:

Comments:

Comments:

Material Description

12 x 12 Beige Speckled

Checkered Floor Tile

(ABATED)

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Spring : No Change

Material

Quantity

Material

Units

Material Location

Room 179

Change in Assessment Category

YES

X NO

42M	12 x 12 Red and White Checkered Floor Tile Mastic (not Observed)	500	SF	Room 179		Miscellaneous	No	None	0	YES	X NO
2016 - Fal	I: No Change		<u> </u>		_ _						
Comments											
2017 - Spi	ring: No Change										
Comments	3:										
2017 - Fal	I: No Change										
Comments	3:										
2018 - Spi	ring : No Change										
Comments	3:			<u> </u>	_						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12 x 12 Brown, Beige and Red Floor Tile	2000	SF	Cafeteria Court		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

		-				0 ,			_		
43M	12 x 12 Brown, Beige and Red Floor Tile Mastic	2000	SF	Cafeteria Court		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	No Change				]						
Comments:											
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	No Change										
Comments:					  -						
2018 - Spring	g : No Change										

Material

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	Beige Linoleum	500	SF	Room 013		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

2016 - Fall:	: No Change										
Comments	Comments:										
	ing: No Change										
Comments	:										
	: No Change										
Comments	:										
2018 - Spri	ing : No Change										
Comments	:										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

2016 - Fall: No	o Change			
Comments:				
2017 - Spring:	No Change			
Comments:				
2017 - Fall: No	o Change	 	<u>.</u>	
Comments:				
2018 - Spring	: No Change			
Comments:				

10000

Material

Quantity

500

Material

Units

SF

SF

Material Location

Room 013

Stairwells

HA No

44M

45

Material Description

Beige Linoleum Adhesive

Gray Terrazo

Change in Assessment Category

X NO

X NO

YES

YES

46	Beige Terrazzo	2000	SF	Main Hallway		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	<b>3</b>											
2017 - Spring	g: No Change											
Comments:					]							
2017 - Fall: N	lo Change											
Comments:					<u> </u>							
2018 - Spring	g : No Change											
Comments:					-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Yes

Friable

Damage

Туре

Damage

Quantity

0

None

Damage

Units

2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Spring	: No Change		
Comments:	_	•	

4000

SF

Lunchroom

Material

Quantity

Material

Units

Material Location

HA No

47

Material Description

1 x 1 Ceiling Tile

YES

X NO

47M	1 x 1 Ceiling Tile Adhesive	4000	SF	Lunchroom	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2018 - Spring	: No Change									
Comments:										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	2 x 4 Lay In Ceiling Panels	50000	SF	1st, 2nd and 3rd Floor Hallways		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	2 x 4 Lay In Smooth Ceiling Panels	900	SF	Band Room and 014		Miscellaneous	Yes	None	0		YES X NO
0040 Fall N	- Ohana				1						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	2 x 2 Lay In Ceiling Panels	6000	SF	Rooms 204, 205, and 213		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
150A	12x12 White w/ multicolored specks VFT	700	SF	Rooms 073, 156, 106		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments	:											
2017 - Spri	ng: No Change											
Comments	:											
2017 - Fall:	No Change											
Comments	•											
2018 - Spri	ng : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
150AM	12x12 White w/ multicolored specks VFT Mastic	700	SF	Room 023, 156, 106		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

Page 70

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
151	Gray linoleum	1000	SF	Rooms 150, 012, 009		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments												
2017 - Fall:	No Change											
Comments	:				_							
2017 - Spri	ng: No Change											
Comments	:				_							
2018 - Spri	ng : No Change											
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
152	12x12 Purple w/dark purple specks VFT	300	SF	Room 106		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	ory
152M	12x12 Purple w/dark purple specks VFT Mastic	300	SF	Room 106		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: N	lo Change				]							

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
153	12x12 Gray w/black + dark greay specks VFT	2900	SF	Room 267 (Anthony wing)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 72

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
153M	12x12 Gray w/black + dark greay specks VFT Mastic	2900	SF	Room 267 (Anthony wing)		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
155	12x12 White w/ specks VFT	300	SF	Room 159		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
155M	12x12 White w/ specks VFT Mastic	300	SF	Room 159		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments	);											
2017 - Spri	ing: No Change											
Comments	S:											
2017 - Fall:	: No Change											
Comments	S:											
2018 - Spri	ing : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
156	12x12 Beige w/specks VFT	300	SF	Room 159		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
156M	12x12 Beige w/specks VFT Mastic	300	SF	Room 159		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change											
Comments	): 											
2017 - Spr	ing: No Change											
Comments	<b>S</b> :				_							
2017 - Fall	: No Change											
Comments	<b>:</b>				_							
2018 - Spr	ing : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
157	12x12 Pink w/specks VFT	500	SF	Room 179		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

157M	12x12 Pink w/specks VFT Mastic	500	SF	Room 179	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	lo Change									
2017 - Fall: N Comments:	lo Change									
2017 - Spring Comments:	g: No Change									
2018 - Spring Comments:	g : No Change									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
158	12x12 Tan VFT	1000	SF	Mobile Unit		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Quantity

Material

Units

HA No

158M	12x12 Tan VFT Mastic	1000	SF	Mobile unit		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change				]						
Comments:					-						
2017 - Spring	g: No Change										
Comments:					-						
2017 - Fall: N	lo Change										
Comments:											
2018 - Spring	g : No Change										
Comments:	-				1						

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
159	12x12 Algae green w/streaks VFT	300	SF	Hangar		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

159M	12x12 Algae green w/streaks VFT Mastic	300	SF	Hangar		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change	<u> </u>	<u> </u>	<u> </u>							
Comments:											
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2018 - Spring	: No Change										
Comments:											
L					I						

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Categ
160	12x12 White w/streaks VFT	300	SF	Hangar		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Spring Comments:	g: No Change				-							

2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
160M	12x12 White w/streaks VFT Mastic	300	SF	Hangar		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:					1							
2017 - Fall: N	lo Change											
Comments:					1							
2017 - Spring	g: No Change											
Comments:					<u> </u>							

Н	IA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
1	61	Linoleum Gray w/black and white stripes	4000	SF	Room 208, 208A, 145		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2018 - Spring : No Change

Comments:

162	12x12 Red VFT	456	SF	Room 217, 117	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:	<u> </u>									
2017 - Spring	g: No Change									
Comments:	•									
2017 - Fall: N	lo Change									
Comments:	•									
2018 - Spring	g : No Change									
Comments:	,									

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
162M	12x12 Red VFT Mastic	456	SF	Room 217, 117		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
163	12x12 Black VFT	456	SF	Room 217 (auditorium), 117		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
163M	12x12 Black VFT Mastic	456	SF	Room 217 (Auditorium), 117		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

164	Black Spray-on fireproofing	250	SF	Hangar	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2017 - Spring	ı: No Change									
Comments:										
2018 - Spring	: No Change									
Comments:										

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
165	12x12 Dark blue w/streaks VFT	288	SF	Mens + Womens toilets - Hangar		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categ	gory
165M	12x12 Dark blue w/streaks VFT Mastic	288	SF	Mens + Womens toilets - Hangar		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
166	12x12 Light blue w/ streaks VFT	144	SF	Womens toilets - Hangar		Miscellaneous	No	None	0		YES X NO	

0040 5 11 N1 O1	
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Page 83

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
166M	12x12 Light blue w/ streaks VFT Mastic	144	SF	Womens toilets - Hangar		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				1							
Comments	): :											
2017 - Fall	: No Change											
Comments	<b>:</b>				_							
2017 - Spr	ing: No Change											
Comments	<b>:</b>				_							
2018 - Spr	ing : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
167	12x12 Brown w/streaks VFT	144	SF	Mens toilet - hangar		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
167M	12x12 Brown w/streaks VFT Mastic	144	SF	Mens toilets - Hangar		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:					-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
168	12x12 Blue VFT	70	SF	Hangar		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2018 - Spring : No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
168M	12x12 Blue VFT Mastic	70	SF	Hangar		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	No Change											
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
169	MJP E/F/V on Aircell Pipe Insulation	3	SF	Hangar- storage room 7		Miscellaneous	No	None	0		YES X NO

2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change		<u>.</u>	
Comments:				
2017 - Spring	: No Change		<u>.</u>	
Comments:				
2018 - Spring	: No Change			
Comments:				

2018 - Spring : No Change

Comments:

HA No	0	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Cate	egory
170		12x12 Brown w/black + white specks VFT	148	SF	Hangar		Miscellaneous	No	None	0		YES X NO	
	- Fall: N	o Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
0010 0 1 11 01	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
170M	12x12 Brown w/black + white specks VFT Mastic	148	SF	Hangar		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

AP-1	acoustical plaster	8000	SF	hangar		Surface	Yes	None	0		YES	X NO
2016 - Fall	: No Change				7							
Comments	): 											
2017 - Spr	ing: No Change											
Comments	<b>S:</b>				_							
2017 - Fall	: No Change											
Comments	<b>S:</b>				_							
2018 - Spr	ing : No Change											
Comments	S:				_							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

		Quantity	Units		Type	Category		Type	Quantity	Units		
В	Joint Insulation on Fiberglass Insulated Piping	75	LF	Basement, Janitor's Closet, Northeast Corner Stairs, 3rd Floor Fan Room, Fan Room #12, Potting Room		TSI	Yes	None	0		YES	Х NO
2016 - Fall: No	o Change				]							
Comments:												
2017 - Fall: No	o Change											

2017 - Fall: No Change
Comments:

2017 - Spring: No Change
Comments:

HA No

**Material Description** 

Material

Quantity

Material

Units

Material Location

2018 - Spring : No Change Comments:

Page 88

BB-1	Tan Baseboard ABATED			1943 - Room 278 and 278 Office		Miscellaneous	No				YES	X NO
2016 - Fall	: No Change											
Comments												
2017 - Spri	ng: No Change				_							
Comments												
2017 - Fall:	: No Change											
Comments	:											
2018 - Spri	ng : No Change											
Comments	:				_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
DD 2	Tourquise Baseboard			1042 Poom 277		Missollaneous	No				Dvco I	V NO

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

1943 - Room 277

Material

Units

Material Quantity

HA No

BB-2

Material Description

(ABATED)

YES

X NO

BB-3	4" Baseboard ABATED	282 Front and Back, 286 Front and Back, 285 Back Office	Miscellaneous	No		YES	X NO
2016 - Fall: 1	No Change						
Comments:							
2017 - Fall: N	No Change						
Comments:							
2017 - Sprin	g: No Change						
Comments:							
2018 - Sprin	g : No Change						
Comments:	<u>g</u>						

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

1943 - Room 281, 280,

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
BB-4	Black Baseboard ABATED			1939 - Room 166		Miscellaneous	No				YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

BB-4A	black baseboard	100	LF	rooms 271, 113, 282		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				]							
Comments:	V				]							
2017 - Fall: I	No Change											
Comments:					1							
2017 - Sprin	g: No Change				-							
Comments:					-							
2018 - Sprin	g : No Change											
Comments:					<u> </u>							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Friable

No

Miscellaneous

Damage

Type

None

0

Damage

Quantity

Damage

Units

2016 - Fall: No Cl	nange		
Comments:			
2017 - Fall: No Cl	nange		
Comments:			
2017 - Spring: No	Change		
Comments:			
2018 - Spring : No	Change		
Comments:			

300

HA No

BB-5

Material Description

Brown Baseboard

Material

Quantity

Material

Units

LF

Material Location

1939 - Room 128, 115,

Women's Restroom and

Corridor

YES

X NO

	·	Quantity	Units		Type	Category		Туре	Quantity	Units		
BB-5A	green baseboard	100	LF	room 153		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Spring	g: No Change				-							
Comments:												

Material

Friable

Damage

Damage

Comments:

2017 - Fall: No Change
Comments:

Material Material Location

2018 - Spring : No Change

Material Description

Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
BB-6	brown baseboard	70	LF	rooms 209, ,218, 115 (ABATED 282)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Damage Change in Assessment Category

BB-7	blue baseboard	100	LF	connecting room between 113 and 115		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				]							
Comments:												
2017 - Fall: N	No Change											
Comments:	•				1							
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change				=							
Comments:	-											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

Damage

Quantity

Damage

Units

HA No

BBM-1

Material Description

Mastic Beneath Tan

Baseboard (ABATED)

Material

Units

Material

Quantity

Material Location

1943 - Room 278 and

278 Office

YES

X NO

16 - Fall: Norments:	
mments: I7 - Spring	
17 - Spring	
mments:	
7 - Fall: N	
mments:	
8 - Spring	
mments:	
	Change in Assessment Category
No	
No	,
No	YES X NO
No	3 -

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

ABATED

Material

Quantity

Material

Units

Material Location

Office

BBM-4	Mastic Beneath Black Baseboard ABATED		1939 - Room 166	Miscellaneous	No		YES	X NO
2016 - Fall: No	o Change							
Comments:								
2017 - Spring:	: No Change							
Comments:								
2017 - Fall: No	n Change							
Comments:	o onange							
Comments.								
2018 - Spring	: No Change							
Comments:		•						

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
BBM-4A	black baseboard mastic	150	LF	rooms , 113, 28 (ABATED 271)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

BBM-5	Mastic Beneath Brown Baseboard	300	LF	1939 - Room 128, 115, Women's Restroom and Corridor		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change			•	]						
Comments:	io onango										
2017 - Fall: N	lo Change										
Comments:	•										
2017 - Spring	j: No Change										
Comments:											
	j : No Change										
Comments:											
					J						

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

BBM-5A green baseboard mastic 100 LF room 153 Miscellaneous No None 0 Test X NO	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	BBM-5A	green baseboard mastic	100	LF	room 153		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
BBM-6	brown baseboard mastic	400	LF	rooms 209, ,218, 282, 115		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	:				]							
2017 - Fall:	No Change											
Comments:	:				_							
2017 - Sprii	ng: No Change											
Comments:	:				_							
2018 - Sprii	ng : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
BBM-7	blue baseboard mastic	100	LF	connecting room between 113 and 115		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Pipe Joint Insulation on Preformed Pipe Insulated Piping	216	LF	Pipe Space, East and West Dressing Room, Room 117, 1939 Fan Room, Room 114		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Fitting Insulation on Preformed Insulated Piping	2180	LF	1939 Pipe Space, East and West Dressing Room in 117		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

DE-1	12 x 12 Yellow Floor Tile	1400	SF	Driver's Education Building (Separate Building)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change											
					_							
Comments	ii.											
2017 - Spri	ing: No Change											
Comments	<u> </u>											
2017 - Fall	: No Change											
Comments	:											
2018 - Spri	ing : No Change											
Comments	:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessi	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

Damage

Type

Type

None

No

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

X NO

DE-2	12 x 12 Yellow Floor Tile Mastic	1400	SF	Classroom (Separate Building)
			•	
2016 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2018 - Spring	: No Change			
Comments:			•	

Quantity

Units

HA No

Material Description

12 x 12 Yellow Floor Tile

Material

Units

Material

Quantity

Material Location

Driver's Education

Driver's Education

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
DW-1	Drywall	1200	SF	1943- Rm 266, 274, 274D, 274A, 278, 285		Miscellaneous	Yes	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
DW-2	Drywall Compound	1200	SF	1943 - Room 266, 274, 274D, 274A 278,285		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Aircell Pipe Insulation	6450	LF	1939 Above Teacher's Lunchroom, Throughout Fan Rooms and Basement Storage		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FD-1	Insulation in fire rated doors	412	EA	throughout facility		TSI	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
FT-1	12 x 12 Beige, gray w/tan pattern floor tile	250	SF	Hangar Class Area		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: N	o Change											

2016 - Fall: No Change	
Comments:	
0047 Fall Na Obarra	
2017 - Fall: No Change	
Comments:	
2017 0 : 11 01	
2017 - Spring: No Change	
Comments:	
0040 Order No Observe	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT-10	12x12 green w/ white & dk green specks floor tile	750	SF	Rooms 110 and (ABATED 275)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

FT-11	12x12 cream with white & dk green floor tile (NOT OBSERVED)	2800	SF	Rooms 282, 283, 286, 287		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change	•		•	]	•	•	•	•	•	•	
Comments:												
2017 - Sprin	g: No Change											
Comments:	<u> </u>											
2017 - Fall: N	No Change											
Comments:	<u> </u>											
2018 - Sprin	g : No Change											
Comments:												

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT-2	12x12 cream with multi- colored specks floor tile	500	SF	rooms 153 (ABATED 157)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

12x12 cream with white &

Material

Quantity

Material

Units

FT-3	12x12 yellow floor tile	700	SF	room 115	Miscellaneous	No	None	0	YES	X NO
2016 - Fall	No Change									
Comments:	<b>v</b>									
2017 - Sprir	ng: No Change									
Comments:										
2017 - Fall:	No Change									
Comments:										
	ng : No Change									
Comments:										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT-4	12x12 maroon floor tile	700	SF	room 115		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
FT-5	12x12 light blue floor tile	2800	SF	rooms 109, 114, 113, 112		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments:	No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
FT-8	12x12 tan with brown and white streaks floor tile	4900	SF	rooms 206, 204, 214, 216A, 218, 208		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
FT-9	dark blue with gray and light blue linoleum	700	SF	room 208		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: N	lo Change		_		]							

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
FTM-1	12x12 beige Gray w/tan pattern floor tile mastic	2580	SF	Hangar Class Area		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

FTM-10	12x12 green w/ white & dark green speck floor tile mastic	750	SF	rooms 110 and 275		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Chango			·	1						•	
	NO Change				4							
Comments:	Comments:											
2017 - Fall: N	No Change				]							
Comments:	-											
					1							
2017 - Spring	g: No Change											
Comments:	•											
					1							
2018 - Spring	g : No Change											
Comments:	<u> </u>				1							
					1							
					=							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
1		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

Friable

No

Damage

Туре

Damage

Quantity

Damage

Units

	(ABATED)			
2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Spring	: No Change			
Comments:				
			•	•

Material

Quantity

Material

Units

Material Location

rooms 282, 283, 286, 287

HA No

FTM-11

Material Description

12x12 cream with reddish

brown floor tile mastic

YES

Change in Assessment Category

X NO

FTM-2	12x12 cream with multi- colored specks floor tile mastic	500	SF	rooms 153 (abated 157)		Miscellaneous	No	None	0		YES	X NO
	. 01	•	*	•	1	•	•	•	•	•		
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	ı : No Change											
Comments:	-											

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
FTM-3	12x12 yellow floor tile mastic	700	SF	room 115		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	2016 - Fall: No Change Comments:											

2017 - Spring: No Change
Comments:

2017 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

2018 - Spring : No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Catego	ry
FTM-4	12x12 brown floor tile mastic	700	SF	room 115		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: No Change												

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FTM-5	12x12 light blue floor tile mastic	2800	SF	rooms 109, 114, 113, 112		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

FTM-8	12x12 Tan w/ Brown & White Streaks Floor Tile Mastic (NOT OBSERVED)	Tooms 204, 206, 212, 214, 216A, 218		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change		1						
Comments									
2017 - Fall:	No Change								
Comments									
2017 - Spri	ng: No Change								
Comments									
2018 - Spri	ng : No Change		_						
Comments									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FTM-9	dark blue with gray and light blue linoleum mastic	700	SF	room 208		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

12x12 Tan w/ Brown &

Material

Quantity

Material

Units

Н	Duct Covering On Breeching (NOT OBSERVED)	1590	SF	Boiler Room, Throughout Fan Rooms		TSI	No	None	0	YES	X NO
2016 - Fall:	No Change				1						
Comments:					1						
Comments.					-						
2017 - Fall:	No Change										
Comments:											
2017 - Sprir	ng: No Change										
Comments:											
2018 - Sprir	ng : No Change										
Comments:											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-1000	Transite Counter and Table Tops	800	SF	Rms. 012, 022, 023, 024		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Duct Covering On

Material

Quantity

Material

Units

I	Tank #1 Jacket (Abated)			Boiler Room		TSI					YES	X NO
2016 - Fall:	No Change											
Comments												
2017 - Spri	ng: No Change											
Comments	:											
	No Change											
Comments	:				_							
	ng : No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
J	Tank #1 Insulation (Mag Block) (Abated)			Boiler Room		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

K	Tank #2 Jacket (Abated)			Boiler Room		TSI					YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:					_							
	g: No Change											
Comments:					_							
	g : No Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
L	Tank #2 Insulation ( Mag Block) (Abated)			Boiler Room		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

М	Tank #3 Jacket (Abated)			Boiler Room		TSI					YES	X NO
2016 - Fall: N	No Change											
Comments:												
	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:					_							
	g : No Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
N	Tank #3 (Mag Block) (Abated)			Boiler Room		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Material

Quantity

Material

Units

HA No

Material Description

0	Tank Jacket (Abated)			Kitchen Prep.		TSI					YES	X NO
2016 - Fall: N	o Change				]							
Comments:	Comments:											
2017 - Spring	: No Change											
Comments:					-							
2017 - Fall: N	o Change				-							
Comments:					-							
2018 - Spring	: No Change				1							
Comments:					1							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
Р	Tank Insulation (Abated)			Kitchen Prep.		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Q	Tank Insulation (Abated)			Hangar		TSI					YES	X NO
2016 - Fall: N	lo Change				]							
Comments:					-							
2017 - Spring: No Change												
Comments:					_							
2017 - Fall: N	lo Change				_							
Comments:	-											
2018 - Spring	ı : No Change				1							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
R	Tank Jacket (Abated)			Hangar		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

S	Fireproofing		SF	Hangar		Surface	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	<u> </u>				]							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:					-							
2018 - Spring	g : No Change											
Comments:					-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

TSI

Asbestos

Type

Material

Category

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

Т	Duct Covering (MATERIAL REMOVED)								
		•							
2016 - Fall: N	lo Change								
Comments:									
2017 - Fall: N	lo Change								
Comments:									
2017 - Spring	ı: No Change								
Comments:									
2018 - Spring	ı : No Change								
Comments:	-								

Material

Quantity

Material

Units

Material Location

HA No

Material Description

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
U	Preform Pipe Insulation	100	LF	1943 - Side of tunnels		TSI	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
U-1	Preform Fittings	10	LF	1943 - Side of tunnels		TSI	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment (	Category
V	Aircell Pipe Insulation	200	LF	1943 - Side of tunnels		TSI	Yes	None	0		YES X	NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
W	MJP E/F/V on Aircell Pipe Insulation	25	LF	1943 - Sides of tunnels		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
X	Aircell Joints	840	LF	1939 Above Teacher's Lunchroom (Attic), Throughout Fan Rooms and Basement Storage		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Υ	12"x12" White/Black/Red /Gray Floor Tile	5000	SF	TThroughout Classrooms and Corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Z	12"x12" White/Black/Red /Gray Floor Tile Adhesive	5000	SF	TThroughout Classrooms and Corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

	hicago Vocational Career Academy High School
Date: 12	/12/2018
the Asbestos	fy you in accordance with Illinois and Federal Asbestos Regulations, that a copy of Management Plan is available at each school during school hours by appointment. eview the Asbestos Management Plan must be made at least 24 hours in advance.
The last inspe	e advised that CPS conducts asbestos inspections of all Schools every three years. ection was completed in 2016. veillances are conducted every six months.
CHECK ONE	
А сору	of this notice was sent home in each child's backpack.
А сору	of this notice was printed in the school's newsletter and sent home with each child
А сору	of this notice was printed in the school's calendar and sent home with each child
Other.	
A COPY O	F THIS NOTICE MUST BE PLACED IN THE
	OL'S ASBESTOS MANAGEMENT PLAN.