Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

53091

Oracle Unit:

Building ID:

1300

Address: 2345 S. Christiana Region: 03 Mail Room: Asbestos Surveyor: Dye, Ms. Venguanette X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/11/2019 Email Address: vdye@cps.edu A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type YES 01 X NO Carpet Mastic Rooms 470 & 472 Miscellaneous 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

David G Farragut Career Academy High School

School:

Oracle Unit: 53091

02	2' x 4' Fissured Ceiling Tile			Throughout Building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
	g: No Change											
Comments:					<u> </u>							
2018 - Fall: N	lo Change											
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
03	12"x12" Light Tan Floor Tile - ABATED			3rd & 4th Floor Corridors, Rms 338,340,372,374,438,447 ,449,461,462,462A,465,		Miscellaneous					YES	X NO

Asbestos Type Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03M	12" x 12" Light Tan Floor Tile Mastic - ABATED			3rd & 4th Floor Corridors, Rms 338,340,372,438,447,449 ,461,462,462A,465, Freight Elevator		Miscellaneous					YES X NO
2016 - Fall: 1 Comments:	No Change										
2017 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	12" x12" Light Tan Replacement Floor Tile	20	SF	3rd Floor Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

04M	12" x 12" Light Tan Replacement Floor Tile Mastic	20	SF	3rd Floor Hallway		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:					=							
2017 - Fall: N	No Change											
Comments:	10 Change				-							
2017 - Spring	g: No Change											
Comments:	g. No Change				-							
	N. Oleman				1							
2018 - Fall: N	No Change											
Comments:					1							
					4							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
1	1		1		1	1	1	1	1	1	1	

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

05

Comments:

2016 - Fall: No Change

Material Description

Black Baseboard

Material

Quantity

Material

Units

Material Location

Throughout Building

Change in Assessment Category

X NO

YES

05M	Black Baseboard Mastic			Throughout Building		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:					1							
2017 - Fall:	No Change											
Comments:												
	ıg: No Change											
Comments:					1							
2018 - Fall:	No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
06	12" x 12" Tan Floor Tile	20	SF	First Floor North Corridor		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

Material

Units

Material

Quantity

Material Location

of South Building

HA No

Material Description

Page 5

	Madio			or court Building								
2016 - Fall: I	No Change				7							
Comments:	<u> </u>				1							
2017 - Fall: I	No Change											
Comments:					_							
	g: No Change											
Comments:					4							
2018 - Fall: I	No Change											
Comments:					4							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment	Category
0.7	5			All Floors in South								

Surface

Asbestos

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

Material

Quantity

20

Material

Units

SF

Material Location

of South Building

Building

First Floor North Corridor

HA No

06M

07

Material Description

12" x 12" Tan Floor Tile

Plaster Walls (Veneer)

Mastic

Change in Assessment Category

X NO

X NO

YES

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	12" x 12" Olive Green Floor Tile	2000	SF	First Floor Corridor as Replacement Tiles		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M80	12" x 12" Olive Green Floor Tile Mastic	2000	SF	First Floor Corridor as Replacement Tiles		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

09	12" x 12" Grey Floor Tile - REMOVED			In Corridors of South Building		Miscellaneous					YES	X NO
2016 - Fall	: No Change											
Comments												
2017 - Spri	ng: No Change											
Comments												
2017 - Fall	: No Change				_							
Comments	<u> </u>											
2018 - Fall	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
09M	12" x 12" Grey Floor Tile Mastic - ABATED			In Corridors of South Building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

12" x 12" Grey Floor Tile -

Material

Quantity

Material

Units

10	Carpet			Main Office		Miscellaneous					YES	X NO
2016 - Fall:	No Change]							
Comments:]							
2017 - Fall:	No Change				-							
Comments:												
	ng: No Change		<u> </u>									
Comments:					1							
2018 - Fall:	<u>~</u>											
Comments:					1							
					J							
HA No	HA No Material Description Material Units Material Location					Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
11	11 Carpet Mastic Office					Miscellaneous					YES	X NO
2016 - Fall:	016 - Fall: No Change											

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Units

Material

Quantity

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12" x 12" White/Blue Streak Floor Tile	288	SF	175		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12M	12" x 12" White/Blue Streaks Floor Tile Mastic	288	SF	175		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

13	Interlocking Wall Tiles			Rooms 173, 175 & 176		Surface					YES	X NO
2016 - Fal	: No Change				7							
Comments												
2017 - Fal	: No Change											
Comments	S:											
	ing: No Change											
Comments	3:				_							
2018 - Fal	: No Change											
Comments	S:				_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
14	2' x 4' Woven Ceiling Tile			1st Floor Corridor in		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

South Building

	15	Veneer Plaster Walls			South Building lower Level, US Army/ROTC Office and Stairwell		Surface					YES	X NO
I	2016 - Fall: N	o Change			•	7							
	Comments:	o Onango											
	•												
	2017 - Fall: N	o Change											
	Comments:												
	2017 - Spring	: No Change											
	Comments:												
						_							
	2018 - Fall: N	o Change											
	Comments:												
I													
	HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
			Quantity	Units		Туре	Category		Туре	Quantity	Units		
	16	Veneer Plaster			Corridors and		Surface					YES	X NO
	10	1011001 1 100101			Classrooms		Canaco					i_5	V IAO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

South Building lower

HA No

Material Description

Material

Quantity

Material

Units

17	1' x 1' Acoustical Ceiling Tile			South Building, Electronic Shop		Miscellaneous					YES	X NO
2016 - Fall:	No Change				7							
Comments:					1							
2017 - Fall:	No Change											
Comments:	-											
2017 - Sprir	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
18	1' x 1' Acoustical Ceiling Tile Mastic			Electronic Shop		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Material

Units

Material Quantity

HA No

Material Description

19	TSI Cover on Pipe Fittings			Basement		Miscellaneous					YES	X NO
2016 - Fall	: No Change				7							
Comments):				_							
	: No Change											
Comments	:	4										
2017 - Spr	ing: No Change											
Comments	:				4							
2018 - Fall	: No Change											
Comments	:				4							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
20	TSI Insulation on Pipe			Basement		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

TSI on Large Pipe Elbows (>4" diameter) and Cover Basement						TSI					YES	X NO
2016 - Fall: I	No Change				7							
Comments:												
2017 - Fall: I	No Change											
Comments:												
	g: No Change											
Comments:					_							
2018 - Fall: I	No Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
22	TSI on Large Pipe(>4" diameter) Plaster Insulation Basement					TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

TSI on Large Pipe Elbows

24	24 TSI Valves Insulation Cover Basement					TSI					YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
	g: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
HA No	HA No Material Description Material Material Location Quantity Units					Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
25	25 .5" Pipe TSI Elbow Insulation & Cover Basement					TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Material

Quantity

Material

Units

HA No

Material Description

26	2' x 4' Ceiling Panels			Corridor		Miscellaneous					YES	X NO
2016 - Fall	: No Change				1							
Comments					1							
2017 - Fall	: No Change											
Comments	:											
2017 - Spr	ing: No Change											
Comments	:											
2018 - Fall	: No Change											
Comments	:											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
27	Veneer Plaster			On Metal in Men's Room		Surface					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

28	12" x 12" Tan Floor Tile w/Streaks	20925	SF	2nd&3rd Flr Corridors, Band,Drama Of., 112,113,114,308,317,400 , 401,437,439,440,446,450 ,451,		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change]						
Comments:											
2017 - Spring	: No Change				-						
Comments:					1						
2017 - Fall: N	lo Change				=						
Comments:	<u> </u>				=						
2018 - Fall: N	lo Change				-						
Comments:	<u> </u>				=						
					J						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
28M	12" x 12" Tan Floor Tile w/Streaks Mastic	20925	SF	2nd&3rd Flr Corridors, Band,Drama Of., 112,113,114,308,317,400 , 401,437,439,440,446,450 ,451		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	II: No Change s:											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
•	

HA No

Material Description

Material

Quantity

Material

Units

Material Location

29	Carpet Mastic			3rd Floor Library		Miscellaneous					YES	X NO
2016 - Fall: N	No Change]							
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:					_							
2018 - Fall: N	No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
30	Fire Doors	500	SF	Basement Mechanical Rooms		TSI	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material

Quantity

Material

Units

	·	Quantity	Units		Type	Category		Туре	Quantity	Units		
31	Exterior Brick (Not AHERA)					Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
32	Exterior Brick Mortar (Not AHERA)					Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:												

Material

Friable

Damage

Damage

Damage

HA No

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material Description

Material

Material

Material Location

33	Roof Flashing (Not AHERA)				Miscellaneous					YES	X NO
2016 - Fall:	No Change				7							
Comments	<u> </u>											
	No Change											
Comments					-							
	ng: No Change											
Comments					-							
	No Change											
Comments					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
0.4	Insulation Inside Vault		0.5	Second, Third, & Fourth								

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

HA No

34

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Quantity

200

SF

Material

Units

Material Location

Floor Corridor

YES

X NO

											1
004C F-II	No Observe										
2016 - Fall:	: No Change										
Comments	:										
2017 Falls	· No Chango				_						
	2017 - Fall: No Change										
Comments	:										
2017 - Spri	ng: No Change										
Comments											
2018 - Fall:	: No Change										
Comments	:										
		·									
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:		•		

700

HA No

35

36

Material Description

4" Maroon Baseboard

4" Maroon Baseboard

Adhesive

Material

Quantity

700

Material

Units

LF

LF

Material Location

North Building Corridors

North Building Corridors

Change in Assessment Category

X NO

X NO

YES

YES

37	Drywall and Joint Compound	1500	SF	North Building	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
	g: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Drywall and Joint Compound	600	SF	South Building		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	No Change]						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

39	Purple Carpet Mastic	402-405, 408-427, 429- 436, 441-445, 448, 300- 304, 307, 310, 312, 314, 316, 318-322, 324, 326	Miscellaneous			YES	X NO
2016 - Fall: I	No Change						
Comments:							
2017 - Fall: I	No Change						
Comments:	Ţ						
2017 - Sprin	g: No Change						
Comments:							
2018 - Fall: I	No Change						
Comments:							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Purple Carpet Mastic			270, Counselor, Office, Attendance		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12" x 12" White Floor Tile w/ Brown Streaks	6000	SF	South Building Corridors, Room 443, 462, 463,465, 472, 474, 474A, 474B, 474D,		Miscellaneous	No	Loc	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12" x 12" White Floor Tile w/Brown Streaks Mastic	3000	SF	South Building Corridors, Rooms 462, 463, and 465		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Assess	sment Category
43	Lab Counters and Sinks	200	SF	South Building Science Rooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12" x 12" Beige Floor Tile w/ Brown Streaks	700	SF	ROTC Basement Classroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 26

45	12" x 12" Beige Floor Tile w/Brown Streaks Mastic	700	SF	ROTC Basement Classroom (In Building Suspension room)		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change				7							
Comments	0				-							
2017 Fal	I: No Change				-							
Comment	·				-							
					_							
	ring: No Change											
Comments	S:				_							
2018 - Fal	I: No Change				-							
Comments	S:											
					╛							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessr	nent Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

No

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

46	Blue Stage Curtain	6000	SF	Auditorium
		•	•	
2016 - Fall: N	lo Change			
Comments:				
2017 - Spring	ı: No Change			
Comments:				
2017 - Fall: N	lo Change			
Comments:				
2018 - Fall: N	lo Change			
Comments:				
		•	•	

Quantity

Units

HA No

Material Description

Material

Units

Material

Quantity

Material Location

ROTC Basement

Change in Assessment Category

X NO

YES

											
2016 - Fall:	No Change				7						
Comments:											
	ng: No Change										
Comments:											
2017 - Fall:	<u> </u>										
Comments:											
2018 - Fall:	No Change										
Comments:					_						
					_						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

1000

Material

Quantity

10000

Material

Units

SF

SF

464

Material Location

Auditorium

HA No

47

48

Material Description

Red Stage Curtain

Floor Sheeting

Change in Assessment Category

X NO

X NO

YES

YES

49	Lab Tops, Counters & Sinks	200	SF	Room 464	Miscellaneous	No	None	0	YES	X NO
2016 - Fal	I: No Change									
Comments										
2017 - Spr	ring: No Change									
Comments	S:									
2017 - Fal	I: No Change									
Comments	S:									
2018 - Fal	I: No Change									
Comments	S:									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	Blue Carpet Mastic	700	SF	374		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

51	Tectum Panels	1000	SF	ROTC Rifle Range		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	o Change										
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											
					J						

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	Adhesive Beneath Tectum Panels	10000	SF	Auditorium, 113, 114, 101, 102		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

53	12" x 12" Gray w/Brown & White Floor Tile			Room 103		Miscellaneous					YES	X NO
2016 - Fall: N	No Change											
Comments:	to onango											
2017 - Spring	g: No Change											
Comments:	<i></i>											
2017 - Fall: N	No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
54	12" x 12" Gray w/Brown &			Room 103		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

12" x 12" Gray w/Brown &

White Floor Tile Mastic

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor	гу
55	12" x 12" Light Gray w/ White Floor Tile	900	SF	Room 101		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: N Comments:	lo Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	12" x 12" Light Gray w/ White Floor Tile Mastic	900	SF	Room 101		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

57	2" Black Baseboard			Room 101		Miscellaneous					YES	X NO
2016 - Fall: N	o Change]							
Comments:												
2017 - Fall: No Change												
Comments:												
2017 - Spring: No Change												
Comments:					-							
2018 - Fall: N	o Change				-							
Comments:				-								
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
58	2" Black Baseboard Mastic			Room 101		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

2016 - Fall: No Change

Material Description

59	Caulk Around Sink	3	LF	Room 172		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:]										
2017 - Fall: No Change												
Comments:					-							
2017 - Spring	g: No Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					1							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

60

Comments:

Comments:

Comments:

Comments:

Material Description

Exterior Door Caulk - Not

AHERA

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material

Quantity

Material

Units

Material Location

Room 172

YES

X NO

61	12" x 12" Brown Floor Tile	607	SF	Basement Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				7							
Comments	0											
Comments	·•											
2017 - Fall	: No Change											
Comments):											
2017 - Spr	ing: No Change											
Comments) :											
2018 - Fall	: No Change				4							
Comments												
Comments) .											
L												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

No

None

0

Friable

Damage

Type

Damage

Quantity

Damage

Units

		auditorium entran
2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		
_		-

1000

SF

HA No

62

Material Description

12" x 12" Brown Floor Tile

Mastic

Material

Quantity

Material

Units

Material Location

Basement Corridor,

dressing rooms,

Break Room, 3 basement

locker rooms, Audotorium

YES

X NO

63		2nd Floor Roof Field - (Not AHERA)			Second Floor Roof off ROTC Office							YES	X NO
201	16 - Fall: N	o Change]							
	mments:	<u> </u>											
201	17 - Fall: N	o Change											
Cor	mments:												
		: No Change				-							
Cor	mments:					-							
201	18 - Fall: N	o Change											
Comments:					-								
						1							
НА	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
64		Roof Flashing - (Not			2nd Floor Roof off ROTC Office		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Material

Units

Material

Quantity

Material Location

HA No

Material Description

AHERA)

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Change in Assessment Category

Damage

Units

65	Beige Caulk on Metal - (Not AHERA)			2nd Floor Roof off ROTC Office		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	J-]							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:					1							
2018 - Fall: N	lo Change											
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
66	Black Metal Sealant - (Not AHERA)			2nd Floor Roof off ROTC Office		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

67	Sink			Room 103		Miscellaneous					YES	X NO
2016 - Fall: N	No Change											
Comments:	J.											
2017 - Fall: N	No Change											
Comments:												
	g: No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
68	Non-Skid Stair Treads			Room 113		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
69	4" Brown Vinyl Baseboard	70	LF	Room 113		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70	4" Brown Vinyl Baseboard Mastic	70	LF	Room 113		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	·
<u> </u>	

71	Spray on Fire Proofing			Components Throughout North Building		Miscellaneous					YES	X NO
2016 - Fall	No Change				1							
Comments:												
2017 - Sprii	ng: No Change				_							
Comments:	<u> </u>				- -							
2017 - Fall:	No Change				-							
Comments:	-]							
2018 - Fall:	No Change											
Comments:]							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
										<u> </u>		

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

0

None

Damage

YES

Units

10000

SF

Auditorium

HA No

72

Material Description

Gray Carpet Mastic

Material

Quantity

Material

Units

Material Location

Structural Beams and

Change in Assessment Category

73	Adhesive on Wall			Storage across from 172		Miscellaneous					YES	X NO
2016 - Fall: N	No Change]							
Comments:					1							
	g: No Change											
Comments:					 							
2017 - Fall: N	No Change											
Comments:					_							
2018 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
74	Exterior Door Caulk - (Not AHERA)			South Building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
75	12" x 12" White w/Multi- Colored Specks FT	11	SF	Room 463		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
76	12" x 12" White w/Multi- Colored Specks FT Mastic	11	SF	Room 463		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	·
<u> </u>	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment (Category
80	12 x 12 White VFT with blue streaks w/mastic	20000	SF	Classrooms throughout on 3rd and 4th floor north building. Teachers lounge, Copy Room 175,200, 202, Faculty Center faculty dining room.		Miscellaneous	No	None	0		YES X	NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
0040 Fall No Observe	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
81	12" x 12" blue and light blue checked VFT and glue	1000	SF	272, 161		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

82	brown checked VFT& and Mastic	500	SF	167		Miscellaneous	No	None	0	YES	X NO
2016 - F	all: No Change										
Comme	nts:										
2017 - S	pring: No Change										
Comme	nts:										
2017 - F	all: No Change										
Comme	nts:										
2018 - F	all: No Change										
Comme	nts:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
83	12" x 12" blue and gray checked VFT& Mastic	2000	SF	163 -165, 160		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No

Material Description

12" x 12" off white and

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
84	12 x 12 White with tan streaks VFT & glue	1000	SF	P.E. Office 130A, 130B, 474C		Miscellaneous	No	Dist	150		YES X NO
0010 5 11					1						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
85	18" x 18" Blue Gray Floor tile	2850	SF	2nd floor lunchroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

85m	Mastic for HA 85	2850	SF	2nd floor lunchroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:]							
2017 - Spring	g: No Change											
Comments:	-]							
2017 - Fall: N	No Change											
Comments:					 							
2018 - Fall: N	No Change											
Comments:					 							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

Damage

Quantity

0

Damage

Units

2850

Material

Units

SF

Material

Quantity

Material Location

3rd Floor Lunchroom

HA No

86

Material Description

18" x 18"

YES

X NO

86m	Mastic for HA 86	2850	SF	Third floor lunchroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:					1							
2017 - Spring	g: No Change				1							
Comments:					1							
2017 - Fall: N	lo Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
		1	†		1		†	†	†	1		

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

HA No

87

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Light blue mottle lineloum

Material

Quantity

650

SF

Room 464

Material

Units

Material Location

Change in Assessment Category

YES

87M	Mastic for HA 87	650	SF	Room 464		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change]							
Comments:	<u> </u>				1							
2017 - Sprin	g: No Change											
Comments:					1							
2017 - Fall: I	No Change				-							
Comments:					-							
2018 - Fall: I	No Change											
Comments:					 -							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
00	12" x 12" Tan floor tile with			5 074								

Type

Material

Category

Miscellaneous

Friable

Damage

Type

None

Damage

Quantity

Damage

Units

HA No

88

Comments:

Comments:

Comments:

Comments:

Material Description

Brown Streaks

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material

Quantity

Material

Units

Material Location

Room 374

Change in Assessment Category

YES

88M	Mastic for HA 88			Rom 374		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>											
2017 - Spring	g: No Change				-							
Comments:												
2017 - Fall: N	lo Change											
Comments:					1							
2018 - Fall: N	lo Change											
Comments:					<u> </u>							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

105

Material

Units

SF

Material Quantity

Material Location

1st, 2nd, and 3rd floor in

Hallway as a Pattern

HA No

89

Material Description

12"X12" Dark Blue W/lite

Blue Floor Tile

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
89M	12"X12" Dark Blue W/lite Blue Floor Tile Mastic	105	SF	1st, 2nd, and 3rd floor in Hallway as a pattern		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
90	12"X12" Dark Yellow W/White Floor Tile	105	SF	1st, 2nd, and 3rd floor in Hallway as a pattern		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

90M	12"X12" Dark Yellow W/White Floor Tile Mastic	105	SF	1st, 2nd, and 3rd floor in Hallway as a pattern		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change											
Comment	s:											
	ring: No Change											
Comment	S:											
	II: No Change											
Comment	S:											
	II: No Change											
Comment	S:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
				Basement Corridors,								

TSI

Asbestos

Type

Material

Category

Friable

Yes

Loc

Damage

Туре

Damage

Quantity

70

Damage

Units

100

LF

HA No

91

2016 - Fall: No Change

Material Description

12"X12" Dark Yellow

Cardboard Pipe Insulation

Material

Quantity

Material

Units

Material Location

1st, 2nd, and 3rd floor in

Work Rooms, Storage

Spaces

Rooms, and Mechanical

Change in Assessment Category

YES

YES

	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	92	Hard Joint Compound on Aircell Pipe Insulation	60	SF	Basement Corridors, Work Rooms, Storage Rooms, and Mechanical Spaces		TSI	Yes	Loc	2		YES X NO
Ī	2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-100	Aircell pipe insulation debris			Unexcavated spaces beneath the basement		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-101	White woven copper Wire Insulation			Old stage light fixtures in Auditorium		TSI		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: David G Farragut Career Academy High School Date: 1/11/2019
Date
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
·
A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.