

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2018 - Fall

**School:** Marie Sklodowska Curie Metropolitan High School  
**Address:** 4959 S. Archer

**Oracle Unit:** 53101  
**Region:** 04

**Building ID:** 1820  
**Mail Room:** 44

**CHECK HERE IF NO CHANGE TO ASBESTOS**

**Asbestos Surveyor:** Leyva, Joseph  
**Survey Date:** 11/21/2018  
**Email Address:** jmleyva@aol.com

A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via:  
 Each child's backpack   
 Notice printed in school's newsletter   
 Notice printed in school's calendar   
 Other

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 1 A   | 1' x 1' Ceiling Tile |                   |                | A Building - Lobby<br>Hallway Stairwells,<br>Building B Corridor |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: Abated       |
| Comments: New ceiling     |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 2A    | 2x4 Ceiling Tile     |                   |                | A Building, Kitchen |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 2B    | 2x4 Ceiling          | 9600              | SF             | B Building, Pool  |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 3     | Spray-on Fire Proofing |                   |                | Throughout Building |               | Surface           |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 4     | Fiberglass Pipe      |                   |                | Throughout Building A and B |               |                   |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description         | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 5     | Fiberglass Pipe Hard Fitting |                   |                | Throughout Building A and B |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description       | Material Quantity | Material Units | Material Location     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 6     | Fiberglass Duct Insulation |                   |                | Throughout Building A |               |                   |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location                                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 7     | Plaster              | 5000              | SF             | Men's Room and Rooms 623B, 525, 309, 201, Hall, B20 |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8     | 2x4 Insulation       | 350000            | SF             | Classroom Hallways, Main Office, Library, (A/B Buildings) |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                         | Material Quantity | Material Units | Material Location                              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 9.1   | Transite Board Lab Hood, Classrooms and Pool | 3252              | SF             | Rooms 346, 349, 350, 352, 353, 354B, 363 & 360 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                        | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 9.2   | Trasite Board Around Ceiling and Sky Lights | 3252              | SF             | Sky Light Board in Pool |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description             | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10    | 2' x 4' Fiberglass Ceiling Panel |                   |                | Building A -TV Studio Closet |               |                   |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11    | Duct Work Tape       | 1040              | SF             | A Building - Metal Shop |               | TSI               | Yes     | Dist        | 15              |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description       | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 12    | Fiberglass Duct Insulation |                   |                | A Building - Metal Shop |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 13    | Tank Breeching       | 600               | SF             | B Building - Pool Equipment Room |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 14    | Tank Insulation      | 320               | SF             | B Building - Pool Equipment Room |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description  | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 15    | Inner Duct Insulation | 500               | SF             | B Building - Auditorium |               | TSI               | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location                             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 16    | Spray-on Fire Proofing | 1600              | SF             | Building B - Small Room at Rear of Auditorium |               | Surface           | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description  | Material Quantity | Material Units | Material Location                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|--------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 17    | 2' x 4' Sound Baffles | 3500              | SF             | Building B - Rooms 510, 514, and 616 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description        | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 18    | Metal Encased Sound baffles | 2000              | SF             | B Building - Little Theatre |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location                           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 19    | Fire Doors           | 23730             | SF             | Throughout Building A and B, Original Doors |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description            | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 20    | Fiberglass Batting Above Lights | 50000             | SF             | A Building - Classrooms, Corridors, Main Office, Library |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location                       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 21    | Klieg Lights         | 1000              | LF             | B Building - Room 606 in Stage Cat Walk |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                        | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22.1  | 12" x 12" Cream/Brown/Tan/White Speckles FT | 52000             | SF             | B Building - Classrooms, Lockers, Lunch Rooms, Bldg A-throughout |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description                      | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22.10 | 12" x 12" White w/Brown Specks Floor Tile | 4500              | SF             | Rooms 127, 129, 195/196, 226-231, 256, 327, 329, 331, 333 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                   | Material Quantity | Material Units | Material Location                           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22.11 | 12" x 12" Pinkish Beige Mix Floor Tile | 28000             | SF             | See Locations in the Comments Section Below |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description                          | Material Quantity | Material Units | Material Location                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22.12 | 12" x 12" Lt. Gray w/Brown Streaks Floor Tile | 13000             | SF             | Room 143,148,152,159,160,165,380,381 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                      | Material Quantity | Material Units | Material Location                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22.13 | 12" x 12" White w/Peach Specks Floor Tile | 600               | SF             | Principal's Office & Conference Room |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22.14 | 12" x 12" White Floor Tile | 81                | SF             | Room 620          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                              | Material Quantity | Material Units | Material Location                          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22.3  | 12"x12" Off-White Floor Tile Brown/White Speckles | 1160              | SF             | A & B Buildings, Class Rooms and Corridors |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                      | Material Quantity | Material Units | Material Location              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22.4  | 12x12 Brown VFT w/ Brown & White Speckles | 25000             | SF             | A Building, Classrooms, Office |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description              | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22.5  | 12x12 Cream VAT w/ White Speckles | 2000              | SF             | A Building, Faculty Dining Area |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                      | Material Quantity | Material Units | Material Location                                       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22.6  | 12x12 Black VFT w/ Black & Brown Speckles | 8000              | SF             | B Building, 1st & 2nd Floor Hallway, Rooms 643, and 635 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                        | Material Quantity | Material Units | Material Location                               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22.7  | 12x12 VFT w/ Brown, White, and Tan Speckles | 3200              | SF             | A Building, 3rd and 2nd Floor Rooms, Lunchrooms |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                          | Material Quantity | Material Units | Material Location             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22.8  | 12x12 Off White FT w/Brn, Tan, White Speckles | 1160              | SF             | 160 West Section, 161 and 144 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                         | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22.9  | 12x12 Yellow FT w/Tan, Yellow,White Speckles | 1200              | SF             | Room 150          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23.1  | 12x12 VAT Mastic     | 125500            | SF             | HA was split into HA 23.1 A-23.1F |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                                    | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23.1A | Mastic under 12x12 VFT<br>Brown, Tan, White<br>Speckles | 52000             | SF             | B Building, Classrooms,<br>Lockers, Lunch Rooms,<br>Bldg A-Throughout |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                                  | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23.1B | Mastic Under 12x12 Off-Wh<br>VFT w/ Yel & Bwn Speckle | 15000             | SF             | Bldg. A and Bldg B<br>Throughout |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                             | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23.1C | Mastic for 12x12 Off-Wh VAT w/ Bwn & Wh Speckles | 20000             | SF             | Bldg. A -2nd, 3rd Flr Hall 263, Bldg. B 1st Flr Hall, 619 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description                         | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23.1D | Mastic for 12x12 Bwn VATw/ Bwn & Wh Speckles | 25000             | SF             | bldg A: 1st Flr Hall, 334, 364, 366, 367 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                     | Material Quantity | Material Units | Material Location                              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23.1E | Mastic for 12x12 Cream VAT, Wht Speckles | 2000              | SF             | bldg. A: 1st fir NW Corner Faculty Dining Area |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description                             | Material Quantity | Material Units | Material Location                                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23.1F | Mastic for 12x12 Black Vat w/ Blk & Bwn Speckles | 8000              | SF             | bldg. B: 1st Flr Hall, 2nd Flr Hall, Room 635,643 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                             | Material Quantity | Material Units | Material Location                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23.2  | Mastic for 12x12 VAT, Brown, Tan, & Wht Speckles | 17500             | SF             | Throughout Bldg A Class Rooms-249, 290 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description                              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23.3  | 12x12 Off White FT w/Brn, Tan, White Speck Mastic | 1160              | SF             | Room 160          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                               | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23.4  | 12x12 Yellow w/Tan, Yell, White Speckles FT Mastic | 1200              | SF             | Room 150          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                             | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23.5  | 12" x 12" White w/Brown Specks Floor Tile Mastic | 4500              | SF             | Rooms 127, 129, 195/196, 226-231, 256, 327, 329, 331, 333 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description                          | Material Quantity | Material Units | Material Location                           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23.6  | 12" x 12" Pinkish Beige Mix Floor Tile Mastic | 28000             | SF             | See Locations in the Comments Section Below |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                         | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23.7  | 12" x 12" Lt. Gray w/Brown Streaks FT Mastic | 13000             | SF             | Room 159          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                             | Material Quantity | Material Units | Material Location                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23.8  | 12" x 12" White w/Peach Specks Floor Tile Mastic | 600               | SF             | Principal's Office & Conference Room |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23.9  | 12" x 12" White Floor Tile Mastic | 81                | SF             | Room 620          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 24    | 4" Black Baseboard   | 150               | LF             | A Building, Basement |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description      | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 25    | 4" Black Baseboard Mastic | 200               | LF             | A Building Basement |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 26    | Main Water Fitting   | 32                | SF             | A Building Pump Room |               | TSI               | Yes     | Loc         | 3               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 27    | Dry Wall             | 1000              | SF             | Stairway to Roof, Basement Corridor, Rms 163, 164, 165, 524 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 28A   | Drywall Joint Compound | 200               | LF             | A Building, Stairway to Roof, Basement Hallway, Rooms 163, 164, 165, and 524 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description   | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 28B   | Drywall Joint compound |                   |                | Rooms 524, 163, 164, 165 |               | Surface           |         | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 29    | Exterior Brick       |                   |                | Exterior of Building |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                     |
|-------------------------------------|
| 2016 - Fall: No Change              |
| Comments:                           |
|                                     |
| 2017 - Spring: No Change            |
| Comments:                           |
|                                     |
| 2017 - Fall: Other                  |
| Comments:Tuck-pointed               |
|                                     |
| 2018 - Spring : No Change           |
| Comments:                           |
|                                     |
| 2018 - Fall: Repaired               |
| Comments:Whole building tuckpointed |
|                                     |

| HA No | Material Description              | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 30    | Exterior Brick Mortar - Non AHERA |                   |                | Exterior of Building |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                     |
|-------------------------------------|
| 2016 - Fall: No Change              |
| Comments:                           |
|                                     |
| 2017 - Spring: No Change            |
| Comments:                           |
|                                     |
| 2017 - Fall: Other                  |
| Comments:Tuck-pointed               |
|                                     |
| 2018 - Spring : No Change           |
| Comments:                           |
|                                     |
| 2018 - Fall: Repaired               |
| Comments:Whole building tuckpointed |
|                                     |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 31A   | Interior Casing Caulk | 7000              | LF             | A Building, 3rd Floor (Rm 313, Elec. Box), 2nd Floor (SW Stairway, Rm 164 Entrance) |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description  | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 31B   | Interior Casing Caulk | 7000              | LF             | B building, Auditorium E. Hallway S. Door, Rm 536, 1st Floor Hallway Storage Cabinet |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description              | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 32A   | Exterior Casing Caulk - Non AHERA |                   |                | A Building, (Rm 187, 159, SW Entrance), B Building (N, NE, SE Entrances) |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description              | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 32B   | Exterior Casing Caulk - Non AHERA |                   |                | A Building, (Rm 187, 159, SW Entrance), B Building (N, NE, SE Entrances) |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description    | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 33    | Fiberglass Pipe Fitting |                   |                | B Building, Pool Equipment Room |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location                           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34    | Carpet Mastic        | 28000             | SF             | A Building, Offices, Classrooms, Auditorium |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34.1  | Gray Carpet Adhesive | 3875              | SF             | Office, Spotlight Room, Projection Room, 242B, 525B & 611A |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34.10 | Brown/Green/Light Brown Carpet Adhesive | 750               | SF             | Room 613          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34.11 | Green Carpet Adhesive |                   |                | Room 236C         |               | Miscellaneous     |         | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description  | Material Quantity | Material Units | Material Location                          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34.2  | Brown Carpet Adhesive | 6000              | SF             | Library 234, All Rooms Branching Off, 242B |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location                          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34.3  | Blue Carpet Adhesive |                   |                | Main Office Rear Room, Rooms 165, 167A,238 |               | Miscellaneous     |         | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description        | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34.4  | Bright Blue Carpet Adhesive | 1320              | SF             | Room 270          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description        | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34.5  | Light Brown Carpet Adhesive | 750               | SF             | Room 153          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description           | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34.6  | Gray/White Mix Carpet Adhesive | 1700              | SF             | Room 145, 168A    |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34.7  | Brown/Light Brown Carpet Adhesive | 1320              | SF             | Rooms 192 & 193   |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description     | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34.8  | Gray/Red Carpet Adhesive | 5950              | SF             | Auditorium Balcony |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description             | Material Quantity | Material Units | Material Location         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34.9  | Blue/Blue/Orange Carpet Adhesive | 2404              | SF             | Rooms 611, 612, 616 & 620 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description     | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 35    | Science Lab Black Tables |                   |                | A Building Rms 346, 347, 349, 350, 351, 353, 354, 355, 383, 363, 361 & 360 |               | Miscellaneous     | No      |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 36    | A Building Roof Material |                   |                | A Building Roof   |               | Surface           |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2016 - Fall: No Change  |
| Comments:   |
|   |
| 2017 - Spring: No Change  |
| Comments:   |
|   |
| 2017 - Fall: Other  |
| Comments:Old roof off temp roof on to be completed summer of 2018 |
|   |
| 2018 - Spring : No Change   |
| Comments:   |
|   |
| 2018 - Fall: Other  |
| Comments:New roof   |
|   |

| HA No | Material Description     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 37    | B Building Roof Material |                   |                | B Building Roof   |               | Surface           |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2016 - Fall: No Change  |
| Comments:   |
|   |
| 2017 - Spring: No Change  |
| Comments:   |
|   |
| 2017 - Fall: Other  |
| Comments:Some replaced some temp some not to be replaced until summer of 2018 |
|   |
| 2018 - Spring : No Change   |
| Comments:   |
|   |
| 2018 - Fall: Other  |
| Comments:New roof   |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description        | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 38    | Blue Floor Matting Adhesive | 2400              | SF             | Room 544          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 39    | Red Floor Matting Adhesive | 2500              | SF             | Room 540          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 40    | White Stair Treads   | 90                | SF             | Pool Steps        |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description        | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 41    | White Stair Treads Adhesive | 90                | SF             | Pool Steps        |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 42    | 4" Black Vinyl Baseboard | 266               | LF             | Rooms 144 & 167   |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 43    | 4" Black Vinyl Baseboard Adhesive | 266               | SF             | Rooms 144 & 167   |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 44    | 4" Brown Vinyl Baseboard | 156               | LF             | Rooms 146B, 150   |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 45    | 4" Brown Vinyl Baseboard Adhesive | 156               | LF             | Rooms 146B, 150   |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                               | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 46    | Chalk Board/Poster Board/<br>Marker Board Adhesive | 11000             | SF             | Classrooms        |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description      | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 47    | Brown/Gray Swirl Flooring | 1320              | SF             | Room 340          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description               | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 48    | Brown/Gray Swirl Flooring Adhesive | 1320              | SF             | Room 340          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description          | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 49    | 2' x 4' Lay in Ceiling Panels | 1320              | SF             | Room 340          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 50    | Lab Counters & Sinks | 200               | SF             | Room 340          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 51    | Fume Hood            | 20                | SF             | Room 340          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 52    | Lab Table Top        | 20                | SF             | Room 346          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 53    | Lab Sink Tops        | 45                | SF             | Rooms 346, 349    |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 54    | Flange Gaskets       | 8                 | SF             | Pool Equipment Room |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                             | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 55    | Cement Mat.on F.glass Insul. Jacket Water Heater | 200               | SF             | NE Penthouse      |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 56    | Tank Insulation      | 200               | SF             | NW Penthouse      |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: Abated       |
| Comments:New tank         |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location                                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 57    | Tank Insulation      | 200               | SF             | Equipment Room Behind Second Floor Men's Washroom |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description        | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 58    | Interior Materials in Kilns | 200               | SF             | Room 627          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description      | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 59    | Tan Mix Terrazzo Flooring | 14000             | SF             | Kitchen, 1st-3rd Floor Service Areas, Stairwells, Room 359 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 60    | Grey Mix Carpet Adhesive | 800               | SF             | Room 145          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description         | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 61    | Black Stairway Landing Tread | 500               | SF             | Stairway          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 62    | Black Stairway Adhesive | 500               | SF             | Stairways         |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 63    | Brown Stairway Tread | 300               | SF             | Auditorium        |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description          | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 64    | Brown Stairway Tread Adhesive | 300               | SF             | Auditorium        |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 65    | Yellowish Terrazzo   | 3000              | SF             | Gym Lobby         |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description             | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 66    | 9"x9" Carmel w/White Streaks VFT | 200               | SF             | Room 538A         |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 67    | 9"x9" Carmel w/White Streaks VFT Mastic | 200               | SF             | Room 538A         |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 68    | 12"x12" Carmel VFT   | 550               | SF             | 1st Floor Middle Hallway |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description      | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 69    | 12"x12" Carmel VFT Mastic | 550               | PERCENT        | 1st Floor Middle Hallway |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description  | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 70    | Vault Door Insulation | 42                | SF             | Main Office       |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description              | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 71    | hot Water Storage Tank Insulation | 160               | SF             | Penthouses NE and NW |               | TSI               | Yes     | Dist        | 10              |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*



---

Robert Christlieb

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***

NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Marie Sklodowska Curie Metropolitan High School

Date: 12/3/2018

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**