Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Chicago Technology Academy High School 63091 4810 School: **Oracle Unit: Building ID:** Address: 1301 W. 14th Region: 03 Mail Room: Asbestos Surveyor: Brown, Lloyd X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/10/2019 Email Address: lbrown110@cps.edu A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type 1' x 1' Ceiling Tile w/Large YES X NO Throughout Facility 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

		Quantity	Units		Type	Category		Туре	Quantity	Units		
2	2.5' x 8' Ceiling Tile			Gymnasium							YES	X NO
2016 - Fall: N	No Change				\neg							
Comments:	J											
2017 - Fall: N	No Change											
Comments:	-											
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
3	Hard Ceiling Plaster			Throughout Facility							YES	X NO
2016 - Fall: N	No Change											
Comments:	-											

Material

Friable

Damage

Damage

Damage

HA No

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material Description

Material

Material

Material Location

Page 2

6	1' x 1' Ceiling Tile w/Small Holes			Throughout Facility							YES	X NO
2016 - Fall: N	lo Change]							
Comments:]							
2017 - Fall: N	lo Change											
Comments:					 							
2017 - Spring	j: No Change											
Comments:					 							
2018 - Fall: N	lo Change											
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
8	1' x 1' Ceiling Tile w/Large Holes Adhesive			Throughout Facility							YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

10	9" x 9" Olive Floor Tile w/Dark Specks	9100	SF	Rooms 106, 112, 114, 118, 119, 203-207, 218, Rec Room & Hall		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: I	No Change		•	•]						
Comments:					1						
2017 - Fall: I	No Change				=						
Comments:					1						
2017 - Sprin	g: No Change				=						
Comments:											
2018 - Fall: I	No Change				-						
Comments:	-				1						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	9" x 9" Olive Floor Tile w/Dark Specks Mastic	9100	SF	Rooms 106, 112, 114, 118, 119, 203-207, 218, Rec Room & Hall		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Oracle Unit: 63091

12	9" x 9" Beige Floor Tile	350	SF	Office, Rooms 117, 121, 201, 202, 211. 213, 214, 215, 219		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change			<u> </u>]						
Comments:											
2017 - Fall:	No Change				-						
Comments:	:]						
2017 - Spri	ng: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:			•								

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	9" x 9" Beige Floor Tile Mastic	350	SF	Office, Rooms 117, 121, 201, 202, 211. 213, 214, 215, 219		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	9" x 9" Light Brown Floor Tile w/Specks	15000	SF	117, 211, 213, 215, 217, 219, 221, Office		Miscellaneous	No	None	0		YES X NO
											_

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	9" x 9" Light Brown Floor Tile w/Specks Mastic	15000	SF	Rooms117, 211, 213, 215, 217, 219, 221, Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

16	9" x 9" Olive Floor Tile w/White Specks	6850	SF	Office, Rooms 201, 202, 203, 205, 207, 209, Storage		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change		<u> </u>]						
Comments:	J										
2017 - Fall: N	lo Change										
Comments:	-										
2017 - Spring	j: No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:	·			·							
					j						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
17	9" x 9" Olive Floor Tile w/White Specks Mastic	6850	SF	Office, Rooms 201, 202, 203, 205, 207, 209, Storage		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

Material

Quantity

Material

Units

HA No

Material Description

2018 - Fall: No Change Comments:

18	9" x 9" Brown FT patch w/Multi-Colored Streaks	200	SF	Rooms 115,121, 203, 205, 207, 209, 213, 214		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change				1						
Comments:											
2017 - Fall:	No Change										
Comments:	- To Gridings				= -						
2017 - Sprin	g: No Change				-						
Comments:					- -						
2018 - Fall:	No Change										
Comments:											
]						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
19	9"x9" Brn FT Patch w/Multi- Colored Strks Mastic	200	SF	1st and 2nd floor Corridors, Rooms 115, 121, 203, 205, 207, 209, 213, 214		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

20	9" x 9" Brown Floor Tile w/Orange Specks- Removed			Patches Throughout Second Floor Corridor							YES	X NO
2016 - Fall: N	Jo Change				1							
Comments:	10 Onlange											
					1							
2017 - Fall: N	No Change				1							
Comments:					1							
]							
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
04	9" x 9" Brown Floor Tile w/			Patches Throughout							VEC	X NO
21	Orange Specks Mastic- Removed			Second Floor Corridor							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	9" x 9" Cream Floor Tile Patch	200	SF	205, 207		Miscellaneous	No	None	0		YES X NO
					-						

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	9" x 9" Cream Floor Tile Mastic Patch	210	SF	205, 207		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessn	nent Category
24	9" x 9" Tan Floor Tile Patch	20	SF	206		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change												

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	9"x 9" Tan Floor Tile Mastic Patch	20	SF	Patches in 206		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

26	9" x 9" Aqua Floor Tile - REMOVED			1st Floor Corridor Across From the Boiler Room		Miscellaneous					YES	X NO
2016 - Fa	II: No Change]							
Comment												
2017 - Fa	II: No Change											
Comment	S:											
2017 - Sp	ring: No Change											
Comment	s:				=							
2018 - Fa	II: No Change											
Comment	s:				=							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
27	9" x 9" Aqua Floor Tile Mastic - REMOVED			1st Floor Corridor Across From the Boiler Room		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No

Material Description

Mastic - REMOVED

2016 - Fall: No Change

Comments:

Material

Units

Material

Quantity

Material Location

From the Boiler Room

Change in Assessment Category

Damage

Units

28	w/Streaks - REMOVED			Floor Corridor		Miscellaneous					YES	X NO
2016 - Fall:	No Change				1							
	140 Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
29	9" x 9" Gray Floor Tile w/ Streaks Mastic- Removed			As Patches in the Second		Miscellaneous					YES	X NO

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

HA No

28

Material Description

9" x 9" Gray Floor Tile

Streaks Mastic- Removed

2016 - Fall: No Change

Comments:

Material

Units

Material

Quantity

Material Location

Floor Corridor

As Patches in the Second

Change in Assessment Category

X NO

YES

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12" x 12" White Floor Tile w/Specks & Streaks	220	SF	Various Locations Throughout First Floor		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	No Change]						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12"x12" White Floor Tile w/Specks & Streaks Mastic	200	SF	Various Locations Throughout First Floor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Cateo	jory
32	12" x 12" Beige Floor Tile w/Wh & Brn Strks	450	SF	Throughout Facility		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: N	lo Change]							

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12" x12" Beige Floor Tile w/ Wh & Brn Strks Mastic	450	SF	Throughout Facility		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

34	12"x12" Tan Floor Tile w/White and Brown Streaks	1679	SF	Throughout Facility		Miscellaneous	No	None	0		YES	X NO
0040 5 11 1	N. O.				7							
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:	-											
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
					1							
•					_							
ΗΔ Νο	Material Description	Material	Material	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

No

Friable

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

35	w/Wh and Brn Streaks Mastic	1679	SF	Room, 111, 1st floor hallway, 2nd floor hallway
2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				

Quantity

1679

Units

SF

HA No

35

Material Description

12"x12" Tan Floor Tile

w/Wh and Brn Streaks

Material

Units

Material

Quantity

Material Location

Throughout Facility, Main

Office, Rm 109, Lunch

Change in Assessment Category

X NO

36	12" x 12" Brown Floor Tile w/Multi-Colored Specks	100	SF	Throughout Facility		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments					1							
Comments	•				-							
2017 - Fall:	No Change											
Comments												
2017 - Spri	ng: No Change											
Comments	:											
0040 5 11												
	No Change											
Comments	:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
	12"x12" Brn Floor Tile			Kitabaa Otaaaa Daaaa								

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

37

Comments:

Comments:

Comments:

Comments:

Material Description

w/Multi-Colored Spks

Mastic

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material

Quantity

Material

Units

Material Location

Kitchen Storage Room on

platform

YES

X NO

38	12" x 12" White Floor Tile w/Gray Specks	2500	SF	Gymnasium	Miscellaneous	No	None	0	YES	X NO
2016 - Fall	: No Change									
Comments	:									
2017 - Fall	: No Change									
Comments	:									
2017 - Spri	ing: No Change									
Comments	:									
2018 - Fall	: No Change									

Material

Category

Asbestos

Type

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12" x 12" White Floor Tile w/Gray Specks Mastic	4000	SF	Gymnasium		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessmer	t Category
40	12" x 12" Dark Gray Floor Tile w/Brown Specks	100	SF	Room 214		Miscellaneous	No	None	0		YES	NO
2016 - Fall:	: No Change											
Comments:	:											
2017 Fall:	No Changa											

2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12"x12" Dark Gray Floor Tile w/Brown Specks Mastic	100	SF	Room 214		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 19

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
42	12"x12" Tan Floor Tile w/Brown & White Specks	20	SF	As Patches in 2nd Floor Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12"x12" Tan Floor Tile w/Brn & White Specks Mastic	20	SF	As Patches in 1st Floor Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

											l	
44	1'x1' Ceiling Tile With Small Holes Glue			Throughout Facility							YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	.o oago											
2017 Fall: N	la Changa				_							
2017 - Fall: N Comments:	io Change				-							
Comments.					-							
2017 - Spring	g: No Change				1							
Comments:												
0040 Falls N	la Obasa				-							
2018 - Fall: N	io Change				_							
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
45	Vibration Isolator Cloth			Gymnasium							YES	X NO
2016 - Fall: N	lo Change	<u> </u>		<u> </u>	1							
Comments:					1							
					1							

Material

Category

Asbestos

Type

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

	·	Quantity	Units		Туре	Category		Туре	Quantity	Units		3 ,
46	Interior Window Glaze			Throughout Facility							YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
	ng: No Change											
Comments:												
2018 - Fall:	•											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
47	Roof Field - Not AHERA			Roof		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:												

Material

Asbestos

Damage

Damage

Damage

Friable

HA No

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material Description

Material

Material

Material Location

Page 22

48	Roof Flashing - Not AHERA			Roof		Miscellaneous					YES	X NO
2016 - Fall:	No Change				1							
Comments:	<u> </u>]							
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
49	Parapet Wall Light Color Caulk - Not AHERA			Roof Parapet Wall		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

50	Parapet Wall Dark Color Caulk - Not AHERA			Roof Parapet Wall		Miscellaneous					YES	X NO
2016 - Fall:	No Change				1							
Comments:												
2017 - Fall:	No Change				-							
Comments:	110 Ondrigo]							
2017 - Sprin	ng: No Change				-							
Comments:	· ·											
2018 - Fall:	No Change											
Comments:]							
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
51	Exterior Brick - Not AHERA			Exterior		Miscellaneous					YES	X NO
2016 - Fall:	No Change	•	•	•]	•	•	•	•	•	•	
Comments:	· · · · · · · · · · · · · · · · · · ·				1							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Material Description

Material

Units

Material

Quantity

Material Location

52	Exterior Brick Mortar - Not AHERA			Exterior		Miscellaneous					YES	X NO
2016 - Fall	: No Change				7							
Comments												
2017 - Fall	: No Change											
Comments	:				-							
	ing: No Change											
Comments): 				_							
	: No Change											
Comments): -				-							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
53	Exterior Window Glaze - Not AHERA			Exterior		Miscellaneous					YES	X NO
2016 - Fall	: No Change				7							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

54	Not AHERA			Exterior		Miscellaneous					YES	X NO
2016 - Fall: N	o Change				1							
Comments:	-				1							
2017 - Fall: N	lo Change				_							
Comments:] -							
2017 - Spring	: No Change				-							
Comments:					-							
2018 - Fall: N	o Change				-							
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
55	Carpet Mastic			Room 212		Miscellaneous		None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

56	12" x 12" Beige w/Streaks Mottled Floor Tile	8000	SF	1st/2nd Floor Corridors, Principal's Office, Room 214 and 1A		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change				1						
Comments:											
Comments.					_						
2017 - Fall:	No Change				-						
Comments:]						
2017 - Sprir	ng: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
]						

Type

Material

Category

Material

Friable

Friable

Damage

Damage

Type

Damage

Quantity

Damage

Damage

Damage

Units

		Quantity	Units		Туре	Category		Туре	Quantity	Units	3
57	12"x12" Beige w/Streaks Mottled Floor Tile Mastic	8000	SF	1st/2nd Floor Corridors, Principal's Office, Room 214 and 1A		Miscellaneous	No	None	0		YES
2016 - F	Fall: No Change				1						
Comme											
2017 - F	Fall: No Change										
Comme	ents:										
2017	Spring: No Chango				_						

Asbestos

2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No

HA No

Material Description

Material Description

Material

Material

Units

Material

Quantity

Material

Material Location

Material Location

1st/2nd Floor Corridors,

Change in Assessment Category

Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	12"x12"Off-White w/Mauve & Blue Streaks Floor Tile	820	SF	Patches in Main Office, Library		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change]						

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	12"x12"Off-White w/Mauve & Blue Streaks FT Mastic	820	SF	Patches in Main Office, Library		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

60	12" x 12" Beige w/Dk. Beige Streaks Floor Tile	5000	SF	102 & 101 (Checkboard pattern)		Miscellaneous	No	None	0	YES	X NO
2016 - Fa	II: No Change										
Comment					-						
Comment	.s.				+						
2017 - Fa	II: No Change										
Comment	S:										
2017 - Sp	ring: No Change				-						
Comment											
2018 - Fa	II: No Change										
Comment											
]						

Type

Asbestos

Type

Material

Material

Category

Category

Friable

Friable

No

Damage

Damage

Type

None

Type

Damage

Quantity

Damage

Quantity

0

Damage

Damage

Units

Units

61	12" x 12" Brownish Gray w/Streaks FT	5000	SF	Rooms 107, 105, 103, 102 & 101 (Checkboard pattern)		Miscellaneous
2016 - Fall: N	o Change]	
Comments:					-	
2017 - Fall: No	o Change					
Comments:					-	
2017 - Spring:	: No Change					
Comments:				·		
2018 - Fall: N	o Change					
Comments:						

Material

Quantity

Material

Material

Units

Units

Material

Quantity

Material Location

Rooms 107, 105, 103,

Material Location

Rooms 107, 105, 103,

HA No

HA No

Material Description

12" x 12" Beige w/Dk.

Material Description

Change in Assessment Category

Change in Assessment Category

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Catego
62	Mastic for HA 60 & 61 (Checkboard pattern)	10000	SF	Rooms 107, 105, 103, 102 & 101		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change]						

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	12x12 White FT Patch	10	SF	Room 109		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

64	12x12 White FT Patch Mastic	10	SF	Room 109	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	9x9 Grey with White Specs	72	SF	Rm. 104C in Boiler Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

66	9x9 Grey with White Specs Mastic	72	SF	Rm. 104 C in Boiler Room		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change]						
	o Change										
Comments:											
0017 0 :	N. 61				1						
2017 - Spring	: No Change										
Comments:											
Oommonto.											
2017 - Fall: N	o Change										
Comments:	-										
Committeents.											
2018 - Fall: N	o Change										

Material

Category

Friable

Damage

Type

Asbestos

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	Dark Grey Carpet Mastic	264	SF	Rm. 109		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

68	Blue with Blue Specs			Rm. 113, 115		Miscellaneous					YES	X NO
2016 - Fall:	No Change				7							
Comments:	<u> </u>											
2017 - Sprin	ng: No Change											
Comments:												
2017 - Fall:												
Comments:					_							
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

Damage

Quantity

0

None

Damage

Units

69	12x12 Grey with White Green Burgundy Specs	1440	SF	Lunch Room, 109					
2016 - Fall: N	o Change								
Comments:		<u>.</u>	<u> </u>						
2017 - Fall: N	o Change								
Comments:									
	·								
2017 - Spring	: No Change	<u>.</u>	<u> </u>						
Comments:									
	·								
2018 - Fall: N	2018 - Fall: No Change								
Comments:									

Material

Quantity

Material

Units

Material Location

HA No

Material Description

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70	Blue with Blue Specs Mastic	1200	SF	Rm. 113, 115		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	12x12 Grey with White Green Burgundy Specs	1440	SF	Lunch Room, Rm. 109		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessn	nent Category
72	Green Grout Floor (Ceramic)	700	SF	1st Floor Men's Toilet, Unisex Toilet		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments:	No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	Beige Floor Grout (Ceramic)	500	SF	1st Floor Women's Toilet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Page 35

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
74	Brown Floor Grout (Ceramic)	1000	SF	2nd Floor Girls/Boys Toilet		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2040 Falls No Obassas	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category		
75	9x9 Salmon Floor Tile	10	SF	Rm. 219		Miscellaneous	No	None	0		YES X NO		

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	ent Category
76	9x9 Salmon Floor Tile Mastic	10	SF	Rm. 219		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	Ceramic Floor Tile	3000	SF	1st/2nd Floor Stair Wells & Landings		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

78	Yellow Linoleum	3000	SF	Rms. 101, 102		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change	<u> </u>		<u>- </u>]							
Comments:	-											
2017 - Fall: N	No Change											
Comments:					 							
	g: No Change											
Comments:					-							
2018 - Fall: I	No Change											
Comments:												
					J							
HA No	Material Description	Material	Material	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

TIANO	iviaterial Description	Quantity	Units	Waterial Education	Type	Category	Thabic	Type	Quantity	Units	Orlange in Assess	Sment Oategory
79	Yellow Linoleum Mastic	3000	SF	Rms. 101, 102		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												
2017 - Fall: N	o Change											

Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
80	2' X 4' Ceiling Tile	3000	SF	Rms. 101, 102		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fal	II: No Change											
Comments	s:											
2017 - Spr	ring: No Change											
Comments	S:											
2017 - Fal	II: No Change											
Comments	S:											
2018 - Fal	II: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
81	Elbows on Runs	6	SF	Gym		TSI	Yes	Loc	2		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Comments:

2016 - Fall: N	No Change										
Comments:	V										
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	No Change										
Comments:											
2018 - Fall: N	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor

TSI

Asbestos

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

Loc

None

Damage

Quantity

2

Damage

Units

HA No

82

С

2016 - Fall: No Change

Material Description

Wall Board Glue Pucks

Cardboard Insulation on

Material

Quantity

150

Material

Units

SF

Material Location

All Classrooms

Boiler Room

Change in Assessment Category

X NO

X NO

YES

YES

D	Hard Joint Cmpd. On Cardboard Pipe Insulation			Boiler Room		TSI		None			YES	X NO
2016 - Fall	I: No Change]							
Comments]							
2017 - Spr	ing: No Change											
Comments	S:											
2017 - Fall	I: No Change											
Comments	S:				_							
2018 - Fall	I: No Change											
Comments	S:				_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

TSI

Asbestos

Type

Material

Category

Friable

Yes

None

0

Damage

Туре

Damage

Quantity

Damage

Units

_	7 Aircent ipe insulation	230		Ceilings, Teacher Storage Room 110B				
2016 - Fall: N	o Chango							
_	o Change							
Comments:								
2017 - Fall: N	o Change							
Comments:								
2017 - Spring	: No Change							
Comments:								
2018 - Fall: N	o Change							
Comments:	·			·				
1		·	·	·				

258

LF

HA No

Е

Material Description

Aircell Pipe Insulation

Material

Quantity

Material

Units

Material Location

Gym Storage, Boiler Room, Unexcavated Area, Above Corridor

Page 41

YES

X NO

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
F	Hard Joint Compound on Aircell Pipe Insulation	50	SF	Gym Storage, Boiler Room, Unexcavated Area, Above Corridor Ceilings		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
					1							

Material

Friable

Damage

Damage

2010 - I all. No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Mag Block Insulation on Domestic Water Tank			Boiler Room							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Damage Change in Assessment Category

Н	Water Main Line Insulation			Boiler Room		Miscellaneous					YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:					_							
2018 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
J	Mag Block Insulation	10	LF	Boiler Room, Gym Storage		TSI	Yes	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Storage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	Duct Jacket	320	SF	Boiler Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Chicago Technology Academy High School
Date: 1/18/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Oracle Unit: 63091 Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.