

Chicago Public Schools

6 Month Asbestos Surveillance

2018 - Fall

School: Perspectives - Math and Science Academy
Address: 3663 S. Wabash

Oracle Unit: 66056
Region: 04

Building ID: 5570
Mail Room: 42

Asbestos Surveyor: Hamp, Mr. Alexander
Survey Date: 12/26/2018
Email Address: _____

CHECK HERE IF NO CHANGE TO ASBESTOS

A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via:
 Each child's backpack
 Notice printed in school's newsletter
 Notice printed in school's calendar
 Other |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 1 | 9"x9" Brown Floor Tile | | | 1944 Corridors | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 2A | 12"x12" Tan Floor Tile w/Pink Streaks | 50 | SF | Basement Washroom | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 2B | 12"x12" Tan Floor Tile w/Pink Streaks Mastic | 50 | SF | Basement Washroom | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 2C | 12"x12" Brown Floor Tile w/Black and Tan Streaks | 900 | SF | Rm. 200 (106, 107, 201-208, 301- 303, 305 - 308, Teachers Lounge & 2nd & 3rd Floor Corridor of 1944 Building) | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 2D | 12"x12" Rose Floor Tile w/Black and White Streaks | 900 | SF | Rm. 200 (106, 107, 201-208, 302, 303, 305, 307, 308 and 2nd & 3rd Floor Corridor of 1944 Building) | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 2E | 12"x12" Tan Floor Tile w/Black Streaks | 50 | SF | Teacher's Lounge Ramp | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 2F | 12"x12" Gray Floor Tile w/Black and White Streaks | | | 1st and 3rd Floor Corridors of 1944 Building and Room 107 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 2G | 12"x12" Maroon and Black Floor Tile | | | 3rd Floor Corridor of 1944 Building, Room 106 and Room 307 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 2H | 12"x12" Beige Floor Tile w/Rose Streaks | 22000 | SF | 109, 111,113,115,117,119,121,210,212-215, 217, 219, 221,309-315,317,319, 321, All Corridors | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 2I | 12"x12" Brown Floor Tile w/Black and Tan Streaks | 1000 | SF | Rm. 200 (All Purpose Room, 2nd Floor Corridor of 1944 Building, Room 302, and Room 307) | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 2J | 12"x12" Rose Floor Tile w/White Streaks | 1000 | SF | 1st, 2nd & 3rd Floor Corridors of 1944 Building, 105, 106, 303, 304, 306, 307 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 3/3A | Gray Linoleum and Mastic | | | 116, 114, 211 | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 4 | Plaster | | | Throughout 1944 Building | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 5 | Plaster | | | Throughout 1957 Building | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 6 | Number Skipped | | | | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 7 | 9"x 9" Brown Floor Tile w/ White Streaks Mastic | | | Corridors in 1944 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8A | 12"x12" Tan Floor Tile w/Pink Streaks Mastic | 10 | SF | Basement Washroom | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8B | 12"x12" Pink Floor Tile w/White Streaks Mastic | | | Basement Washroom and 3rd Floor Corridor of 1944 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8C | 12" x 12" Brown FT w/Blk & Tan Streaks Mastic | | | Basement Washroom, 301, 302, 306, 307 and 3rd Floor Corridor of 1944 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8D | 12"x12" Rose Floor Tile w/Black and White Streaks | | | 106, 107, 201- 208, 302, 303, 305, 307, 308 and 2nd & 3rd Floor Corridor of 1944 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8E | 12"x12" Tan Floor Tile w/Black Streaks Mastic | 50 | SF | Teacher's Lounge Ramp | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8F | 12"x12" Gray Floor Tile w/Blk and Wh Strks Mastic | | | 1st and 3rd Floor Corridors of 1944 Building and Room 107 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8G | 12"x12" Maroon and Black Floor Tile Mastic | | | 3rd Floor Corridor of 1944 Building, Room 106 and Room 307 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8H | 12"x12" Beige Floor Tile w/Rose Streaks Mastic | 22000 | SF | 105,106,109, 111,113,115,117,119,121,210,212-215, 217, 219, 221,309-315,317,319, 321, All Corridors | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8I | 12"x12" Brn Floor Tile w/Blk & Tan Streaks Mastic | | | All Purpose Room, 2nd Floor Corridor of 1944 Building, Room 302, and Room 307 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8J | 12"x12" Rose Floor Tile w/White Streaks Mastic | | | 1st, 2nd & 3rd Floor Corridors of 1944 Building, 105, 106, 303, 304, 306, 307 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 9 | Linoleum Mastic | | | 116, 114, 211 | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10 D | 9"x9" Flesh Colored Floor Tile | | | 110 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10A | 9" x 9" Beige Floor Tile w/Rose Streaks | 2750 | SF | 1st, 2nd, and 3rd Floor Corridors of 1957 Building, Rm. 118 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10B | 9"x9" Rose Floor Tile w/White Streaks | 2750 | SF | 1st, 2nd, and 3rd Floor Corridors of 1957 Building and Room 116 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10C | 9"x9" Dark Pink Floor Tile w/White Streaks | 50 | SF | 1st, 2nd, and 3rd Floor Corridors of 1957 Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10E | 9"x9" Tan Floor Tile w/Dark Pink Streaks | 100 | SF | 3rd Floor Corridor of 1957 Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11A | 9" x 9" Beige Floor Tile w/Rose Streaks Mastic | 1500 | SF | 1st, 2nd, and 3rd Floor Corridors of 1957 Building and Room 116 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11B | 9"x9" Rose Floor Tile w/White Streaks Mastic | 1500 | SF | 1st, 2nd, and 3rd Floor Corridors of 1957 Building and Room 116 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11C | 9"x9" Dark Pink Floor Tile w/White Streaks | 50 | SF | 1st, 2nd, and 3rd Floor Corridors of 1957 Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11D | 9" x 9" Flesh Colored Floor Tile Mastic | | | Room 110 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11E | 9" x 9" Tan Floor Tile w/ Dark Pink Streaks Mastic | 100 | SF | 3rd Floor Corridor of 1957 Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 12A | 12"x12" Gray Floor Tile | | | Lunchroom | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 12B | 12"x12" Flesh Colored Floor Tile | | | Kitchen Office | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 12C | 12"x12" Gray Floor Tile w/Brown and White Streaks | 196 | SF | Washrooms in 116, 216, 316 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 13A | 12"x12" Gray Floor Tile Mastic | | | Lunchroom | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 13B | 12"x12" Flesh Colored Floor Tile Mastic | | | Kitchen Office | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 13C | 12"x12" Gray Floor Tile w/Brn & Wh Streaks Mastic | 196 | SF | Washrooms in 116, 216, 316 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 14 | 18"x24" Brown Border Floor Tiles | 1000 | SF | Throughout 1944 Building, Rm. 200 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 15 | 18"x24" Brown Border Floor Tiles Mastic | 1000 | SF | Throughout 1944 Building, Rm. 200 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 16 | Black and White Ceramic Tile Grout | | | 1944 Building Washrooms | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 17 | 1"x1" Ceramic Tile Grout | 40 | SF | 110 and 114 Washrooms | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 18 | Firebrick in Incinerator | | | Boiler Room | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 19 | Cinder Block | | | Basement | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 20 | Cinder Block Mortar | | | Basement | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 21 | Block | | | Basement | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22 | Glazed Brick | | | Throughout 1957 Building | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23 | Glazed Brick Mortar | | | Throughout 1957 Building | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 24 | Glazed Brick Mortar | | | Lunchroom and Kitchen | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 25 | Glazed Brick | | | Throughout 1944 Building | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 26 | Glazed Brick Mortar | | | Throughout 1944 Building | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 27 | Terrazzo | | | 1944 Building | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 28 | Terrazzo | | | 1957 Building | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 29 | Quarry Tile | | | Kitchen | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 30 | Quarry Tile Mortar | | | Kitchen | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 31 | Interior Window Caulk | | | 1944 Building | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 32 | Interior Window Caulk | 5000 | LF | 1957 Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 33 | Baseboard | | | 109, 110, 114 | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34 | Baseboard Mastic | | | 109, 110, 114 | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 35 | Multi-Brown Ceramic Tile Grout | | | Washrooms and Entrances | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 36 | Blue Carpet Mastic | | | Rooms 104 and 311 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 37 | Blue and Purple Carpet Mastic | | | Room 220 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 38 | Gray Carpet Mastic | | | Room 108 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 39 | Purple Carpet Mastic | | | Room 216 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 40 | Insulation Inside Firedoors | 200 | SF | Boiler Room, Entrances and Exits | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 41 | Exterior Brick | | | 1944 Building | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 42 | Exterior Brick | | | 1957 Building | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 43 | Exterior Brick Mortar | | | 1944 Building | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 44 | Exterior Brick Mortar | | | 1957 Building | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 45 | Roofing Material Not AHERA | | | Roof | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 46 | Roof Flashing Material Not AHERA | | | Lower Level Roof | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 47 | 1" Brown Ceramic Tile Grout | 50 | SF | Washrooms in 110 and 114 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 48 | 12" x 12" White Floor Tile w/ Red, Blue & Yellow | | | 105 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 49 | 12" x 12" Wh Floor Tile w/ Colored Spots Mastic | | | 105 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 50 | 12" x 12" Lt. Brown w/White Speckles FT | | | Room 108 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 51 | 12" x 12" Lt. Brown w/White Speckles FT Mastic | | | Room 108 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 52 | Boiler Gaskets | 40 | LF | Boiler Room | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 53 | 12" x 12" White w/Black Speckles FT | | | Room 104 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 54 | 12" x 12" White w/Black Speckles FT Mastic | | | Room 104 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 55 | 12"X12" Lt Brown w/Specks Floor Tile | | | Gym | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 56 | 12"X12" Lt Brown w/Specks Floor Tile Mastic | | | Gym | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 57 | 12" X 12" Blotted Tan VFT | 20000 | SF | 1944 Building Rms: 101, 103, 104-108, 110, 111, 201, 203-208, 210, 301, 303-308, 310, 1st, 2nd, 3rd Floor Halls | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 58 | 12" x 12" Blotted Light Gray VFT | 750 | SF | 1944 Building Rms: 101, 103, 104-108, 110, 111, 201, 203-208, 210, 301, 303-308, 310, 1st, 2nd, 3rd Floor Halls | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 59 | 12" x 12" Blotted Gray VFT | 750 | SF | 1944 Building Rms: 101, 103, 104-108, 110, 111, 201, 203-208, 210, 301, 303-308, 310, 1st, 2nd, 3rd Floor Halls | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 60 | 12" x 12" Blotted Brown/Gray VFT | 750 | SF | 1944 Building Rms: 101, 103, 104-108, 110, 111, 201, 203-208, 210, 301, 303-308, 310, 1st, 2nd, 3rd Floor Halls | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 61 | 12" x 12" Blotted Blue VFT | 750 | SF | 1944 Building Rms: 101, 103, 104-108, 110, 111, 201, 203-208, 210, 301, 303-308, 310, 1st, 2nd, 3rd Floor Halls | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 62 | Mastic Associated with HAs: 57, 58, 59, 60, 61 | 23750 | SF | 1944 Building Rms: 101, 103, 104-108, 110, 111, 201, 203-208, 210, 301, 303-308, 310, 1st, 2nd, 3rd Floor Halls | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 63 | Lab Counter Tops | 1000 | SF | Rms. 105, 110, 111, 206, 213 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 64 | Lab Table Tops | 500 | SF | Rms. 105, 110, 111, 206, 213 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 65 | Black Sink Insulation | 1 | EA | Staff Lounge | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 66 | Brown Carpet Mastic | 300 | SF | Rm. 226 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| A | Fiberglass Pipe Insulation | | | Boiler Room | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| B1 | Bottom Tank Insulation-Abated | | | Boiler Room | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| B2 | Top Tank Insulation-Abated | | | Boiler Room | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| B3 | Tank Insulation | | | Boiler Room | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| C | Aircell Pipe Insulation | | | Basement, Tunnel, and Crawlspace | | TSI | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| D | Cementitious Joint Insulation off Aircell | | | Basement, Tunnel, and Crawlspace | | TSI | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| E | Cardboard Pipe Insulation | | | Pump Room, Tunnel, Crawlspace | | TSI | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| F | Cementitious Pipe Joint Insulation | 100 | LF | Pump Room | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| G1 | Top Tank Insulation Jacket-Abated | | | Boiler Room | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| G2 | Bottom Tank Insulation Jacket-Abated | | | Boiler Room | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| H | Wrap Around Aircell Joints | 4500 | LF | Basement, Tunnel, and Crawlspace | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.



Robert Christlieb

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Perspectives - Math and Science Academy
Date: 12/26/2018

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
-

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.